

Radon Testing Results Summary: Riverdale High School

Notes:

- The radon **Action Level** is **4.0 pCi/L**.

Legend:

- Test results **equal to or greater than the Action Level** of 4.0 pCi/L are **highlighted in red and precede a "High" value** in the "Initial Level" or "Final Level" column.

Building Name	Room Description (per floor plan)	Initial Test Date	Initial Test Kit Serial #	Initial Test Type	Initial Test Result (pCi/L)	Initial Level	Final Retest Date	Final Test Kit Serial #	Final Test Type	Final Test Result (pCi/L)	Final Level
Main Building	Video Room	8/12/21	AA128704	Detector Kit	3.0	Low					
Main Building	103	8/12/21	AA128703	Detector Kit	0.6	Low					
Main Building	Library Office	8/12/21	AA128702	Detector Kit	1.4	Low					
Main Building	Library	8/12/21	AA128705	Detector Kit	0.8	Low					
Main Building	Library	8/12/21	AA128721	Detector Kit	0.9	Low					
Main Building	102	8/12/21	AA128722	Detector Kit	0.8	Low					
Main Building	101	8/12/21	AA128723	Detector Kit	1.3	Low					
Main Building	100A	8/12/21	AA128724	Detector Kit	1.1	Low					
Main Building	100B	8/12/21	AA128752	Detector Kit	1.0	Low					
Main Building	Stairway Landing	8/12/21	AA128751	Detector Kit	1.2	Low					
Main Building	East Lockeroom A	8/12/21	AA128753	Detector Kit	0.8	Low					
Main Building	East Lockeroom B	8/12/21	AA128754	Detector Kit	1.1	Low					
Main Building	West Lockeroom	8/12/21	AA128755	Detector Kit	0.8	Low					
Main Building	124	8/12/21	AA128756	Detector Kit	2.4	Low					
Main Building	127	8/12/21	AA128757	Detector Kit	2.7	Low					
Main Building	126	8/12/21	AA128706	Detector Kit	1.7	Low					
Main Building	Gym Lobby	8/12/21	AA128720	Detector Kit	Missing	Low					
Main Building	Weight Room	8/12/21	AA128719	Detector Kit	Missing	Low					
Main Building	129	8/12/21	AA128717	Detector Kit	1.8	Low					
Main Building	Locker Area	8/12/21	AA128713	Detector Kit	1.4	Low					
Main Building	Gymnasium	8/12/21	AA128712	Detector Kit	0.8	Low					
Main Building	Gymnasium	8/12/21	AA128714	Detector Kit	0.9	Low					