

Poppy Yoder Report Photos

March 4, 2014

Slip Resistant Treads are Worn



Support Structure Deficiencies



Existing Stairs Replacement




Non-Compliant Tread/Riser Height



Stairs Require Concrete Landing



Non-Compliant Existing Aisle



Press Box Requires Renovations/Replacement



Existing ADA Ramp

Needs to extend length of bleachers

