MCHS

Construction Project Update – January 7, 2019

Construction Project Update

- Buildings
  - CTE…Work continues on interior CMU walls. Area 1 CMU to second floor deck. Second floor metal deck has been installed in Area 1 to 90%.
  - CTE…Substantial rain has caused additional delays. Scheduling meeting to be held Thursday, January 10.
  - HS…Gymnasium East and North CMU walls are complete. South and West Gym walls are in construction. Slab on Grade has been poured for Performing Arts and Auditorium Stage Sub-Floor.
  - HS…the high school schedule completion date was not presented. Should have date after Thursdays scheduling meeting.

Construction Project Update

- Next 30 days
  - Continue work on the CMU walls necessary for structural steel support CTE.
  - Spray Foam Insulation at CTE scheduled to begin January 7 pending weather.
  - Pour CTE Area 1 composite deck scheduled for January 11 pending weather.
  - Continue sub-grade work at outbuildings pending site conditions.
  - Next Progress Meeting is scheduled for February 7, 2019.

CTE Building from Bus Parking Lot



Extremely wet site conditions



Performing Arts Slab On Grade




Auditorium Stage and Main Gymnasium Walls
01/03/2019

Locker Rooms Slab on Grade




Installed flashing for Spray Foam Insulation
01/03/2019

CTE Courtyard from Machining to Construction Trades



Hallway CMU from Flex Lab to Office Conference Room



Second Floor Hallway – Health Rooms Right, HVAC Left




Office Area Below
01/03/2019



View into Flex Labs from Second Floor


Storage Mezzanine Wood Working Shop
01/03/2019


Wood Working from Storage Mezzanine
01/03/2019


Classroom/Mezzanine from Back Door Wood Working
Paint
Booth
Location
01/03/2019

Service Road connection to MCC Back Parking Lot



Service Road Behind CTE from Wood Working Door



END – Questions?