Harrison ES – Preschool Classrooms Addition & HVAC Upgrades





Harrison ES – Preschool Classrooms Addition & HVAC Upgrades



> Completed Work:

- Poured the new sidewalk adjacent to the playground and along the school building, improving the pathway for student access.
- > 80% of the concrete footers have been poured.
- > 50% of the foundation walls have been completed.

Upcoming Work / Look Ahead:

- Complete pouring of the remaining foundation walls.
- Begin excavation and pouring of the remaining footers.
- Start backfilling the slab area.
- Commence installation of drainage lines in the parking lot area.
- Reopen the egress path for safe access.




Concrete footer and foundation are in progress.





New sidewalk adjacent to the playground is in Progress.





New sidewalk adjacent to the school building improving the playground access.



Week Ending September 20, 2024



Poured sidewalk to the storage container

