



Environmental Hazards Services, L.L.C.
 7469 Whitepine Rd
 Richmond, VA 23237
 Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Client: Stohl Environmental
 3860 California Road
 Orchard Park, NY 14127

Report Number: 21-01-03839
 Received Date: 01/27/2021
 Reported Date: 02/19/2021
 Sampled By: Joseph Coleman
 Tech Certification #:

Project/Test Address: 2020L-178; West Valley School; 5359 School St; West Valley, NY 14171

Client Number:
 33-5980

Laboratory Results

Fax Number:
 716-312-8092

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-01-03839-001	178-1	01/20/2021	CLASSROOM B-109	19.1	02/04/2021	
21-01-03839-002	178-2	01/20/2021	CLASSROOM B-109	9.97	02/04/2021	
21-01-03839-003	178-3	01/20/2021	CLASSROOM B-108	3.76	02/04/2021	
21-01-03839-004	178-4	01/20/2021	CLASSROOM B-108	5.33	02/04/2021	
21-01-03839-005	178-5	01/20/2021	CLASSROOM B-107	5.74	02/04/2021	
21-01-03839-006	178-6	01/20/2021	CLASSROOM B-107	7.28	02/04/2021	
21-01-03839-007	178-7	01/20/2021	CLASSROOM B-106	7.07	02/04/2021	
21-01-03839-008	178-8	01/20/2021	CLASSROOM B-106	5.58	02/04/2021	
21-01-03839-009	178-9	01/20/2021	CLASSROOM B-105	<1.00	02/04/2021	
21-01-03839-010	178-10	01/20/2021	CLASSROOM B-105	4.35	02/04/2021	
21-01-03839-011	178-11	01/20/2021	CLASSROOM B-104	<1.00	02/04/2021	
21-01-03839-012	178-12	01/20/2021	CLASSROOM B-104	<1.00	02/04/2021	
21-01-03839-013	178-13	01/20/2021	CLASSROOM B-103	<1.00	02/04/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-01-03839

Project/Test Address: 2020L-178; West Valley School; 5359 School St; West Valley, NY 14171

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-01-03839-014	178-14	01/20/2021	CLASSROOM B-103	<1.00	02/04/2021	
21-01-03839-015	178-15	01/20/2021	CLASSROOM B-102	5.96	02/04/2021	
21-01-03839-016	178-16	01/20/2021	CLASSROOM B-102	2.06	02/04/2021	
21-01-03839-017	178-17	01/20/2021	CLASSROOM B-101	3.00	02/04/2021	
21-01-03839-018	178-18	01/20/2021	CLASSROOM B-101	<1.00	02/04/2021	
21-01-03839-019	178-19	01/20/2021	CLASSROOM C-109 LAV	23.4	02/04/2021	
21-01-03839-020	178-20	01/20/2021	CLASSROOM C-109 LEFT	<1.00	02/04/2021	
21-01-03839-021	178-21	01/20/2021	CLASSROOM C-109 RIGHT	<1.00	02/04/2021	
21-01-03839-022	178-22	01/20/2021	CLASSROOM C-107	4.14	02/04/2021	
21-01-03839-023	178-23	01/20/2021	CLASSROOM C-107	4.01	02/04/2021	
21-01-03839-024	178-24	01/20/2021	CLASSROOM C-106	4.59	02/04/2021	
21-01-03839-025	178-25	01/20/2021	CLASSROOM C-106	54.0	02/04/2021	
21-01-03839-026	178-26	01/20/2021	CLASSROOM C-105	1.08	02/04/2021	
21-01-03839-027	178-27	01/20/2021	CLASSROOM C-105	2.04	02/04/2021	
21-01-03839-028	178-28	01/20/2021	CLASSROOM C-104	13.3	02/04/2021	
21-01-03839-029	178-29	01/20/2021	CLASSROOM C-104	12.0	02/04/2021	
21-01-03839-030	178-30	01/20/2021	CLASSROOM C-103	9.96	02/04/2021	
21-01-03839-031	178-31	01/20/2021	CLASSROOM C-103	6.84	02/08/2021	
21-01-03839-032	178-32	01/20/2021	CLASSROOM C-102	<1.00	02/08/2021	
21-01-03839-033	178-33	01/20/2021	CLASSROOM C-101	<1.00	02/08/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-01-03839

Project/Test Address: 2020L-178; West Valley School; 5359 School St; West Valley, NY 14171

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-01-03839-034	178-34	01/20/2021	ROOM C-100 KITCHEN SINK	<1.00	02/08/2021	
21-01-03839-035	178-35	01/20/2021	ROOM C-100 BOYS BATHROOM	<1.00	02/08/2021	
21-01-03839-036	178-36	01/20/2021	ROOM C-100 GIRLS BATHROOM	1.32	02/08/2021	
21-01-03839-037	178-37	01/20/2021	C-117 GIRLS BATHROOM	<1.00	02/08/2021	
21-01-03839-038	178-38	01/20/2021	C118 BOYS BATHROOM	<1.00	02/08/2021	
21-01-03839-039	178-39	01/20/2021	GIRLS LOCKER ROOM	33.1	02/08/2021	
21-01-03839-040	178-40	01/20/2021	KITCHEN DISHWASHER SINK	1.36	02/08/2021	
21-01-03839-041	178-41	01/20/2021	KITCHEN LEFT SINK	3.84	02/08/2021	
21-01-03839-042	178-42	01/20/2021	KITCHEN RIGHT SINK	4.84	02/08/2021	
21-01-03839-043	178-43	01/20/2021	KITCHEN STORAGE SINK	7.45	02/08/2021	
21-01-03839-044	178-44	01/20/2021	CAFETERIA	1.31	02/08/2021	
21-01-03839-045	178-45	01/20/2021	CAFETERIA	1.26	02/08/2021	
21-01-03839-046	178-48	01/20/2021	BOYS LOCKER ROOM	<1.00	02/08/2021	
21-01-03839-047	178-49	01/20/2021	BOYS LOCKER ROOM LEFT	2.97	02/08/2021	
21-01-03839-048	178-50	01/20/2021	BOYS LOCKER ROOM RIGHT	7.14	02/08/2021	
21-01-03839-049	178-51	01/20/2021	GYM HALL NEAR C-121	1.06	02/08/2021	
21-01-03839-050	178-52	01/20/2021	GYM HALL NEAR C-121	1.32	02/08/2021	
21-01-03839-051	178-53	01/20/2021	ROOM A-103 LAV	<1.00	02/08/2021	
21-01-03839-052	178-54	01/20/2021	ROOM A-103	<1.00	02/08/2021	
21-01-03839-053	178-55	01/20/2021	ROOM A-101 LAV	1.53	02/08/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-01-03839

Project/Test Address: 2020L-178; West Valley School; 5359 School St; West Valley, NY 14171

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-01-03839-054	178-56	01/20/2021	ROOM A-101	<1.00	02/08/2021	
21-01-03839-055	178-57	01/20/2021	ROOM A-123 LAV	2.57	02/08/2021	
21-01-03839-056	178-58	01/20/2021	ROOM A-123	<1.00	02/08/2021	
21-01-03839-057	178-59	01/20/2021	ROOM A-129A GIRLS LAV	7.55	02/08/2021	
21-01-03839-058	178-60	01/20/2021	NEAR A-129A	<1.00	02/08/2021	
21-01-03839-059	178-61	01/20/2021	ROOM A-127 LEFT	<1.00	02/08/2021	
21-01-03839-060	178-62	01/20/2021	ROOM A-127 RIGHT	<1.00	02/08/2021	
21-01-03839-061	178-63	01/20/2021	ROOM A-210 WINDOW SIDE	3.75	02/08/2021	
21-01-03839-062	178-64	01/20/2021	ROOM A-210 HALLWAY SIDE	3.23	02/08/2021	
21-01-03839-063	178-65	01/20/2021	ROOM A-209 LAV	19.7	02/08/2021	
21-01-03839-064	178-66	01/20/2021	NEAR GIRLS BATHROOM 2ND FLOOR	<1.00	02/08/2021	
21-01-03839-065	178-67	01/20/2021	NEAR GIRLS BATHROOM 2ND FLOOR	1.11	02/08/2021	
21-01-03839-066	178-68	01/20/2021	2ND FLOOR GIRLS BATHROOM	10.3	02/08/2021	
21-01-03839-067	178-69	01/20/2021	2ND FLOOR BOYS BATHROOM	18.2	02/08/2021	
21-01-03839-068	178-70	01/20/2021	NEAR BOYS BATHROOM 2ND FLOOR	<1.00	02/08/2021	
21-01-03839-069	178-71	01/20/2021	NEAR BOYS BATHROOM 2ND FLOOR	<1.00	02/08/2021	
21-01-03839-070	178-72	01/20/2021	BUS GARAGE LAV	<1.00	02/08/2021	
21-01-03839-071	178-73	01/20/2021	A-107 BOYS BATHROOM	3.83	02/08/2021	
21-01-03839-072	178-74	01/20/2021	ROOM A-112	8.76	02/08/2021	
21-01-03839-073	178-75	01/20/2021	BOYS BATHROOM A-119	<1.00	02/08/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980

Report Number: 21-01-03839

Project/Test Address: 2020L-178; West Valley School; 5359 School St; West Valley, NY 14171

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-01-03839-074	178-76	01/20/2021	GIRLS BATHROOM A-120	<1.00	02/08/2021	
21-01-03839-075	178-77	01/20/2021	ROOM A-113	<1.00	02/08/2021	
21-01-03839-076	178-78	01/20/2021	ROOM A-113	<1.00	02/08/2021	
21-01-03839-077	178-79	01/20/2021	ROOM A-114	4.48	02/08/2021	
21-01-03839-078	178-80	01/20/2021	ROOM A-114	5.37	02/08/2021	
21-01-03839-079	178-81	01/20/2021	BOYS LOCKER ROOM OFFICE	8.90	02/08/2021	

Method: SM 3113B-2010
 Analyst: Jennalee Hertzler
 Accreditation #: NY 11714

Reviewed By Authorized Signatory:



Tasha Eaddy

QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-178

Client: West Valley CSD

Contact: Bill Sloand

Building: West Valley School

Location: 5359 School St, West Valley, NY 14171

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
178-1	Classroom B-109	S	23:05			
178-2	Classroom B-109	DF	23:05			
178-3	Classroom B-108	S	23:07			
178-4	Classroom B-108	DF	23:07			
178-5	Classroom B-107	S	23:10			
178-6	Classroom B-107	DF	23:10			
178-7	Classroom B-106	S	23:15			
178-8	Classsrom B-106	DF	23:15			
178-9	Classroom B-105	S	23:18			
179-10	Classroom B-105	DF	23:18			
178-11	Classroom B-104	S	23:20			
178-12	Classroom B-104	DF	23:20			
178-13	Classroom B-103	S	23:23			
178-14	Classroom B-103	DF	23:23			
178-15	Classroom B-102	S	23:26			
178-16	Classroom B-102	DF	23:26			
178-17	Classroom B-101	S	23:29			
178-18	Classroom B-101	DF	23:29			

21-01-03839



Due Date:
02/24/2021
 (Wednesday)
 AE

JM

Notes:

Please e-mail lab results to labs@stohlenv.com

If checked, also e-mail results to:

Ehenderson@StohlEnv.com

Sampled By: Joseph Coleman Print Name Joseph Coleman Stohl Env: Joseph Coleman Date: 1/20/2021

Relinquished By: E. Henderson Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 1/25/2021

Received (Name / Lab): K. Harris Date: 1.27.21 Time: 11:19 AM

Sample Login (Name / Lab): T. Ashman Date: 2/3/21 Time: 5:30

Analysis (Name / Lab): J. Hertler Date: 2/8/21 Time: 12:30pm

QA/QC Review (Name / Lab): Joshua Ruddy Date: 2/19/21 Time: 11:03 am

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-178

Client: West Valley CSD

Contact: Bill Sloand

Building: West Valley School

Location: 5359 School St, West Valley, NY 14171

LEAD
 Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
178-19	Classroom C-109 Lav	S	23:38			
178-20	Classroom C-109 Left	S	23:39			
178-21	Classroom C-109 Right	S	23:40			
178-22	Classroom C-107	S	23:42			
178-23	Classroom C-107	DF	23:43			
178-24	Classroom C-106	S	23:45			
178-25	Classroom C-106	DF	23:45			
178-26	Classroom C-105	S	23:48			
178-27	Classroom C-105	DF	23:48			
178-28	Classroom C-104	S	23:52			
178-29	Classroom C-104	DF	23:52			
178-30	Classroom C-103	S	23:53			
178-31	Classroom C-103	DF	23:54			
178-32	Classroom C-102	S	23:57			
178-33	Classroom C-101	S	0:00			
178-34	Room C-100 Kitchen Sink	S	0:10			
178-35	Room C-100 Boys bathroom	S	0:11			
178-36	Room C-100 Girls Bathroom	S	0:12			

Notes:
 Please e-mail lab results to labs@stohlenv.com

Sampled By: Joseph Coleman Print Name Joseph Coleman Date: 1/20/2021
 Relinquished By: Eric Henderson Jr. Print Name Eric Henderson Jr. Date: 1/25/2021
 Received (Name / Lab): RT HARRIS Date: 1/27/21 Time: 11:19 AM
K. Slaves
 Sample Login (Name / Lab): T. Shannon Date: 2/3/21 Time: 5:30p
 Analysis (Name / Lab): G. Dertnyler Date: 2/8/21 Time: 12:30 pm
 QA/QC Review (Name / Lab): _____ Date: _____ Time: _____
 Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-178

Client: West Valley CSD

Contact: Bill Sloand

Building: West Valley School

Location: 5359 School St, West Valley, NY 14171

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
178-37	C-117 Girls Bathroom	S	0:15			
178-38	C118 Boys Bathroom	S	0:16			
178-39	Girls Locker Room	DF	0:20			
178-40	Kitchen Dishwasher Sink	S	0:30			
178-41	Kitchen Left Sink	S	0:32			
178-42	Kitchen Right Sink	S	0:33			
178-43	Kitchen Storage Sink	S	0:34			
178-44	Cafeteria	DF	0:37			
178-45	Cafeteria	DFB	0:38			
178-48	Boys locker room	DF	0:50			
178-49	Boys locker room Left	S	1:00			
178-50	Boys locker room Right	S	1:00			
178-51	Gym hall near C-121	DFB	1:03			
178-52	Gym hall near C-121	DF	1:04			
178-53	Room A-103 Lav	S	1:08			
178-54	Room A-103	S	1:09			

Notes:

Please e-mail lab results to labs@stohlenv.com

Sampled By: Joseph Coleman Print Name Joseph Coleman Stohl Env: Joseph Coleman Date: 1/20/2021

Relinquished By: Eric Henderson Jr. Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 1/25/2021

Received (Name / Lab): RTHARRIS / K Slaves Date: 1.27.21 Time: 11:19 AM

Sample Login (Name / Lab): T. Johnson Date: 2/3/21 Time: 5:30p

Analysis (Name / Lab): G. Hertzler Date: 2/8/21 Time: 12:30pm

QA/QC Review (Name / Lab): _____ Date: _____ Time: _____

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____



Chain of Custody Document

3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS
 STOHL Job # 2020L-178

Client: West Valley CSD Contact: Bill Sloand
 Building: West Valley School Location: 5359 School St, West Valley, NY 14171

LEAD	
Water by SM 19, 21 - 23 3113B (-04, -10)	<u>X</u>
	Turnaround <u>20 Days</u>

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
178-55	Room A-101 Lav	S	1:11			
178-56	Room A-101	S	1:12			
178-57	Room A-123 Lav	S	1:14			
178-58	Room A-123	S	1:15			
178-59	Room A-129A Girls Lav	S	1:17			
178-60	Near A-129A	DF	1:18			
178-61	Room A-127 Left	S	1:20			
178-62	Room A-127 Right	S	1:21			
178-63	Room A-210 Window Side	S	1:29			
178-64	Room A-210 Hallway Side	S	1:29			
178-65	Room A-209 Lav	S	1:32			
178-66	Near girls bathroom 2nd floor	DFB	1:33			
178-67	Near girls bathroom 2nd floor	DF	1:34			
178-68	2nd Floor girls bathroom	S	1:36			
178-69	2nd Floor boys bathroom	S	1:41			
178-70	Near boys bathroom 2nd floor	DF	1:42			
178-71	Near boys bathroom 2nd floor	DFB	1:43			
178-72	Bus garage Lav	S	1:48			

Notes:
 Please e-mail lab results to labs@stohlenv.com

Sampled By: Joseph Coleman Print Name Stohl Env: Joseph Coleman Date: 1/20/2021
 Relinquished By: Eric Henderson Jr. Print Name Stohl Env: Eric Henderson Jr. Date: 1/25/2021
 Received (Name / Lab): KT HAARIS Date: 1-19-21 Time: 11:19 AM
JK Stearns
 Sample Login (Name / Lab): T. Ashman Date: 2/3/21 Time: 5:30p
 Analysis (Name / Lab): J. Hertzyler Date: 2/8/21 Time: 12:30pm
 QA/QC Review (Name / Lab): _____ Date: _____ Time: _____
 Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____



3860 California Road, Orchard Park, New York 14127
 PHONE (716) 312-0070 FAX (716) 312-8092
 WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-178

Client: West Valley CSD

Contact: Bill Sloand

Building: West Valley School

Location: 5359 School St, West Valley, NY 14171

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround 20 Days

Sample #	Location	Outlet Type	Time	Cooler Model	Lab ID	Results
178-73	A-107 boys bathroom	S	1:53			
178-74	Room A-112	S	1:56			
178-75	Boys bathroom A-119	S	1:59			
178-76	Girls bathroom A-120	S	2:00			
178-77	Room A-113	S	2:05			
178-78	Room A-113	S	2:06			
178-79	Room A-114	S	2:07			
178-80	Room A-114	DF	2:08			
178-81	Boys locker room office	S	2:10			

Notes:
 Please e-mail lab results to labs@stohlenv.com

Sampled By: Joseph Coleman Print Name Joseph Coleman Stohl Env: Joseph Coleman Date: 1/20/2021

Relinquished By: Eric Henderson Jr. Print Name Eric Henderson Jr. Stohl Env: Eric Henderson Jr. Date: 1/25/2021

Received (Name / Lab): K. Harris / J. Slaves Date: 1-27-21 Time: 11:19 am

Sample Login (Name / Lab): J. Laberna Date: 2/3/21 Time: 5:30

Analysis (Name / Lab): J. Hestler Date: 2/8/21 Time: 12:30 pm

QA/QC Review (Name/Lab): _____ Date: _____ Time: _____

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____