

# Lead in School Drinking Water Report

## Okanogan Junior / Senior High School



### EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: [leadfreekids@doh.wa.gov](mailto:leadfreekids@doh.wa.gov).

## DEFINITIONS

Fixture Housing  
Location

Room/space where  
fixture is located  
(i.e. room number,  
gym, playground)

Fixture Housing Type

Structure that contains  
the individual fixtures  
where water samples  
were collected from.  
Fixture housing may  
contain one or more  
individual fixture for  
sampling.

Fixture Location  
Details

Location within a  
room or space where  
fixture housing is  
located, starting to the  
left of the entrance and  
rotating clockwise, of  
the total number of  
fixture housings in a  
room or space  
(e.g. 1/5, 2/5)

Fixture Type

Tap, Sprayer, Water  
Fountain, Water Bottle  
Filler, Ice maker

Fixture Position

Left, Center, Right

Date(s) collected: 2024-10-09

Date(s) analyzed: 2024-10-28, 2024-10-29

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	398909	Main Building - Jr / Sr High	Sink	Science Office	1 of 2	Tap	center	160
2	398923	Shop Building	Sink - Multi-Compartment	Football Concessions	1 of 1	Tap	left	16
3	398908	Dawson Gym Building	Sink - Multi-Compartment	Concessions	2 of 2	Tap	right	11
4	398906	Dawson Gym Building	Sink - Multi-Compartment	Concessions	2 of 2	Tap	left	5
5	398904	Dawson Gym Building	Sink	Concessions	1 of 2	Tap	center	3
6	398911	Main Building - Jr / Sr High	Sink	Science Office	2 of 2	Tap	center	3
7	398913	Main Building - Jr / Sr High	Sink	Music Office	1 of 1	Tap	center	3
8	398915	Main Building - Jr / Sr High	Sink	Counselors Office	1 of 1	Tap	center	3
9	398929	Main Building - Jr / Sr High	Fountain	Middle School Playground	1 of 1	Water Fountain	center	3
10	398901	Main Building - Jr / Sr High	Sink	High School Office	1 of 1	Tap	center	2

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
11	398917	Main Building - Jr / Sr High	Sink	Library	1 of 1	Tap	center	2
12	398938	Main Building - Jr / Sr High	Sink	Rm.118	2 of 2	Tap	center	2
13	398925	Shop Building	Sink - Multi-Compartment	Football Concessions	1 of 1	Tap	right	1
14	398931	Main Building - Jr / Sr High	Fountain	Tennis Courts	1 of 1	Water Fountain	center	1
15	398936	Main Building - Jr / Sr High	Sink	Rm.118	1 of 2	Tap	center	1
16	398900	Dawson Gym Building	Fountain - Multi-Level	Main Foyer	1 of 1	Water Fountain	left	<1
17	398902	Dawson Gym Building	Fountain - Multi-Level	Main Foyer	1 of 1	Water Fountain	right	<1
18	398903	Main Building - Jr / Sr High	Fountain with Bottle Filler	High School Hallway	1 of 1	Water Bottle Filler	center	<1
19	398905	Main Building - Jr / Sr High	Fountain with Bottle Filler	High School Hallway	1 of 1	Water Fountain	right	<1
20	398907	Main Building - Jr / Sr High	Sink - Multi-Compartment	Teachers Lounge	1 of 1	Tap	center	<1
21	398910	Dawson Gym Building	Fountain with Bottle Filler	Boys Hallway	1 of 1	Water Bottle Filler	center	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
22	398912	Dawson Gym Building	Fountain with Bottle Filler	Boys Hallway	1 of 1	Water Fountain	right	<1
23	398914	Dawson Gym Building	Fountain	Main Gym	1 of 1	Water Fountain	center	<1
24	398916	Dawson Gym Building	Ice Machine	Maintenance Ice Machine	1 of 1	Other	center	<1
25	398918	Shop Building	Fountain	Metal Shop	1 of 1	Water Fountain	center	<1
26	398919	Main Building - Jr / Sr High	Fountain	Service Hallway	1 of 1	Tap	center	<1
27	398920	Shop Building	Fountain	Wood Shop	1 of 1	Water Fountain	center	<1
28	398921	Main Building - Jr / Sr High	Ice Machine	Middle School Gym	1 of 1	Other	center	<1
29	398922	Main Building - Jr / Sr High	Sink	Kitchen	2 of 4	Tap	center	<1
30	398924	Main Building - Jr / Sr High	Sink	Nurses Room	1 of 1	Tap	center	<1
31	398926	Main Building - Jr / Sr High	Sink	Staff Rm.133	1 of 1	Tap	center	<1
32	398927	Main Building - Jr / Sr High	Fountain	Football Feild	1 of 1	Water Fountain	center	<1
33	398928	Main Building - Jr / Sr High	Sink	Rm.132	1 of 1	Tap	center	<1

---

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
34	398930	Main Building - Jr / Sr High	Fountain - Multi-Level with Bottle Filler	Middle School Restroom	1 of 1	Water Fountain	left	<1
35	398932	Main Building - Jr / Sr High	Fountain - Multi-Level with Bottle Filler	Middle School Restroom	1 of 1	Water Bottle Filler	center	<1
36	398934	Main Building - Jr / Sr High	Fountain - Multi-Level with Bottle Filler	Middle School Restroom	1 of 1	Water Fountain	right	<1

---