



2150 Smithtown Ave., Suite 3, Ronkonkoma, NY 11779  
T: 631.580.3191 • F: 631.580.3195 • W: [envirohealth.org](http://envirohealth.org)

July 20, 2017

Mr. Anthony Dragone  
Greenport UFSD  
720 Front Street  
Greenport, NY 11944

RE: Lead in Water Testing

Enclosed you will find new updated charts and new lab results from your latest lead in water sampling. Please use these to replace the charts in your book. The lab results should be added to the back of each corresponding school appendix. In this way your book will continually be updated.

Thank you. If you have any questions, please feel free to contact us.

Sincerely,

Glenn Neuschwender  
President

Lead in Drinking Water Test Results

As of 7/20/17

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
3rd Fl Girls Gang BR	SK	4.08	-	-	None	-	-
<b>3rd Fl Girl's BR (Hands)</b>	<b>SK</b>	<b>16.3</b>	<b>&lt;1.0</b>	<b>&lt;1.0</b>	<b>FR</b>	<b>Completed FR</b>	<b>162 (Sept. 2, 2016) &lt;1.0 (Sept. 9, 2016)</b>
3rd Fl Hall by RM 306 (Right)	WF	ND	-	-	None	-	-
3rd Fl ADA BR	SK	3.58	-	-	None	-	-
3rd Fl Hall by Rm 315 (Right)	WF	ND	-	-	None	-	-
3rd Fl Boy's Gang BR	SK	746	-	-	None	-	-
2nd Fl Hall by RM 218 (Right)	WF	ND	-	-	None	-	-
2nd Fl Boy's Gang BR	SK	13.2	-	-	None	-	-
Room 214	SK	11.6	-	-	None	-	-
Faculty BR Men	SK	5.92	-	-	None	-	-
Faculty BR Women	SK	6.1	-	-	None	-	-
2nd Fl Hall by RM 206 (Right)	WF	ND	-	-	None	-	-
2nd Fl Girl's Gang BR (Door)	SK	2.62	-	-	None	-	-
<b>2nd Fl Girl's Gang BR (Left)</b>	<b>SK</b>	<b>16.3</b>	<b>&lt;1.0</b>	<b>&lt;1.0</b>	<b>FR</b>	<b>Completed FR</b>	<b>17 (Sept. 2, 2016) &lt;1.0 (Sept. 9, 2016)</b>
2nd Fl Girl's Gand BR (Right)	SK	11.9	-	-	None	-	-
Hall by RM 105 (Right)	WF	ND	-	-	None	-	-
<b>1st Fl Girl's Gang BR (Door)</b>	<b>SK</b>	<b>26.6</b>	<b>2</b>	<b>1.1</b>	<b>FR</b>	<b>CAP</b>	<b>-</b>
1st Fl Girl's Gang BR (Left)	SK	7.06	-	-	None	-	-
1st Fl Girl's Gang BR (Right)	SK	2.01	-	-	None	-	-
Btw RM 105 & 106 Boy's BR	SK	2.3	-	-	None	-	-
Btw RM 105 & 106 Girl's BR	SK	2.76	-	-	None	-	-

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 7/20/17

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Main Office BR	SK	2.23	-	-	None	-	-
Hall by RM 112 (Right)	WF	ND	-	-	None	-	-
1st Fl Boy's Gang BR	SK	9.83	-	-	None	-	-
Art RM 114	SS	7.26	-	-	None	-	-
Art RM 115 (Left)	SK	3.87	-	-	None	-	-
Gym Men's BR (Right)	SK	9.75	-	-	None	-	-
Gym Men's BR (Middle)	SK	25.8	2.1	1.2	FR	Completed FR	#8.2 (Sept. 2, 2016)
Gym Women's BR (Left)	SK	118	9.2	7.9	FR	Completed FR	2120 (Sept. 2, 2016) #1.0 (Sept. 9, 2016)
Gym Women's BR (Middle)	SK	30.6	6.5	4.5	FR	Completed FR	337 (Sept. 2, 2016) <1.0 (Sept. 9, 2016)
Hall by RM 150	WF	80.8	7.1	2.6	FR	CAP	-
RM 150 Auto Shop (Middle)	SS	9.62	-	-	None	-	-
RM 151 Tech RM (Middle)	SS	13.2	-	-	None	-	-
Big Gym Boy's Side	WF	ND	-	-	None	-	-
RM 152C Boy's Coaches Office BR	SK	8.34	-	-	None	-	-
Big Gym Boy's LR	WF	25	24	6.9	FRSLV	CAP	-
Big Gym Boy's LR (Right)	SK	11.8	-	-	None	-	-
Hose Bib Near Gym Storage	SP	36.7	<1.0	<1.0	FR	Completed FRSLV	#3 (Sept. 2, 2016)
RM 109 Superintendent Office BR	SK	13.6	-	-	None	-	-
Boy's Coaches RM Ice Mach	SP	94.2	1.8	1.3	FR	Completed FRSLV	<1.0 (Sept. 2, 2016)
Big Gym Girl's Side	WF	ND	-	-	None	-	-
Girls Coaches Office BR	SK	46.8	2.7	<1.0	FR	Completed FR	51 (Sept. 2, 2016) <1.0 (Sept. 9, 2016)

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 7/20/17

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
Big Gym Girl's LR	WF	874	44	8.8	FRSLV	CAP	-
Big Gym Girl's LR BR (Left)	SK	19.2	2.7	4.7	FR	Completed FR	42 (Sept. 2, 2016) #1.8 (Sept. 9, 2016)
Hall by RM 157	WF	ND	-	-	None	-	-
RM 144	SK	6.93	-	-	None	-	-
RM 145	WF	255	53	13	FRSLV	CAP	-
RM 146	SK	21.4	17	2.1	FRSLV	Completed FR	28 (Sept. 2, 2016) <1.0 (Sept. 9, 2016)
RM 147	WF	90.3	3.2	1.5	FR	CAP	-
NE ADA Boy's BR	SK	32.9	35	12	FRSLV	Completed FR	22 (Sept. 2, 2016) <1.0 (Sept. 9, 2016)
Boy's BR by RM 156	SK	17.3	5.8	2.6	FR	-	-
Girl's BR by RM 156	SK	2.05	-	-	None	-	-
RM 137 Aid's BR	SK	2.21	-	-	None	-	-
RM 144 Home Ec Station #1	SK	13.8	-	-	None	-	-
RM 144 Home Ec Station #2	SK	9.23	-	-	None	-	-
RM 144 Home Ec Station #3	SK	3.72	-	-	None	-	-
RM 144 Home Ec Station #4	SK	4.32	-	-	None	-	-
RM 144 Home Ec Station #5	SK	3.28	-	-	None	-	-
Small Gym	WF	ND	-	-	None	-	-
Kitchen 3 Piece	SK	4.69	-	-	None	-	-
Kitchen SK by Serving Line	SK	6.17	-	-	None	-	-
Kitchen SK Next to Fridge	SK	57.9	4.9	<1.0	FR	Completed FR	60 (Sept. 2, 2016) <1.0 (Sept. 9, 2016)

Action Level = 15.0 parts per billion (ppb) (ug/L)

Lead in Drinking Water Test Results

As of 7/20/17

Sample Location	Fixture Type	1 <sup>st</sup> Draw Results (ppb)	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Remedial Recommendation	Remedial Response	Post Remediation Test Results
RM 140 Aid's Break RM	SK	3.54	-	-	None	-	-
RM 101 Pre K	SK	8.1	-	-	None	-	-
RM 141 BR	SK	3.56	-	-	None	-	-
RM 102 Pre K	SS	1.7	-	-	None	-	-
Nurse Office	SK	10	<1.0	<1.0	None	-	-
Nurse Office BR	SK	2.9	1.9	1.4	None	-	-
Kitchen Handwashing	SK	6.9	<1.0	<1.0	None	-	-
1FD Auto Shop	SP	7.6			None		
2FD Exterior, O/S Business Office	SP	<1.0			None		
3FD, Exterior, Kindergarten	SP	<1.0			None		

## Code Key

### Remediation Type Codes

FR	=	Fixture replacement
FRSLV	=	Replacement of fixture, supply lines, and valves
FRSLVPA	=	Replacement of fixture, supply lines, valves and plumbing assessment
SIGN	=	Warning sign posting
CAP	=	Remove fixture or cap line

### Room ID Codes

CC	=	Custodian Closet
MPR	=	Multi Purpose Room
Café	=	Cafeteria
Sci	=	Science Lab
PE	=	Physical Ed
BR	=	Bathroom
LR	=	Locker Room
RM	=	Room

### Fixture Type Codes

WF	=	Water Fountain
SK	=	Sink
SS	=	Slop Sink
SP	=	Spigot
PF	=	Pot Filler
HB	=	Hose Bib
IM	=	Ice Machine
WC	=	Water Cooler
SH	=	Shower

### Result Code

ND	=	Not Detected
<	=	Less Than
-	=	No Testing Required

## Additional First Draw Results

**Laboratory Report**

NYE Report #: 2173695-1558

July 20, 2017

John Driscoll  
Enviroscience Consultants, Inc.  
2150 Smithtown Avenue  
Ronkonkoma, NY 11779

Project: Greenport UFSD, Greenport, NY; 2173695

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on July 18, 2017. New York Environmental analyzed the samples on July 19, 2017 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	18 Jul 2017
Date Received:	18 Jul 2017
Date Analyzed:	19 Jul 2017

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

<u>Lab ID</u>	<u>Client ID</u>	<u>Sample Location/Description</u>	<u>MDL</u>	<u>Result</u>	<u>Units</u>	<u>Flag</u>
170718P005	1	1FD, Auto Shop; Initial	1.0	7.60	µg/L	
170718P006	2	2FD Exterior, O/S Business Off; Initial	1.0	<1.0	µg/L	
170718P007	3	3FD, Exterior, Kindergarten; Initial	1.0	<1.0	µg/L	

Comment:



