

Lead Tests - Ruch Elementary School - Cafeteria/Gymnasium/Media Center/Rooms 5-6 - # 20481100						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481100-001DW	20481100-001DW21A	Media Center Work Room - Drinking Fountain	01/16/20	3.3	None.
2	20481100-002SF	20481100-002SF21A	Media Center Work Room - Sink	01/16/20	5.8	None.
3	20481100-003DW	20481100-003DW21A	Computer Room - Drinking Fountain	01/16/20	0.4	This sink has a lead filter on it.
4	20481100-004CF	20481100-004CF21A	Computer Room - Sink	01/16/20	1.6	This sink has a lead filter on it.
5	20481100-005DW	20481100-005DW21A	Gym - Drinking Fountain	01/16/20	1.7	None.
6	20481100-006KF	20481100-006KF21A	Kitchen Food Prep - Sink (Left)	01/16/20	3.2	None.
7	20481100-007KF	20481100-007KF21A	Kitchen Food Prep/Eyewash - Sink (Right)	07/24/23	6.6	None.
8	20481100-013KF	20481100-013KF21A	Kitchen - Sink (Pre-rinse/Dishwasher)	05/17/22	2.8	Faucet changed 5/16/22.
9	20481100-008KF	20481100-008KF21A	Kitchen - Sink (Hand Wash)	01/16/20	1.6	This sink has a lead filter on it.
10	20481100-009BF	20481100-009BF21A	Kitchen Unisex Restroom - Sink	03/18/20	3.4	This sink has a lead filter on it.
11	20481100-010DW	20481100-010DW21A	Room 6 - Drinking Fountain	01/16/20	5.6	None.
12	20481100-011CF	20481100-011CF21A	Room 6 - Sink	01/16/20	1.6	This sink has a lead filter on it.
13	20481100-012DW	20481100-012DW21A	Outside Room 6 - Drinking Fountain	07/24/23	0.6	This sink has a lead filter on it.
14	20481100-014BF	20481100-014BF21A	Gym - Boy's Locker Room Right Side Of The Stage - Sink (L)	05/17/22	1.6	Added Filter 05/16/22.
15	20481100-015BF	20481100-015BF21A	Gym - Boy's Locker Room Right Side Of The Stage - Sink (R)	01/16/20	11.7	
16	20481100-016BF	20481100-016BF21A	Gym - Girl's Locker Room Left Side Of The Stage - Sink (L)	01/16/20	13.1	
17	20481100-017BF	20481100-017BF21A	Gym - Girl's Locker Room Left Side Of The Stage - Sink (R)	01/16/20	12.1	
Lead Tests - Ruch Elementary School - Rooms 10-13 Building - # 20481101						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481101-001DW	20481101-001DW21A	Room 10 - Drinking Fountain	01/16/20	5.0	None.
2	20481101-002CF	20481101-002CF21A	Room 10 - Sink	01/16/20	1.6	This sink has a lead filter on it.
3	20481101-003DW	20481101-003DW21A	Room 11 - Drinking Fountain	01/16/20	3.4	None.
4	20481101-004CF	20481101-004CF21A	Room 11 - Sink	01/16/20	1.1	None.
5	20481101-005DW	20481101-005DW21A	Room 12 - Drinking Fountain	01/16/20	2.4	None.
6	20481101-006CF	20481101-006CF21A	Room 12 - Sink	01/16/20	3.9	None.
7	20481101-007DW	20481101-007DW21A	Outside Room 13 - Drinking Fountain	07/24/23	2.7	None.
8	20481101-008DW	20481101-008DW21A	Room 13 - Drinking Fountain	01/16/20	3.6	None.
9	20481101-009CF	20481101-009CF21A	Room 13 - Sink	01/16/20	8.0	None.
Lead Tests - Ruch Elementary School - Rooms 7-9 Building - # 20481102						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481102-001DW	20481102-001DW21A	Room 7 - Drinking Fountain	01/16/20	8.7	None.
2	20481102-002CF	20481102-002CF21A	Room 7 - Sink	01/16/20	1.8	None.
3	20481102-003DW	20481102-003DW21A	Room 8 - Drinking Fountain	01/16/20	4.8	None.
4	20481102-004CF	20481102-004CF21A	Room 8 - Sink	01/16/20	7.7	None.
5	20481102-005DW	20481102-005DW21A	Room 9 - Drinking Fountain	01/27/20	3.3	This sink has a lead filter on it.
6	20481102-006CF	20481102-006CF21A	Room 9 - Sink	01/16/20	3.1	None.
7	20481102-007BF	20481102-007BF21A	Boy's Restroom Outside Room 9 - Sink	01/16/20	2.7	None.
8	20481102-008BF	20481102-008BF21A	Girl's Restroom Outside Room 9 - Sink	01/16/20	4.9	None.
Lead Tests - Ruch Elementary School - Rooms 2-4 Building - # 20481103						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481103-001BF	20481103-001BF21A	Staff Restroom Outside The Main Office - Sink	01/16/20	1.7	None.
2	20481103-002DW	20481103-002DW21A	Room 2 - Drinking Fountain	01/16/20	6.8	None.
3	20481103-003CF	20481103-003CF21A	Room 2 - Sink	01/27/20	7.5	This sink has a lead filter on it.
4	20481103-004DW	20481103-004DW21A	Room 3 - Drinking Fountain	01/16/20	7.8	None.
5	20481103-005CF	20481103-005CF21A	Room 3 - Sink	01/16/20	5.0	None.
6	20481103-006DW	20481103-006DW21A	Room 4 - Drinking Fountain	01/16/20	2.7	None.
7	20481103-007CF	20481103-007CF21A	Room 4 - Sink	01/27/20	2.0	None.
Lead Tests - Ruch Elementary School - Main Office Building - # 20481104						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481104-001NS	20481104-001NS21A	Health Room - Sink	07/24/23	1.8	None.
2	20481104-002BF	20481104-002BF21A	Health Room Restroom - Sink	11/01/24	2.7	Lead filter installed Oct 2024.
3	20481104-003DW	20481104-003DW21A	Sports Field - Drinking Fountain (On Wellhouse)	04/26/21	2.4	None.
Lead Tests - Ruch Elementary School - Front Restrooms Building - # 20481105						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481105-001DW	20481105-001DW21A	Outside Main Office - Drinking Fountain (Left)	07/24/23	ND	None.
2	20481105-002DW	20481105-002DW21A	Outside Main Office - Drinking Fountain (Right)	01/16/20	4.1	None.
3	20481105-003BF	20481105-003BF21A	Boy's Restroom Adjacent To Main Office - Sink (Left)	01/16/20	9.1	None.
4	20481105-004BF	20481105-004BF21A	Boy's Restroom Adjacent To Main Office - Sink (Right)	01/16/20	3.1	None.
5	20481105-005BF	20481105-005BF21A	Boy's Restroom Adjacent To Main Office - Sink (Center)	01/16/20	2.8	None.
6	20481105-006BF	20481105-006BF21A	Boy's Restroom (Unisex Area) Adjacent To Main Office - Sink	08/26/21	2.0	None.
7	20481105-007BF	20481105-007BF21A	Girl's Restroom Adjacent To Main Office - Sink (Left)	01/16/20	2.8	None.
8	20481105-008BF	20481105-008BF21A	Girl's Restroom Adjacent To Main Office - Sink (Right)	01/16/20	7.1	None.
9	20481105-009BF	20481105-009BF21A	Girl's Restroom Adjacent To Main Office - Sink (Center)	01/16/20	5.2	None.
10	20481105-010BF	20481105-010BF21A	Girl's Restroom (Unisex Area) Adjacent To Main Office - Sink	08/26/21	1.5	None.
Lead Tests - Ruch Elementary School - Staff Break Room Building - # 20481106						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481106-001SF	20481106-001SF21A	Staff Break Room - Sink	01/16/20	1.9	None.
2	20481106-002SF	20481106-002SF21A	Room Adjacent To Staff Break Room - Sink	01/16/20	2.9	This sink has a lead filter on it.
N/A	N/A	N/A	Staff Break Room - Drinking Fountain	06/30/16	4.6	This drinking fountain was removed during the seismic upgrade.
Lead Tests - Ruch Elementary School - Rooms 14-15 - # 20481107						
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Remarks
1	20481107-001DW	20481107-001DW21A	Room 15 - Drinking Fountain	03/18/20	6.6	This sink has a lead filter on it.
2	20481107-002CF	20481107-002CF21A	Room 15 - Sink	01/16/20	1.6	This sink has a lead filter on it.
3	20481107-003DW	20481107-003DW21A	Room 14 - Drinking Fountain	03/18/20	2.8	This sink has a lead filter on it.
4	20481107-004CF	20481107-004CF21A	Room 14 - Sink	03/18/20	3.8	This sink has a lead filter on it.

*None Detected (ND) = 0.10 Or Less PPB

= Fixture Where Water Has The Potential of Being Consumed (All of These Will Be Tested When Testing The Whole School)

*ODE's required action level is 15 parts per billion (PPB)

*The E.P.A.'s recommended action level for lead in schools is 20 PPB. Oregon's action level for schools changed to 15 PPB in 2019 in accordance with OAR 333-061-0400. In 2021, ODE changed the unit of measurement for reporting to parts per billion (PPB).

*The E.P.A. action level for copper is 1.30

*Lead test results will be posted on the MSD/Facilities website within 5 days minus the school map for security purposes.