


William Penn Fire Update



Photo courtesy of Local 21 News.



William Penn Fire

- City condemned this North end of the building.
- We are working with a structural engineer to determine if that entire section must be demolished.
- Area was tested for asbestos. Glue dots used for blackboards were positive.
 - Debris from fire can likely be treated as non-asbestos.
- Closely working with the Department of Environmental Protection as we progress through the process.

William Penn – Security Steps

- Security company began on 1/1/24 to provide 24/7 coverage.
 - They saw a lot of activity the first couple of nights. Police called.
 - Activity has decreased the past two nights.
- Installed several cameras around the campus. Security company is using them to monitor the site.
- Aggressive boarding up of the building. Hired a local company to assist our maintenance employees.
- Chief Enterline also consulted with us on identifying the areas intruders could get in.

William Penn Building - Next Steps

- We are in the process of developing a proposal to:
 - Address the fire damaged area.
 - Structural Engineering Report
 - Department of Environmental Protection
 - Public Review.
 - Remove the known asbestos and other environmental hazards and debris from the entire building.