

J.C. Broderick & Associates, Inc.

Environmental Consulting & Testing



Nassau Office
4034 Holly Road
Suite 107
Seaford, NY 11783
516.852.0162

Suffolk Office
1775 Expressway Drive North
Hauppauge, NY 11788
631.584.5492
fax: 631.584.3395

January 6, 2015

Mr. Charles Abner
Syosset Central School District
PO Box 9029
Syosset, New York 11791

**Re: Indoor Radon Sampling
Baylis Elementary School
And South Grove School
Sampling Dates: December 23-29, 2013**

JCB#: 14-30715

Dear Mr. Abner:

J.C. Broderick and Associates, Inc. (JCB) was retained to perform indoor radon sampling within the above referenced school buildings. This sampling was performed as an annual update to the District's Radon Measurement Plan.

The sampling was performed by experienced JCB representatives utilizing Short-Term test devices. The sampling was conducted while the heating systems were in operation and the buildings were closed for a minimum of 12 hours prior to the placement of the test devices.

The samples were assigned unique identification numbers, logged into a chain of custody document, and delivered to an accredited laboratory for the analysis of Radon. The results were compared with the decision making flowchart found in the EPA Radon Measurement in Schools (EPA 402-R-92-014) guidance document which establishes an action level of 4 pCi/L.

The results of the sampling performed revealed the following:

- All results for both school buildings were reported below the above referenced action level.

Based upon these results, no action is recommended at this time. Please see the attached laboratory reports to be included in the District's Radon Measurement Plan.

If there are any questions or if more information is needed, please feel free to contact our office.

Sincerely,

A handwritten signature in black ink, appearing to read 'Kristen Gabriel', written over a light blue horizontal line.

Kristen Gabriel
J. C. Broderick & Associates, Inc.

m#4



RECEIVED
EMSL
CINNAMINSON, N.J.

**CHAIN OF CUSTODY
RADON LABORATORY SERVICES
(COMMERCIAL USE)**

JCBR50
3-5 day
JCY
12/30/14

EMSL ANALYTICAL, INC.
200 ROUTE 130 NORTH
CINNAMINSON, NJ 08077
PHONE: 800-220-3675
FAX: 856-786-0327

EMSL ANALYTICAL, INC.

2014 DEC 30 A 11:05

EMSL Job #: 381407247

Company Information

Company Name: JC Braderick and Associates
 EMSL Account #: JCBR50 3day
 Contact: Kristen Gabriel
 Address: 1775 express drive north
 City: Havppauge
 State: NY Zip Code: 11788
 Phone: 631 5845492
 Fax: _____
 Email: KGabriel@JCBraderick.com

Project / Property Information:

Name: Baylis Elementary School
 Address: 580 Woodbury Road
 City: Plainview
 Municipality: _____ County: Nassau
 State: NY Zip Code: 11803
 PO#/Project#: _____
 Please check box if this is a Post Mitigation Test
 Technician Name: Sarah Gilman
 Technician Certification #: _____
 Technician Signature: [Signature]

Disclaimer

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages arising out of or in connection with EMSL's services there under or the delivery, use, reliance upon or interpretation of test results by client or third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereafter.

Box Number	Device Number	Location	Exposure Period Beginning Date and Time	Exposure Period Ending Date and Time	Temperature, °F	Humidity, %
112707	189699	2070 NE Desk	12/23/14 1:20	12/29/14 9:28	68	52
112797	189661	2068 SW Desk	12/23/14 1:24	12/29/14 9:34	68	49
112799	189686	2073 NE Desk	12/23/14 1:27	12/29/14 9:27	68	49
112801	189626	2065 NE Desk	12/23/14 1:30	12/29/14 9:35	68	50
112794	189742	2073 (southern one) west wall	12/23/14 1:33	12/29/14 9:26	70	52
112783	189709	2063 NE Desk	12/23/14 1:36	12/29/14 9:36	68	50
112796	189640	2061 SE Desk	12/23/14 1:39	12/29/14 9:39	70	51
112793	189656	2015 South Desk	12/23/14 1:45	12/29/14 8:42	72	75 65%
112832	189668	2013 SW Desk	12/23/14 1:49	12/29/14 9:02	72	55
112832	189752 ^{DUP}	2013 Duplicate SW Desk	12/23/14 1:49	12/29/14 9:02	72	55
✓ 112790	189730	2012 East Desk	12/23/14 1:52	12/29/14 8:42	72	51
112825	189665	2011 NE Desk	12/23/14 1:56	12/17/14 8:45	72	53

Relinquished By:

Received By: [Signature]
12/30/14

★ CHANGE DUE TO CALIBRATION FACTOR
JCY 12/15



EMSL ANALYTICAL, INC.

CHAIN OF CUSTODY
 RADON LABORATORY SERVICES
 (COMMERCIAL USE)

RECEIVED
 EMSL
 CINNAMINSON, NJ

EMSL Job #: 381407247

EMSL ANALYTICAL, INC.
 200 ROUTE 130 NORTH
 CINNAMINSON, NJ 08077

PHONE: 800-220-3675
 FAX: 856-786-0327

2014 DEC 30 A 11:05

Box Number	Device Number	Location	Exposure Period Beginning Date and Time	Exposure Period Ending Date and Time	Temperature, °F	Humidity, %
✓ 112825	189759 Blank	2011 Blank NE Desk	12/23/14 1:56	12/29/14 8:45	72	53
112800	189727	2010 SW Desk	12/23/14 2:00	12/29/14 9:00	72	58
112789	189739	2009 SW Desk	12/23/14 2:02	12/29/14 8:59	72	52
112805	189632	2008 East Desk	12/23/14 2:05	12/29/14 8:47	70	51
112805	189756 Blank	2008 East Desk Blank	12/23/14 2:05	12/29/14 8:47	70	51
✓ 112833	189734	2007 East Desk	12/23/14 2:08	12/29/14 8:49	72	52
✓ 112784	189664	2005 North Desk	12/23/14 2:14	12/29/14 8:51	74	52
112823	189738	2006 SW Desk	12/23/14 2:20	12/29/14 8:53	72	55
112834	189652	2002 SW Table	12/23/14 2:26	12/29/14 8:50	70	50
112806	189662	2014 Center Table	12/23/14 2:29	12/29/14 9:02	72	51
112839	189725	2020 East Table	12/23/14 2:34	12/29/14 8:77	72	50
112835	189596	2026 East Desk	12/23/14 2:38	12/29/14 8:97	72	55
112835	189803 Blank	2026 Blank East Desk	12/23/14 2:38	12/29/14 9:17	72	55
112792	189659	2029 South Desk	12/23/14 2:42	12/29/14 9:16	74	60
112792	189764 DUP	Duplicate 2029 South Desk	12/23/14 2:42	12/29/14 9:16	74	60
112786	189710	2032 South Desk	12/23/14 2:44	12/29/14 9:15	72	51
112841	189566	2035 SE Desk	12/23/14 2:47	12/29/14 9:13	70	52
112840	189624	2038 East Desk	12/23/14 2:49	12/29/14 9:10	72	54
112803	189719	2041 North Desk	12/23/14 2:51	12/29/14 9:08	72	51
112798	189606	2044 NE Desk	12/23/14 2:54	12/29/14 9:05	72	52
112798	189777 DUP	Duplicate 2044 NE Desk	12/23/14 2:54	12/29/14 9:05	72	52
112791	189688	2053 NE Desk	12/23/14 2:58	12/29/14 9:20	72	50
112811	189713	2048 Center Desk	12/23/14 3:00	12/29/14 9:21	72	55
112829	189675	2077 South Table	12/23/14 3:03	12/29/14 9:24	74	53
112815	189628	Band NE Desk	12/23/14 3:07	12/29/14 9:32	78	40
112815	189772 Blank	Band Blank NE Desk	12/23/14 3:07	12/29/14 9:32	78	40
112802	189625	2049A Center table	12/23/14 3:15	12/29/14 9:23	74	38

Relinquished By:

Received By: *Hannah*
 12/30/14



EMSL ANALYTICAL, INC.

**CHAIN OF CUSTODY
RADON LABORATORY SERVICES
(COMMERCIAL USE)**

EMSL ANALYTICAL, INC.
200 ROUTE 130 NORTH
CINNAMINSON, NJ 08077

PHONE: 800-220-3675
FAX: 856-786-0327

EMSL Job #: **381407247**

Box Number	Device Number	Location	Exposure Period Beginning Date and Time	Exposure Period Ending Date and Time	Temperature, °F	Humidity, %
112802	189770 DVP	2049A center Duplicate Table	12/23/14 3:25	12/29/14 9:23	74	38
112795	189660	2062 North Desk	12/23/14 3:15	12/29/14 9:19	74	48
112795	189776 Blank	2062 North Desk Blank	12/23/14 3:15	12/29/14 9:19	74	48
112826	189687	2046/west-2047 Desk	12/23/14 3:25	12/29/14 9:07	72	48
112824	189623	2049	12/23/14 3:28	12/29/14 9:22	72	51
112788	189676	Room C North Desk	12/23/14 3:31	12/29/14 9:30	78	48
112788	189848 DVP	Dup. Room C North Desk	12/23/14 3:31	12/29/14 9:30	78	48
112858	189650 DVP	Class A exterior wall	12/23/14 3:26	12/29/14 9:12	72	30
112858	189554	class A Dup. Exterior Wall	12/23/14 3:26	12/29/14 9:12	72	30
112867	189513	Class B interior wall	12/23/14 3:23	12/29/14 9:11	72	30
112785	189706	Right Music Risers	12/23/14 3:25	12/29/14 9:33	70	30
112785	189805 Blank	Right Music Blank Risers	12/23/14 3:25	12/29/14 9:33	70	30
112856	189681	Left Music Risers	12/23/14 3:26	12/29/14 9:31	78	20
<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="writing-mode: vertical-rl; transform: rotate(180deg);"> RECEIVED EMSL CINNAMINSON, N.J. 2014 DEC 30 A 11:05 </div> </div>						

Relinquished By:
Received By: *[Signature]*
12/30/14

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407247
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:05 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **Baylis Elementary School**

Test Site: **Baylis Elementary School**
580 Woodbury Road
Plainview, NY 11803

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112787**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189699	2070 - NE Desk	1.7	12/23/2014	12/29/2014	68	52	Customer
381407247-0001			1:20:00 PM	9:28:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112797

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189661	2068 - SW Desk	1.9	12/23/2014	12/29/2014	68	49	Customer
381407247-0002			1:24:00 PM	9:34:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112799

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189686	2073 - NE Desk	1.7	12/23/2014	12/29/2014	68	49	Customer
381407247-0003			1:27:00 PM	9:27:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112801

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189626	2065 - NE Desk	1.5	12/23/2014	12/29/2014	68	50	Customer
381407247-0004			1:30:00 PM	9:35:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112794

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189742	2073 - (Southern One) West Wall	1.8	12/23/2014	12/29/2014	70	52	Customer
381407247-0005			1:33:00 PM	9:26:00 AM			

Sample Notes: Radon device exposed >96 hours

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407247
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:05 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **Baylis Elementary School**

Test Site: **Baylis Elementary School**
580 Woodbury Road
Plainview, NY 11803

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112783**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189709	2063 - NE Desk	1.7	12/23/2014	12/29/2014	68	50	Customer
381407247-0006			1:36:00 PM	9:36:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112796

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189640	2061 - SE Desk	1.7	12/23/2014	12/29/2014	70	51	Customer
381407247-0007			1:39:00 PM	9:39:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112793

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189656	2015 - South Desk	1.8	12/23/2014	12/29/2014	72	65	Customer
381407247-0008			1:45:00 PM	8:42:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112832

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189668	2013 - SW Desk	1.3	12/23/2014	12/29/2014	72	55	Customer
381407247-0009			1:49:00 PM	9:02:00 AM			

Sample Notes: Radon device exposed >96 hours

189752	2013 - SW Desk	1.5	12/23/2014	12/29/2014	72	55	Duplicate
381407247-0010			1:49:00 PM	9:02:00 AM			

Sample Notes: Radon device exposed >96 hours

Duplicate RPD = 14.3%

Samples for EMSL Kit 112790

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189730	2012 - East Desk	1.4	12/23/2014	12/29/2014	72	51	Customer
381407247-0011			1:52:00 PM	8:42:00 AM			

Sample Notes: Radon device exposed >96 hours

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407247
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:05 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **Baylis Elementary School**

Test Site: **Baylis Elementary School**
580 Woodbury Road
Plainview, NY 11803

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112825**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189665 381407247-0012	2011 - NE Desk	1.3	12/23/2014 1:56:00 PM	12/29/2014 8:45:00 AM	72	53	Customer
Sample Notes: Radon device exposed >96 hours							
189759 381407247-0013	2011 - NE Desk	0	12/23/2014 1:56:00 PM	12/29/2014 8:45:00 AM	72	53	Blank
Sample Notes: Radon device exposed >96 hours							

Samples for EMSL Kit 112800

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189727 381407247-0014	2010 - SW Desk	1.5	12/23/2014 2:00:00 PM	12/29/2014 9:00:00 AM	72	58	Customer
Sample Notes: Radon device exposed >96 hours							

Samples for EMSL Kit 112789

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189739 381407247-0015	2009 - SW Desk	1.4	12/23/2014 2:02:00 PM	12/29/2014 8:59:00 AM	72	52	Customer
Sample Notes: Radon device exposed >96 hours							

Samples for EMSL Kit 112805

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189632 381407247-0016	2008 - East Desk	1.7	12/23/2014 2:05:00 PM	12/29/2014 8:47:00 AM	70	51	Customer
Sample Notes: Radon device exposed >96 hours							
189756 381407247-0017	2008 - East Desk	0	12/23/2014 2:05:00 PM	12/29/2014 8:47:00 AM	70	51	Blank
Sample Notes: Radon device exposed >96 hours							

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407247
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:05 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **Baylis Elementary School**

Test Site: **Baylis Elementary School**
580 Woodbury Road
Plainview, NY 11803

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112833**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189734	2007 - East Desk	1.4	12/23/2014	12/29/2014	72	52	Customer
381407247-0018			2:08:00 PM	8:49:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112784

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189664	2005 - North Desk	1.3	12/23/2014	12/29/2014	74	52	Customer
381407247-0019			2:14:00 PM	8:51:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112823

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189738	2006 - SW Desk	1.5	12/23/2014	12/29/2014	72	55	Customer
381407247-0020			2:20:00 PM	8:53:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112834

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189652	2002 - SW Table	1.7	12/23/2014	12/29/2014	70	50	Customer
381407247-0021			2:26:00 PM	8:50:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112806

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189662	2014 - Center Table	1.4	12/23/2014	12/29/2014	72	51	Customer
381407247-0022			2:29:00 PM	9:02:00 AM			

Sample Notes: Radon device exposed >96 hours

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407247
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:05 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **Baylis Elementary School**

Test Site: **Baylis Elementary School**
580 Woodbury Road
Plainview, NY 11803

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112839**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189725	2020 - East Table	1.7	12/23/2014	12/29/2014	72	50	Customer
381407247-0023			2:34:00 PM	8:41:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112835

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189596	2026 - East Desk	2.1	12/23/2014	12/29/2014	72	55	Customer
381407247-0024			2:38:00 PM	9:17:00 AM			

Sample Notes: Radon device exposed >96 hours

189803	2026 - East Desk	-0.1	12/23/2014	12/29/2014	72	55	Blank
381407247-0025			2:38:00 PM	9:17:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112792

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189659	2029 - South Desk	2.3	12/23/2014	12/29/2014	74	60	Customer
381407247-0026			2:42:00 PM	9:16:00 AM			

Sample Notes: Radon device exposed >96 hours

189764	2029 - South Desk	1.9	12/23/2014	12/29/2014	74	60	Duplicate
381407247-0027			2:42:00 PM	9:16:00 AM			

Sample Notes: Radon device exposed >96 hours

Duplicate RPD = 19%

Samples for EMSL Kit 112786

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189710	2032 - South Desk	2.1	12/23/2014	12/29/2014	72	51	Customer
381407247-0028			2:44:00 PM	9:15:00 AM			

Sample Notes: Radon device exposed >96 hours

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407247
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:05 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **Baylis Elementary School**

Test Site: **Baylis Elementary School**
580 Woodbury Road
Plainview, NY 11803

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112841**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189566	2035 - SE Desk	1.9	12/23/2014	12/29/2014	70	52	Customer
381407247-0029			2:47:00 PM	9:13:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112840

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189624	2038 - East Desk	2.1	12/23/2014	12/29/2014	72	54	Customer
381407247-0030			2:49:00 PM	9:10:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112803

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189719	2041 - North Desk	2.3	12/23/2014	12/29/2014	72	51	Customer
381407247-0031			2:51:00 PM	9:08:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112798

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189606	2044 - NE Desk	2	12/23/2014	12/29/2014	72	52	Customer
381407247-0032			2:54:00 PM	9:05:00 AM			

Sample Notes: Radon device exposed >96 hours

189777	2044 - NE Desk	2.1	12/23/2014	12/29/2014	72	52	Duplicate
381407247-0033			2:54:00 PM	9:05:00 AM			

Sample Notes: Radon device exposed >96 hours

Duplicate RPD = 4.9%

Samples for EMSL Kit 112791

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189688	2053 - NE Desk	2.2	12/23/2014	12/29/2014	72	50	Customer
381407247-0034			2:58:00 PM	9:20:00 AM			

Sample Notes: Radon device exposed >96 hours

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407247
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:05 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **Baylis Elementary School**

Test Site: **Baylis Elementary School**
580 Woodbury Road
Plainview, NY 11803

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112811**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189713	2048 - Center Desk	2	12/23/2014	12/29/2014	72	55	Customer
381407247-0035			3:00:00 PM	9:21:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112829

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189675	2077 - South Table	1.8	12/23/2014	12/29/2014	74	53	Customer
381407247-0036			3:03:00 PM	9:26:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112815

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189628	Band - NE Desk	0.7	12/23/2014	12/29/2014	78	40	Customer
381407247-0037			3:07:00 PM	9:32:00 AM			

Sample Notes: Radon device exposed >96 hours

189772	Band - NE Desk	0.1	12/23/2014	12/29/2014	78	40	Blank
381407247-0038			3:07:00 PM	9:32:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112802

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189625	2049A - Center Table	1.7	12/23/2014	12/29/2014	74	38	Customer
381407247-0039			3:15:00 PM	9:23:00 AM			

Sample Notes: Radon device exposed >96 hours

189770	2049A - Center Table	1.8	12/23/2014	12/29/2014	74	38	Duplicate
381407247-0040			3:15:00 PM	9:23:00 AM			

Sample Notes: Radon device exposed >96 hours

Duplicate RPD = 5.7%

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407247
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:05 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **Baylis Elementary School**

Test Site: **Baylis Elementary School**
580 Woodbury Road
Plainview, NY 11803

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112795**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189660	2062 - North Desk	1.8	12/23/2014	12/29/2014	74	48	Customer
381407247-0041			3:15:00 PM	9:19:00 AM			

Sample Notes: Radon device exposed >96 hours

189776	2062 - North Desk	-0.1	12/23/2014	12/29/2014	74	48	Blank
381407247-0042			3:15:00 PM	9:19:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112826

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189687	2046/2047 - West Desk	2	12/23/2014	12/29/2014	72	48	Customer
381407247-0043			3:25:00 PM	9:07:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112824

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189623	2049	2.1	12/23/2014	12/29/2014	72	51	Customer
381407247-0044			3:28:00 PM	9:22:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112788

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189676	Room C - North Desk	1.6	12/23/2014	12/29/2014	78	48	Customer
381407247-0045			3:31:00 PM	9:30:00 AM			

Sample Notes: Radon device exposed >96 hours

189848	Room C - North Desk	1.8	12/23/2014	12/29/2014	78	48	Duplicate
381407247-0046			3:31:00 PM	9:30:00 AM			

Sample Notes: Radon device exposed >96 hours

Duplicate RPD = 11.8%

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407247
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:05 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **Baylis Elementary School**

Test Site: **Baylis Elementary School**
580 Woodbury Road
Plainview, NY 11803

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112858**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189650 381407247-0047	Class A - Exterior Wall	1.1	12/23/2014 3:20:00 PM	12/29/2014 9:12:00 AM	72	30	Duplicate

Sample Notes: Radon device exposed >96 hours

189554 381407247-0048	Class A - Exterior Wall	1.1	12/23/2014 3:20:00 PM	12/29/2014 9:12:00 AM	72	30	Customer
--------------------------	----------------------------	-----	--------------------------	--------------------------	----	----	----------

Sample Notes: Radon device exposed >96 hours

Duplicate RPD = 0%

Samples for EMSL Kit 112867

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189513 381407247-0049	Class B - Interior Wall	1.6	12/23/2014 3:23:00 PM	12/29/2014 9:11:00 AM	72	30	Customer

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112785

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189706 381407247-0050	Right Music Risers	1.4	12/23/2014 3:25:00 PM	12/29/2014 9:33:00 AM	70	30	Customer

Sample Notes: Radon device exposed >96 hours

189805 381407247-0051	Right Music Risers	0.1	12/23/2014 3:25:00 PM	12/29/2014 9:33:00 AM	70	30	Blank
--------------------------	--------------------	-----	--------------------------	--------------------------	----	----	-------

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112856

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189681 381407247-0052	Left Music Risers	1.4	12/23/2014 3:26:00 PM	12/29/2014 9:31:00 AM	78	20	Customer

Sample Notes: Radon device exposed >96 hours



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-0327

<http://www.EMSL.com>

cinnaminsonradonlab@emsl.com

EMSL Order: 381407247

CustomerID: JCBR50

CustomerPO:

ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
Fax:
Received: 12/30/14 11:05 AM
Analysis Date: 12/31/2014
Collected: 12/23/2014

Project: **Baylis Elementary School**

Test Site: **Baylis Elementary School**
580 Woodbury Road
Plainview, NY 11803

Test Report: Radon in Air Test Results

The radon test was performed using a liquid scintillation radon detector/s and counted on a liquid scintillation counter using approved EPA testing protocols for Radon in Air testing. The EPA recommends fixing your home if the average of two short-term tests taken in the lowest lived-in level of the home show radon levels that are equal to or greater than 4.0pCi/L. The EPA recommends retesting your home every two years.

Please contact EMSL Analytical, Inc. or your State Health Department for further information.

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of Radon in Air.

Report Note

Analyst(s)

Laura Freeman (52)

Garrett A. Ray, Laboratory Manager
Certified Radon Measurement Specialist NRSB 5SS0093
NJ MES12264, FL R2001, NE 116, PA 2572

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder. The test results meets all NELAC requirements unless otherwise specified. Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ

Initial report from 01/02/2015 10:11:02

Please visit www.radontestinglab.com

1910 4590



CHAIN OF CUSTODY
RADON LABORATORY SERVICES
(COMMERCIAL USE)

EMSL ANALYTICAL, INC.
200 ROUTE 130 NORTH
CINNAMINSON, NJ 08077

PHONE: 800-220-3675
FAX: 856-786-0327

EMSL Job #: 381407246

2014 DEC 30 A 11:04

Company Information

Company Name: JC Brodeur and associates
EMSL Account #: JCBRS0 3day
Contact: Kristen Gabriel
Address: 1775 express drive north
City: Hempstead
State: NY Zip Code: 11788
Phone: 631 584 5492
Fax: _____
Email: KGabriel@JCBrodeur.com

Project / Property Information:

Name: South Grove School
Address: 60 Colony Lane
City: Syosset
Municipality: _____ County: NY
State: NY Zip Code: 11791
PO#/Project#: _____
 Please check box if this is a Post Mitigation Test
Technician Name: Sarah Gilliar
Technician Certification #: _____
Technician Signature: [Signature]

Disclaimer

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages arising out of or in connection with EMSL's services there under or the delivery, use, reliance upon or interpretation of test results by client or third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereafter.

Box Number	Device Number	Location	Exposure Period Beginning Date and Time	Exposure Period Ending Date and Time	Temperature °F	Humidity %
✓ 112814	189740	2023 - on table E wall	12:05 12/23/14	12/29/14 7:10	70°	50
✓ 112809	189715	2015 - table W wall	12:11 12/23/14	12/29/14 7:12	70°	50
✓ 112810	189618	2008 - table W wall	12:15 12/23/14	12/29/14 7:14	72°	50°
✓ 112812	189729	2005 - table S wall	12:19 12/23/14	12/29/14 7:15	72°	50
✓ 112812	189813	2005 - table S wall	12:19 12/23/14	12/29/14 7:15	72°	50
✓ 112804	189603	2002 - table N wall	12:23 12/23/14	12/29/14 7:17	70°	50
✓ 112807	189617	2011 - desk W wall	12:28 12/23/14	12/29/14 7:18	70°	50
✓ 112808	189614	2018 - Shelf S wall	12:29 12/23/14	12/29/14 7:19	72°	50
✓ 112808	189767	2018 Shelf S wall	12:29 12/23/14	12/29/14 7:19	72°	50
✓ 112813	189682	2002 - table W wall	12:15 12/23/14	12/29/14 7:39	72	50

Relinquished By: _____
Received By: Suffern consequence 12/29/14



CHAIN OF CUSTODY
RADON LABORATORY SERVICES
 (COMMERCIAL USE)

EMSL ANALYTICAL, INC.
 200 ROUTE 130 NORTH
 CINNAMINSON, NJ 08077

EMSL ANALYTICAL, INC.

EMSL Job #: 381407246

CINNAMINSON, NJ PHONE: 800-220-3675
 FAX: 856-786-0327

2014 DEC 30 A 11:05

Box Number	Device Number	Location	Exposure Period Beginning Date and Time	Exposure Period Ending Date and Time	Temperature °F	Humidity %
112842	189541	2060 table South	12:43-12/23/14	12/29/14 7:40	72	50
112842	189694 DUP	2060 table South	12:43-12/23/14	12/29/14 7:40	68	60
112845	189555	2058-table west wall	1:08 12/23/14	12/29/14 7:41	68	60
112845	189570 blank	2058-table wall	1:08 12/23/14	12/29/14 7:41	68	60
112854	189562	2056-table east	1:13 12/23/14	12/29/14 7:43	68	50
112837	189749 123	Re office desk	1:17 12/23/14	12/29/14 7:45	70	50
112859	189643	Re office desk	1:19 12/23/14	12/29/14 7:45	70	50
112817	189634	2054 W desk	1:22 12/23/14	12/29/14 7:47	68°	50
112853	189711	2052 SC table	1:23 12/23/14	12/29/14 7:48	70	50
112838	189598	2050 SW desk	1:26 12/23/14	12/29/14 7:50	69°	50
112838	189708 DUP	2050 SW desk	1:26 12/23/14	12/29/14 7:50	69°	50
112855	189679	2045 SW wall	1:30 12/23/14	12/29/14 7:28	70	50
112855	189578 blank	2045 SW wall	1:30 12/23/14	12/29/14 7:28	68°	50
112806	189720	2068 W wall	1:32 12/23/14	12/29/14 7:25	70°	50
112821	189631	2044 SW wall	1:36 12/23/14	12/29/14 7:24	70°	50
112827	189602	2027 file cabinet W.	1:40 12/23/14	12/29/14 7:54	72°	50
112852	189638	2030 NE table	1:42 12/23/14	12/29/14 7:55	72°	50
112852	189651 DUP	2030 NE table	1:42 12/23/14	12/29/14 7:55	72°	50
112844	189586	2032 nurse table W.	1:44 12/23/14	12/29/14 7:56	70	50
112803	189619	music desk 72 South	1:48 12/23/14	12/29/14 7:23	68°	50
112822	189658	2071 desk C	1:50 12/23/14	12/29/14 7:58	70	50
112822	189767 DUP	2071	1:50 12/23/14	12/29/14 7:58	70	50
112851	189646	2095 table S	1:51 12/23/14	12/29/14 7:59	70	50
112848	189498	2075 table east	1:53 12/23/14	12/29/14 8:00	70	50
112848	189629 DUP	2078 table east	1:53 12/23/14	12/29/14 8:00	70	50
112885	189507	2081 table S	1:55 12/23/14	12/29/14 8:01	68	50
112885	189653 blank	2081 table S	1:55 12/23/14	12/29/14 8:01	68	50

Relinquished By:

Received By:



**CHAIN OF CUSTODY
RADON LABORATORY SERVICES
(COMMERCIAL USE)**

EMSL ANALYTICAL, INC.
200 ROUTE 130 NORTH
CINNAMINSON, NJ 08077

PHONE: 800-220-3675
FAX: 856-786-0327

EMSL ANALYTICAL, INC.

EMSL Job #:

Box Number	Device Number	Location	Exposure Period Beginning Date and Time	Exposure Period Ending Date and Time	Temperature °F	Humidity %
112846	189733	2088 ewall	12/23/14 1:58	12/29/14 8:02	70	50
112862	189564	2089 W wall	12/23/14 2:00	12/29/14 8:04	70	50
112862	189722 DUP	2089 N wall	12/23/14 2:00	12/29/14 8:04	70	50
112884	189567	2043 W desk	12/23/14 2:17	12/29/14 7:26	70	50
112869	189702	Psych office desk	12/23/14 2:20	12/29/14 7:21	70	50
112878	189630	2016 table north	12/23/14 2:34	12/29/14 8:14	72	40
112878	189615 DUP	2016 table north	12/23/14 2:34	12/29/14 8:14	72	40
112865	189543	2013 wall north	12/23/14 2:40	12/29/14 8:12	68	40
112865	189583	2013 wall north	12/23/14 2:40	12/29/14 8:12	68	40
112861	189667	2015 wall south	12/23/14 2:41	12/29/14 8:11	68	40
112850	189622	2018 S desk	12/23/14 2:45	12/29/14 8:17	72	50
112843	189721	2020 W table	12/23/14 2:48	12/29/14 8:14	70	50
112860	189605	2024 S table	12/23/14 2:49	12/29/14 8:15	70	50
112820	189576	2022 W table	12/23/14 2:50	12/29/14 8:17	72	50
112816	189705	2022A S desk	12/23/14 2:52	12/29/14 8:18	72	50
112868	189540	2025 W table	12/23/14 2:53	12/29/14 8:19	70	50
112869	189641 DUP	2025 W table	12/23/14 2:53	12/29/14 8:19	70	50
112875	189558	2027 SE desk	12/23/14 2:54	12/29/14 8:21	70	30
112875	189683	2027 S desk	12/23/14 2:54	12/29/14 8:22	70	30
112876	189696	2027 W table	12/23/14 2:56	12/29/14 8:22	70	40
112819	189663	2009 desk	12/23/14 3:00	12/29/14 8:23	72	30

CINNAMINSON, NJ
 DEC 30 11:05 AM '14

Relinquished By:
Received By:

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407246
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:04 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **South Grove School**

Test Site: **South Grove School**
60 Colony Lane
Syosset, NY 11791

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112814**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189740	2023 - Table E Wall	1.3	12/23/2014	12/29/2014	70	50	Customer
381407246-0001			12:05:00 PM	7:10:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112809

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189715	2015 - Table W Wall	1.4	12/23/2014	12/29/2014	70	50	Customer
381407246-0002			12:11:00 PM	7:12:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112810

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189618	2008 - Table W Wall	1.4	12/23/2014	12/29/2014	72	50	Customer
381407246-0003			12:15:00 PM	7:14:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112812

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189729	2005 - Table S Wall	1.2	12/23/2014	12/29/2014	72	50	Customer
381407246-0004			12:19:00 PM	7:15:00 AM			

Sample Notes: Radon device exposed >96 hours

189813	2005 - Table S Wall	1.2	12/23/2014	12/29/2014	72	50	Duplicate
381407246-0005			12:19:00 PM	7:15:00 AM			

Sample Notes: Radon device exposed >96 hours

Duplicate RPD = 0%

Samples for EMSL Kit 112804

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189603	2002 - Table N Wall	1.4	12/23/2014	12/29/2014	70	50	Customer
381407246-0006			12:23:00 PM	7:17:00 AM			

Sample Notes: Radon device exposed >96 hours

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407246
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:04 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **South Grove School**

Test Site: **South Grove School**
60 Colony Lane
Syosset, NY 11791

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112807**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189617	2011 - Desk N Wall	1.4	12/23/2014	12/29/2014	70	50	Customer
381407246-0007			12:28:00 PM	7:18:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112808

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189614	2018 - Shelf S Wall	1.4	12/23/2014	12/29/2014	72	50	Customer
381407246-0008			12:29:00 PM	7:19:00 AM			

Sample Notes: Radon device exposed >96 hours

189769	2018 - Shelf S Wall	1.1	12/23/2014	12/29/2014	72	50	Duplicate
381407246-0009			12:29:00 PM	7:19:00 AM			

Sample Notes: Radon device exposed >96 hours

Duplicate RPD = 24%

Samples for EMSL Kit 112813

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189682	2062 - Table W Wall	1.5	12/23/2014	12/29/2014	72	50	Customer
381407246-0010			12:15:00 PM	7:39:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112842

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189541	2060 - Table South	1.2	12/23/2014	12/29/2014	72	50	Customer
381407246-0011			12:43:00 PM	7:40:00 AM			

Sample Notes: Radon device exposed >96 hours

189694	2060 - Table South	1.2	12/23/2014	12/29/2014	68	60	Duplicate
381407246-0012			12:43:00 PM	7:40:00 AM			

Sample Notes: Radon device exposed >96 hours

Duplicate RPD = 0%

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407246
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:04 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **South Grove School**

Test Site: **South Grove School**
60 Colony Lane
Syosset, NY 11791

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112845**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189555 381407246-0013	2058 - Table West Wall	1.5	12/23/2014 1:08:00 PM	12/29/2014 7:41:00 AM	60	60	Customer

Sample Notes: Radon device exposed >96 hours

189570 381407246-0014	2058 - Table West Wall	0	12/23/2014 1:08:00 PM	12/29/2014 7:41:00 AM	68	60	Blank
--------------------------	---------------------------	---	--------------------------	--------------------------	----	----	-------

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112854

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189562 381407246-0015	2056 - Table East	1.2	12/23/2014 1:13:00 PM	12/29/2014 7:43:00 AM	68	50	Customer

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112837

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189749 381407246-0016	PE Office (123) - Desk W	1.8	12/23/2014 1:17:00 PM	12/29/2014 7:45:00 AM	70	50	Customer

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112859

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189643 381407246-0017	PE Office (124)	1.5	12/23/2014 1:19:00 PM	12/29/2014 7:45:00 AM	70	50	Customer

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112817

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189634 381407246-0018	2054 - NW Desk	1.1	12/23/2014 1:22:00 PM	12/29/2014 7:47:00 AM	70	50	Customer

Sample Notes: Radon device exposed >96 hours

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407246
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:04 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **South Grove School**

Test Site: **South Grove School**
60 Colony Lane
Syosset, NY 11791

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112853**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189711	2052 - SE Table	1.3	12/23/2014	12/29/2014	70	50	Customer
381407246-0019			1:23:00 PM	7:48:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112838

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189598	2050 - SW Desk	1.4	12/23/2014	12/29/2014	69	50	Customer
381407246-0020			1:26:00 PM	7:50:00 AM			

Sample Notes: Radon device exposed >96 hours

189708	2050 - SW Desk	1.3	12/23/2014	12/29/2014	69	50	Duplicate
381407246-0021			1:26:00 PM	7:50:00 AM			

Sample Notes: Radon device exposed >96 hours

Duplicate RPD = 7.4%

Samples for EMSL Kit 112855

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189679	2045 - E Wall Table	1.6	12/23/2014	12/29/2014	70	50	Customer
381407246-0022			1:30:00 PM	7:28:00 AM			

Sample Notes: Radon device exposed >96 hours

189578	2045 - E Wall Table	0	12/23/2014	12/29/2014	68	50	Blank
381407246-0023			1:30:00 PM	7:28:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112866

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189720	2068 - W Wall	1.5	12/23/2014	12/29/2014	70	50	Customer
381407246-0024			1:32:00 PM	7:23:00 AM			

Sample Notes: Radon device exposed >96 hours

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407246
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:04 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **South Grove School**

Test Site: **South Grove School**
60 Colony Lane
Syosset, NY 11791

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112821**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189631	2044 - S Wall	1.5	12/23/2014	12/29/2014	70	50	Customer
381407246-0025			1:36:00 PM	7:24:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112827

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189602	2027 - File Cab W	1.3	12/23/2014	12/29/2014	72	50	Customer
381407246-0026			1:40:00 PM	7:54:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112852

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189638	2030 - NE Table	1.3	12/23/2014	12/29/2014	72	50	Customer
381407246-0027			1:42:00 PM	7:55:00 AM			

Sample Notes: Radon device exposed >96 hours

189651	2030 - NE Table	1.4	12/23/2014	12/29/2014	72	50	Duplicate
381407246-0028			1:42:00 PM	7:55:00 AM			

Sample Notes: Radon device exposed >96 hours

Duplicate RPD = 7.4%

Samples for EMSL Kit 112844

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189586	2032 - NurseTable W	1.4	12/23/2014	12/29/2014	70	50	Customer
381407246-0029			1:44:00 PM	7:56:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112863

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189619	Music Desk #2 - South	1.5	12/23/2014	12/29/2014	68	50	Customer
381407246-0030			1:48:00 PM	7:23:00 AM			

Sample Notes: Radon device exposed >96 hours

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407246
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:04 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **South Grove School**

Test Site: **South Grove School**
60 Colony Lane
Syosset, NY 11791

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112822**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189658 381407246-0031	2071 - Desk E	1.4	12/23/2014 1:50:00 PM	12/29/2014 7:58:00 AM	70	50	Customer
Sample Notes: Radon device exposed >96 hours							
189767 381407246-0032	2071 - Desk E	1.5	12/23/2014 1:50:00 PM	12/29/2014 7:58:00 AM	70	50	Duplicate
Sample Notes: Radon device exposed >96 hours							

Duplicate RPD = 6.9%

Samples for EMSL Kit 112851

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189646 381407246-0033	2075 - Table S	1.6	12/23/2014 1:51:00 PM	12/29/2014 7:59:00 AM	70	50	Customer
Sample Notes: Radon device exposed >96 hours							

Samples for EMSL Kit 112848

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189498 381407246-0034	2078 - Table East	1.2	12/23/2014 1:53:00 PM	12/29/2014 8:00:00 AM	70	50	Customer
Sample Notes: Radon device exposed >96 hours							
189629 381407246-0035	2078 - Table East	1.6	12/23/2014 1:53:00 PM	12/29/2014 8:00:00 AM	70	50	Duplicate
Sample Notes: Radon device exposed >96 hours							

Duplicate RPD = 28.6%

Samples for EMSL Kit 112885

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189507 381407246-0036	2081 - Table S	1.4	12/23/2014 1:55:00 PM	12/29/2014 8:01:00 AM	68	50	Customer
Sample Notes: Radon device exposed >96 hours							
189653 381407246-0037	2081 - Table S	0	12/23/2014 1:55:00 PM	12/29/2014 8:01:00 AM	68	50	Blank
Sample Notes: Radon device exposed >96 hours							

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407246
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:04 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **South Grove School**

Test Site: **South Grove School**
60 Colony Lane
Syosset, NY 11791

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112846**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189733	2088 - E Wall	1.2	12/23/2014	12/29/2014	70	50	Customer
381407246-0038			1:58:00 PM	8:02:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112862

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189564	2089 - W wall	1.5	12/23/2014	12/29/2014	70	50	Customer
381407246-0039			2:00:00 PM	8:04:00 AM			

Sample Notes: Radon device exposed >96 hours

189722	2089 - W wall	1.5	12/23/2014	12/29/2014	70	50	Duplicate
381407246-0040			2:00:00 PM	8:04:00 AM			

Sample Notes: Radon device exposed >96 hours

Duplicate RPD = 0%

Samples for EMSL Kit 112884

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189567	2043 - W Desk	1.5	12/23/2014	12/29/2014	70	50	Customer
381407246-0041			2:17:00 PM	7:26:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112869

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189702	Psych Office - Desk South	1.5	12/23/2014	12/29/2014	70	50	Customer
381407246-0042			2:20:00 PM	7:21:00 AM			

Sample Notes: Radon device exposed >96 hours

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407246
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:04 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **South Grove School**

Test Site: **South Grove School**
60 Colony Lane
Syosset, NY 11791

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112878**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189630	2016 - Table North	2.6	12/23/2014	12/29/2014	72	40	Customer
381407246-0043			2:34:00 PM	8:14:00 AM			

Sample Notes: Radon device exposed >96 hours

189615	2016 - Table North	2.5	12/23/2014	12/29/2014	72	40	Duplicate
381407246-0044			2:34:00 PM	8:14:00 AM			

Sample Notes: Radon device exposed >96 hours

Duplicate RPD = 3.9%

Samples for EMSL Kit 112865

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189543	2013 - Wall North	2	12/23/2014	12/29/2014	68	40	Customer
381407246-0045			2:40:00 PM	8:12:00 AM			

Sample Notes: Radon device exposed >96 hours

189583	2013 - Wall North	0.1	12/23/2014	12/29/2014	68	40	Blank
381407246-0046			2:40:00 PM	8:12:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112861

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189667	2015 - Wall South	2.4	12/23/2014	12/29/2014	68	40	Customer
381407246-0047			2:41:00 PM	8:11:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112850

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189622	2018 - S Desk	3.4	12/23/2014	12/29/2014	72	50	Customer
381407246-0048			2:45:00 PM	8:13:00 AM			

Sample Notes: Radon device exposed >96 hours



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077
Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407246
CustomerID: JCBR50
CustomerPO:
ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
Fax:
Received: 12/30/14 11:04 AM
Analysis Date: 12/31/2014
Collected: 12/23/2014

Project: **South Grove School**

Test Site: **South Grove School**
60 Colony Lane
Syosset, NY 11791

Test Report: Radon in Air Test Results

Samples for EMSL Kit 112843

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189721	2020 - W Table	2.9	12/23/2014	12/29/2014	70	50	Customer
381407246-0049			2:48:00 PM	8:14:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112860

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189605	2024 - S Table	2.5	12/23/2014	12/29/2014	70	50	Customer
381407246-0050			2:49:00 PM	8:15:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112820

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189576	2022 - W Table	2.8	12/23/2014	12/29/2014	72	50	Customer
381407246-0051			2:50:00 PM	8:17:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112816

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189705	2022A - S Desk	2.5	12/23/2014	12/29/2014	72	50	Customer
381407246-0052			2:52:00 PM	8:18:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112868

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189540	2025 - NW Table	2.3	12/23/2014	12/29/2014	70	50	Customer
381407246-0053			2:53:00 PM	8:19:00 AM			

Sample Notes: Radon device exposed >96 hours

189641	2025 - NW Table	2.4	12/23/2014	12/29/2014	70	50	Duplicate
381407246-0054			2:53:00 PM	8:19:00 AM			

Sample Notes: Radon device exposed >96 hours

Duplicate RPD = 4.3%

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077
 Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407246
 CustomerID: JCBR50
 CustomerPO:
 ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
 Fax:
 Received: 12/30/14 11:04 AM
 Analysis Date: 12/31/2014
 Collected: 12/23/2014

Project: **South Grove School**

Test Site: **South Grove School**
60 Colony Lane
Syosset, NY 11791

Test Report: Radon in Air Test Results**Samples for EMSL Kit 112875**

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189558	2027 - SE Desk	2.3	12/23/2014	12/29/2014	70	30	Customer
381407246-0055			2:54:00 PM	8:21:00 AM			

Sample Notes: Radon device exposed >96 hours

189683	2027 - SE Desk	0.1	12/23/2014	12/29/2014	70	30	Blank
381407246-0056			2:54:00 PM	8:21:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112876

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189696	2029 - NW Table	2	12/23/2014	12/29/2014	70	40	Customer
381407246-0057			2:56:00 PM	8:22:00 AM			

Sample Notes: Radon device exposed >96 hours

Samples for EMSL Kit 112819

Liquid Scintillation ID	Location	Radon Activity pCi/L	Start	Stop	Temperature F	Humidity %	Sample Type
189663	2009 - N Desk	3.3	12/23/2014	12/29/2014	72	30	Customer
381407246-0058			3:00:00 PM	8:23:00 AM			

Sample Notes: Radon device exposed >96 hours

The radon test was performed using a liquid scintillation radon detector/s and counted on a liquid scintillation counter using approved EPA testing protocols for Radon in Air testing. The EPA recommends fixing your home if the average of two short-term tests taken in the lowest lived-in level of the home show radon levels that are equal to or greater than 4.0pCi/L. The EPA recommends retesting your home every two years.

Please contact EMSL Analytical, Inc. or your State Health Department for further information. All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of Radon in Air.

Report Note



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077
Phone/Fax: (800) 220-3675 / (856) 786-0327
<http://www.EMSL.com> cinnaminsonradonlab@emsl.com

EMSL Order: 381407246
CustomerID: JCBR50
CustomerPO:
ProjectID:

Attn: **Kristen Gabriel**
J.C. Broderick & Associates
1775 Expressway Drive North, Suite 1
Hauppauge, NY 11788

Phone: (631) 584-5492
Fax:
Received: 12/30/14 11:04 AM
Analysis Date: 12/31/2014
Collected: 12/23/2014

Project: **South Grove School**

Test Site: **South Grove School**
60 Colony Lane
Syosset, NY 11791

Test Report: Radon in Air Test Results

Analyst(s)

Tiffanie Cosgrove (58)

Garrett A. Ray, Laboratory Manager
Certified Radon Measurement Specialist NRSB 5SS0093
NJ MES12264, FL R2001, NE 116, PA 2572

In no event shall EMSL be liable for indirect, special, consequential, or incidental damages, including, but not limited to, damages for loss of profit or goodwill regardless of the negligence (either sole or concurrent) of EMSL and whether EMSL has been informed of the possibility of such damages, arising out of or in connection with EMSL's services thereunder or the delivery, use, reliance upon or interpretation of test results by client or any third party. We accept no legal responsibility for the purposes for which the client uses the test results. In no event shall EMSL be liable to a client or any third party, whether based upon theories of tort, contract or any other legal or equitable theory, in excess of the amount paid to EMSL by client thereunder. The test results meets all NELAC requirements unless otherwise specified. Accreditations: NRSB ARL6006, NJ DEP 03036, MEB 92525, PA 2573, IN 00455, IA L00032, RI RAS-024, ME 20200C, NE RMB-1083, NY ELAP 10872, NM 885-10L, FL RB2034, OH RL-39, NRPP #106178AL, KS-LB-0005

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ

Initial report from 01/02/2015 09:29:42

Please visit www.radontestinglab.com