

1.2 Executive Summary of Sampling and Analysis:

Total Number of Samples Collected by Building Classified by First Draw & Follow-up Samples:

Building Name	Date of Sample Events	Total Number Samples Collected	Initial First Draw Samples		Follow-up Samples	
			Analyzed at or Below Action Level of 15 ppb	Analyzed Above Action Level of 15 ppb	First Draw Samples	
					Analyzed at or Below Action Level of 15 ppb	Analyzed Above Action Level of 15 ppb
Orchard Park Middle School	10/9/2020	179	170	9	N/A	N/A
	10/20/2020	1	1	0		
	12/11/2020	7	N/A	N/A	3	4
	4/9/2021	4	N/A	N/A	3	1
Total:		187				

** Follow-up samples are samples collected subsequent to "Step 1" First Draw samples to verify initial findings of lead contamination, to assist in problem assessment to determine remediation and/or verify that lead levels are at or below action level post-remediation.

Sample Results: Initial First Draw and Follow-up First Draw

Sample #	Classroom or other Location	Fixture/Outlet type	Date Sampled	Laboratory Analysis in ppb
126.5-25	Men's Room Across from Room 330 Middle	Sink	10/1/2020	19.3
			12/11/2020	12.5 – Cleared
126.5-94	Room 252 Left	Sink	10/1/2020	23.9
			12/11/2020	19.0
			4/9/2021	9.15 - Cleared
126.5-110	Room 234 1 st on Left from Door	Sink	10/1/2020	15.6
			12/11/2020	<1.00 – Cleared
126.5-121	Room 242	Sink	10/1/2020	17.7
			12/11/2020	27.8
			4/9/2021	31.7
126.5-154	Kitchen Handsink	Sink	10/1/2020	18.9
			12/11/2020	1.42 – Cleared
126.5-184	Room 121	Sink	10/1/2020	33.8
			COMPLETELY REMOVED FROM SERVICE	
126.5-193	Room 1S4	Sink	10/1/2020	208
			COMPLETELY REMOVED FROM SERVICE	
126.5-205	Room 137 Left Most	Sink	10/1/2020	15.1
			12/11/2020	17.5
			4/9/2021	<1.00 - Cleared
126.5-207	Room 137 Right Middle	Sink	10/1/2020	30.3
			12/11/2020	19.3
			4/9/2021	1.79 - Cleared

Note: It is recommended that the District continue to prohibit use of any outlet identified above the action level until further mitigation and additional sampling and analysis is performed.