

1.2 Executive Summary of Sampling and Analysis:

Total Number of Samples Collected by Building Classified by First Draw & Follow-up Samples:

Building Name	Date of Sample Events	Total Number Samples Collected	Initial First Draw Samples		Follow-up Samples	
			Analyzed at or Below Action Level of 15 ppb	Analyzed Above Action Level of 15 ppb	Analyzed at or Below Action Level of 15 ppb	Analyzed Above Action Level of 15 ppb
Orchard Park High School	10/9/2020	124	121	3	N/A	N/A
	10/20/2020	17	6	1		
	12/11/2020	4	N/A	N/A	4	0
Total:		135				

** Follow-up samples are samples collected subsequent to "Step 1" First Draw samples to verify initial findings of lead contamination, to assist in problem assessment to determine remediation and/or verify that lead levels are at or below action level post-remediation.

Sample Results: Initial First Draw and Follow-up First Draw

Date	Sample #	Classroom or other Location	Fixture/Outlet type	Laboratory Analysis in ppb
10/1/2020	126.6-149	Room 120 3 rd Clockwise from Door	Sink	15.1
12/11/2020	126.6-149	Room 120 3 rd Clockwise from Door	Sink	4.94 – Cleared
10/1/2020	126.6-245	Kitchen Back Wall Left	Sink	30.3
12/11/2020	126.6-245	Kitchen Back Wall Left	Sink	4.31 – Cleared
10/20/2020	126.6-240	Kitchen Soup Faucet	Sink	29.8
12/11/2020	126.6-240	Kitchen Soup Faucet	Sink	7.06 – Cleared
10/1/2020	126.6-246	Kitchen Back Wall Middle	Sink	18.0
12/11/2020	126.6-246	Kitchen Back Wall Middle	Sink	7.82 – Cleared

Note: It is recommended that the District continue to prohibit use of any outlet identified above the action level until further mitigation and additional sampling and analysis is performed.

1.2 Executive Summary of Sampling and Analysis:

Total Number of Samples Collected by Building Classified by First Draw & Follow-up Samples:

Building Name	Date of Sample Event	Total Number Samples Collected	First Draw Samples		Confirmatory Samples **	
			Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb	Number of Samples at or Below Action level of 15 ppb	Number of Samples Above Action Level of 15 ppb
Orchard Park Athletic Complex	10/20/2020	7	4	3	N/A	N/A
	4/9/2021	3	N/A	N/A	3	0

** Follow-up samples are samples collected subsequent to "Step 1" First Draw samples to verify initial findings of lead contamination, to assist in problem assessment to determine remediation and/or verify that lead levels are at or below action level post-remediation.

Sample Results: Initial First Draw and Follow-up First Draw

Sample #	Classroom or other Location	Fixture/Outlet type	Date Sampled	Laboratory Analysis in ppb
126.8-1	Concession Room	Sink	10/20/2020	37.1
			4/9/2021	3.66 – Cleared
126.8-7	Women's Room	Sink	10/20/2020	15.6
			4/9/2021	8.19 – Cleared
126.8-8	Men's Room	Sink	10/20/2020	21.7
			4/9/2021	8.71 – Cleared