

#### WATER SAMPLING AND REPORTING SERVICES

COLUMBIA PUBLIC SCHOOLS
ALPHA HART LEWIS ELEMENTARY SCHOOL
5801 ARBOR POINTE PARKWAY
COLUMBIA, MISSOURI

Prepared for:

COLUMBIA PUBLIC SCHOOLS
COLUMBIA, MISSOURI

Prepared by:

GEOTECHNOLOGY, LLC, DBA UES St. Louis, Missouri

Date:

**JULY 20, 2024** 

Project No.:

J044517.01







Environmental
Geotechnical Engineering
Materials Testing
Field Inspections & Code Compliance
Geophysical Technology

July 20, 2024

Mr. David Seamon District Project Manager Columbia Public Schools 1818 West Worley Street Columbia, Missouri 65203

Re: Water Sampling and Reporting Services Columbia Public Schools

Alpha Hart Lewis Elementary School

5801 Arbor Pointe Parkway

Columbia, Missouri Project No. J044517.01

Dear Mr. Seamon:

In accordance with Columbia Public Schools' (CPS) Request for Proposal No. C-24043, dated October 10, 2023, Geotechnology, LLC, dba UES, is pleased to provide this drinking water sampling report for the referenced project. Our scope of services included flushing and sampling of drinking water from potable water outlets, laboratory analysis of water samples, and a letter report.

#### SITE AND PROJECT DESCRIPTION

The subject property consists of the existing Columbia Public Schools Alpha Hart Lewis Elementary School, located west of Arbor Pointe Parkway between Waco Road and Goldenwood Drive in Columbia, Missouri. The purpose of the drinking water sampling was to identify potable water outlets that may require remediation in accordance with the State of Missouri's *Get the Lead out of School Drinking Water Act* (RSMo 160.077).

#### DRINKING WATER SAMPLING

RSMo 160.077 sets standards for lead concentrations in school drinking water, stating that each Missouri school shall provide drinking water with a lead concentration level below five (5) parts per billion (ppb). This Act requires schools to conduct the inventory, sampling, remediation, and monitoring at all potable drinking water outlets used or potentially used for drinking, food preparation, and cooking or cleaning utensils.

In general conformance with the RSMo 160.077 requirements, and the Environmental Protection Agency's (EPA) 3Ts for Reducing Lead in Drinking Water in Schools and Child Care Facilities manual, initial water flushing and sampling activities were conducted on January 11 and 12, 2024, by Mr. Brad Lohrum, a Missouri-licensed lead risk assessor. Mr. Lohrum was assisted by Mr. Robert Haefner, a Missouri-licensed lead risk assessor, and Mr. Seth Lamble, a



Missouri-licensed lead inspector. Copies of training certificates and lead licenses for Messrs. Lohrum, Haefner, and Lamble are included in Appendix A.

An inventory of potable drinking water outlets was provided to UES by CPS. UES personnel sampled the identified outlets utilizing the EPA's "first-draw" methods. The identified outlets were flushed, then allowed to sit undisturbed for a period of 8-18 hours. Following this stagnation period, the first 250 milliliters (ml) of water expelled from the outlets were collected in laboratory-provided containers. A copy of the drinking water sampling forms, which include a list of sample locations, and the times and dates of flushing and sampling activities, is included in Appendix B. Floor plans depicting approximate sample locations are included as Figures 1 and 2.

Using standard chain-of-custody procedures, the drinking water samples were submitted to Teklab, Inc. of Collinsville, Illinois, an independent, certified Missouri Department of Natural Resources (MDNR) Drinking Water and National Environmental Laboratory Accreditation Program (NELAP) accredited laboratory, for analysis of lead content via EPA Method 200.8: Determination of Trace Elements in Waters and Wastes by Inductively Coupled Plasma-Mass Spectrometry.

#### **RESULTS**

Laboratory analyses detected the presence of lead at or above 5 ppb in the following sample.

TABLE 1
DRINKING WATER OUTLETS AT OR ABOVE 5 PARTS PER BILLION

Sample Number / Location and Fixture Type	Results
AHL-03 / Kitchen Dish Wash Sink – Left	7.8 ppb

UES will not be able to represent that the site contains no lead-bearing water outlets beyond those detected or observed by UES during flushing and sampling activities. Copies of the drinking water analytical results are included in Appendix C.

#### **RECOMMENDATIONS**

Our recommendations are summarized below:

 It is our understanding that the outlet identified in Table 1 has either been removed, marked as non-potable, or has otherwise been taken out of service. Should this fixture be put back into service following remediation activities, or if a replacement fixture is to be put into service, further sampling and testing should be conducted.

\* \* \* \* \* \*



The following attachments are included in and complete this report:

Figure 1 - Drinking Water Sample Locations – First Floor
Figure 2 - Drinking Water Sample Locations – Second Floor

Appendix A - Certificates and Licenses of Environmental Professionals

Appendix B - Drinking Water Sampling Forms

Appendix C - Drinking Water Laboratory Data Sheets

Appendix D - Limitations of Report

\* \* \* \* \* \*

We appreciate the opportunity to provide our professional environmental consulting services to Columbia Public Schools on this project. If you have any questions or comments, please contact me at (314) 997-7440.

Very truly yours,

**UES** 

Bradley J. Lohrum Project Manager

BJL/MSR:bjl/jsj



#### **NOTES**

- 1. Drawing not to scale.
- 2. Drawing adapted from "Alpha Hart Lewis Elementary First Floor Plan", provided by the client, dated 06/11/2019.
- Sample locations were identified in the field relative to building features and are approximate only.

Drawn By: BJL	Ck'd By: BJL	App'vd By: MSR
Date: 7-20-24	Date: 7-20-24	Date: 7-20-24




5810 Arbor Pointe Parkway Columbia, Missouri

DRINKING WATER SAMPLING LOCATIONS - FIRST FLOOR

Project Number J044517.01

FIGURE 1



#### **NOTES**

- 1. Drawing not to scale.
- 2. Drawing adapted from "Alpha Hart Lewis Elementary Second Floor Plan", provided by the client, dated 06/11/2019.
- 3. Sample locations were identified in the field relative to building features and are approximate only.

Drawn By: BJL	Ck'd By: BJL	App'vd By: MSR
Date: 7-20-24	Date: 7-20-24	Date: 7-20-24



5810 Arbor Pointe Parkway Columbia, Missouri

DRINKING WATER SAMPLING LOCATIONS - SECOND FLOOR

Project Number J044517.01

FIGURE 2



#### **APPENDIX A**

**CERTIFICATES AND LICENSES OF ENVIRONMENTAL PROFESSIONALS** 

# PUBLIC HEALTH & SOCIAL JUSTICE

SAINT LOUIS UNIVERSITY

CENTER FOR ENVIRONMENTAL EDUCATION AND TRAINING

verifies that

# **Bradley Lohrum**

817 S Sappington Road, Crestwood, MO 63126

has attended 8 contact hours of training and successfully passed an examination

#### Lead Risk Assessor Refresher

St. Louis, MO

Certificate # CEET 325 - 12/12/2022 - 189152

Examination Date: 12/12/2022

CEUs: 0.8

Christopher C. King PhD

Director, Center for Environmental Education and Training

Certificate expiration is 3 years from examination date for Illinois Dept. of Public Health

Center for Environmental Education and Training, 3545 Lafayette, St. Louis, MO 63104 (314) 977-8256 sh.edu/x39753.xml

This training course has been accredited by the Illinois Department of Public Health, and by the Missouri Department of Health & Senior Services.

# STATE OF MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES

# **LEAD OCCUPATION LICENSE REGISTRATION**

Issued to:

# Bradley J. Lohrum

The person, firm or corporation whose name appears on this certificate has fulfilled the requirements for licensure as set forth in the Missouri Revised Statutes 701.300-701.338, as long as not suspended or revoked, and is hereby authorized to engage in the activity listed below.

Lead Risk Assessor
Category of License

Issuance Date: 1/20/2023
Expiration Date: 1/20/2025

License Number: 230120-300006460

Paula F. Nickelson
Acting Director
Department of Health and Senior Services

Davea I. Nichel



# SAINT LOUIS UNIVERSITY

# CENTER FOR ENVIRONMENTAL EDUCATION AND TRAINING

verifies that

# **Robert Haefner**

3951 Dover PI, St. Louis, MO 63116

has attended 8 contact hours of training and successfully passed examination for

### **Lead Risk Assessor Refresher**

St. Louis, MO

Certificate #

CEET 325 3/6/2023

118035

Examination Date:

3/6/2023

**CEUs: 0.8** 

)35

Rene Dulle, MBA, Director

Center for Environmental Education & Training

Center for Environmental Education and Training | 3545 Lafayette Ave., St. Louis, MO 63104 (314) 977-8256 |slu.edu/public-health-social-justice/centers-institutes/ceet.php

The training course has been accredited by the Missouri Dept, of Health and Senior Services, and by the Illinois Dept, of Public Health. Certificate expiration is 3 years from examination date for Illinois Dept, of Public Health.

# STATE OF MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES

# LEAD OCCUPATION LICENSE REGISTRATION

Issued to

# Robert J. Haefner

The person, firm or corporation whose name appears on this certificate has fulfilled the requirements for licensure as set forth in the Missouri Revised Statutes 701.300-701.338, as long as not suspended or revoked, and is hereby authorized to engage in the activity listed below.

Lead Risk Assessor Category of License

Issuance Date: Expiration Date:

License Number:

3/28/2023

3/30/2025

150330-300004672

POPULI SUPREN

Paula F. Nickelson

**Acting Director** 

Department of Health and Senior Services

Lead Licensing Program, PO Box 570, Jefferson City, MO 65102

# COLLEGE FOR PUBLIC HEALTH & SOCIAL JUSTICE

SAINT LOUIS UNIVERSITY

CENTER FOR ENVIRONMENTAL EDUCATION AND TRAINING

verifies that

# Seth Lamble

12040 Chaparral Drive, Bridgeton, Missouri 63044

contact hours of training and successfully passed an examination has attended

### **Lead Inspector Refresher**

St. Louis, MO

Certificate #

**CEET 315** 

1/4/2022

118633

**Examination Date:** 

**CEUs: 0.8** 

1/4/2022

Director, Center for Environmental **Education and Training** 

Christopher C. King PhD

Certificate expiration is 3 years from examination date for Illinois Dept. of Public Health

Center for Environmental Education and Training, 3545 Lafayette, St. Louis, MO 63104 (314) 977-8256 slu.edu/x39753.xml

This training course has been accredited by the Illinois Department of Public Health, and by the Missouri Department of Health & Senior Services.

# STATE OF MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES

# **LEAD OCCUPATION LICENSE REGISTRATION**

Issued to:

# Seth P. Lamble

The person, firm or corporation whose name appears on this certificate has fulfilled the requirements for licensure as set forth in the Missouri Revised Statutes 701.300-701.338, as long as not suspended or revoked, and is hereby authorized to engage in the activity listed below.

### **Lead Inspector**

Category of License

Issuance Date: 4/25/2022 Expiration Date: 4/25/2024

License Number: 160425-300004897

Paula F. Nickelson Acting Director

Daves I. Nichels

Department of Health and Senior Services

Lead Licensing Program, PO Box 570, Jefferson City, MO 65102

# STATE OF MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES

# **Lead Abatement Contractor License**

The person, firm or corporation whose name appears on this certificate is licensed as a Lead Abatement Contractor as set forth in the Missouri Revised Statutes 701.300-701.338 and 19 CSR 30-70.180, as long as not suspended or revoked, and is hereby authorized to engage in lead-bearing substance activities.

Issued to:

# Geotechnology, LLC

11816 Lackland Road, Suite 150 St. Louis, MO 63146

Issuance Date: 2/8/2022 Expiration Date: 2/8/2024

License Number: 060208-0095



Donald G. Kauerauf Director

Department of Health and Senior Services

Lead Licensing Program, PO Box 570, Jefferson City, MO 65102



#### **APPENDIX B**

**DRINKING WATER SAMPLING FORMS** 



### DRINKING WATER SAMPLING FORM

Project Name: Columbia Public Schools Water

Sampling and Reporting Services

Building Name: Alpha Hart Lewis Elementary

Project Number: J044517.01

Address: 5801 Arbor Pointe Parkway

Columbia, Missouri

Sample ID	Fixture Type	Location	Flushed By - Date - Time	Sampled By - Date - Time
AHL-01	S	Kitchen Food Prep - Center	RJH - 1/11/24 - 20:22	RJH - 1/12/24 - 5:47
AHL-02	S	Kitchen Food Prep - West	RJH - 1/11/24 - 20:22	BJL - 1/12/24 - 5:47
AHL-03	S	Kitchen Dish Wash - Left	SPL - 1/11/24 - 20:22	BJL - 1/12/24 - 5:47
AHL-04	S	Kitchen Dish Wash - Right	SPL - 1/11/24 - 20:22	BJL - 1/12/24 - 5:47
AHL-05	ICE	Kitchen	SPL - 1/11/24 - 20:22	RJH - 1/12/24 - 5:48
AHL-06	WF	Commons - Left	SPL - 1/11/24 - 20:24	RJH - 1/12/24 - 5:49
AHL-07	WF	Commons - Right	SPL - 1/11/24 - 20:24	RJH - 1/12/24 - 5:49
AHL-08	WF	Gym - Left	SPL - 1/11/24 - 20:26	RJH - 1/12/24 - 5:51
AHL-09	WF	Gym - Right	SPL - 1/11/24 - 20:26	RJH - 1/12/24 - 5:51
AHL-10	WF	Room B100 - Left	RJH - 1/11/24 - 20:28	RJH - 1/12/24 - 5:52
AHL-11	WF	Room B100 - Right	RJH - 1/11/24 - 20:28	SPL - 1/12/24 - 5:52
AHL-12	WF	Room B109 - Left	RJH - 1/11/24 - 20:30	RJH - 1/12/24 - 5:53
AHL-13	WF	Room B109 - Right	SPL - 1/11/24 - 20:30	SPL - 1/12/24 - 5:53
AHL-14	S	Room B107	SPL - 1/11/24 - 20:31	RJH - 1/12/24 - 5:54
AHL-15	S	Room B112	RJH - 1/11/24 - 20:32	SPL - 1/12/24 - 5:54
AHL-16	S	Room B110	SPL - 1/11/24 - 20:33	RJH - 1/12/24 - 5:55
AHL-17	S	Room C117	RJH - 1/11/24 - 20:34	RJH - 1/12/24 - 5:56
AHL-18	S	Room C115	SPL - 1/11/24 - 20:35	RJH - 1/12/24 - 5:57
AHL-19	WF	Hallway at Room C113 - Left	RJH - 1/11/24 - 20:37	SPL - 1/12/24 - 5:57
AHL-20	WF	Hallway at Room C113 - Right	SPL - 1/11/24 - 20:37	RJH - 1/12/24 - 5:57
AHL-21	S	Room C114	SPL - 1/11/24 - 20:38	RJH - 1/12/24 - 5:58
AHL-22	WF	Room C105 - Left	RJH - 1/11/24 - 20:40	RJH - 1/12/24 - 5:59
AHL-23	BF	Room C105 - Right	RJH - 1/11/24 - 20:40	SPL - 1/12/24 - 5:59
AHL-24	WF	Room C105 - Right	RJH - 1/11/24 - 20:40	SPL - 1/12/24 - 5:59
AHL-25	S	Room C104	RJH - 1/11/24 - 20:42	SPL - 1/12/24 - 6:00

BF=Bottle Filling
B=Bubbler

FW=Filtered Water ICE=Ice Machine

S=Classroom/Other Sink WF=Water Fountain



## DRINKING WATER SAMPLING FORM

Project Name: Columbia Public Schools Water

Sampling and Reporting Services

Building Name: Alpha Hart Lewis Elementary

Project Number: J044517.01

Address: 5801 Arbor Pointe Parkway

Columbia, Missouri

Sample ID	Fixture Type	Location	Flushed By - Date - Time	Sampled By - Date - Time
AHL-26	S	Room C108	SPL - 1/11/24 - 20:44	RJH - 1/12/24 - 6:01
AHL-27	S	Room C107	SPL - 1/11/24 - 20:46	RJH - 1/12/24 - 6:01
AHL-28	S	Room C106	SPL - 1/11/24 - 20:46	SPL - 1/12/24 - 6:02
AHL-29	WF	Room D105 - Left	RJH - 1/11/24 - 20:49	RJH - 1/12/24 - 6:04
AHL-30	WF	Room D105 - Right	RJH - 1/11/24 - 20:49	SPL - 1/12/24 - 6:04
AHL-31	S	Room D103	SPL - 1/11/24 - 20:50	SPL - 1/12/24 - 6:04
AHL-32	S	Room D104	RJH - 1/11/24 - 20:51	RJH - 1/12/24 - 6:05
AHL-33	S	Room D106	SPL - 1/11/24 - 20:52	RJH - 1/12/24 - 6:06
AHL-34	S	Room D107	RJH - 1/11/24 - 20:52	RJH - 1/12/24 - 6:07
AHL-35	S	Room D108	SPL - 1/11/24 - 20:53	RJH - 1/12/24 - 6:08
AHL-36	S	Room D206	RJH - 1/11/24 - 20:54	RJH - 1/12/24 - 6:08
AHL-37	S	Room D209	SPL - 1/11/24 - 20:55	RJH - 1/12/24 - 6:09
AHL-38	S	Room D204	RJH - 1/11/24 - 20:56	RJH - 1/12/24 - 6:10
AHL-39	S	Room D211	SPL - 1/11/24 - 20:57	RJH - 1/12/24 - 6:10
AHL-40	WF	Room D200 - Left	RJH - 1/11/24 - 20:58	RJH - 1/12/24 - 6:11
AHL-41	WF	Room D200 - Right	RJH - 1/11/24 - 20:58	RJH - 1/12/24 - 6:11
AHL-42	S	Room D214	SPL - 1/11/24 - 20:58	RJH - 1/12/24 - 6:13
AHL-43	S	Room C215	RJH - 1/11/24 - 21:01	SPL - 1/12/24 - 6:15
AHL-44	WF	Room C200 - Left	SPL - 1/11/24 - 21:01	RJH - 1/12/24 - 6:15
AHL-45	WF	Room C200 - Right	SPL - 1/11/24 - 21:01	SPL - 1/12/24 - 6:15
AHL-46	WF	Room C205 - Left	SPL - 1/11/24 - 21.:02	RJH - 1/12/24 - 6:16
AHL-47	WF	Room C205 - Right	SPL - 1/11/24 - 21:02	RJH - 1/12/24 - 6:16
AHL-48	S	Room C203	RJH - 1/11/24 - 21:03	SPL - 1/12/24 - 6:16
AHL-49	WF	Room B204 - Left	SPL - 1/11/24 - 21.:07	RJH - 1/12/24 - 6:17
AHL-50	WF	Room B204 - Right	SPL - 1/11/24 - 21:07	RJH - 1/12/24 - 6:17

BF=Bottle Filling
B=Bubbler

FW=Filtered Water ICE=Ice Machine

S=Classroom/Other Sink WF=Water Fountain





### DRINKING WATER SAMPLING FORM

Project Name: Columbia Public Schools Water

Sampling and Reporting Services

Building Name: Alpha Hart Lewis Elementary

Project Number: J044517.01

Address: 5801 Arbor Pointe Parkway

Columbia, Missouri

Sample ID	Fixture Type	Location	Flushed By - Date - Time	Sampled By - Date - Time
AHL-51	WF	Room B209 - Left	SPL - 1/11/24 - 21:08	SPL - 1/12/24 - 6:18
AHL-52	WF	Room B209 - Right	SPL - 1/11/24 - 21:08	SPL - 1/12/24 - 6:18
AHL-53	S	Room B207	SPL - 1/11/24 - 21:09	RJH - 1/12/24 - 6:19
AHL-54	S	Room B212	SPL - 1/11/24 - 21:15	RJH - 1/12/24 - 6:20
AHL-55	S	Room A228	RJH - 1/11/24 - 21:18	RJH - 1/12/24 - 6:21
AHL-56	S	Room A218	SPL - 1/11/24 - 21:19	RJH - 1/12/24 - 6:23
AHL-57	WF	Room A217 - Left	SPL - 1/11/24 - 21:21	BJL - 1/12/24 - 6:23
AHL-58	WF	Room A217 - Right	SPL - 1/11/24 - 21:21	BJL - 1/12/24 - 6:23
	_			
	_			



#### **APPENDIX C**

**DRINKING WATER LABORATORY DATA SHEETS** 



February 14, 2024

Brad Lohrum Geotechnology, Inc. 11816 Lackland Road St. Louis, MO 63146

TEL: (314) 997-7440 FAX: (314) 997-2067

**RE:** J044517.01 **WorkOrder:** 24011320

Dear Brad Lohrum:

TEKLAB, INC received 60 samples on 1/19/2024 10:00:00 AM for the analysis presented in the following report.

Samples are analyzed on an as received basis unless otherwise requested and documented. The sample results contained in this report relate only to the requested analytes of interest as directed on the chain of custody. NELAP accredited fields of testing are indicated by the letters NELAP under the Certification column. Unless otherwise documented within this report, Teklab Inc. analyzes samples utilizing the most current methods in compliance with 40CFR. All tests are performed in the Collinsville, IL laboratory unless otherwise noted in the Case Narrative.

All quality control criteria applicable to the test methods employed for this project have been satisfactorily met and are in accordance with NELAP except where noted. The following report shall not be reproduced, except in full, without the written approval of Teklab, Inc.

If you have any questions regarding these tests results, please feel free to call.

Sincerely,

Shelly A. Hennessy

Shelly A Hennessy

Project Manager

(618)344-1004 ex 36

SHennessy@teklabinc.com

Illinois 100226 Kansas E-10374 Louisiana 05002 Louisiana 05003 Oklahoma 9978



# **Report Contents**

http://www.teklabinc.com/

Client: Geotechnology, Inc.

Work Order: 24011320

Client Project: J044517.01

Report Date: 14-Feb-24

#### This reporting package includes the following:

Cover Letter	1
Report Contents	2
Definitions	3
Case Narrative	5
Accreditations	6
Laboratory Results	7
Receiving Check List	9
Chain of Custody	Appended



#### **Definitions**

http://www.teklabinc.com/

Client: Geotechnology, Inc. Work Order: 24011320

Client Project: J044517.01 Report Date: 14-Feb-24

#### Abbr Definition

- \* Analytes on report marked with an asterisk are not NELAP accredited
- CCV Continuing calibration verification is a check of a standard to determine the state of calibration of an instrument between recalibration.
- CRQL A Client Requested Quantitation Limit is a reporting limit that varies according to customer request. The CRQL may not be less than the MDL.
  - DF Dilution factor is the dilution performed during analysis only and does not take into account any dilutions made during sample preparation. The reported result is final and includes all dilution factors.
  - DNI Did not ignite
- DUP Laboratory duplicate is a replicate aliquot prepared under the same laboratory conditions and independently analyzed to obtain a measure of precision.
- ICV Initial calibration verification is a check of a standard to determine the state of calibration of an instrument before sample analysis is initiated.
- IDPH IL Dept. of Public Health
- LCS Laboratory control sample is a sample matrix, free from the analytes of interest, spiked with verified known amounts of analytes and analyzed exactly like a sample to establish intra-laboratory or analyst specific precision and bias or to assess the performance of all or a portion of the measurement system.
- LCSD Laboratory control sample duplicate is a replicate laboratory control sample that is prepared and analyzed in order to determine the precision of the approved test method. The acceptable recovery range is listed in the QC Package (provided upon request).
- MBLK Method blank is a sample of a matrix similar to the batch of associated sample (when available) that is free from the analytes of interest and is processed simultaneously with and under the same conditions as samples through all steps of the analytical procedures, and in which no target analytes or interferences should present at concentrations that impact the analytical results for sample analyses.
- MDL "The method detection limit is defined as the minimum measured concentration of a substance that can be reported with 99% confidence that the measured concentration is distinguishable from method blank results."
- MS Matrix spike is an aliquot of matrix fortified (spiked) with known quantities of specific analytes that is subjected to the entire analytical procedures in order to determine the effect of the matrix on an approved test method's recovery system. The acceptable recovery range is listed in the QC Package (provided upon request).
- MSD Matrix spike duplicate means a replicate matrix spike that is prepared and analyzed in order to determine the precision of the approved test method. The acceptable recovery range is listed in the QC Package (provided upon request).
- MW Molecular weight
- NC Data is not acceptable for compliance purposes
- ND Not Detected at the Reporting Limit
- NELAP NELAP Accredited
  - PQL Practical quantitation limit means the lowest level that can be reliably achieved within specified limits of precision and accuracy during routine laboratory operation conditions.
  - RL The reporting limit the lowest level that the data is displayed in the final report. The reporting limit may vary according to customer request or sample dilution. The reporting limit may not be less than the MDL.
  - RPD Relative percent difference is a calculated difference between two recoveries (ie. MS/MSD). The acceptable recovery limit is listed in the QC Package (provided upon request).
  - SPK The spike is a known mass of target analyte added to a blank sample or sub-sample; used to determine recovery deficiency or for other quality control purposes.
  - Surr Surrogates are compounds which are similar to the analytes of interest in chemical composition and behavior in the analytical process, but which are not normally found in environmental samples.
  - TIC Tentatively identified compound: Analytes tentatively identified in the sample by using a library search. Only results not in the calibration standard will be reported as tentatively identified compounds. Results for tentatively identified compounds that are not present in the calibration standard, but are assigned a specific chemical name based upon the library search, are calculated using total peak areas from reconstructed ion chromatograms and a response factor of one. The nearest Internal Standard is used for the calculation. The results of any TICs must be considered estimated, and are flagged with a "T". If the estimated result is above the calibration range it is flagged "ET"
- TNTC Too numerous to count ( > 200 CFU )



#### **Definitions**

http://www.teklabinc.com/

Client: Geotechnology, Inc. Work Order: 24011320

Client Project: J044517.01 Report Date: 14-Feb-24

#### **Qualifiers**

- B Analyte detected in associated Method Blank
  - E Value above quantitation range
  - I Associated internal standard was outside method criteria
  - M Manual Integration used to determine area response
  - R RPD outside accepted recovery limits
  - T TIC(Tentatively identified compound)

- # Unknown hydrocarbon
- RL shown is a Client Requested Quantitation Limit
- H Holding times exceeded
- J Analyte detected below quantitation limits
- ND Not Detected at the Reporting Limit
  - S Spike Recovery outside recovery limits
  - X Value exceeds Maximum Contaminant Level



### **Case Narrative**

http://www.teklabinc.com/

Work Order: 24011320

Report Date: 14-Feb-24

Client: Geotechnology, Inc.

Cooler Receipt Temp: NA °C

Client Project: J044517.01

#### Locations

	Collinsville		Springfield		Kansas City
Address	5445 Horseshoe Lake Road	Address	3920 Pintail Dr	Address	8421 Nieman Road
	Collinsville, IL 62234-7425		Springfield, IL 62711-9415		Lenexa, KS 66214
Phone	(618) 344-1004	Phone	(217) 698-1004	Phone	(913) 541-1998
Fax	(618) 344-1005	Fax	(217) 698-1005	Fax	(913) 541-1998
Email	jhriley@teklabinc.com	Email	KKlostermann@teklabinc.com	Email	jhriley@teklabinc.com
	Collinsville Air		Chicago		
Address	5445 Horseshoe Lake Road	Address	1319 Butterfield Rd.		
	Collinsville, IL 62234-7425		Downers Grove, IL 60515		
Phone	(618) 344-1004	Phone	(630) 324-6855		
Fax	(618) 344-1005	Fax			
Email	EHurley@teklabinc.com	Email	arenner@teklabinc.com		



### **Accreditations**

#### http://www.teklabinc.com/

Client: Geotechnology, Inc. Work Order: 24011320

Client Project: J044517.01 Report Date: 14-Feb-24

State	Dept	Cert #	NELAP	Exp Date	Lab
Illinois	IEPA	100226	NELAP	1/31/2025	Collinsville
Kansas	KDHE	E-10374	NELAP	4/30/2024	Collinsville
Louisiana	LDEQ	05002	NELAP	6/30/2024	Collinsville
Louisiana	LDEQ	05003	NELAP	6/30/2024	Collinsville
Oklahoma	ODEQ	9978	NELAP	8/31/2024	Collinsville
Arkansas	ADEQ	88-0966		3/14/2024	Collinsville
Illinois	IDPH	17584		5/31/2025	Collinsville
Iowa	IDNR	430		6/1/2024	Collinsville
Kentucky	UST	0073		1/31/2025	Collinsville
Missouri	MDNR	00930		10/31/2026	Collinsville
Missouri	MDNR	930		1/31/2025	Collinsville



# **Laboratory Results**

http://www.teklabinc.com/

Client: Geotechnology, Inc. Work Order: 24011320

Client Project: J044517.01 Report Date: 14-Feb-24

Matrix: DRINKING WATER

Sample ID	Client Sample ID	Certification Qual	RL	Result	Units	DF	Date Analyzed	Date Collected
EPA 600 4.1.4 Lead	l, 200.8 R5.4, META	LS BY ICPMS (TOTAL)						
24011320-001	A LMS-79	NELAP	1.0	< 1.0	μg/L	1	02/09/2024 5:19	01/12/2024 5:12
24011320-002/	A LMS-80	NELAP	1.0	2.3	µg/L	1	02/02/2024 20:27	01/12/2024 5:12
24011320-003/	A LMS-81	NELAP	1.0	2.9	µg/L	1	02/02/2024 20:31	01/12/2024 5:13
24011320-004	A LMS-82	NELAP	1.0	3.0	μg/L	1	02/02/2024 20:35	01/12/2024 5:13
24011320-005/	A LMS-83	NELAP	1.0	2.4	µg/L	1	02/02/2024 20:38	01/12/2024 5:14
24011320-006	A LMS-84	NELAP	1.0	< 1.0	μg/L	1	02/02/2024 20:49	01/12/2024 5:14
24011320-007	A LMS-85	NELAP	1.0	2.2	μg/L	5	02/12/2024 16:18	01/12/2024 5:15
24011320-008/	A LMS-86	NELAP	1.0	< 1.0	µg/L	5	02/12/2024 16:52	01/12/2024 5:15
24011320-009/	A LMS-87	NELAP	1.0	1.6	μg/L	5	02/12/2024 16:57	01/12/2024 5:16
24011320-010	A LMS-88	NELAP	1.0	< 1.0	µg/L	1	02/03/2024 5:18	01/12/2024 5:16
24011320-011	A LMS-89	NELAP	1.0	< 1.0	µg/L	1	02/03/2024 5:22	01/12/2024 5:17
24011320-012	A LMS-90	NELAP	1.0	< 1.0	µg/L	1	02/03/2024 5:26	01/12/2024 5:17
24011320-013/	A LMS-91	NELAP	1.0	< 1.0	µg/L	1	02/03/2024 5:31	01/12/2024 5:18
24011320-014	A LMS-92	NELAP	1.0	1.3	µg/L	1	02/03/2024 5:47	01/12/2024 5:18
24011320-015/	A LMS-93	NELAP	1.0	< 1.0	µg/L	5	02/12/2024 17:01	01/12/2024 5:19
24011320-016	A LMS-94	NELAP	1.0	< 1.0	µg/L	1	02/03/2024 5:35	01/12/2024 5:19
24011320-017/	A LMS-95	NELAP	1.0	1.1	µg/L	1	02/03/2024 5:39	01/12/2024 5:20
24011320-018/	A LMS-96	NELAP	1.0	< 1.0	µg/L	1	02/03/2024 5:43	01/12/2024 5:20
24011320-019/	A LMS-97	NELAP	1.0	1.6	µg/L	1	02/03/2024 6:12	01/12/2024 5:20
24011320-020/	A LMS-98	NELAP	1.0	6.1	µg/L	5	02/08/2024 12:41	01/12/2024 5:20
24011320-021	A LMS-99	NELAP	1.0	< 1.0	µg/L	1	02/03/2024 6:16	01/12/2024 5:21
24011320-022/	A LMS-100	NELAP	1.0	< 1.0	µg/L	1	02/03/2024 6:20	01/12/2024 5:21
24011320-023/	A LMS-101	NELAP	1.0	1.0	µg/L	1	02/03/2024 6:24	01/12/2024 5:23
24011320-024	A LMS-102	NELAP	1.0	< 1.0	µg/L	1	02/06/2024 3:16	01/12/2024 5:23
24011320-025/	A LMS-103	NELAP	1.0	4.4	µg/L	1	02/06/2024 3:19	01/12/2024 5:24
24011320-026/	A LMS-104	NELAP	1.0	1.9	µg/L	5	02/08/2024 11:27	01/12/2024 5:24
24011320-027/	A LMS-105	NELAP	1.0	15.2	µg/L	5	02/08/2024 11:32	01/12/2024 5:24
24011320-028/	A LMS-106	NELAP	1.0	< 1.0	µg/L	1	02/06/2024 3:23	01/12/2024 5:26
24011320-029/	A LMS-107	NELAP	1.0	< 1.0	µg/L	1	02/06/2024 3:27	01/12/2024 5:26
24011320-030/	A LMS-108	NELAP	1.0	< 1.0	μg/L	1	02/06/2024 3:30	01/12/2024 5:26
24011320-031/	A LMS-109	NELAP	1.0	< 1.0	µg/L	1	02/09/2024 4:55	01/12/2024 5:26
24011320-032/	A LMS-110	NELAP	1.0	1.1	μg/L	1	02/06/2024 20:40	01/12/2024 5:29
24011320-033/	A LMS-111	NELAP	1.0	< 1.0	µg/L	1	02/09/2024 4:59	01/12/2024 5:29
24011320-034	A LMS-112	NELAP	1.0	< 1.0	μg/L	1	02/06/2024 21:15	01/12/2024 5:32
24011320-035/	A LMS-113	NELAP	1.0	< 1.0	μg/L	1	02/09/2024 5:03	01/12/2024 5:32
24011320-036	A LMS-114	NELAP	1.0	4.3	μg/L	1	02/06/2024 21:23	01/12/2024 5:32
24011320-037	A AHL-01	NELAP	1.0	< 1.0	μg/L	1	02/06/2024 21:28	01/12/2024 5:47
24011320-038	A AHL-02	NELAP	1.0	< 1.0	μg/L	1	02/06/2024 21:32	01/12/2024 5:47
24011320-039	A AHL-03	NELAP	1.0	7.8	μg/L	5	02/08/2024 11:36	01/12/2024 5:47
24011320-040	A AHL-04	NELAP	1.0	1.3	μg/L	1	02/06/2024 21:36	01/12/2024 5:47
24011320-041	A AHL-05	NELAP	1.0	< 1.0	μg/L	1	02/06/2024 21:45	01/12/2024 5:48
24011320-042	A AHL-06	NELAP	1.0	< 1.0	μg/L	1	02/09/2024 5:16	01/12/2024 5:49
24011320-043	A AHL-07	NELAP	1.0	< 1.0	μg/L	1	02/14/2024 9:15	01/12/2024 5:49
24011320-044	A AHL-08	NELAP	1.0	< 1.0	μg/L	1	02/02/2024 17:36	01/12/2024 5:51
24011320-045		NELAP	1.0	< 1.0	μg/L	1	02/02/2024 18:01	01/12/2024 5:51
24011320-046		NELAP	1.0	< 1.0	μg/L	1	02/02/2024 17:40	01/12/2024 5:52
24011320-047		NELAP	1.0	< 1.0	μg/L	1	02/02/2024 17:44	01/12/2024 5:52
24011320-048		NELAP	1.0	< 1.0	μg/L	1	02/02/2024 17:48	01/12/2024 5:53



# **Laboratory Results**

http://www.teklabinc.com/

Client: Geotechnology, Inc. Work Order: 24011320

Client Project: J044517.01 Report Date: 14-Feb-24

Matrix: DRINKING WATER

Sample ID	Client Sample ID	Certification Qual	RL	Result	Units	DF	Date Analyzed	Date Collected
EPA 600 4.1.4	1, 200.8 R5.4, META	LS BY ICPMS (TOTAL)						
Lead								
24011320-049	A AHL-13	NELAP	1.0	< 1.0	μg/L	1	02/02/2024 17:52	01/12/2024 5:53
24011320-050	A AHL-14	NELAP	1.0	1.7	μg/L	1	02/02/2024 17:56	01/12/2024 5:54
24011320-051	A AHL-15	NELAP	1.0	1.2	μg/L	1	02/02/2024 18:25	01/12/2024 5:54
24011320-052	A AHL-16	NELAP	1.0	3.0	μg/L	5	02/08/2024 11:40	01/12/2024 5:55
24011320-053	A AHL-17	NELAP	1.0	1.6	μg/L	1	02/02/2024 18:29	01/12/2024 5:56
24011320-054	A AHL-18	NELAP	1.0	3.0	μg/L	1	02/02/2024 18:34	01/12/2024 5:57
24011320-055	A AHL-19	NELAP	1.0	< 1.0	μg/L	1	02/02/2024 18:38	01/12/2024 5:57
24011320-056	A AHL-20	NELAP	1.0	< 1.0	μg/L	1	02/02/2024 18:54	01/12/2024 5:57
24011320-057	A AHL-21	NELAP	1.0	2.1	μg/L	5	02/08/2024 12:11	01/12/2024 5:58
24011320-058	A AHL-22	NELAP	1.0	< 1.0	μg/L	1	02/02/2024 18:42	01/12/2024 5:59
24011320-059	A AHL-23	NELAP	1.0	< 1.0	μg/L	1	02/02/2024 18:46	01/12/2024 5:59
24011320-060	A AHL-24	NELAP	1.0	< 1.0	μg/L	1	02/02/2024 18:50	01/12/2024 5:59



Client: Geotechnology, Inc.

#### **Receiving Check List**

http://www.teklabinc.com/

Work Order: 24011320

Client Project: J044517.01 Report Date: 14-Feb-24 Carrier: Employee Received By: MEK Completed by: Reviewed by: Mary E. Kemp On: On: 19-Jan-24 19-Jan-24 Mary E Kemp Ellie Hopkins Extra pages included 0 Pages to follow: Chain of custody Shipping container/cooler in good condition? Yes **✓** No 🗔 Not Present Temp °C NA Type of thermal preservation? **V** Ice \_ Blue Ice None Dry Ice Chain of custody present? **~** No L Yes Chain of custody signed when relinquished and received? **~** Yes No L **~** Chain of custody agrees with sample labels? No 🗀 Yes **~** No 🗌 Samples in proper container/bottle? Yes **V** No 🗌 Sample containers intact? Yes Sufficient sample volume for indicated test? Yes **~** No **~** No  $\square$ All samples received within holding time? Yes NA 🗸 Field Lab Reported field parameters measured: Yes 🗸 No 🗌 Container/Temp Blank temperature in compliance? When thermal preservation is required, samples are compliant with a temperature between 0.1°C - 6.0°C, or when samples are received on ice the same day as collected. Water - at least one vial per sample has zero headspace? Yes 🗌 No 🗀 No VOA vials 🗸 No TOX containers Water - TOX containers have zero headspace? Yes No 🗌 Yes 🗹 No 🗌 Water - pH acceptable upon receipt? NA 🗹 NPDES/CWA TCN interferences checked/treated in the field? Yes No 🗀 Any No responses must be detailed below or on the COC.

Samples were checked for turbidity and then preserved with nitric acid upon arrival in the laboratory. - MaryKemp - 1/19/2024 11:07:48 AM

pg. 34 of 74 Work order # <u>24011320</u>

TEKLAB, INC. 5445 Horseshoe Lake Road - Collinsville, IL 62234 - Phone: (618) 344-1004 - Fax: (618) 344-1005

Client: Address: City / State / Zip Contact: E-Mail:  Geotechnology, LI 11816 Lackland R St. Louis, MO 631 blohrum@teamues.com  Geotechnology, LI 11816 Lackland R St. Louis, MO 631 blohrum@teamues.com	Phone: (314) 997-7440  Fax:	Samples on: SICE BLUE ICE NA Preserved in: LAB FIELD Lab Notes  Client Comments:	FOR LAB USE ONLY
Are these samples known to be hazardous?  Are there any required reporting limits to be n limits in the comment section. Yes  Project Name/Number	Yes No negt on the requested analysis?. If yes, please provide	MATRIX INDICAT	TE ANALYSIS REQUESTED
J044517.0    Results Requested  Standard 1-2 Day (100% Surcharge)  □ Other □ □ 3 Day (50% Surcharge)	Billing Instructions # and Type of Containers  UNPRE UNPRE NAGOH HCL HCL HCL HCL HCL HCL HCL HCL HCL HC	DW - Lead E200.8 Groundwater Special Waste Sludge Soil Drinking Water Aqueous	
Lab Use Only   Sample Identification	Date/Time Sampled 5	Received By  A Phy  Many Yang	Date/Time ///3/24 1/19/24 1000

BottleOrder:

80481



pg. 35 of 74 Work order # 240(1320

TEKLAB, INC. 5445 Horseshoe Lake Road - Collinsville, IL 62234 - Phone: (618) 344-1004 - Fax: (618) 344-1005

<b></b>			···																							×. /					***************************************		muneés.
Client:	_	Geotechnology, L	LC										.	Sar	npl	es e	on:	<b>***</b>	ICE		BLUE	ICE	繆	NO I	CE			°	C	LTG	₩		
Address:		118 <b>1</b> 6 Lackland F	Road											Pre	ser	vec	l in	· 38	LAB	额	FIELD	)			F	OR L	_AB	USE	ON	<u>_Y</u>			2000 m
City / State	/ Zip	St. Louis, MO 63	146											Lab	No	tes	5																9000
Contact:	Brad Lol	num			Phone	9:	(;	314)	997	-744	Ю																						Security
E-Mail:	blohrum	@teamues.com			Fax:		_						<b>.</b>	Clie	n# C	`^n		nte	.,						`					-	<del></del>		
									J.,		Æ	<del>.</del>		211 <del>C</del> 1	111	,UI3	13116	= i sta	<b>&gt;</b> ,														
Are these samples Are these samples						WII	appi	ıy	Ш	res	<u> ,c</u>	No.																					
Are there any requ	ired repo	rting limits to be i	met on th			is?.	If ye	s, p	lease	e pro	ovide		ı																				
limits in the comm	ent section	on. 🗌 Yes 💆	No																														
Project I	Name/N	lumber		Sam	ple Co	lec	tor	's i	lam	e				ľ	/A	RI.	X					INC	ICA	TE/	4ΝA	LYS	IS R	EQU	EST	ED			
1049	4<1	7.01	•	PM	ad L	λ	ľV	W						٥			S	0	DW														
			Rillin	g Instru	ctions	#	and	Ту	pe of	Co	ntain	ers	Ì≽	真		S	pec	irot															
Results Standard	1-2 Day (	00% Surcharge)	Dimin	ig ilistiu	Clions	C			_	T,	z	ج ا	ue	ing.	Soil	Sludge	ial	ınd	Lead			Ì											İ
Other	3 Day	(50% Surcharge)				R	Š	Na O	1250	됤	ntain NaHSC4	ΙĬ	suc	<b>Drinking Water</b>	_	ge	Special Waste	Groundwater	E2(														ĺ
Lab Use Only	Samp	le Identification	Dat	te/Time Sa	mpled	ES	w	I	Ž.		H Ç	7		ter			te	er	E200.8														
240132041	AHL	_ 05	1/12	124:	5:48									X					X														
1 042	AHI	- 0b	1 1	!	5:49									K					X														
043	1	01			+	П				1				K					X				•										
044		08			5:51									K				********	X														
645		09			+	П								X					X		Ì												
046		10		Ę	5;52	П				T				X					X														
047		i(			+									X					X														
048		12		5	:53					T				X					X														
049		13			7	П				T		1	1	X					χ														
050		14			:54	H			Ħ	$\dagger$	$\dagger$	$\dagger$		X					$\hat{\nabla}$														
1 0001	Relino	uished By	1		, 0	<u> </u>	Date	/Ti	me					<i>V</i> \	<b>!</b>			Re	ceive	d By	, <u></u>	L		-	Т	<u> </u>	<u> </u>	Di	ate/T	me		<u> </u>	
Ballel	1	~		ī	18/21	_	_								Z	7	1)	, li	10							1/	10		24				
W40.14	<u> </u>	Z.s	ili.	<del>-   /</del>	1/19		u	n	11	2/	00	,			N		المستعدد		11						1	Mic	7 la			00			
		F34	0		1171				10	, -						<i>(</i> )	<u>بب</u> ک	5	<u></u>	MN	\\				+	- 1	110	-{	ن ن	زيا س			
													-											<del></del>	+-								



pg. 36 of 74 Work order # 24011320

TEKLAB, INC. 5445 Horseshoe Lake Road - Collinsville, IL 62234 - Phone: (618) 344-1004 - Fax: (618) 344-1005

										11101							EQ.	ice	<b>■ BLU</b> E	: ICE	EES N	OICE				°С		T0#		***
Client:		Geotechnology, LLC									_	•									INC. IA					_		TG#		9 9
Address:		11816 Lackland Ro									_	1						LAB	FIEL	ט			FOR	LA	<u> </u>	<u>)E U</u>	NLI			action of the contract of the
	/ Zip	St. Louis, MO 6314	16									1	.ab	No	tes	3														No. opposite
Contact:	Brad Lo			Phon	e:	-	314	997-	/44(	)		L										- 24								
E-Mail:	blohrun	n@teamues.com		Fax:		-					_	C	lier	ıt C	on	ıme	ents	s:				·				·				
Are these samples Are there any requirements in the comm	known ired rep ent sect	to be involved in litig to be hazardous? orting limits to be me ion.	Yes	No requested analy	sis?	. If y	es, p	lease	pro	X vide	No									TR.FPS	IO A T	E AN	i a i v	/OIO	DEC	ME	ote:			
Project I				Sample Co					<b>Э</b>		ŀ			IAT	KI.	X	ı			טאו	CAI	EAN	IALT	212	KEU	10E	21EI	<del>,</del> —		<b>T</b> *
1040	151	7.01	-	ared Lo	M	<b>V</b> U	W	<u> </u>					Dri			Sp	ନ୍ଦ	D₩												
Results	s Requ	ıested	Billing	Instructions	,	# an	d Ty	pe of	Con	taine	s	Aqueous	nki		S	eci	Š	- 1.6												
<b>—</b>		(100% Suichaige)					1	1 1	_   =	.   <u>.</u>		ueo	ng 1	<u>S.</u>	gbn	al v	Mp	ad I												
Other	3 Da	y (50% Surcharge)			3	ő	후	H2504	<u> </u>	NaHSO4	OTHER	sn	Drinking Water		e	Special Waste	Groundwater	DW - Lead E200.8						-						
Lab Use Only	Sam	ple Identification	Date	/Time Sampled	۳			4		4	~		er			æ	~	0.8								$\bot$		$\perp$	$\bot$	
a401132005)	AH	L- 15	1/12/	24 5:54									X					X										_		
1 052	AH	L- 16	1	5:55	$\parallel$								X					X												
053		17		5:56	П	Τ		П	T				X					$\chi$												
024		16		5:51	$\dagger \dagger$	T	T	$\Box$	T				X													T	$\Box$			
		1 d		2,01	${}^{\dag}$	T	T	f-f	$\dagger$	$\Box$	┪		$\overrightarrow{\chi}$					$ \hat{\mathbf{v}} $		1	十			1	1	$\top$	十	1		
055			<del>  -</del>		╫	+	┢	$\vdash$	┿	┿			X	$\dashv$				$ \cdot\rangle$	<del>-   </del>		$\dashv$	_		$\dashv$	+	_		+	+	+
056	-			سك	Н	+	╄	-	+	+	$\dashv$							$\frac{A}{2}$		$\dashv$	$\dashv$		_	+	┪	+	+	+	-	+
057	$\dashv$	2	<b></b>	<u>5:58</u>	$\parallel$	$\bot$	$\vdash$	$\sqcup$	-		4		Ϋ́	_				Ŋ			$\dashv$	_	_	+	_	+	+	+	+	+
058	$\perp$	22		5:59		$oxed{\bot}$	L		_				X					X.			_			_		+	4			-
059		ఎ3		1									X					X												
J 060	丄	24	لر		Г								X					X						1						
	Relin	quished By				Dat	e/Ti	me			I						Re	ceive	ed By				,				e/Tim	е		
Bren Mil	A		 A	1/18/	24						T				Z	-//	LA	10	)				P	1/2	<b>3</b> /2	24				
	 	Lo II	J	1/1/2	N	4	7	1	) ,"	$\infty$				-1V	1~	,	١.	4/1	4.43				1 1	910	34	ì	٥٥	<del></del>		
<u> </u>		- 12 g VV	1	1,17		<u>~ /</u>		F	·············		7				4_4	<u> </u>	ð	اماد							. ,		<u></u>	.::Turner		
											1	-																		<del>,</del>



February 12, 2024

**Brad Lohrum** Geotechnology, Inc. 11816 Lackland Road St. Louis, MO 63146

TEL: (314) 997-7440 FAX: (314) 997-2067

**RE:** J044517.01 **WorkOrder:** 24011321

Dear Brad Lohrum:

TEKLAB, INC received 60 samples on 1/19/2024 10:00:00 AM for the analysis presented in the following report.

Samples are analyzed on an as received basis unless otherwise requested and documented. The sample results contained in this report relate only to the requested analytes of interest as directed on the chain of custody. NELAP accredited fields of testing are indicated by the letters NELAP under the Certification column. Unless otherwise documented within this report, Teklab Inc. analyzes samples utilizing the most current methods in compliance with 40CFR. All tests are performed in the Collinsville, IL laboratory unless otherwise noted in the Case Narrative.

All quality control criteria applicable to the test methods employed for this project have been satisfactorily met and are in accordance with NELAP except where noted. The following report shall not be reproduced, except in full, without the written approval of Teklab, Inc.

If you have any questions regarding these tests results, please feel free to call.

Sincerely,

Patrick Riley Project Manager

(618)344-1004 ex 44

patrickriley@teklabinc.com

Illinois 100226 Kansas E-10374 Louisiana 05002 Louisiana 05003 Oklahoma 9978



# **Report Contents**

http://www.teklabinc.com/

Client: Geotechnology, Inc.

Work Order: 24011321

Client Project: J044517.01

Report Date: 12-Feb-24

#### This reporting package includes the following:

Cover Letter	1
Report Contents	2
Definitions	3
Case Narrative	5
Accreditations	6
Laboratory Results	7
Receiving Check List	9
Chain of Custody	Appended



#### **Definitions**

http://www.teklabinc.com/

Client: Geotechnology, Inc.

Work Order: 24011321

Client Project: J044517.01 Report Date: 12-Feb-24

#### **Abbr Definition**

- \* Analytes on report marked with an asterisk are not NELAP accredited
- CCV Continuing calibration verification is a check of a standard to determine the state of calibration of an instrument between recalibration.
- CRQL A Client Requested Quantitation Limit is a reporting limit that varies according to customer request. The CRQL may not be less than the MDL.
  - DF Dilution factor is the dilution performed during analysis only and does not take into account any dilutions made during sample preparation. The reported result is final and includes all dilution factors.
  - DNI Did not ignite
- DUP Laboratory duplicate is a replicate aliquot prepared under the same laboratory conditions and independently analyzed to obtain a measure of precision.
- ICV Initial calibration verification is a check of a standard to determine the state of calibration of an instrument before sample analysis is initiated.
- IDPH IL Dept. of Public Health
- LCS Laboratory control sample is a sample matrix, free from the analytes of interest, spiked with verified known amounts of analytes and analyzed exactly like a sample to establish intra-laboratory or analyst specific precision and bias or to assess the performance of all or a portion of the measurement system.
- LCSD Laboratory control sample duplicate is a replicate laboratory control sample that is prepared and analyzed in order to determine the precision of the approved test method. The acceptable recovery range is listed in the QC Package (provided upon request).
- MBLK Method blank is a sample of a matrix similar to the batch of associated sample (when available) that is free from the analytes of interest and is processed simultaneously with and under the same conditions as samples through all steps of the analytical procedures, and in which no target analytes or interferences should present at concentrations that impact the analytical results for sample analyses.
- MDL "The method detection limit is defined as the minimum measured concentration of a substance that can be reported with 99% confidence that the measured concentration is distinguishable from method blank results."
- MS Matrix spike is an aliquot of matrix fortified (spiked) with known quantities of specific analytes that is subjected to the entire analytical procedures in order to determine the effect of the matrix on an approved test method's recovery system. The acceptable recovery range is listed in the QC Package (provided upon request).
- MSD Matrix spike duplicate means a replicate matrix spike that is prepared and analyzed in order to determine the precision of the approved test method. The acceptable recovery range is listed in the QC Package (provided upon request).
- MW Molecular weight
- NC Data is not acceptable for compliance purposes
- ND Not Detected at the Reporting Limit
- NELAP NELAP Accredited
  - PQL Practical quantitation limit means the lowest level that can be reliably achieved within specified limits of precision and accuracy during routine laboratory operation conditions.
  - RL The reporting limit the lowest level that the data is displayed in the final report. The reporting limit may vary according to customer request or sample dilution. The reporting limit may not be less than the MDL.
  - RPD Relative percent difference is a calculated difference between two recoveries (ie. MS/MSD). The acceptable recovery limit is listed in the QC Package (provided upon request).
  - SPK The spike is a known mass of target analyte added to a blank sample or sub-sample; used to determine recovery deficiency or for other quality control purposes.
  - Surr Surrogates are compounds which are similar to the analytes of interest in chemical composition and behavior in the analytical process, but which are not normally found in environmental samples.
  - TIC Tentatively identified compound: Analytes tentatively identified in the sample by using a library search. Only results not in the calibration standard will be reported as tentatively identified compounds. Results for tentatively identified compounds that are not present in the calibration standard, but are assigned a specific chemical name based upon the library search, are calculated using total peak areas from reconstructed ion chromatograms and a response factor of one. The nearest Internal Standard is used for the calculation. The results of any TICs must be considered estimated, and are flagged with a "T". If the estimated result is above the calibration range it is flagged "ET"
- TNTC Too numerous to count ( > 200 CFU )



#### **Definitions**

http://www.teklabinc.com/

Client: Geotechnology, Inc. Work Order: 24011321

Client Project: J044517.01 Report Date: 12-Feb-24

#### Qualifiers

- # Unknown hydrocarbonC RL shown is a Client Requested Quantitation Limit
- H Holding times exceeded
- J Analyte detected below quantitation limits
- ND Not Detected at the Reporting Limit
  - S Spike Recovery outside recovery limits
  - X Value exceeds Maximum Contaminant Level

- B Analyte detected in associated Method Blank
- E Value above quantitation range
- I Associated internal standard was outside method criteria
- M Manual Integration used to determine area response
- R RPD outside accepted recovery limits
- T TIC(Tentatively identified compound)



### **Case Narrative**

http://www.teklabinc.com/

Work Order: 24011321

Report Date: 12-Feb-24

Client: Geotechnology, Inc.

Client Project: J044517.01

Cooler Receipt Temp: NA °C

#### Locations

	Collinsville		Springfield		Kansas City
Address	5445 Horseshoe Lake Road	Address	3920 Pintail Dr	Address	8421 Nieman Road
	Collinsville, IL 62234-7425		Springfield, IL 62711-9415		Lenexa, KS 66214
Phone	(618) 344-1004	Phone	(217) 698-1004	Phone	(913) 541-1998
Fax	(618) 344-1005	Fax	(217) 698-1005	Fax	(913) 541-1998
Email	jhriley@teklabinc.com	Email	KKlostermann@teklabinc.com	Email	jhriley@teklabinc.com
	Collinsville Air		Chicago		
Address	5445 Horseshoe Lake Road	Address	1319 Butterfield Rd.		
	Collinsville, IL 62234-7425		Downers Grove, IL 60515		
Phone	(618) 344-1004	Phone	(630) 324-6855		
Fax	(618) 344-1005	Fax			
Email	EHurley@teklabinc.com	Email	arenner@teklabinc.com		
	•				



### **Accreditations**

#### http://www.teklabinc.com/

Client: Geotechnology, Inc. Work Order: 24011321

Client Project: J044517.01 Report Date: 12-Feb-24

State	Dept	Cert #	NELAP	Exp Date	Lab
Illinois	IEPA	100226	NELAP	1/31/2025	Collinsville
Kansas	KDHE	E-10374	NELAP	4/30/2024	Collinsville
Louisiana	LDEQ	05002	NELAP	6/30/2024	Collinsville
Louisiana	LDEQ	05003	NELAP	6/30/2024	Collinsville
Oklahoma	ODEQ	9978	NELAP	8/31/2024	Collinsville
Arkansas	ADEQ	88-0966		3/14/2024	Collinsville
Illinois	IDPH	17584		5/31/2025	Collinsville
Iowa	IDNR	430		6/1/2024	Collinsville
Kentucky	UST	0073		1/31/2025	Collinsville
Missouri	MDNR	00930		10/31/2026	Collinsville
Missouri	MDNR	930		1/31/2025	Collinsville



# **Laboratory Results**

http://www.teklabinc.com/

Client: Geotechnology, Inc.

Work Order: 24011321

Client Project: J044517.01

Report Date: 12-Feb-24

Matrix: DRINKING WATER

Sample ID	Client Sample ID	Certification Qual	RL	Result	Units	DF	Date Analyzed	Date Collected
EPA 600 4.1.4	4, 200.8 R5.4, META	LS BY ICPMS (TOTAL)						
Lead								
24011321-001	A AHL-25	NELAP	1.0	< 1.0	μg/L	1	02/09/2024 3:03	01/12/2024 6:00
24011321-002	A AHL-26	NELAP	1.0	2.4	μg/L	1	02/09/2024 3:07	01/12/2024 6:01
24011321-003	A AHL-27	NELAP	1.0	< 1.0	μg/L	1	02/09/2024 3:10	01/12/2024 6:01
24011321-004	A AHL-28	NELAP	1.0	< 1.0	μg/L	1	02/09/2024 14:23	01/12/2024 6:02
24011321-005	A AHL-29	NELAP	1.0	< 1.0	μg/L	5	02/08/2024 13:15	01/12/2024 6:04
24011321-006	A AHL-30	NELAP	1.0	< 1.0	μg/L	1	02/09/2024 14:34	01/12/2024 6:04
24011321-007	A AHL-31	NELAP	1.0	1.3	μg/L	1	02/03/2024 0:14	01/12/2024 6:04
24011321-008	A AHL-32	NELAP	1.0	< 1.0	μg/L	1	02/03/2024 0:18	01/12/2024 6:05
24011321-009	A AHL-33	NELAP	1.0	1.4	μg/L	1	02/03/2024 0:22	01/12/2024 6:06
24011321-010	A AHL-34	NELAP	1.0	< 1.0	μg/L	1	02/03/2024 0:25	01/12/2024 6:07
24011321-011	A AHL-35	NELAP	1.0	1.1	μg/L	1	02/03/2024 0:29	01/12/2024 6:08
24011321-012	A AHL-36	NELAP	1.0	1.4	μg/L	1	02/03/2024 0:33	01/12/2024 6:08
24011321-013	A AHL-37	NELAP	1.0	1.6	μg/L	1	02/03/2024 0:36	01/12/2024 6:09
24011321-014	A AHL-38	NELAP	1.0	1.2	μg/L	1	02/03/2024 0:40	01/12/2024 6:10
24011321-015	A AHL-39	NELAP	1.0	2.2	μg/L	1	02/03/2024 1:02	01/12/2024 6:10
24011321-016	A AHL-40	NELAP	1.0	< 1.0	μg/L	1	02/03/2024 1:06	01/12/2024 6:11
24011321-017	A AHL-41	NELAP	1.0	< 1.0	μg/L	1	02/03/2024 1:09	01/12/2024 6:11
24011321-018	A AHL-42	NELAP	1.0	1.6	μg/L	1	02/03/2024 1:13	01/12/2024 6:13
24011321-019	A AHL-43	NELAP	1.0	< 1.0	μg/L	1	02/03/2024 1:17	01/12/2024 6:15
24011321-020	A AHL-44	NELAP	1.0	< 1.0	μg/L	1	02/03/2024 1:20	01/12/2024 6:15
24011321-021	A AHL-45	NELAP	1.0	< 1.0	μg/L	1	02/03/2024 1:24	01/12/2024 6:15
24011321-022	A AHL-46	NELAP	1.0	< 1.0	μg/L	1	02/03/2024 1:28	01/12/2024 6:16
24011321-023	A AHL-47	NELAP	1.0	< 1.0	μg/L	1	02/03/2024 1:31	01/12/2024 6:16
24011321-024	A AHL-48	NELAP	1.0	1.2	μg/L	1	02/09/2024 14:38	01/12/2024 6:16
24011321-025	A AHL-49	NELAP	1.0	1.1	μg/L	5	02/08/2024 13:19	01/12/2024 6:17
24011321-026	A AHL-50	NELAP	1.0	1.0	μg/L	5	02/08/2024 13:11	01/12/2024 6:17
24011321-027	A AHL-51	NELAP	1.0	< 1.0	μg/L	1	02/09/2024 14:49	01/12/2024 6:18
24011321-028	A AHL-52	NELAP	1.0	< 1.0	μg/L	1	02/09/2024 14:53	01/12/2024 6:18
24011321-029	A AHL-53	NELAP	1.0	1.4	μg/L	1	02/09/2024 15:07	01/12/2024 6:19
24011321-030	A AHL-54	NELAP	1.0	1.5	μg/L	1	02/09/2024 15:11	01/12/2024 6:20
24011321-031	A AHL-55	NELAP	1.0	1.2	μg/L	1	02/09/2024 15:15	01/12/2024 6:21
24011321-032	A AHL-56	NELAP	1.0	< 1.0	μg/L	1	02/09/2024 15:18	01/12/2024 6:23
24011321-033	A AHL-57	NELAP	1.0	< 1.0	μg/L	1	02/09/2024 15:22	01/12/2024 6:23
24011321-034	A AHL-58	NELAP	1.0	< 1.0	μg/L	1	02/09/2024 15:26	01/12/2024 6:23
24011321-035	A FCS-08-2	NELAP	1.0	< 1.0	µg/L	1	02/09/2024 15:29	01/15/2024 16:03
24011321-036	A FCS-09-2	NELAP	1.0	< 1.0	µg/L	1	02/09/2024 4:37	01/15/2024 16:08
24011321-037	A SBE-01	NELAP	1.0	4.6	µg/L	1	02/09/2024 4:41	01/15/2024 22:24
24011321-038	A SBE-02	NELAP	1.0	7.8	µg/L	1	02/09/2024 4:44	01/15/2024 22:24
24011321-039	A SBE-03	NELAP	1.0	4.5	µg/L	1	02/09/2024 4:48	01/15/2024 22:24
24011321-040	A SBE-04	NELAP	1.0	< 1.0	µg/L	1	02/09/2024 4:52	01/15/2024 22:24
24011321-041	A SBE-05	NELAP	1.0	< 1.0	µg/L	1	02/03/2024 6:29	01/15/2024 22:27
24011321-042	A SBE-06	NELAP	1.0	< 1.0	μg/L	1	02/03/2024 6:33	01/15/2024 22:27
24011321-043	A SBE-07	NELAP	1.0	< 1.0	μg/L	1	02/03/2024 6:37	01/15/2024 22:29
24011321-044	A SBE-08	NELAP	1.0	< 1.0	μg/L	1	02/03/2024 6:41	01/15/2024 22:29
24011321-045	A SBE-09	NELAP	1.0	< 1.0	μg/L	1	02/03/2024 6:45	01/15/2024 22:29
24011321-046	A SBE-10	NELAP	1.0	< 1.0	μg/L	1	02/03/2024 6:49	01/15/2024 22:29
24011321-047	A SBE-11	NELAP	1.0	< 1.0	μg/L	1	02/03/2024 7:06	01/15/2024 22:29
24011321-048	A SBE-12	NELAP	1.0	< 1.0	µg/L	1	02/03/2024 7:35	01/15/2024 22:29



### **Laboratory Results**

#### http://www.teklabinc.com/

Report Date: 12-Feb-24

Work Order: 24011321 Client: Geotechnology, Inc. Client Project: J044517.01

Matrix: DRINKING WATER

RL DF Sample ID **Client Sample ID Certification Qual** Result Units **Date Analyzed Date Collected** EPA 600 4.1.4, 200.8 R5.4, METALS BY ICPMS (TOTAL) Lead < 1.0 < 1.0 24011321-051A < 1.0 < 1.0 24011321-053A 02/03/2024 7:27 01/15/2024 22:32 < 1.0 < 1.0 < 1.0 < 1.0 24011321-057A 02/03/2024 8:04 < 1.0 01/15/2024 22:37 < 1.0 24011321-059A < 1.0 01/15/2024 22:38 SBE-24 < 1.0



#### **Receiving Check List**

http://www.teklabinc.com/

Work Order: 24011321 Client: Geotechnology, Inc. Client Project: J044517.01 Report Date: 12-Feb-24 Carrier: Employee Received By: MEK Completed by: Reviewed by: Mary E. Kemp On: On: 19-Jan-24 19-Jan-24 Mary E Kemp Ellie Hopkins Extra pages included 0 Pages to follow: Chain of custody Shipping container/cooler in good condition? Yes **✓** No 🗔 Not Present Temp °C NA Type of thermal preservation? **V** Ice \_ Blue Ice None Dry Ice Chain of custody present? **~** No L Yes Chain of custody signed when relinquished and received? **~** Yes No L **~** Chain of custody agrees with sample labels? No 🗀 Yes **~** No 🗌 Samples in proper container/bottle? Yes **V** No 🗌 Sample containers intact? Yes Sufficient sample volume for indicated test? Yes **~** No **~** No  $\square$ All samples received within holding time? Yes NA 🗸 Field Lab Reported field parameters measured: Yes 🗸 No 🗌 Container/Temp Blank temperature in compliance? When thermal preservation is required, samples are compliant with a temperature between 0.1°C - 6.0°C, or when samples are received on ice the same day as collected. Water - at least one vial per sample has zero headspace? Yes 🗌 No 🗀 No VOA vials 🗸 No TOX containers Water - TOX containers have zero headspace? Yes No 🗌 Yes 🗹 No 🗌 Water - pH acceptable upon receipt? NA 🗹 NPDES/CWA TCN interferences checked/treated in the field? Yes No 🗀

Samples were checked for turbidity and then preserved with nitric acid upon arrival in the laboratory. - MaryKemp - 1/19/2024 11:23:21 AM

Any No responses must be detailed below or on the COC.

pg. 37 of 74 Work order # <u>24011321</u>

TEKLAB, INC. 5445 Horseshoe Lake Road - Collinsville, IL 62234 - Phone: (618) 344-1004 - Fax: (618) 344-1005

J																				(010) 011									
Client:		Geotechnology, LL	.c											Sar	npl	es e	on:		ICE	BLUE ICE	X w	OICE	1	VA	°(	C	LTG#	<b>#</b>	on follows
Address:		11816 Lackland Ro	oad											Pre	ser	vec	in t	; <b>X</b>	LAB	FIELD	•	<u>F</u>	OR I	_AB	USE	ONL	<u>.Y</u>		
City / State	/ Zip	St. Louis, MO 631	46												No			<i>/</i> `											4
Contact:	Brad Lo	ohrum			Phone	<b>:</b> :	(	314)	997	-744	10	•																	Streethe
E-Mail:	blohrun	m@teamues.com			Fax:								t	lie	nt (	CO.	nme	nte	::			\$' '		/			,		
Are these sample	known	to be involved in liti	astion?	2 If yee	a curcharae	Hita	ann	11/	[] ·	Voc	- 1⁄2	CNo	_	,,,	.,				••										
Are these sample:	known	to be hazardous?	Ye	s 🔀	No	94121	чрр	13		100	<i>–</i>	, <b>-</b> 0 10	1																
Are there any requ	ired rep	oorting limits to be m tion. 📗 Yes 🏽 🏋	et on ti	he requ	ested analys	is?.	If ye	es, p	ieas	e pr	ovide		ı																
		•	. No				_						┸							23.15%	0 A T	- 331	A 1 1/0	10.0	-011	COT			
		Number			ample Co					ie			L	<u> </u>	VΑ	KI.	X			IND	CAL	E AN	ALYS	15 KI	E QU	E 5   1	<u>=</u> 0		1
Joh			_	By	rad La	aΝ	<b>,</b> V L	<i>)</i>	<u> </u>					DI.			Sp	ਹੁ	DW									İ	
Result Standard	s Requ	uested	Billir	ng Ins	tructions	#	and	Ту	pe of	Co	ntain	ers	Ą			S	eciá	no.	- Lead										
r		(100% Surcharge)				١ş	Ξ	z	ᇙᅵ	_	Z Na	ers OTHER	řeo	<b>Drinking Water</b>	Soil	Sludge	W	Groundwater	ad E										
						景	ő	皇	H2SO4	卢	췭	黃	S	Vate		(D	aste	ater	E200.8										
Lab Use Only	Sam	ple Identification	Da	te/Time	e Sampled	Ľ		Ļ	Щ		*	_	L	۳	ļ		ų,		.8					<u> </u>					
34011321	AH	1-25	1/17	44	6:00	Ц				4				X	_				X								<b></b>		
bua	AH	L- Zb	ľ	1	6:01	Ц						╧		X	_				X					ļ					
003	1	27			+									X					X										
004		28			b:07									X					X										
005		29			6:04									X					X										
a		30	1 1		1	П		Γ		7	$\top$	T		V					X										
රා		31								$\top$		T		V					X										
008		32	11		6,05			Г	П	十		T		X					$\overrightarrow{\chi}$										
209			1 1		10:00				$\vdash$	十		T		X					$\hat{\mathbf{y}}$										
<b>V</b>		<u> 33</u> - 21L			6:01	Н	T		H	十	$\neg$	T	-	Ŕ			Н		Ŷ									$\top$	
DIO	Relin	iquished By	1 4		W 10 1	<u>. )</u>	Date	l ≥/Ti	me	_		١.,	_	1/ \	1			Re	ceive	ed By					Da	te/Ti	me		
tad lun	1/2	~~			1/18/1		_									12_	1	11	<b>7</b> .				//	18	124	/			
P/VI CANO	, E	1-0	11.		1/18/1	1	r.f	,		0,	D				M		1,72	t	111				1119			200			
		Ty	401		11.72				4				<b></b>		<i>;</i>	<u> </u>	<u>ائٽ</u> ا	ठे	ru			_	स्प	150 1		<u> </u>			
													<del> </del>									$\dashv$							

pg. 38 of 74 Work order # <u>2401321</u>

TEKLAB, INC. 5445 Horseshoe Lake Road - Collinsville, IL 62234 - Phone: (618) 344-1004 - Fax: (618) 344-1005

Client: Address:  City / State / Zip St. Louis, MO 63146  Contact: E-Mail:  Diohnum@teamues.com Fax:  Are these samples known to be hazardous? Are these samples known to be hazardous?  Are these samples known to be hazardous?  Project Name/Number  Sample Collector's Name  MATRIX  NOTICE Preserved in:  Lab Notes  Client Comments:  Client Comments:  Client Comments:  NATRIX  INDICATE ANALYSIS REQUESTED  ANALYSIS REQUESTED  Results Requested Standard  1-2 Day (100% Surcharge)  Other  3 Day (50% Surcharge)  Date/Time Sampled
Address: 11816 Lackland Road  City / State / Zip  St. Louis, MO 63146  Contact: Brad Lohrum Phone: (314) 997-7440  E-Mail: blohrum@teamues.com Fax: Client Comments:  Are these samples known to be involved in litigation? If yes, a surcharge will apply Yes No Are these samples known to be hazardous? Yes No Are there any required reporting limits to be met on the requested analysis?. If yes, please provide limits in the comment section. Yes No  Project Name/Number Sample Collector's Name MATRIX INDICATE ANALYSIS REQUESTED  Results Requested Standard 1-2 Day (100% Surcharge)  Billing Instructions # and Type of Containers of Standard 1-2 Day (100% Surcharge)  Billing Instructions # and Type of Containers of Standard 1-2 Day (100% Surcharge)
City / State / Zip St. Louis, MO 63146  Contact: Brad Lohrum Phone: (314) 997-7440  E-Mail: blohrum@teamues.com Fax: Client Comments:  Are these samples known to be involved in liftigation? If yes, a surcharge will apply Yes No Are these samples known to be hazardous? Yes No Are there any required reporting limits to be met on the requested analysis? If yes, please provide limits in the comment section. Yes No  Project Name/Number Sample Collector's Name MATRIX INDICATE ANALYSIS REQUESTED  Results Requested Billing Instructions # and Type of Containers Standard 1-2 Day (100% Surcharge) Billing Instructions # and Type of Containers Standard 1-2 Day (100% Surcharge) Billing Instructions # and Type of Containers Standard 1-2 Day (100% Surcharge)
Contact: E-Mail:    Brad Lohrum
E-Mail: blohrum@teamues.com
Are these samples known to be involved in litigation? If yes, a surcharge will apply Yes No Are these samples known to be hazardous? Yes No Are there any required reporting limits to be met on the requested analysis?. If yes, please provide limits in the comment section. Yes No  Project Name/Number Sample Collector's Name MATRIX INDICATE ANALYSIS REQUESTED  Results Requested Billing Instructions # and Type of Containers A Results Requested In 1-2 Day (100% Surcharge)  Billing Instructions # and Type of Containers A Results Requested In 1-2 Day (100% Surcharge)
Are these samples known to be hazardous?
Are there any required reporting limits to be met on the requested analysis? If yes, please provide limits in the comment section. Yes No  Project Name/Number Sample Collector's Name MATRIX INDICATE ANALYSIS REQUESTED  Results Requested Billing Instructions # and Type of Containers of Standard 1-2 Day (100% Surcharge)  Billing Instructions # and Type of Containers of Standard 1-2 Day (100% Surcharge)
Project Name/Number Sample Collector's Name MATRIX INDICATE ANALYSIS REQUESTED  WHY517,01 Broad Lower Drinking Standard 1-2 Day (100% Surcharge)  # and Type of Containers A prinking Signal of the standard 1-2 Day (100% Surcharge)  # and Type of Containers A prinking Signal of the standard 1-2 Day (100% Surcharge)
Results Requested Standard 1-2 Day (100% Surcharge)  Billing Instructions  # and Type of Containers  # and Type of Contain
Results Requested   Standard   1-2 Day (100% Surcharge)   Billing Instructions   # and Type of Containers   # and Type of Contain
Results Requested Standard 1-2 Day (100% Surcharge)  Billing Instructions # and Type of Containers   Sundard   Sunda
Standard   1-2 Day (100% Surcharge)   UNA   HOUSE   Soi:
□ Other □ □ 3 Day (50% Surcharge) □ 전 경 등 문 등 문 등 표 등 표 등 등 등 등 등 등 등 등 등 등 등 등
Cother 3 Day (50% Surcharge)  Lab Use Only Sample Identification
34011321 TO AHL - 35 1/12/24 6:08 1 X X
1012 012 AHL 36 + 1 X X
1014 01 5 18 6:18 X
05 014 39 +
016 017) 40 6711
017 018 41 +
018 019 49 6:13 11 1   X   X
019 020 4-3 6:15 XXX
* 020 - 44 - + 11 1 1 X 1 X 1 X 1 X 1 X 1 X 1 X X X X
Relinguished By Date/Time Received By Date/Time
Predleton 1/18/24 P.N. 1/18/24
1-1 1/9/24 10:00 Man 9/11/2 11/9/24 1000
V I

pg. 39 of 74 Work order # <u>24011321</u>

TEKLAB, INC, 5445 Horseshoe Lake Road - Collinsville, IL 62234 - Phone: (618) 344-1004 - Fax: (618) 344-1005

-												,													,		,					
Client:		Geotechnology, Ll	LC										San	npl	es (	on:	<b>38</b>	ICE	189	BLU	E ICE	驟	NO I	Œ	_		0	C	LTO	G#		-
Address:		11816 Lackland R	toad			**********	************	***************************************	***************************************	***************************************	*****		Pre	ser	vec	l in	: 🚳	LAB	魔	FIEL	.D			F	OR I	AB	USE	ON	<u>LY</u>			
City / Sta	te / Zip	St. Louis, MO 631	146										Lab	No	otes	5																, in the second
Contact:		Lohrum		_ Phone	<b>}</b> :	(;	314)	997-	7440	)																						All Cheeses In
E-Mail:	blohn	um@teamues.com		Fax:									lier	nt (	`on	m	nt	ς.											:			, in the second
Are these same	nles know	m to be involved in lit	ination? If ves	a surchama	llise	anni	ν	П	Yes	X	No	_#	,,,,,,		,	1111	-110	<b>.</b>														
		m to be involved in it. m to be hazardous?			**!	appi	,		. 03		. 140	l																				
Are there any r	equired re	eporting limits to be nection.	net on the requ	uested analysi	is?.	If ye	s, p	lease	e prov	/ide		l																				
					•			-				┸									23.15				/^							***
_		e/Number		ample Col					e			┡	1	/IA1	KI.	X	_		r	т т	INL	JICA	IE/	MA	LYS	IS K	EQU	JEST	T	1	_	
	451	***************************************	BV.	ed Lov									Dri			Sp	ଦ୍ର	DW														
Resu	Its Rec	quested ay (100% Surcharge)	Billing Ins	structions	#	and	Ту	e of	Con	7	ers	Aqueous	Drinking Water	ر در	Slu	Special Waste	Groundwater	- Lead														
Other		Day (50% Surcharge)			Ę	Ę	N.	ᅰ	≖ĺ≅	Na.	잌	leot	۷ وا	Soil	Sludge	W	idw	ad E												Marran		
			1		麗	03	오	H2SO4	ᄗ	NaMSO4	듀	S	Vate		Ü	aste	ater	E200.									ŀ					
Lab Use Onl	y Sai	mple Identification	Date/Tim	e Sampled	Ľ				4	<u> </u>			۳			٠,		8								ļ		╄		<u> </u>	<b>Ļ</b>	
24011321 -03	AH	L-45	1/12/24	b:15	Ц				┸				X					X									ļ	$ldsymbol{oxedsymbol{oxedsymbol{oxedsymbol{eta}}}$		<u> </u>	<u> </u>	<u> </u>
023	a Af	11-46	1	6716	Ш								X					X														
Oa'	3 1	47		1									X					X											WIANDIA UAL			
02	1	48		4	Π				T	T			X					X														
ರಿತಿ	_	49		6:17		T			7				V					χ														1
) 0a		7		1	$\parallel$								$\overrightarrow{V}$					Ŷ										<b>†</b>		1		T
1		51		6:15	$\dag$			$\dashv$	_	<del> </del>			7					$\overrightarrow{\gamma}$								<b> </b>	<b> </b>	<b>†</b>	$\vdash$	T	T	T
03		57		<u> </u>	$\dashv$			-										$\overrightarrow{V}$							$\vdash$		<del> </del>		+	$\vdash$	$\vdash$	+
<u>D</u> 2			<del>                                     </del>	619	$\vdash$			-	+	+-			$\nearrow$					$\rightarrow$								<del> </del>	<del> </del>	$\vdash$	-	$\vdash$	$\vdash$	+
02		53			H	H			╬	-		-	$\Diamond$		_	Н		$\frac{1}{\lambda}$									_	+-	<del> </del>	$\vdash$	$\vdash$	+
¥ 03		154 inquished By		6:20	Ų	Date	/T:						<b>\</b>				D۵	ćelv	ad B	)				T -				ate/T	ime		<u> </u>	
Bron		inquisited by		1/18/2		Jale	7   11	(IE					6	2	$\overline{}$	.10	Ne		su b	у				╅	,	119	<u> </u>	74	<u> </u>			
DIADU	W /9	0 -1		1/10/2	T  100	/1		<i></i>	a				r	7		W		<u> </u>						+		/	<u>-/</u> -	<u>7</u> 7		<del></del>	<del></del>	
***			1421	1/19	12	<u>-Y</u>		.V!	n		-		1	110	21	4	7	un	P					+	» }	ala	<u> </u>	<u>li</u>	)() ≈			
											_													+	······································							
				ł																												

pg. 40 of 74 Work order # <u>2401321</u>

TEKLAB, INC. 5445 Horseshoe Lake Road - Collinsville, IL 62234 - Phone: (618) 344-1004 - Fax: (618) 344-1005

Client:		Geotechnology, L	LC			<del></del>									Sa	am	pies	5 01	n:	<b>200</b>	ICE	В	LUE K	Œ	■ NC	ICE				°С	LTG	# 	
Address:		11816 Lackland F	Road											_								F						LAE	3 US	E ON	LY		
City / State	/ Zip	St. Louis, MO 63	146												La	b l	Not	es															
Contact:	Brad L	ohrum				Phon	e:	(	314)	997	-74	40		_																			
E-Mail:	blohrur	n@teamues.com				Fax:		_						-	Cli	ent	: Co	mr	ne	nts	:						***************************************	*		,	: ,		
Are these sample:	known	to be involved in li	tigatio	n? If ye	s, a s	urcharge	will	арр	ly		Yes	s <u>5</u>	≤n																				
•		to be hazardous?	_	_																													
Are there any requi	ifred rep ent sec	orting limits to be r tion. Yes	net on ⊷No	the red	queste	ed analys	sis?.	If y	es, p	leas	e pr	ovide	•																				
		Number			Sam	ple Co	lled	cto	's l	Van	ne			┰	••••	N.	ATF	ΧIΣ		1			Į.	VDIC	ATE	AN	ALY:	SIS	REQ	UEST	ED		
Joy						lak								r	-	3			٦		DW									T			
Result			Dill	ing in	ctru	ctions	T #	and	i Ty	pe of	f Co	ontair	iers	┫᠈	۶ ا	5	را	200	ξ΄	င္ခ													
Standard	1-2 Day	(100% Surcharge)	Diii	ing in	i5ti u	CHOHS				<b>-</b>		_ z	<u> </u>	-		2			<u> </u>	nd	Lead												
Other	☐ 3 Da	y (50% Surcharge)					UNPRES	Ş	la O	H2SO4	핅	MeOH	S I S I S I S I S I S I S I S I S I S I	Š	Aguacia Aguacia	٠ آ	_ ge	Shecial Avaste	2	Groundwater	m l												
Lab Use Only	Sam	ple Identification	E	Date/Tii	ne Sa	mpled	S	ω		4		T Z	1	'	<u> </u>			તિ	•	4	200.8												
24011321 -031	AH	L-55	1/	2/21	1 6	2:21	$\int$								ľ	X					X												
632	AH	L 56	'	1		6:23									2	V					X												
033	i	57				1	П								۱	$\overline{A}$			T		X												
034	1	- 58	1.	4		1	П	Π	Γ				T	Т	K				T	7	X												
035	Fre	-08-2	1/	5/2	- 1	6:03									X		- I				X												
036	CCC	- 19-2			i	6:08		T					1	T	X	1					X												
037	<b< td=""><td>E- 01</td><td>17</td><td><!--21</td--><td></td><td>22:24</td><td><math>\Box</math></td><td></td><td></td><td></td><td></td><td></td><td></td><td>T</td><th>k</th><td>Ť</td><td></td><td></td><td></td><td></td><td>X</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td></b<>	E- 01	17	21</td <td></td> <td>22:24</td> <td><math>\Box</math></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>T</td> <th>k</th> <td>Ť</td> <td></td> <td></td> <td></td> <td></td> <td>X</td> <td></td>		22:24	$\Box$							T	k	Ť					X												
039	513	E- 02	1	1	, ,	1	П						T	T	1	Ť					文												
039	1	03					$\Box$							t	7	T					X												
1 040	1	04			-		Н						$\dagger$	t	7	<del>}</del>			1		X												
v 010	Relin	quished By				,	1 1	Date	: e/Ti	me	- 1			Ĺ				1		Red	eive	d By						1	Ĺ	ate/I	ime		
Basley	an	~~			I	118/2	4										L	- /	2 4	Q,	7						//	12	129	[			
1		Rad			1	12/	2	4	/	10:	10	D)					 V10	<del>о -</del> Хаа	λ	5	Tu.	γ2					ilic	lau	1 1	000	>		
		1 10	-		1	•											·····		ð			ş											
														T																			



#### **APPENDIX D**

**LIMITATIONS OF REPORT** 

# ENVIRONMENTAL SAMPLING LIMITATIONS OF REPORT

- The Report has been prepared on behalf of and for the exclusive use of the addressee, solely for use in documenting specific sample results. This report and the findings contained herein shall not, in whole or in part, be disseminated or conveyed to any other party, nor used by any other party in whole or in part, without the prior written consent of UES.
- 2. The sampling was performed in accordance with generally accepted practices of other consultants undertaking similar projects at the same time and in the same geographical area, and UES endeavored to observe that degree of care and skill ordinarily exercised by other consultants under similar circumstances and conditions. The findings and conclusions stated herein must be considered not as scientific certainties, but rather as professional opinions concerning the significance of the limited data gathered during the course of the project. UES does not and cannot represent that the site contains no hazardous waste or material, or other latent condition beyond that observed by UES.
- 3. In the event that information is developed relative to environmental or hazardous waste or material issues at the site and not contained in this report, such information shall be brought to UES' attention. UES will evaluate such information and, based on this evaluation, may modify the conclusions stated in this Report.
- 4. The conclusions and recommendations contained in this Report are based in part upon the data obtained from a limited number of water samples. The identified presence of contaminated water is limited to the extent that they could be identified by instrumentation and sampling and testing. There is a potential for contaminated water above the indicated concentrations to occur elsewhere on the site. The nature and extent of variations between these explorations may not become evident until further exploration. If variations or other latent conditions then appear evident, and/or if changes are made in regulations, it will be necessary to reevaluate the conclusions and recommendations of this report.
- 5. If quantitative laboratory testing was performed as part of the assessment by an outside laboratory, UES has relied upon the data provided, and has not conducted an independent evaluation of the reliability to these data.
- 6. Chemical analyses have been performed for specific parameters during the course of this sampling as described in the text. Do not assume that a given analyte is not present at the site simply because it was not present at the test locations. The analyte may exist on the site where tests were not performed. In addition, it should be noted that additional chemical constituents not tested for during the sampling could be present in water at the site.