

ANALYTICAL REPORT

PREPARED FOR

Attn: Ian St. John
St. John Environmental Consulting
5515 Grace Ave.
Saint Louis, Missouri 63116

Generated 7/1/2024 8:14:00 AM

JOB DESCRIPTION

St. Joseph School District - Oak Grove Elem

JOB NUMBER

810-109394-1

Eurofins Eaton Analytical South Bend

Job Notes

This report may not be reproduced except in full, and with written approval from the laboratory. The results relate only to the samples tested. For questions please contact the Project Manager at the e-mail address or telephone number listed on this page.

The test results in this report relate only to the samples as received by the laboratory and will meet all requirements of the methodology, with any exceptions noted. This report shall not be reproduced except in full, without the express written approval of the laboratory. All questions should be directed to the Eurofins Eaton Analytical, LLC Project Manager.

Authorization



Generated
7/1/2024 8:14:00 AM

Authorized for release by
Pamela Brown, Project Manager
Pamela.Brown@et.eurofinsus.com
(574)233-4777

Table of Contents

Cover Page 1

Table of Contents 3

Definitions/Glossary 4

Case Narrative 5

Detection Summary 7

Client Sample Results 11

QC Sample Results 18

QC Association Summary 21

Lab Chronicle 23

Certification Summary 30

Method Summary 31

Sample Summary 32

Chain of Custody 33

Receipt Checklists 39



Definitions/Glossary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Qualifiers

Metals

Qualifier	Qualifier Description
J	Result is less than the RL but greater than or equal to the MDL and the concentration is an approximate value.

Glossary

Abbreviation	These commonly used abbreviations may or may not be present in this report.
α	Listed under the "D" column to designate that the result is reported on a dry weight basis
%R	Percent Recovery
CFL	Contains Free Liquid
CFU	Colony Forming Unit
CNF	Contains No Free Liquid
DER	Duplicate Error Ratio (normalized absolute difference)
Dil Fac	Dilution Factor
DL	Detection Limit (DoD/DOE)
DL, RA, RE, IN	Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample
DLC	Decision Level Concentration (Radiochemistry)
EDL	Estimated Detection Limit (Dioxin)
LOD	Limit of Detection (DoD/DOE)
LOQ	Limit of Quantitation (DoD/DOE)
MCL	EPA recommended "Maximum Contaminant Level"
MDA	Minimum Detectable Activity (Radiochemistry)
MDC	Minimum Detectable Concentration (Radiochemistry)
MDL	Method Detection Limit
ML	Minimum Level (Dioxin)
MPN	Most Probable Number
MQL	Method Quantitation Limit
NC	Not Calculated
ND	Not Detected at the reporting limit (or MDL or EDL if shown)
NEG	Negative / Absent
POS	Positive / Present
PQL	Practical Quantitation Limit
PRES	Presumptive
QC	Quality Control
RER	Relative Error Ratio (Radiochemistry)
RL	Reporting Limit or Requested Limit (Radiochemistry)
RPD	Relative Percent Difference, a measure of the relative difference between two points
TEF	Toxicity Equivalent Factor (Dioxin)
TEQ	Toxicity Equivalent Quotient (Dioxin)
TNTC	Too Numerous To Count

Case Narrative

Client: St. John Environmental Consulting
Project: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Job ID: 810-109394-1

Eurofins Eaton Analytical South Bend

Job Narrative 810-109394-1

Analytical test results meet all requirements of the associated regulatory program listed on the Accreditation/Certification Summary Page unless otherwise noted under the individual analysis. Data qualifiers are applied to indicate exceptions. Noncompliant quality control (QC) is further explained in narrative comments.

- Matrix QC may not be reported if insufficient sample or site-specific QC samples were not submitted. In these situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD may be performed, unless otherwise specified in the method.
- Surrogate and/or isotope dilution analyte recoveries (if applicable) which are outside of the QC window are confirmed unless attributed to a dilution or otherwise noted in the narrative.

Regulated compliance samples (e.g. SDWA, NPDES) must comply with the associated agency requirements/permits.

Receipt

The samples were received on 6/25/2024 9:00 AM. Unless otherwise noted below, the samples arrived in good condition, and, where required, properly preserved and on ice.

Receipt Exceptions

Samples received with lid removed from the bottle resulting in the loss of all volume:

SJOG-3 Sink
SJOG-4 Sink
SJOG-12 Sink
SJOG-22 Sink
SJOG-24 Bubbler
SJOG-25 Sink
SJOG-27 Sink
SJOG-34 Sink
SJOG-35 Sink
SJOG-40 Sink

The following sample(s) was listed on the Chain of Custody (COC); however, no sample(s) was received:

SJOG-7 Sink
SJOG-9 Sink
SJOG-10 WF
SJOG-11 WF
SJOG-13 Sink
SJOG-14 Sink
SJOG-15 WF
SJOG-16 WF
SJOG-20 WF
SJOG-36 Sink
SJOG-39 Sink
SJOG-41 Sink
SJOG-42 Bubbler
SJOG-43 Sink
SJOG-44 Bubbler
SJOG-45 Sink
SJOG-46 Bubbler
SJOG-47 Sink
SJOG-48 Bubbler
SJOG-49 WF
SJOG-50 WF
SJOG-51 Sink
SJOG-52 Sink
SJOG-53 Sink
SJOG-54 Sink
SJOG-55 WF

Eurofins Eaton Analytical South Bend

Case Narrative

Client: St. John Environmental Consulting
Project: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Job ID: 810-109394-1 (Continued)

Eurofins Eaton Analytical South Bend

SJOG-56 WF
SJOG-57 Sink
SJOG-58 Sink
SJOG-59 Sink

Metals

No additional analytical or quality issues were noted, other than those described above or in the Definitions/ Glossary page.

Eurofins Eaton Analytical South Bend

Detection Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 1 Sink

Lab Sample ID: 810-109394-1

No Detections.

Client Sample ID: SJOG - 2 Sink

Lab Sample ID: 810-109394-2

No Detections.

Client Sample ID: SJOG - 5 Sink

Lab Sample ID: 810-109394-3

No Detections.

Client Sample ID: SJOG - 6 Sink

Lab Sample ID: 810-109394-4

No Detections.

Client Sample ID: SJOG - 8 ICE

Lab Sample ID: 810-109394-5

No Detections.

Client Sample ID: SJOG - 17 Sink

Lab Sample ID: 810-109394-6

No Detections.

Client Sample ID: SJOG - 18 Sink

Lab Sample ID: 810-109394-7

No Detections.

Client Sample ID: SJOG - 19 Sink

Lab Sample ID: 810-109394-8

No Detections.

Client Sample ID: SJOG - 21 WF

Lab Sample ID: 810-109394-9

No Detections.

Client Sample ID: SJOG - 23 Bubbler

Lab Sample ID: 810-109394-10

No Detections.

Client Sample ID: SJOG - 26 Bubbler

Lab Sample ID: 810-109394-11

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	0.57		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJOG - 28 Sink

Lab Sample ID: 810-109394-12

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	1.6		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJOG - 29 Sink

Lab Sample ID: 810-109394-13

No Detections.

Client Sample ID: SJOG - 30 Sink

Lab Sample ID: 810-109394-14

No Detections.

Client Sample ID: SJOG - 31 Sink

Lab Sample ID: 810-109394-15

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	0.75		0.50		ug/L	1		200.8	Total/NA

This Detection Summary does not include radiochemical test results.

Eurofins Eaton Analytical South Bend

Detection Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 32 Sink

Lab Sample ID: 810-109394-16

No Detections.

Client Sample ID: SJOG - 33 Sink

Lab Sample ID: 810-109394-17

No Detections.

Client Sample ID: SJOG - 37 Sink

Lab Sample ID: 810-109394-18

No Detections.

Client Sample ID: SJOG - 38 Sink

Lab Sample ID: 810-109394-19

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	68		5.0		ug/L	10		200.8	Total Recoverable

Client Sample ID: SJOG - 7 Sink

Lab Sample ID: 810-109394-20

No Detections.

Client Sample ID: SJOG - 10 WF

Lab Sample ID: 810-109394-21

No Detections.

Client Sample ID: SJOG - 11 WF

Lab Sample ID: 810-109394-22

No Detections.

Client Sample ID: SJOG - 13 SINK

Lab Sample ID: 810-109394-23

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	1.7		0.50		ug/L	1		200.8	Total Recoverable

Client Sample ID: SJOG - 14 SINK

Lab Sample ID: 810-109394-24

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	0.86		0.50		ug/L	1		200.8	Total Recoverable

Client Sample ID: SJOG - 15 WF

Lab Sample ID: 810-109394-25

No Detections.

Client Sample ID: SJOG - 16 WF

Lab Sample ID: 810-109394-26

No Detections.

Client Sample ID: SJOG - 20 WF

Lab Sample ID: 810-109394-27

No Detections.

Client Sample ID: SJOG - 36 Sink

Lab Sample ID: 810-109394-28

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	1.1		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJOG - 41 Sink

Lab Sample ID: 810-109394-29

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	1.2		0.50		ug/L	1		200.8	Total/NA

This Detection Summary does not include radiochemical test results.

Eurofins Eaton Analytical South Bend

Detection Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 42 Bubbler

Lab Sample ID: 810-109394-30

No Detections.

Client Sample ID: SJOG - 43 Sink

Lab Sample ID: 810-109394-31

No Detections.

Client Sample ID: SJOG - 44 Bubbler

Lab Sample ID: 810-109394-32

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	0.61		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJOG - 45 Sink

Lab Sample ID: 810-109394-33

No Detections.

Client Sample ID: SJOG - 46 Bubbler

Lab Sample ID: 810-109394-34

No Detections.

Client Sample ID: SJOG - 47 Sink

Lab Sample ID: 810-109394-35

No Detections.

Client Sample ID: SJOG - 49 WF

Lab Sample ID: 810-109394-36

No Detections.

Client Sample ID: SJOG - 51 Sink

Lab Sample ID: 810-109394-37

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	0.90		0.50		ug/L	1		200.8	Total Recoverable

Client Sample ID: SJOG - 52 Sink

Lab Sample ID: 810-109394-38

No Detections.

Client Sample ID: SJOG - 53 Sink

Lab Sample ID: 810-109394-39

No Detections.

Client Sample ID: SJOG - 54 Sink

Lab Sample ID: 810-109394-40

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	1.4		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJOG - 55 WF

Lab Sample ID: 810-109394-41

No Detections.

Client Sample ID: SJOG - 56 WF

Lab Sample ID: 810-109394-42

No Detections.

Client Sample ID: SJOG - 57 Sink

Lab Sample ID: 810-109394-43

No Detections.

Client Sample ID: SJOG - 58 Sink

Lab Sample ID: 810-109394-44

No Detections.

This Detection Summary does not include radiochemical test results.

Eurofins Eaton Analytical South Bend

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14

Job ID: 810-109394-1

Lab Sample ID: 810-109394-45

No Detections.

5

8

9

Eurofins Eaton Analytical South Bend

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 1 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-1

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 11:20	1

Client Sample ID: SJOG - 2 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-2

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 11:23	1

Client Sample ID: SJOG - 5 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-3

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 11:25	1

Client Sample ID: SJOG - 6 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-4

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 11:28	1

Client Sample ID: SJOG - 8 ICE

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-5

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 11:31	1

Client Sample ID: SJOG - 17 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-6

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 11:45	1

Client Sample ID: SJOG - 18 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-7

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 11:48	1

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 19 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-8

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 11:51	1

Client Sample ID: SJOG - 21 WF

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-9

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 11:54	1

Client Sample ID: SJOG - 23 Bubbler

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-10

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 11:56	1

Client Sample ID: SJOG - 26 Bubbler

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-11

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	0.57		0.50		ug/L			06/29/24 12:05	1

Client Sample ID: SJOG - 28 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-12

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.6		0.50		ug/L			06/29/24 12:08	1

Client Sample ID: SJOG - 29 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-13

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 12:11	1

Client Sample ID: SJOG - 30 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-14

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 12:14	1

Eurofins Eaton Analytical South Bend

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 31 Sink

Lab Sample ID: 810-109394-15

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	0.75		0.50		ug/L			06/29/24 12:16	1

Client Sample ID: SJOG - 32 Sink

Lab Sample ID: 810-109394-16

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 12:25	1

Client Sample ID: SJOG - 33 Sink

Lab Sample ID: 810-109394-17

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 12:28	1

Client Sample ID: SJOG - 37 Sink

Lab Sample ID: 810-109394-18

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 12:30	1

Client Sample ID: SJOG - 38 Sink

Lab Sample ID: 810-109394-19

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Method: EPA 200.8 - Metals (ICP/MS) - Total Recoverable

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	68		5.0		ug/L		06/27/24 13:10	06/28/24 13:22	10

Client Sample ID: SJOG - 7 Sink

Lab Sample ID: 810-109394-20

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 12:33	1

Client Sample ID: SJOG - 10 WF

Lab Sample ID: 810-109394-21

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 12:36	1

Eurofins Eaton Analytical South Bend

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 11 WF

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-22

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 12:39	1

Client Sample ID: SJOG - 13 SINK

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-23

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS) - Total Recoverable

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.7		0.50		ug/L		06/27/24 13:10	06/28/24 13:08	1

Client Sample ID: SJOG - 14 SINK

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-24

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS) - Total Recoverable

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	0.86		0.50		ug/L		06/27/24 13:10	06/28/24 13:10	1

Client Sample ID: SJOG - 15 WF

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-25

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 12:48	1

Client Sample ID: SJOG - 16 WF

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-26

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 12:50	1

Client Sample ID: SJOG - 20 WF

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-27

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 12:53	1

Client Sample ID: SJOG - 36 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-28

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.1		0.50		ug/L			06/29/24 12:56	1

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 41 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-29

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.2		0.50		ug/L			06/29/24 13:10	1

Client Sample ID: SJOG - 42 Bubbler

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-30

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 13:13	1

Client Sample ID: SJOG - 43 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-31

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 13:16	1

Client Sample ID: SJOG - 44 Bubbler

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-32

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	0.61		0.50		ug/L			06/29/24 13:19	1

Client Sample ID: SJOG - 45 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-33

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 13:22	1

Client Sample ID: SJOG - 46 Bubbler

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-34

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS) - Total Recoverable

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L		06/27/24 13:10	06/28/24 13:12	1

Client Sample ID: SJOG - 47 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-35

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 13:24	1

Eurofins Eaton Analytical South Bend

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 49 WF

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-36

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 13:27	1

Client Sample ID: SJOG - 51 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-37

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS) - Total Recoverable

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	0.90		0.50		ug/L		06/27/24 13:10	06/28/24 13:14	1

Client Sample ID: SJOG - 52 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-38

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS) - Total Recoverable

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L		06/27/24 13:10	06/28/24 13:16	1

Client Sample ID: SJOG - 53 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-39

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 13:36	1

Client Sample ID: SJOG - 54 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-40

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.4		0.50		ug/L			06/29/24 13:39	1

Client Sample ID: SJOG - 55 WF

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-41

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 13:41	1

Client Sample ID: SJOG - 56 WF

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-42

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 13:50	1

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 57 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-43

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 13:53	1

Client Sample ID: SJOG - 58 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-44

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 13:55	1

Client Sample ID: SJOG - 59 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:00

Lab Sample ID: 810-109394-45

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 13:58	1

QC Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Method: 200.8 - Metals (ICP/MS)

Lab Sample ID: MB 810-104372/105
Matrix: Drinking Water
Analysis Batch: 104372

Client Sample ID: Method Blank
Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 13:04	1

Lab Sample ID: MB 810-104372/12
Matrix: Drinking Water
Analysis Batch: 104372

Client Sample ID: Method Blank
Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 08:43	1

Lab Sample ID: MB 810-104372/45
Matrix: Drinking Water
Analysis Batch: 104372

Client Sample ID: Method Blank
Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 10:14	1

Lab Sample ID: MB 810-104372/75
Matrix: Drinking Water
Analysis Batch: 104372

Client Sample ID: Method Blank
Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 11:39	1

Lab Sample ID: LCS 810-104372/106
Matrix: Drinking Water
Analysis Batch: 104372

Client Sample ID: Lab Control Sample
Prep Type: Total/NA

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	50.0	48.7		ug/L		97	85 - 115

Lab Sample ID: LCS 810-104372/46
Matrix: Drinking Water
Analysis Batch: 104372

Client Sample ID: Lab Control Sample
Prep Type: Total/NA

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	50.0	49.5		ug/L		99	85 - 115

Lab Sample ID: LCS 810-104372/76
Matrix: Drinking Water
Analysis Batch: 104372

Client Sample ID: Lab Control Sample
Prep Type: Total/NA

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	50.0	47.8		ug/L		96	85 - 115

Lab Sample ID: LLCS 810-104372/11
Matrix: Drinking Water
Analysis Batch: 104372

Client Sample ID: Lab Control Sample
Prep Type: Total/NA

Analyte	Spike Added	LLCS Result	LLCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	0.300	0.299	J	ug/L		100	50 - 150

Eurofins Eaton Analytical South Bend

QC Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Method: 200.8 - Metals (ICP/MS)

Lab Sample ID: 810-109394-10 MS

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: SJOG - 23 Bubbler

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MS Result	MS Qualifier	Unit	D	%Rec	%Rec Limits		
Lead	<0.50		50.0	53.1		ug/L		106	70 - 130		

Lab Sample ID: 810-109394-10 MSD

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: SJOG - 23 Bubbler

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MSD Result	MSD Qualifier	Unit	D	%Rec	%Rec Limits	RPD	RPD Limit
Lead	<0.50		50.0	53.1		ug/L		106	70 - 130	0	20

Lab Sample ID: 810-109394-22 MS

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: SJOG - 11 WF

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MS Result	MS Qualifier	Unit	D	%Rec	%Rec Limits		
Lead	<0.50		50.0	46.7		ug/L		93	70 - 130		

Lab Sample ID: 810-109394-22 MSD

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: SJOG - 11 WF

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MSD Result	MSD Qualifier	Unit	D	%Rec	%Rec Limits	RPD	RPD Limit
Lead	<0.50		50.0	47.2		ug/L		94	70 - 130	1	20

Lab Sample ID: 810-109394-36 MS

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: SJOG - 49 WF

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MS Result	MS Qualifier	Unit	D	%Rec	%Rec Limits		
Lead	<0.50		50.0	49.5		ug/L		99	70 - 130		

Lab Sample ID: 810-109394-36 MSD

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: SJOG - 49 WF

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MSD Result	MSD Qualifier	Unit	D	%Rec	%Rec Limits	RPD	RPD Limit
Lead	<0.50		50.0	48.9		ug/L		98	70 - 130	1	20

Lab Sample ID: MB 810-104188/1-A

Matrix: Drinking Water

Analysis Batch: 104341

Client Sample ID: Method Blank

Prep Type: Total Recoverable

Prep Batch: 104188

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L		06/27/24 13:10	06/28/24 12:55	1

Lab Sample ID: LCS 810-104188/3-A

Matrix: Drinking Water

Analysis Batch: 104341

Client Sample ID: Lab Control Sample

Prep Type: Total Recoverable

Prep Batch: 104188

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits		
Lead	50.0	51.0		ug/L		102	85 - 115		

Eurofins Eaton Analytical South Bend

QC Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Method: 200.8 - Metals (ICP/MS)

Lab Sample ID: LLCS 810-104188/2-A				Client Sample ID: Lab Control Sample			
Matrix: Drinking Water				Prep Type: Total Recoverable			
Analysis Batch: 104341				Prep Batch: 104188			
Analyte	Spike Added	LLCS Result	LLCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	0.300	0.298	J	ug/L		99	50 - 150

QC Association Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Metals

Prep Batch: 104188

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-109394-19	SJOG - 38 Sink	Total Recoverable	Drinking Water	200.8	
810-109394-23	SJOG - 13 SINK	Total Recoverable	Drinking Water	200.8	
810-109394-24	SJOG - 14 SINK	Total Recoverable	Drinking Water	200.8	
810-109394-34	SJOG - 46 Bubbler	Total Recoverable	Drinking Water	200.8	
810-109394-37	SJOG - 51 Sink	Total Recoverable	Drinking Water	200.8	
810-109394-38	SJOG - 52 Sink	Total Recoverable	Drinking Water	200.8	
MB 810-104188/1-A	Method Blank	Total Recoverable	Drinking Water	200.8	
LCS 810-104188/3-A	Lab Control Sample	Total Recoverable	Drinking Water	200.8	
LLCS 810-104188/2-A	Lab Control Sample	Total Recoverable	Drinking Water	200.8	

Analysis Batch: 104341

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-109394-19	SJOG - 38 Sink	Total Recoverable	Drinking Water	200.8	104188
810-109394-23	SJOG - 13 SINK	Total Recoverable	Drinking Water	200.8	104188
810-109394-24	SJOG - 14 SINK	Total Recoverable	Drinking Water	200.8	104188
810-109394-34	SJOG - 46 Bubbler	Total Recoverable	Drinking Water	200.8	104188
810-109394-37	SJOG - 51 Sink	Total Recoverable	Drinking Water	200.8	104188
810-109394-38	SJOG - 52 Sink	Total Recoverable	Drinking Water	200.8	104188
MB 810-104188/1-A	Method Blank	Total Recoverable	Drinking Water	200.8	104188
LCS 810-104188/3-A	Lab Control Sample	Total Recoverable	Drinking Water	200.8	104188
LLCS 810-104188/2-A	Lab Control Sample	Total Recoverable	Drinking Water	200.8	104188

Analysis Batch: 104372

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-109394-1	SJOG - 1 Sink	Total/NA	Drinking Water	200.8	
810-109394-2	SJOG - 2 Sink	Total/NA	Drinking Water	200.8	
810-109394-3	SJOG - 5 Sink	Total/NA	Drinking Water	200.8	
810-109394-4	SJOG - 6 Sink	Total/NA	Drinking Water	200.8	
810-109394-5	SJOG - 8 ICE	Total/NA	Drinking Water	200.8	
810-109394-6	SJOG - 17 Sink	Total/NA	Drinking Water	200.8	
810-109394-7	SJOG - 18 Sink	Total/NA	Drinking Water	200.8	
810-109394-8	SJOG - 19 Sink	Total/NA	Drinking Water	200.8	
810-109394-9	SJOG - 21 WF	Total/NA	Drinking Water	200.8	
810-109394-10	SJOG - 23 Bubbler	Total/NA	Drinking Water	200.8	
810-109394-11	SJOG - 26 Bubbler	Total/NA	Drinking Water	200.8	
810-109394-12	SJOG - 28 Sink	Total/NA	Drinking Water	200.8	
810-109394-13	SJOG - 29 Sink	Total/NA	Drinking Water	200.8	
810-109394-14	SJOG - 30 Sink	Total/NA	Drinking Water	200.8	
810-109394-15	SJOG - 31 Sink	Total/NA	Drinking Water	200.8	
810-109394-16	SJOG - 32 Sink	Total/NA	Drinking Water	200.8	
810-109394-17	SJOG - 33 Sink	Total/NA	Drinking Water	200.8	
810-109394-18	SJOG - 37 Sink	Total/NA	Drinking Water	200.8	
810-109394-20	SJOG - 7 Sink	Total/NA	Drinking Water	200.8	
810-109394-21	SJOG - 10 WF	Total/NA	Drinking Water	200.8	
810-109394-22	SJOG - 11 WF	Total/NA	Drinking Water	200.8	
810-109394-25	SJOG - 15 WF	Total/NA	Drinking Water	200.8	
810-109394-26	SJOG - 16 WF	Total/NA	Drinking Water	200.8	
810-109394-27	SJOG - 20 WF	Total/NA	Drinking Water	200.8	
810-109394-28	SJOG - 36 Sink	Total/NA	Drinking Water	200.8	
810-109394-29	SJOG - 41 Sink	Total/NA	Drinking Water	200.8	
810-109394-30	SJOG - 42 Bubbler	Total/NA	Drinking Water	200.8	

Eurofins Eaton Analytical South Bend

QC Association Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Metals (Continued)

Analysis Batch: 104372 (Continued)

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-109394-31	SJOG - 43 Sink	Total/NA	Drinking Water	200.8	
810-109394-32	SJOG - 44 Bubbler	Total/NA	Drinking Water	200.8	
810-109394-33	SJOG - 45 Sink	Total/NA	Drinking Water	200.8	
810-109394-35	SJOG - 47 Sink	Total/NA	Drinking Water	200.8	
810-109394-36	SJOG - 49 WF	Total/NA	Drinking Water	200.8	
810-109394-39	SJOG - 53 Sink	Total/NA	Drinking Water	200.8	
810-109394-40	SJOG - 54 Sink	Total/NA	Drinking Water	200.8	
810-109394-41	SJOG - 55 WF	Total/NA	Drinking Water	200.8	
810-109394-42	SJOG - 56 WF	Total/NA	Drinking Water	200.8	
810-109394-43	SJOG - 57 Sink	Total/NA	Drinking Water	200.8	
810-109394-44	SJOG - 58 Sink	Total/NA	Drinking Water	200.8	
810-109394-45	SJOG - 59 Sink	Total/NA	Drinking Water	200.8	
MB 810-104372/105	Method Blank	Total/NA	Drinking Water	200.8	
MB 810-104372/12	Method Blank	Total/NA	Drinking Water	200.8	
MB 810-104372/45	Method Blank	Total/NA	Drinking Water	200.8	
MB 810-104372/75	Method Blank	Total/NA	Drinking Water	200.8	
LCS 810-104372/106	Lab Control Sample	Total/NA	Drinking Water	200.8	
LCS 810-104372/46	Lab Control Sample	Total/NA	Drinking Water	200.8	
LCS 810-104372/76	Lab Control Sample	Total/NA	Drinking Water	200.8	
LLCS 810-104372/11	Lab Control Sample	Total/NA	Drinking Water	200.8	
810-109394-10 MS	SJOG - 23 Bubbler	Total/NA	Drinking Water	200.8	
810-109394-10 MSD	SJOG - 23 Bubbler	Total/NA	Drinking Water	200.8	
810-109394-22 MS	SJOG - 11 WF	Total/NA	Drinking Water	200.8	
810-109394-22 MSD	SJOG - 11 WF	Total/NA	Drinking Water	200.8	
810-109394-36 MS	SJOG - 49 WF	Total/NA	Drinking Water	200.8	
810-109394-36 MSD	SJOG - 49 WF	Total/NA	Drinking Water	200.8	

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 1 Sink

Lab Sample ID: 810-109394-1

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 11:20

Client Sample ID: SJOG - 2 Sink

Lab Sample ID: 810-109394-2

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 11:23

Client Sample ID: SJOG - 5 Sink

Lab Sample ID: 810-109394-3

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 11:25

Client Sample ID: SJOG - 6 Sink

Lab Sample ID: 810-109394-4

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 11:28

Client Sample ID: SJOG - 8 ICE

Lab Sample ID: 810-109394-5

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 11:31

Client Sample ID: SJOG - 17 Sink

Lab Sample ID: 810-109394-6

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 11:45

Client Sample ID: SJOG - 18 Sink

Lab Sample ID: 810-109394-7

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 11:48

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 19 Sink

Lab Sample ID: 810-109394-8

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 11:51

Client Sample ID: SJOG - 21 WF

Lab Sample ID: 810-109394-9

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 11:54

Client Sample ID: SJOG - 23 Bubbler

Lab Sample ID: 810-109394-10

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 11:56

Client Sample ID: SJOG - 26 Bubbler

Lab Sample ID: 810-109394-11

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 12:05

Client Sample ID: SJOG - 28 Sink

Lab Sample ID: 810-109394-12

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 12:08

Client Sample ID: SJOG - 29 Sink

Lab Sample ID: 810-109394-13

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 12:11

Client Sample ID: SJOG - 30 Sink

Lab Sample ID: 810-109394-14

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 12:14

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 31 Sink

Lab Sample ID: 810-109394-15

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 12:16

Client Sample ID: SJOG - 32 Sink

Lab Sample ID: 810-109394-16

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 12:25

Client Sample ID: SJOG - 33 Sink

Lab Sample ID: 810-109394-17

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 12:28

Client Sample ID: SJOG - 37 Sink

Lab Sample ID: 810-109394-18

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 12:30

Client Sample ID: SJOG - 38 Sink

Lab Sample ID: 810-109394-19

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total Recoverable	Prep	200.8			104188	NB	EA SB	06/27/24 13:10
Total Recoverable	Analysis	200.8		10	104341	NB	EA SB	06/28/24 13:22

Client Sample ID: SJOG - 7 Sink

Lab Sample ID: 810-109394-20

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 12:33

Client Sample ID: SJOG - 10 WF

Lab Sample ID: 810-109394-21

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 12:36

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 11 WF

Lab Sample ID: 810-109394-22

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 12:39

Client Sample ID: SJOG - 13 SINK

Lab Sample ID: 810-109394-23

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total Recoverable	Prep	200.8			104188	NB	EA SB	06/27/24 13:10
Total Recoverable	Analysis	200.8		1	104341	NB	EA SB	06/28/24 13:08

Client Sample ID: SJOG - 14 SINK

Lab Sample ID: 810-109394-24

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total Recoverable	Prep	200.8			104188	NB	EA SB	06/27/24 13:10
Total Recoverable	Analysis	200.8		1	104341	NB	EA SB	06/28/24 13:10

Client Sample ID: SJOG - 15 WF

Lab Sample ID: 810-109394-25

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 12:48

Client Sample ID: SJOG - 16 WF

Lab Sample ID: 810-109394-26

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 12:50

Client Sample ID: SJOG - 20 WF

Lab Sample ID: 810-109394-27

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 12:53

Client Sample ID: SJOG - 36 Sink

Lab Sample ID: 810-109394-28

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 12:56

Eurofins Eaton Analytical South Bend

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 41 Sink

Lab Sample ID: 810-109394-29

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 13:10

Client Sample ID: SJOG - 42 Bubbler

Lab Sample ID: 810-109394-30

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 13:13

Client Sample ID: SJOG - 43 Sink

Lab Sample ID: 810-109394-31

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 13:16

Client Sample ID: SJOG - 44 Bubbler

Lab Sample ID: 810-109394-32

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 13:19

Client Sample ID: SJOG - 45 Sink

Lab Sample ID: 810-109394-33

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 13:22

Client Sample ID: SJOG - 46 Bubbler

Lab Sample ID: 810-109394-34

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total Recoverable	Prep	200.8			104188	NB	EA SB	06/27/24 13:10
Total Recoverable	Analysis	200.8		1	104341	NB	EA SB	06/28/24 13:12

Client Sample ID: SJOG - 47 Sink

Lab Sample ID: 810-109394-35

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 13:24

Eurofins Eaton Analytical South Bend

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 49 WF

Lab Sample ID: 810-109394-36

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 13:27

Client Sample ID: SJOG - 51 Sink

Lab Sample ID: 810-109394-37

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total Recoverable	Prep	200.8			104188	NB	EA SB	06/27/24 13:10
Total Recoverable	Analysis	200.8		1	104341	NB	EA SB	06/28/24 13:14

Client Sample ID: SJOG - 52 Sink

Lab Sample ID: 810-109394-38

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total Recoverable	Prep	200.8			104188	NB	EA SB	06/27/24 13:10
Total Recoverable	Analysis	200.8		1	104341	NB	EA SB	06/28/24 13:16

Client Sample ID: SJOG - 53 Sink

Lab Sample ID: 810-109394-39

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 13:36

Client Sample ID: SJOG - 54 Sink

Lab Sample ID: 810-109394-40

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 13:39

Client Sample ID: SJOG - 55 WF

Lab Sample ID: 810-109394-41

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 13:41

Client Sample ID: SJOG - 56 WF

Lab Sample ID: 810-109394-42

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 13:50

Eurofins Eaton Analytical South Bend

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Client Sample ID: SJOG - 57 Sink

Lab Sample ID: 810-109394-43

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 13:53

Client Sample ID: SJOG - 58 Sink

Lab Sample ID: 810-109394-44

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 13:55

Client Sample ID: SJOG - 59 Sink

Lab Sample ID: 810-109394-45

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:00

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 13:58

Laboratory References:
EA SB = Eurofins Eaton Analytical South Bend, 110 S Hill Street, South Bend, IN 46617, TEL (574)233-4777

Accreditation/Certification Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Laboratory: Eurofins Eaton Analytical South Bend

The accreditations/certifications listed below are applicable to this report.

Authority	Program	Identification Number	Expiration Date
Missouri	State	880	09-30-24

1
2
3
4
5
6
7
8
9
10
11
12
13
14

Method Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Method	Method Description	Protocol	Laboratory
200.8	Metals (ICP/MS)	EPA	EA SB
200.8	Preparation, Total Recoverable Metals	EPA	EA SB

Protocol References:

EPA = US Environmental Protection Agency

Laboratory References:

EA SB = Eurofins Eaton Analytical South Bend, 110 S Hill Street, South Bend, IN 46617, TEL (574)233-4777

Sample Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Oak Grove Elem

Job ID: 810-109394-1

Lab Sample ID	Client Sample ID	Matrix	Collected	Received
810-109394-1	SJOG - 1 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-2	SJOG - 2 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-3	SJOG - 5 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-4	SJOG - 6 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-5	SJOG - 8 ICE	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-6	SJOG - 17 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-7	SJOG - 18 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-8	SJOG - 19 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-9	SJOG - 21 WF	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-10	SJOG - 23 Bubbler	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-11	SJOG - 26 Bubbler	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-12	SJOG - 28 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-13	SJOG - 29 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-14	SJOG - 30 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-15	SJOG - 31 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-16	SJOG - 32 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-17	SJOG - 33 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-18	SJOG - 37 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-19	SJOG - 38 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-20	SJOG - 7 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-21	SJOG - 10 WF	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-22	SJOG - 11 WF	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-23	SJOG - 13 SINK	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-24	SJOG - 14 SINK	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-25	SJOG - 15 WF	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-26	SJOG - 16 WF	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-27	SJOG - 20 WF	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-28	SJOG - 36 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-29	SJOG - 41 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-30	SJOG - 42 Bubbler	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-31	SJOG - 43 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-32	SJOG - 44 Bubbler	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-33	SJOG - 45 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-34	SJOG - 46 Bubbler	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-35	SJOG - 47 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-36	SJOG - 49 WF	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-37	SJOG - 51 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-38	SJOG - 52 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-39	SJOG - 53 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-40	SJOG - 54 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-41	SJOG - 55 WF	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-42	SJOG - 56 WF	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-43	SJOG - 57 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-44	SJOG - 58 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00
810-109394-45	SJOG - 59 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:00

eurofins Eaton Analytical: South Bend
110 South Hill Street
South Bend, IN 46617
Phone (574) 233-4777

Chain of Custody Record



eurofins Environment Testing
America

Sampler: Ian St. John		Lab PM:	
Phone: 314-853-4668		E-Mail: ian@stjohnenv.com	
State of Origin: MO		Page: Page 1 of 6	
Company: Casey Housman		Job #:	
Address: St. Joseph School District 1415 North 26th Street City: St. Joseph State, Zip: Missouri 64506 Phone: 816-671-4000 Email: CaseyHousman@sjsd.k12.mo.us Project Name: St. Joseph School District Site: Oak Grove Elem		Analysis Requested	
Due Date Requested:		Preservation Codes:	
TAT Requested (days): Standard		A - HCL B - NaOH C - Zn Acetate D - Nitric Acid E - NaHSO4 F - MeOH G - Anchlor H - Ascorbic Acid I - Ice J - DI Water K - EDTA L - EDA Other:	
Compliance Project: ☐ Yes ☒ No		Total Number of Containers	
PO #:		Special Instructions/Note:	
WO #:			
Project #:			
SSOW #:			
Sample Identification		Field Filtered Sample (Yes or No)	
Sample Date		Perform MS/MSD (Yes or No)	
Sample Time		Matrix	
Sample Type (C=Comp, G=grab)		(Water, Solid, Overhead)	
Preservation Code:		ST 06 - 1 Sink	
ST 06 - 2 "		ST 06 - 3 "	
ST 06 - 4 "		ST 06 - 5 "	
ST 06 - 6 "		ST 06 - 7 "	
ST 06 - 8 ICE		ST 06 - 9 Sink	
ST 06 - 10 WF		ST 06 - 11 WF	
Possible Hazard Identification		Sample Disposal (A fee may be assessed if samples are retained longer than 1 month)	
☐ Non-Hazard ☐ Flammable ☐ Skin Irritant ☐ Poison B ☒ Unknown ☐ Radiological		☐ Return To Client ☒ Disposal By Lab ☐ Archive For Months	
Deliverable Requested: I, II, III, IV, Other (specify)		Special Instructions/QC Requirements:	
Empty Kit Relinquished by:		Method of Shipment:	
Relinquished by: [Signature]		Date/Time: Received by: Kameron Williams 6/25/24 0900	
Relinquished by:		Date/Time: Received by:	
Relinquished by:		Date/Time: Received by:	
Custody Seal No.: ☐ Yes ☒ No		Cooler Temperature(s) °C and Other Remarks: Ambient	

Eurofins Eaton Analytical: South Bend
110 South Hill Street
South Bend, IN 46617
Phone (574) 233-4777

Chain of Custody Record



Environment Testing
America

Client Information		Sampler: <u>Ian St. John</u>		Lab P/N:		Carrier Tracking No(s):		COC No:							
Client Contact: <u>Casey Housman</u>		Phone: <u>314-853-4668</u>		E-Mail: <u>ian@stjohnenv.com</u>		State of Origin: <u>MO</u>		Page: <u>2 of 6</u>							
Company: <u>St. Joseph School District</u>		PWSID:		Analysis Requested											
Address: <u>1415 North 26th Street</u>		Due Date Requested:		Perform MS/MSD (Yes or No) ☒ Field Filtered Sample (Yes or No) ☒ Total Number of Containers ☒ Special Instructions/Note:											
City: <u>St. Joseph</u>		TAT Requested (days): <u>Standard</u>													
State, Zip: <u>Missouri 64506</u>		Compliance Project: ☐ Yes ☒ No													
Phone: <u>816-671-4000</u>		PO #:													
Email: <u>CaseyHousman@sjsd.k12.mo.us</u>		WO #:													
Project Name: <u>St. Joseph School District</u>		Project #:		Preservation Codes: A - HCL M - Hexane B - NaOH N - None C - Zn Acetate O - AsNaO2 D - Nitric Acid P - Na2O4S E - NaHSO4 Q - Na2SO3 F - MeOH R - Na2S2O3 G - Anichlor S - H2SO4 H - Ascorbic Acid T - TSP Dodecahydrate I - Ice U - Acetone J - DI Water V - MCAA K - EDTA W - pH 4-5 L - EDA Y - Trizma Z - other (specify)											
Site: <u>Oak Grove Elem</u>		SSOW#:													
Sample Identification		Sample Date								Sample Time		Sample Type (C=Comp, G=grab)		Matrix (W=water, S=solid, O=oil, A=air)	
ST OG-12 Sink		6/24/24 0800								G		W			
ST OG-13 Sink															
ST OG-14 Sink															
ST OG-15 WF															
ST OG-16 WF															
ST OG-17 Sink															
ST OG-18 Sink															
ST OG-19 Sink															
ST OG-20 WF															
ST OG-21 WF															
ST OG-22 Sink															
Possible Hazard Identification		☒ Non-Hazard ☐ Flammable ☐ Skin Irritant ☐ Poison B ☒ Unknown ☐ Radiological		Sample Disposal (A fee may be assessed if samples are retained longer than 1 month)											
Deliverable Requested: I, II, III, IV, Other (specify)		☐ Return To Client ☒ Disposal By Lab ☐ Archive For _____ Months		Special Instructions/QC Requirements:											
Empty Kit Relinquished by:		Date:		Method of Shipment:											
Relinquished by: <u>[Signature]</u>		Date/Time: <u>April 14, 2024</u>		Received by: <u>Kameron Williams 03/25/24 0900</u>											
Relinquished by:		Date/Time:		Received by:											
Relinquished by:		Date/Time:		Received by:											
Custody Seals Intact: ☐ Yes ☒ No		Custody Seal No.:		Cooler Temperature(s) °C and Other Remarks: <u>Ambient</u>											

Chain of Custody Record

Sampler: Ian St. John		Lab Piv:		Carrier Tracking No(s):		COC No:	
Phone: 314-853-4668		E-Mail: ian@stjohnenv.com		State of Origin: MO		Page: 3 of 6	
Client Contact: Casey Housman		PWSID:		Analysis Requested		Job #:	
Company: St. Joseph School District		Due Date Requested:		TAT Requested (days): Standard		Preservation Codes:	
Address: 1415 North 26th Street		Compliance Project: Δ Yes Δ No		Field Filtered Sample (Yes or No)		A - HCL B - NaOH C - Zn Acetate D - Nitric Acid E - NaHSO4 F - MeOH G - Anchlor H - Ascorbic Acid I - Ice J - DI Water K - EDTA L - EDA Other:	
City: St. Joseph		PO #:		Perform MS/MSD (Yes or No)		M - Hexane N - None O - AsNaO2 P - Na2OAS Q - Na2SO3 R - Na2SO4 S - H2SO4 T - TSP Dodecahydrate U - Acetone V - MCAA W - pH 4-5 Y - Trizma Z - other (specify)	
State, Zip: Missouri 64506		WO #:		Total Number of Containers			
Phone: 816-671-4000		Project #:					
Email: CaseyHousman@sjsd.k12.mo.us		SSOW#:					
Project Name: St. Joseph School District		Sample Date		Sample Time		Sample Type (C=Comp, G=grab)	
Site: Oak Grove Elem		Matrix (W=Water, B=Soil, O=Organic)		Preservation Code:			
Sample Identification		6/24/24 0800		G		W	
SJ OG-23 Bubble							
SJ OG-24 Bubble							
SJ OG-25 Sink							
SJ OG-26 Bubble							
SJ OG-27 Sink							
SJ OG-28 Sink							
SJ OG-29 Sink							
SJ OG-30 Sink							
SJ OG-31 Sink							
SJ OG-32 "							
SJ OG-33 "							
Possible Hazard Identification		Poison B		Unknown		Radiological	
☐ Non-Hazard ☐ Flammable ☐ Skin Irritant ☐ Other (specify)							
Deliverable Requested: I, II, III, IV, Other (specify)							
Empty Kit Relinquished by: [Signature]		Date: 6/14/2024		Company: [Signature]		Received by: [Signature]	
Relinquished by: [Signature]		Date/Time: 6/14/2024		Company: [Signature]		Received by: [Signature]	
Relinquished by:		Date/Time:		Company:		Received by:	
Custody Seals Intact: Δ Yes Δ No		Custody Seal No.:		Cooler Temperature(s) °C and Other Remarks: Ambient		Ver: 02/24/23	

Chain of Custody Record

Client Information		Sampler: Ian St. John		Lab PM:		Carrier Tracking No(s):		COC No:	
Client Contact: Casey Housman		Phone: 314-853-4668		E-Mail:		State of Origin: MO		Page: 4 of 6	
Company: St. Joseph School District		Address: 1415 North 26th Street		City: St. Joseph		State, Zip: Missouri 64506		Job #:	
Phone: 816-671-4000		TAT Requested (days): Standard		Compliance Project: Δ Yes Δ No		PO #:		Preservation Codes:	
Email: CaseyHousman@sjsd.k12.mo.us		WO #:		Project #:		SSOW#:		A - HCL B - NaOH C - Zn Acetate D - Nitric Acid E - NaHSO4 F - MeOH G - Anchlor H - Ascorbic Acid I - Ice J - DI Water K - EDTA L - EDA Other:	
Project Name: St. Joseph School District		Sample Date		Sample Time		Sample Type (C=Comp, G=grab)		Matrix (W=water, E=soil, O=organic, B=biological, T=tissue, A=air)	
Site: Oak Grove Elem		Sample Date		Sample Time		Sample Type (C=Comp, G=grab)		Matrix (W=water, E=soil, O=organic, B=biological, T=tissue, A=air)	
Sample Identification		Sample Date		Sample Time		Sample Type (C=Comp, G=grab)		Matrix (W=water, E=soil, O=organic, B=biological, T=tissue, A=air)	
SJ OG-34 Sink		6/24/24		0800		G		W	
SJ OG-35 Sink									
SJ OG-36 Sink									
SJ OG-37 Sink									
SJ OG-38 Sink									
SJ OG-39 Sink									
SJ OG-40 Sink									
SJ OG-41 Sink									
SJ OG-42 Bubble									
SJ OG-43 Sink									
SJ OG-44 Bubble									
Possible Hazard Identification		Non-Hazard		Flammable		Skin Irritant		Poison B	
Deliverable Requested: I, II, III, IV, Other (specify)		Unknown		Radiological					
Empty Kit Relinquished by:		Date:		Time:		Method of Shipment:		Return To Client	
Relinquished by: [Signature]		Date/Time: April 14, 2024						Disposal By Lab	
Relinquished by:		Date/Time:						Archive For	
Relinquished by:		Date/Time:						Months	
Custody Seals Intact: Δ Yes Δ No		Custody Seal No.:						Sample Disposal (A fee may be assessed if samples are retained longer than 1 month)	
Relinquished by: [Signature]		Date/Time: April 14, 2024						Return To Client	
Relinquished by:		Date/Time:						Disposal By Lab	
Relinquished by:		Date/Time:						Archive For	
Relinquished by:		Date/Time:						Months	
Cooler Temperature(s) °C and Other Remarks: Ambient		Received by: [Signature]		Date/Time: 6/25/24		Company: EEA-SB		Special Instructions/QC Requirements:	
Cooler Temperature(s) °C and Other Remarks: Ambient		Received by:		Date/Time:		Company:		Total Number of containers	
Cooler Temperature(s) °C and Other Remarks: Ambient		Received by:		Date/Time:		Company:		Special Instructions/Note:	

Chain of Custody Record

Client Information		Sampler: Ian St. John		Lab PM:		Carrier Tracking No(s):		COC No:	
Client Contact: Casey Housman		Phone: 314-853-4668		E-Mail: ian@stjohnenv.com		State of Origin: MO		Page: 5 of 6	
Company: St. Joseph School District		PWSID:		Analysis Requested		Job #:			
Address: 1415 North 26th Street		Due Date Requested:		Perform MS/MSD (Yes or No)		Total Number of Containers		Preservation Codes:	
City: St. Joseph		TAT Requested (days): Standard		Field Filtered Sample (Yes or No)				A - HCL B - NaOH C - Zn Acetate D - Nitric Acid E - NaHSO4 F - MeOH G - Amchlor H - Ascorbic Acid I - Ice J - DI Water K - EDTA L - EDA Other:	
State, Zip: Missouri 64506		Compliance Project: ☐ Yes ☒ No						M - Hexane N - None O - AshNaO2 P - Na2O4S Q - Na2SO3 R - Na2SO3 S - H2SO4 T - TSP Dodecahydrate U - Acetone V - MCAA W - pH 4-5 Y - Trizma Z - other (specify)	
Phone: 816-671-4000		PO #:							
Email: CaseyHousman@sjsd.k12.mo.us		WO #:							
Project Name: St. Joseph School District		Project #:							
Site: ORK Grove Elem.		SSOW#:							
Sample Identification		Sample Date	Sample Time	Sample Type (C=Comp, G=grab)	Matrix (W=water, S=solid, O=soil, A=air)				
ST 06-45 Sink		6/6/24	0800	G	W				
ST 06-46 Bubble									
ST 06-47 Sink									
ST 06-48 Bubble									
ST 06-49 WF									
ST 06-50 WF									
ST 06-51 Sink									
ST 06-52 Sink									
ST 06-53 Sink									
ST 06-54 Sink									
ST 06-55 WF									
Possible Hazard Identification		☒ Poison B		☐ Radiological					
☐ Non-Hazard		☐ Flammable		☐ Skin Irritant					
Deliverable Requested: I, II, III, IV, Other (specify)		Unknown							
Empty Kit Relinquished by:		Date:		Time:		Special Instructions/QC Requirements:			
Relinquished by: [Signature]		Date/Time: 6/6/24 14:20		Company: [Signature]		Sample Disposal (A fee may be assessed if samples are retained longer than 1 month)			
Relinquished by:		Date/Time:		Company:		☐ Return To Client ☒ Disposal By Lab ☐ Archive For _____ Months			
Relinquished by:		Date/Time:		Company:					
Custody Seals Intact: ☐ Yes ☒ No		Custody Seal No.:		Cooler Temperature(s) °C and Other Remarks: Ambient					

Eurofins Eaton Analytical: South Bend
110 South Hill Street
South Bend, IN 46617
Phone (574) 233-4777

Chain of Custody Record

Sampler: Ian St. John		Lab PM:	Carrier Tracking No(s):		COC No:
Phone: 314-853-4668		E-Mail: ian@stjohnenv.com	State of Origin: MO		Page: 6 of 6
Client Contact: Casey Housman		PWSID:	Job #:		
Company: St. Joseph School District		Analysis Requested			
Address: 1415 North 26th Street		Due Date Requested:	Preservation Codes:		
City: St. Joseph		TAT Requested (days): Standard	A - HCL B - NaOH C - Zn Acetate D - Nitric Acid E - NaHSO4 F - MeOH G - Amchlor H - Ascorbic Acid I - Ice J - DI Water K - EDTA L - EDA Other:		
State, Zip: Missouri 64506		Compliance Project: ☐ Yes ☒ No	M - Hexane N - None O - AsNaO2 P - Na2O4S Q - Na2SO3 R - Na2SO4 S - H2SO4 T - TSP Dodecahydrate U - Acetone V - MCAA W - pH 4-5 Y - Trizma Z - other (specify)		
Phone: 816-671-4000		PO #:	Total Number of containers		
Email: CaseyHousman@sjisd.k12.mo.us		WO #:	Special Instructions/Note:		
Project Name: St. Joseph School District		Project #:			
Site: OPR Grove Elem		SSOW#:			
Sample Identification		Sample Date	Sample Time	Sample Type (C=Comp, G=grab)	Matrix (W=water, S=solid, O=organic, A=air)
ST06-56 WF		6/24/24	0800	G	W
ST06-57 Sink					
ST06-58 Sink					
ST06-59 Sink					
ST06-60 Sink					
ST06-61 Sink					
ST06-62 Sink					
ST06-63 Sink					
ST06-64 Sink					
ST06-65 Sink					
ST06-66 Sink					
ST06-67 Sink					
ST06-68 Sink					
ST06-69 Sink					
ST06-70 Sink					
ST06-71 Sink					
ST06-72 Sink					
ST06-73 Sink					
ST06-74 Sink					
ST06-75 Sink					
ST06-76 Sink					
ST06-77 Sink					
ST06-78 Sink					
ST06-79 Sink					
ST06-80 Sink					
ST06-81 Sink					
ST06-82 Sink					
ST06-83 Sink					
ST06-84 Sink					
ST06-85 Sink					
ST06-86 Sink					
ST06-87 Sink					
ST06-88 Sink					
ST06-89 Sink					
ST06-90 Sink					
ST06-91 Sink					
ST06-92 Sink					
ST06-93 Sink					
ST06-94 Sink					
ST06-95 Sink					
ST06-96 Sink					
ST06-97 Sink					
ST06-98 Sink					
ST06-99 Sink					
ST06-100 Sink					
ST06-101 Sink					
ST06-102 Sink					
ST06-103 Sink					
ST06-104 Sink					
ST06-105 Sink					
ST06-106 Sink					
ST06-107 Sink					
ST06-108 Sink					
ST06-109 Sink					
ST06-110 Sink					
ST06-111 Sink					
ST06-112 Sink					
ST06-113 Sink					
ST06-114 Sink					
ST06-115 Sink					
ST06-116 Sink					
ST06-117 Sink					
ST06-118 Sink					
ST06-119 Sink					
ST06-120 Sink					
ST06-121 Sink					
ST06-122 Sink					
ST06-123 Sink					
ST06-124 Sink					
ST06-125 Sink					
ST06-126 Sink					
ST06-127 Sink					
ST06-128 Sink					
ST06-129 Sink					
ST06-130 Sink					
ST06-131 Sink					
ST06-132 Sink					
ST06-133 Sink					
ST06-134 Sink					
ST06-135 Sink					
ST06-136 Sink					
ST06-137 Sink					
ST06-138 Sink					
ST06-139 Sink					
ST06-140 Sink					
ST06-141 Sink					
ST06-142 Sink					
ST06-143 Sink					
ST06-144 Sink					
ST06-145 Sink					
ST06-146 Sink					
ST06-147 Sink					
ST06-148 Sink					
ST06-149 Sink					
ST06-150 Sink					
ST06-151 Sink					
ST06-152 Sink					
ST06-153 Sink					
ST06-154 Sink					
ST06-155 Sink					
ST06-156 Sink					
ST06-157 Sink					
ST06-158 Sink					
ST06-159 Sink					
ST06-160 Sink					
ST06-161 Sink					
ST06-162 Sink					
ST06-163 Sink					
ST06-164 Sink					
ST06-165 Sink					
ST06-166 Sink					
ST06-167 Sink					
ST06-168 Sink					
ST06-169 Sink					
ST06-170 Sink					
ST06-171 Sink					
ST06-172 Sink					
ST06-173 Sink					
ST06-174 Sink					
ST06-175 Sink					
ST06-176 Sink					
ST06-177 Sink					
ST06-178 Sink					
ST06-179 Sink					
ST06-180 Sink					
ST06-181 Sink					
ST06-182 Sink					
ST06-183 Sink					
ST06-184 Sink					
ST06-185 Sink					
ST06-186 Sink					
ST06-187 Sink					
ST06-188 Sink					
ST06-189 Sink					
ST06-190 Sink					
ST06-191 Sink					
ST06-192 Sink					
ST06-193 Sink					
ST06-194 Sink					
ST06-195 Sink					
ST06-196 Sink					
ST06-197 Sink					
ST06-198 Sink					
ST06-199 Sink					
ST06-200 Sink					
ST06-201 Sink					
ST06-202 Sink					
ST06-203 Sink					
ST06-204 Sink					
ST06-205 Sink					
ST06-206 Sink					
ST06-207 Sink					
ST06-208 Sink					
ST06-209 Sink					
ST06-210 Sink					
ST06-211 Sink					
ST06-212 Sink					
ST06-213 Sink					
ST06-214 Sink					
ST06-215 Sink					
ST06-216 Sink					
ST06-217 Sink					
ST06-218 Sink					
ST06-219 Sink					
ST06-220 Sink					
ST06-221 Sink					
ST06-222 Sink					
ST06-223 Sink					
ST06-224 Sink					
ST06-225 Sink					
ST06-226 Sink					
ST06-227 Sink					
ST06-228 Sink					
ST06-229 Sink					
ST06-230 Sink					
ST06-231 Sink					
ST06-232 Sink					
ST06-233 Sink					
ST06-234 Sink					
ST06-235 Sink					
ST06-236 Sink					
ST06-237 Sink					
ST06-238 Sink					
ST06-239 Sink					
ST06-240 Sink					
ST06-241 Sink					
ST06-242 Sink					
ST06-243 Sink					
ST06-244 Sink					
ST06-245 Sink					
ST06-246 Sink					
ST06-247 Sink					
ST06-248 Sink					
ST06-249 Sink					
ST06-250 Sink					
ST06-251 Sink					
ST06-252 Sink					
ST06-253 Sink					
ST06-254 Sink					
ST06-255 Sink					
ST06-256 Sink					
ST06-257 Sink					
ST06-258 Sink					
ST06-259 Sink					
ST06-260 Sink					
ST06-261 Sink					
ST06-262 Sink					
ST06-263 Sink					
ST06-264 Sink					
ST06-265 Sink					
ST06-266 Sink					
ST06-267 Sink					
ST06-268 Sink					
ST06-269 Sink					
ST06-270 Sink					
ST06-271 Sink					
ST06-272 Sink					
ST06-273 Sink					
ST06-274 Sink					
ST06-275 Sink					
ST06-276 Sink					
ST06-277 Sink					
ST06-278 Sink					
ST06-279 Sink					
ST06-280 Sink					
ST06-281 Sink					
ST06-282 Sink					
ST06-283 Sink					
ST06-284 Sink					
ST06-285 Sink					
ST06-286 Sink					
ST06-287 Sink					
ST06-288 Sink					
ST06-289 Sink					
ST06-290 Sink					
ST06-291 Sink					
ST06-292 Sink					
ST06-293 Sink					
ST06-294 Sink					
ST06-295 Sink					
ST06-296 Sink					
ST06-297 Sink					
ST06-298 Sink					
ST06-299 Sink					
ST06-300 Sink					
ST06-301 Sink					
ST06-302 Sink					
ST06-303 Sink					
ST06-304 Sink					
ST06-305 Sink					
ST06-306 Sink					
ST06-307 Sink					
ST06-308 Sink					
ST06-309 Sink					
ST06-310 Sink					
ST06-311 Sink					
ST06-312 Sink					
ST06-313 Sink					
ST06-314 Sink					
ST06-315 Sink					
ST06-316 Sink					
ST06-317 Sink					
ST06-318 Sink					
ST06-319 Sink					
ST06-320 Sink					
ST06-321 Sink					
ST06-322 Sink					
ST06-323 Sink					
ST06-324 Sink					
ST06-325 Sink					
ST06-326 Sink					
ST06-327 Sink					
ST06-328 Sink					
ST06-329 Sink					
ST06-330 Sink					
ST06-331 Sink					
ST06-332 Sink					
ST06-333 Sink					
ST06-334 Sink					
ST06-335 Sink					
ST06-336 Sink					
ST06-337 Sink					
ST06-338 Sink					
ST06-339 Sink					
ST06-340 Sink					
ST06-341 Sink					
ST06-342 Sink					
ST06-343 Sink					
ST06-344 Sink					
ST06-345 Sink					
ST06-346 Sink					
ST06-347 Sink					
ST06-348 Sink					
ST06-349 Sink					
ST06-350 Sink					
ST06-351 Sink					
ST06-352 Sink					
ST06-353 Sink					
ST06-354 Sink					
ST06-355 Sink					
ST06-356 Sink					
ST06-357 Sink					
ST06-358 Sink					
ST06-359 Sink					
ST06-360 Sink					
ST06-361 Sink					
ST06-362 Sink					
ST06-363 Sink					
ST06-364 Sink					
ST06-365 Sink					
ST06-366 Sink					
ST06-367 Sink					
ST06-368 Sink					
ST06-369 Sink					
ST06-370 Sink					
ST06-371 Sink					
ST06-372 Sink					
ST06-373 Sink					
ST06-374 Sink					
ST06-375 Sink					

Login Sample Receipt Checklist

Client: St. John Environmental Consulting

Job Number: 810-109394-1

Login Number: 109394

List Source: Eurofins Eaton Analytical South Bend

List Number: 1

Creator: Williams, Kameron

Question	Answer	Comment
The cooler's custody seal, if present, is intact.	True	
Sample custody seals, if present, are intact.	True	
Samples were received on ice.	False	Thermal preservation not required.
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	False	Thermal preservation not required.
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	False	Refer to Job Narrative for details.
Sample collection date/times are provided.	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	True	
Samples do not require splitting or compositing.	True	
Container provided by EEA	True	