

ANALYTICAL REPORT

PREPARED FOR

Attn: Ian St. John
St. John Environmental Consulting
5515 Grace Ave.
Saint Louis, Missouri 63116

Generated 7/1/2024 11:33:50 PM

JOB DESCRIPTION

St. Joseph School District - Benton High

JOB NUMBER

810-109396-1

Eurofins Eaton Analytical South Bend

Job Notes

This report may not be reproduced except in full, and with written approval from the laboratory. The results relate only to the samples tested. For questions please contact the Project Manager at the e-mail address or telephone number listed on this page.

The test results in this report relate only to the samples as received by the laboratory and will meet all requirements of the methodology, with any exceptions noted. This report shall not be reproduced except in full, without the express written approval of the laboratory. All questions should be directed to the Eurofins Eaton Analytical, LLC Project Manager.

Authorization



Generated
7/1/2024 11:33:50 PM

Authorized for release by
Pamela Brown, Project Manager
Pamela.Brown@et.eurofinsus.com
(574)233-4777



Table of Contents

Cover Page	1
Table of Contents	3
Definitions/Glossary	4
Case Narrative	5
Detection Summary	6
Client Sample Results	11
QC Sample Results	19
QC Association Summary	23
Lab Chronicle	26
Certification Summary	34
Method Summary	35
Sample Summary	36
Chain of Custody	38
Receipt Checklists	44

Definitions/Glossary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Qualifiers

Metals

Qualifier	Qualifier Description
J	Result is less than the RL but greater than or equal to the MDL and the concentration is an approximate value.

Glossary

Abbreviation	These commonly used abbreviations may or may not be present in this report.
α	Listed under the "D" column to designate that the result is reported on a dry weight basis
%R	Percent Recovery
CFL	Contains Free Liquid
CFU	Colony Forming Unit
CNF	Contains No Free Liquid
DER	Duplicate Error Ratio (normalized absolute difference)
Dil Fac	Dilution Factor
DL	Detection Limit (DoD/DOE)
DL, RA, RE, IN	Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample
DLC	Decision Level Concentration (Radiochemistry)
EDL	Estimated Detection Limit (Dioxin)
LOD	Limit of Detection (DoD/DOE)
LOQ	Limit of Quantitation (DoD/DOE)
MCL	EPA recommended "Maximum Contaminant Level"
MDA	Minimum Detectable Activity (Radiochemistry)
MDC	Minimum Detectable Concentration (Radiochemistry)
MDL	Method Detection Limit
ML	Minimum Level (Dioxin)
MPN	Most Probable Number
MQL	Method Quantitation Limit
NC	Not Calculated
ND	Not Detected at the reporting limit (or MDL or EDL if shown)
NEG	Negative / Absent
POS	Positive / Present
PQL	Practical Quantitation Limit
PRES	Presumptive
QC	Quality Control
RER	Relative Error Ratio (Radiochemistry)
RL	Reporting Limit or Requested Limit (Radiochemistry)
RPD	Relative Percent Difference, a measure of the relative difference between two points
TEF	Toxicity Equivalent Factor (Dioxin)
TEQ	Toxicity Equivalent Quotient (Dioxin)
TNTC	Too Numerous To Count

Case Narrative

Client: St. John Environmental Consulting
Project: St. Joseph School District - Benton High

Job ID: 810-109396-1

Job ID: 810-109396-1

Eurofins Eaton Analytical South Bend

Job Narrative 810-109396-1

Analytical test results meet all requirements of the associated regulatory program listed on the Accreditation/Certification Summary Page unless otherwise noted under the individual analysis. Data qualifiers are applied to indicate exceptions. Noncompliant quality control (QC) is further explained in narrative comments.

- Matrix QC may not be reported if insufficient sample or site-specific QC samples were not submitted. In these situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD may be performed, unless otherwise specified in the method.
- Surrogate and/or isotope dilution analyte recoveries (if applicable) which are outside of the QC window are confirmed unless attributed to a dilution or otherwise noted in the narrative.

Regulated compliance samples (e.g. SDWA, NPDES) must comply with the associated agency requirements/permits.

Receipt

The samples were received on 6/25/2024 9:30 AM. Unless otherwise noted below, the samples arrived in good condition, and, where required, properly preserved and on ice.

Metals

No additional analytical or quality issues were noted, other than those described above or in the Definitions/ Glossary page.

Eurofins Eaton Analytical South Bend

Detection Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 1 ICE						Lab Sample ID: 810-109396-1				
No Detections.										
Client Sample ID: SJBH - 2 Sink						Lab Sample ID: 810-109396-2				
No Detections.										
Client Sample ID: SJBH - 3 Sink						Lab Sample ID: 810-109396-3				
No Detections.										
Client Sample ID: SJBH - 4 Sink						Lab Sample ID: 810-109396-4				
No Detections.										
Client Sample ID: SJBH - 5 Sink						Lab Sample ID: 810-109396-5				
No Detections.										
Client Sample ID: SJBH - 6 Sink						Lab Sample ID: 810-109396-6				
No Detections.										
Client Sample ID: SJBH - 7 Sink						Lab Sample ID: 810-109396-7				
No Detections.										
Client Sample ID: SJBH - 8 WF						Lab Sample ID: 810-109396-8				
No Detections.										
Client Sample ID: SJBH - 9 WF						Lab Sample ID: 810-109396-9				
No Detections.										
Client Sample ID: SJBH - 10 WF						Lab Sample ID: 810-109396-10				
No Detections.										
Client Sample ID: SJBH - 11 WF						Lab Sample ID: 810-109396-11				
No Detections.										
Client Sample ID: SJBH - 12 WF						Lab Sample ID: 810-109396-12				
No Detections.										
Client Sample ID: SJBH - 13 Sink						Lab Sample ID: 810-109396-13				
No Detections.										
Client Sample ID: SJBH - 14 ICE						Lab Sample ID: 810-109396-14				
No Detections.										
Client Sample ID: SJBH - 15 Sink						Lab Sample ID: 810-109396-15				
No Detections.										
Client Sample ID: SJBH - 16 WF						Lab Sample ID: 810-109396-16				
Analyte		Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead		0.64		0.50		ug/L	1		200.8	Total/NA

This Detection Summary does not include radiochemical test results.

Eurofins Eaton Analytical South Bend

Detection Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 17 WF

Lab Sample ID: 810-109396-17

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	1.4		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 18 WF

Lab Sample ID: 810-109396-18

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	1.2		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 19 Sink

Lab Sample ID: 810-109396-19

No Detections.

Client Sample ID: SJBH - 20 Sink

Lab Sample ID: 810-109396-20

No Detections.

Client Sample ID: SJBH - 21 Sink

Lab Sample ID: 810-109396-21

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	1.9		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 22 Sink

Lab Sample ID: 810-109396-22

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	1.2		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 23 Sink

Lab Sample ID: 810-109396-23

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	11		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 24 Sink

Lab Sample ID: 810-109396-24

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	3.2		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 25 Sink

Lab Sample ID: 810-109396-25

No Detections.

Client Sample ID: SJBH - 26 WF

Lab Sample ID: 810-109396-26

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	4.2		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 27 Sink

Lab Sample ID: 810-109396-27

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	1.2		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 28 Sink

Lab Sample ID: 810-109396-28

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	1.6		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 29 WF

Lab Sample ID: 810-109396-29

No Detections.

This Detection Summary does not include radiochemical test results.

Eurofins Eaton Analytical South Bend

Detection Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 30 Sink

Lab Sample ID: 810-109396-30

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	6.9		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 32 Sink

Lab Sample ID: 810-109396-31

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	5.2		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 33 WF

Lab Sample ID: 810-109396-32

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	2.9		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 34 Sink

Lab Sample ID: 810-109396-33

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	2.3		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 35 Sink

Lab Sample ID: 810-109396-34

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	11		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 36 Sink

Lab Sample ID: 810-109396-35

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	16		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 37 Sink

Lab Sample ID: 810-109396-36

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	10		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 38 Sink

Lab Sample ID: 810-109396-37

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	11		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 39 Sink

Lab Sample ID: 810-109396-38

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	1.7		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 40 Sink

Lab Sample ID: 810-109396-39

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	2.3		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 41 Sink

Lab Sample ID: 810-109396-40

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	8.1		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 42 Sink

Lab Sample ID: 810-109396-41

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	3.0		0.50		ug/L	1		200.8	Total/NA

This Detection Summary does not include radiochemical test results.

Eurofins Eaton Analytical South Bend

Detection Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 43 Sink

Lab Sample ID: 810-109396-42

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	3.0		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 44 Sink

Lab Sample ID: 810-109396-43

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	3.3		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 45 Sink

Lab Sample ID: 810-109396-44

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	5.7		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 46 Sink

Lab Sample ID: 810-109396-45

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	3.4		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 47 WF

Lab Sample ID: 810-109396-46

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	2.5		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 48 Sink

Lab Sample ID: 810-109396-47

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	130		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 49 Sink

Lab Sample ID: 810-109396-48

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	8.8		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 50 Sink

Lab Sample ID: 810-109396-49

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	29		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 51 Sink

Lab Sample ID: 810-109396-50

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	9.7		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 52 Sink

Lab Sample ID: 810-109396-51

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	5.5		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 53 Hose Bib

Lab Sample ID: 810-109396-52

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	1.0		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJBH - 54 ICE MACH

Lab Sample ID: 810-109396-53

No Detections.

This Detection Summary does not include radiochemical test results.

Eurofins Eaton Analytical South Bend

Detection Summary

Client: St. John Environmental Consulting

Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 55 WF

Lab Sample ID: 810-109396-55

No Detections.

Client Sample ID: SJBH - 56

Lab Sample ID: 810-109396-55

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	45		0.50		ug/L	1		200.8	Total Recoverable

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 1 ICE

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:30

Lab Sample ID: 810-109396-1

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 11:23	1

Client Sample ID: SJBH - 2 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:30

Lab Sample ID: 810-109396-2

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 11:29	1

Client Sample ID: SJBH - 3 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:30

Lab Sample ID: 810-109396-3

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 11:31	1

Client Sample ID: SJBH - 4 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:30

Lab Sample ID: 810-109396-4

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 11:33	1

Client Sample ID: SJBH - 5 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:30

Lab Sample ID: 810-109396-5

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 11:35	1

Client Sample ID: SJBH - 6 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:30

Lab Sample ID: 810-109396-6

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 11:37	1

Client Sample ID: SJBH - 7 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:30

Lab Sample ID: 810-109396-7

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 17:18	1

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 8 WF

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:30

Lab Sample ID: 810-109396-8

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 17:21	1

Client Sample ID: SJBH - 9 WF

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:30

Lab Sample ID: 810-109396-9

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 17:23	1

Client Sample ID: SJBH - 10 WF

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:30

Lab Sample ID: 810-109396-10

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 17:31	1

Client Sample ID: SJBH - 11 WF

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:30

Lab Sample ID: 810-109396-11

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 17:39	1

Client Sample ID: SJBH - 12 WF

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:30

Lab Sample ID: 810-109396-12

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 17:42	1

Client Sample ID: SJBH - 13 Sink

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:30

Lab Sample ID: 810-109396-13

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 17:44	1

Client Sample ID: SJBH - 14 ICE

Date Collected: 06/24/24 08:00

Date Received: 06/25/24 09:30

Lab Sample ID: 810-109396-14

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 17:47	1

Eurofins Eaton Analytical South Bend

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 15 Sink

Lab Sample ID: 810-109396-15

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 17:49	1

Client Sample ID: SJBH - 16 WF

Lab Sample ID: 810-109396-16

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	0.64		0.50		ug/L			06/28/24 17:52	1

Client Sample ID: SJBH - 17 WF

Lab Sample ID: 810-109396-17

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.4		0.50		ug/L			06/28/24 17:54	1

Client Sample ID: SJBH - 18 WF

Lab Sample ID: 810-109396-18

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.2		0.50		ug/L			06/28/24 17:57	1

Client Sample ID: SJBH - 19 Sink

Lab Sample ID: 810-109396-19

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 18:00	1

Client Sample ID: SJBH - 20 Sink

Lab Sample ID: 810-109396-20

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 08:48	1

Client Sample ID: SJBH - 21 Sink

Lab Sample ID: 810-109396-21

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.9		0.50		ug/L			06/29/24 08:56	1

Eurofins Eaton Analytical South Bend

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 22 Sink

Lab Sample ID: 810-109396-22

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.2		0.50		ug/L			06/29/24 08:59	1

Client Sample ID: SJBH - 23 Sink

Lab Sample ID: 810-109396-23

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	11		0.50		ug/L			06/29/24 09:02	1

Client Sample ID: SJBH - 24 Sink

Lab Sample ID: 810-109396-24

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	3.2		0.50		ug/L			06/29/24 09:05	1

Client Sample ID: SJBH - 25 Sink

Lab Sample ID: 810-109396-25

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 09:07	1

Client Sample ID: SJBH - 26 WF

Lab Sample ID: 810-109396-26

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	4.2		0.50		ug/L			06/29/24 09:10	1

Client Sample ID: SJBH - 27 Sink

Lab Sample ID: 810-109396-27

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.2		0.50		ug/L			06/29/24 09:13	1

Client Sample ID: SJBH - 28 Sink

Lab Sample ID: 810-109396-28

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.6		0.50		ug/L			06/29/24 09:16	1

Eurofins Eaton Analytical South Bend

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 29 WF

Lab Sample ID: 810-109396-29

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 09:19	1

Client Sample ID: SJBH - 30 Sink

Lab Sample ID: 810-109396-30

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	6.9		0.50		ug/L			06/29/24 10:06	1

Client Sample ID: SJBH - 32 Sink

Lab Sample ID: 810-109396-31

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	5.2		0.50		ug/L			06/29/24 09:30	1

Client Sample ID: SJBH - 33 WF

Lab Sample ID: 810-109396-32

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	2.9		0.50		ug/L			06/29/24 09:38	1

Client Sample ID: SJBH - 34 Sink

Lab Sample ID: 810-109396-33

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	2.3		0.50		ug/L			07/01/24 09:33	1

Client Sample ID: SJBH - 35 Sink

Lab Sample ID: 810-109396-34

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	11		0.50		ug/L			06/29/24 09:44	1

Client Sample ID: SJBH - 36 Sink

Lab Sample ID: 810-109396-35

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	16		0.50		ug/L			06/29/24 09:47	1

Eurofins Eaton Analytical South Bend

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 37 Sink

Lab Sample ID: 810-109396-36

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	10		0.50		ug/L			06/29/24 09:49	1

Client Sample ID: SJBH - 38 Sink

Lab Sample ID: 810-109396-37

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	11		0.50		ug/L			06/29/24 09:52	1

Client Sample ID: SJBH - 39 Sink

Lab Sample ID: 810-109396-38

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.7		0.50		ug/L			06/29/24 09:55	1

Client Sample ID: SJBH - 40 Sink

Lab Sample ID: 810-109396-39

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	2.3		0.50		ug/L			06/29/24 09:58	1

Client Sample ID: SJBH - 41 Sink

Lab Sample ID: 810-109396-40

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	8.1		0.50		ug/L			07/01/24 09:35	1

Client Sample ID: SJBH - 42 Sink

Lab Sample ID: 810-109396-41

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	3.0		0.50		ug/L			06/29/24 10:23	1

Client Sample ID: SJBH - 43 Sink

Lab Sample ID: 810-109396-42

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	3.0		0.50		ug/L			06/29/24 10:26	1

Eurofins Eaton Analytical South Bend

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 44 Sink

Lab Sample ID: 810-109396-43

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	3.3		0.50		ug/L			06/29/24 10:34	1

Client Sample ID: SJBH - 45 Sink

Lab Sample ID: 810-109396-44

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	5.7		0.50		ug/L			06/29/24 10:37	1

Client Sample ID: SJBH - 46 Sink

Lab Sample ID: 810-109396-45

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	3.4		0.50		ug/L			06/29/24 10:40	1

Client Sample ID: SJBH - 47 WF

Lab Sample ID: 810-109396-46

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	2.5		0.50		ug/L			06/29/24 10:43	1

Client Sample ID: SJBH - 48 Sink

Lab Sample ID: 810-109396-47

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	130		0.50		ug/L			06/29/24 10:46	1

Client Sample ID: SJBH - 49 Sink

Lab Sample ID: 810-109396-48

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	8.8		0.50		ug/L			06/29/24 10:49	1

Client Sample ID: SJBH - 50 Sink

Lab Sample ID: 810-109396-49

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	29		0.50		ug/L			06/29/24 10:51	1

Eurofins Eaton Analytical South Bend

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 51 Sink

Lab Sample ID: 810-109396-50

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	9.7		0.50		ug/L			06/29/24 11:00	1

Client Sample ID: SJBH - 52 Sink

Lab Sample ID: 810-109396-51

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	5.5		0.50		ug/L			06/29/24 11:03	1

Client Sample ID: SJBH - 53 Hose Bib

Lab Sample ID: 810-109396-52

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.0		0.50		ug/L			06/29/24 11:05	1

Client Sample ID: SJBH - 54 ICE MACH

Lab Sample ID: 810-109396-53

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 11:08	1

Client Sample ID: SJBH - 55 WF

Lab Sample ID: 810-109396-54

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 11:17	1

Client Sample ID: SJBH - 56

Lab Sample ID: 810-109396-55

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Method: EPA 200.8 - Metals (ICP/MS) - Total Recoverable

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	45		0.50		ug/L		06/27/24 13:06	06/28/24 17:48	1

QC Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Method: 200.8 - Metals (ICP/MS)

Lab Sample ID: MB 810-104328/12

Matrix: Drinking Water

Analysis Batch: 104328

Client Sample ID: Method Blank

Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 09:11	1

Lab Sample ID: MB 810-104328/72

Matrix: Drinking Water

Analysis Batch: 104328

Client Sample ID: Method Blank

Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 11:11	1

Lab Sample ID: LCS 810-104328/73

Matrix: Drinking Water

Analysis Batch: 104328

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	50.0	47.1		ug/L		94	85 - 115

Lab Sample ID: LLCS 810-104328/11

Matrix: Drinking Water

Analysis Batch: 104328

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LLCS Result	LLCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	0.300	0.279	J	ug/L		93	50 - 150

Lab Sample ID: 810-109396-1 MS

Matrix: Drinking Water

Analysis Batch: 104328

Client Sample ID: SJBH - 1 ICE

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MS Result	MS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	<0.50		50.0	49.7		ug/L		99	70 - 130

Lab Sample ID: 810-109396-1 MSD

Matrix: Drinking Water

Analysis Batch: 104328

Client Sample ID: SJBH - 1 ICE

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MSD Result	MSD Qualifier	Unit	D	%Rec	%Rec Limits	RPD	RPD Limit
Lead	<0.50		50.0	51.6		ug/L		103	70 - 130	4	20

Lab Sample ID: MB 810-104364/12

Matrix: Drinking Water

Analysis Batch: 104364

Client Sample ID: Method Blank

Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 11:40	1

Lab Sample ID: MB 810-104364/132

Matrix: Drinking Water

Analysis Batch: 104364

Client Sample ID: Method Blank

Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/28/24 16:50	1

Eurofins Eaton Analytical South Bend

QC Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Method: 200.8 - Metals (ICP/MS)

Lab Sample ID: LCS 810-104364/133

Matrix: Drinking Water

Analysis Batch: 104364

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	50.0	48.1		ug/L		96	85 - 115

Lab Sample ID: LLCS 810-104364/11

Matrix: Drinking Water

Analysis Batch: 104364

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LLCS Result	LLCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	0.300	0.314	J	ug/L		105	50 - 150

Lab Sample ID: 810-109396-10 MS

Matrix: Drinking Water

Analysis Batch: 104364

Client Sample ID: SJBH - 10 WF

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MS Result	MS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	<0.50		50.0	50.9		ug/L		101	70 - 130

Lab Sample ID: 810-109396-10 MSD

Matrix: Drinking Water

Analysis Batch: 104364

Client Sample ID: SJBH - 10 WF

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MSD Result	MSD Qualifier	Unit	D	%Rec	%Rec Limits	RPD	RPD Limit
Lead	<0.50		50.0	51.1		ug/L		101	70 - 130	0	20

Lab Sample ID: MB 810-104372/12

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: Method Blank

Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 08:43	1

Lab Sample ID: MB 810-104372/45

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: Method Blank

Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			06/29/24 10:14	1

Lab Sample ID: LCS 810-104372/13

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	50.0	50.3		ug/L		101	85 - 115

Lab Sample ID: LCS 810-104372/46

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	50.0	49.5		ug/L		99	85 - 115

Eurofins Eaton Analytical South Bend

QC Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Method: 200.8 - Metals (ICP/MS)

Lab Sample ID: LLCS 810-104372/11

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte			Spike Added	LLCS Result	LLCS Qualifier	Unit	D	%Rec	%Rec Limits		
Lead			0.300	0.299	J	ug/L		100	50 - 150		

Lab Sample ID: 810-109396-20 MS

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: SJBH - 20 Sink

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MS Result	MS Qualifier	Unit	D	%Rec	%Rec Limits		
Lead	<0.50		50.0	51.1		ug/L		102	70 - 130		

Lab Sample ID: 810-109396-20 MSD

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: SJBH - 20 Sink

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MSD Result	MSD Qualifier	Unit	D	%Rec	%Rec Limits	RPD	RPD Limit
Lead	<0.50		50.0	51.8		ug/L		103	70 - 130	1	20

Lab Sample ID: 810-109396-31 MS

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: SJBH - 32 Sink

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MS Result	MS Qualifier	Unit	D	%Rec	%Rec Limits		
Lead	5.2		50.0	52.7		ug/L		95	70 - 130		

Lab Sample ID: 810-109396-31 MSD

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: SJBH - 32 Sink

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MSD Result	MSD Qualifier	Unit	D	%Rec	%Rec Limits	RPD	RPD Limit
Lead	5.2		50.0	52.4		ug/L		94	70 - 130	1	20

Lab Sample ID: 810-109396-42 MS

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: SJBH - 43 Sink

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MS Result	MS Qualifier	Unit	D	%Rec	%Rec Limits		
Lead	3.0		50.0	52.0		ug/L		98	70 - 130		

Lab Sample ID: 810-109396-42 MSD

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: SJBH - 43 Sink

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MSD Result	MSD Qualifier	Unit	D	%Rec	%Rec Limits	RPD	RPD Limit
Lead	3.0		50.0	51.5		ug/L		97	70 - 130	1	20

Lab Sample ID: 810-109396-53 MS

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: SJBH - 54 ICE MACH

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MS Result	MS Qualifier	Unit	D	%Rec	%Rec Limits		
Lead	<0.50		50.0	47.5		ug/L		94	70 - 130		

Eurofins Eaton Analytical South Bend

QC Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Method: 200.8 - Metals (ICP/MS)

Lab Sample ID: 810-109396-53 MSD

Matrix: Drinking Water

Analysis Batch: 104372

Client Sample ID: SJBH - 54 ICE MACH

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MSD Result	MSD Qualifier	Unit	D	%Rec	%Rec Limits	RPD	RPD Limit
Lead	<0.50		50.0	48.2		ug/L		96	70 - 130	1	20

Lab Sample ID: MB 810-104482/11

Matrix: Drinking Water

Analysis Batch: 104482

Client Sample ID: Method Blank

Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			07/01/24 09:27	1

Lab Sample ID: LCS 810-104482/12

Matrix: Drinking Water

Analysis Batch: 104482

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	50.0	50.1		ug/L		100	85 - 115

Lab Sample ID: LLCS 810-104482/10

Matrix: Drinking Water

Analysis Batch: 104482

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LLCS Result	LLCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	0.300	0.297	J	ug/L		99	50 - 150

Lab Sample ID: MB 810-104187/1-A

Matrix: Drinking Water

Analysis Batch: 104362

Client Sample ID: Method Blank

Prep Type: Total Recoverable

Prep Batch: 104187

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L		06/27/24 13:06	06/28/24 16:34	1

Lab Sample ID: LCS 810-104187/6-A

Matrix: Drinking Water

Analysis Batch: 104362

Client Sample ID: Lab Control Sample

Prep Type: Total Recoverable

Prep Batch: 104187

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	50.0	54.3		ug/L		109	85 - 115

Lab Sample ID: LLCS 810-104187/2-A

Matrix: Drinking Water

Analysis Batch: 104362

Client Sample ID: Lab Control Sample

Prep Type: Total Recoverable

Prep Batch: 104187

Analyte	Spike Added	LLCS Result	LLCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	0.300	0.335	J	ug/L		112	50 - 150

QC Association Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Metals

Prep Batch: 104187

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-109396-55	SJBH - 56	Total Recoverable	Drinking Water	200.8	
MB 810-104187/1-A	Method Blank	Total Recoverable	Drinking Water	200.8	
LCS 810-104187/6-A	Lab Control Sample	Total Recoverable	Drinking Water	200.8	
LLCS 810-104187/2-A	Lab Control Sample	Total Recoverable	Drinking Water	200.8	

Analysis Batch: 104328

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-109396-1	SJBH - 1 ICE	Total/NA	Drinking Water	200.8	
810-109396-2	SJBH - 2 Sink	Total/NA	Drinking Water	200.8	
810-109396-3	SJBH - 3 Sink	Total/NA	Drinking Water	200.8	
810-109396-4	SJBH - 4 Sink	Total/NA	Drinking Water	200.8	
810-109396-5	SJBH - 5 Sink	Total/NA	Drinking Water	200.8	
810-109396-6	SJBH - 6 Sink	Total/NA	Drinking Water	200.8	
MB 810-104328/12	Method Blank	Total/NA	Drinking Water	200.8	
MB 810-104328/72	Method Blank	Total/NA	Drinking Water	200.8	
LCS 810-104328/73	Lab Control Sample	Total/NA	Drinking Water	200.8	
LLCS 810-104328/11	Lab Control Sample	Total/NA	Drinking Water	200.8	
810-109396-1 MS	SJBH - 1 ICE	Total/NA	Drinking Water	200.8	
810-109396-1 MSD	SJBH - 1 ICE	Total/NA	Drinking Water	200.8	

Analysis Batch: 104362

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-109396-55	SJBH - 56	Total Recoverable	Drinking Water	200.8	104187
MB 810-104187/1-A	Method Blank	Total Recoverable	Drinking Water	200.8	104187
LCS 810-104187/6-A	Lab Control Sample	Total Recoverable	Drinking Water	200.8	104187
LLCS 810-104187/2-A	Lab Control Sample	Total Recoverable	Drinking Water	200.8	104187

Analysis Batch: 104364

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-109396-7	SJBH - 7 Sink	Total/NA	Drinking Water	200.8	
810-109396-8	SJBH - 8 WF	Total/NA	Drinking Water	200.8	
810-109396-9	SJBH - 9 WF	Total/NA	Drinking Water	200.8	
810-109396-10	SJBH - 10 WF	Total/NA	Drinking Water	200.8	
810-109396-11	SJBH - 11 WF	Total/NA	Drinking Water	200.8	
810-109396-12	SJBH - 12 WF	Total/NA	Drinking Water	200.8	
810-109396-13	SJBH - 13 Sink	Total/NA	Drinking Water	200.8	
810-109396-14	SJBH - 14 ICE	Total/NA	Drinking Water	200.8	
810-109396-15	SJBH - 15 Sink	Total/NA	Drinking Water	200.8	
810-109396-16	SJBH - 16 WF	Total/NA	Drinking Water	200.8	
810-109396-17	SJBH - 17 WF	Total/NA	Drinking Water	200.8	
810-109396-18	SJBH - 18 WF	Total/NA	Drinking Water	200.8	
810-109396-19	SJBH - 19 Sink	Total/NA	Drinking Water	200.8	
MB 810-104364/12	Method Blank	Total/NA	Drinking Water	200.8	
MB 810-104364/132	Method Blank	Total/NA	Drinking Water	200.8	
LCS 810-104364/133	Lab Control Sample	Total/NA	Drinking Water	200.8	
LLCS 810-104364/11	Lab Control Sample	Total/NA	Drinking Water	200.8	
810-109396-10 MS	SJBH - 10 WF	Total/NA	Drinking Water	200.8	
810-109396-10 MSD	SJBH - 10 WF	Total/NA	Drinking Water	200.8	

QC Association Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Metals

Analysis Batch: 104372

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-109396-20	SJBH - 20 Sink	Total/NA	Drinking Water	200.8	
810-109396-21	SJBH - 21 Sink	Total/NA	Drinking Water	200.8	
810-109396-22	SJBH - 22 Sink	Total/NA	Drinking Water	200.8	
810-109396-23	SJBH - 23 Sink	Total/NA	Drinking Water	200.8	
810-109396-24	SJBH - 24 Sink	Total/NA	Drinking Water	200.8	
810-109396-25	SJBH - 25 Sink	Total/NA	Drinking Water	200.8	
810-109396-26	SJBH - 26 WF	Total/NA	Drinking Water	200.8	
810-109396-27	SJBH - 27 Sink	Total/NA	Drinking Water	200.8	
810-109396-28	SJBH - 28 Sink	Total/NA	Drinking Water	200.8	
810-109396-29	SJBH - 29 WF	Total/NA	Drinking Water	200.8	
810-109396-30	SJBH - 30 Sink	Total/NA	Drinking Water	200.8	
810-109396-31	SJBH - 32 Sink	Total/NA	Drinking Water	200.8	
810-109396-32	SJBH - 33 WF	Total/NA	Drinking Water	200.8	
810-109396-34	SJBH - 35 Sink	Total/NA	Drinking Water	200.8	
810-109396-35	SJBH - 36 Sink	Total/NA	Drinking Water	200.8	
810-109396-36	SJBH - 37 Sink	Total/NA	Drinking Water	200.8	
810-109396-37	SJBH - 38 Sink	Total/NA	Drinking Water	200.8	
810-109396-38	SJBH - 39 Sink	Total/NA	Drinking Water	200.8	
810-109396-39	SJBH - 40 Sink	Total/NA	Drinking Water	200.8	
810-109396-41	SJBH - 42 Sink	Total/NA	Drinking Water	200.8	
810-109396-42	SJBH - 43 Sink	Total/NA	Drinking Water	200.8	
810-109396-43	SJBH - 44 Sink	Total/NA	Drinking Water	200.8	
810-109396-44	SJBH - 45 Sink	Total/NA	Drinking Water	200.8	
810-109396-45	SJBH - 46 Sink	Total/NA	Drinking Water	200.8	
810-109396-46	SJBH - 47 WF	Total/NA	Drinking Water	200.8	
810-109396-47	SJBH - 48 Sink	Total/NA	Drinking Water	200.8	
810-109396-48	SJBH - 49 Sink	Total/NA	Drinking Water	200.8	
810-109396-49	SJBH - 50 Sink	Total/NA	Drinking Water	200.8	
810-109396-50	SJBH - 51 Sink	Total/NA	Drinking Water	200.8	
810-109396-51	SJBH - 52 Sink	Total/NA	Drinking Water	200.8	
810-109396-52	SJBH - 53 Hose Bib	Total/NA	Drinking Water	200.8	
810-109396-53	SJBH - 54 ICE MACH	Total/NA	Drinking Water	200.8	
810-109396-54	SJBH - 55 WF	Total/NA	Drinking Water	200.8	
MB 810-104372/12	Method Blank	Total/NA	Drinking Water	200.8	
MB 810-104372/45	Method Blank	Total/NA	Drinking Water	200.8	
LCS 810-104372/13	Lab Control Sample	Total/NA	Drinking Water	200.8	
LCS 810-104372/46	Lab Control Sample	Total/NA	Drinking Water	200.8	
LLCS 810-104372/11	Lab Control Sample	Total/NA	Drinking Water	200.8	
810-109396-20 MS	SJBH - 20 Sink	Total/NA	Drinking Water	200.8	
810-109396-20 MSD	SJBH - 20 Sink	Total/NA	Drinking Water	200.8	
810-109396-31 MS	SJBH - 32 Sink	Total/NA	Drinking Water	200.8	
810-109396-31 MSD	SJBH - 32 Sink	Total/NA	Drinking Water	200.8	
810-109396-42 MS	SJBH - 43 Sink	Total/NA	Drinking Water	200.8	
810-109396-42 MSD	SJBH - 43 Sink	Total/NA	Drinking Water	200.8	
810-109396-53 MS	SJBH - 54 ICE MACH	Total/NA	Drinking Water	200.8	
810-109396-53 MSD	SJBH - 54 ICE MACH	Total/NA	Drinking Water	200.8	

Analysis Batch: 104482

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-109396-33	SJBH - 34 Sink	Total/NA	Drinking Water	200.8	
810-109396-40	SJBH - 41 Sink	Total/NA	Drinking Water	200.8	

Eurofins Eaton Analytical South Bend

QC Association Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Metals (Continued)

Analysis Batch: 104482 (Continued)

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
MB 810-104482/11	Method Blank	Total/NA	Drinking Water	200.8	
LCS 810-104482/12	Lab Control Sample	Total/NA	Drinking Water	200.8	
LLCS 810-104482/10	Lab Control Sample	Total/NA	Drinking Water	200.8	

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 1 ICE

Lab Sample ID: 810-109396-1

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104328	CA	EA SB	06/28/24 11:23

Client Sample ID: SJBH - 2 Sink

Lab Sample ID: 810-109396-2

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104328	CA	EA SB	06/28/24 11:29

Client Sample ID: SJBH - 3 Sink

Lab Sample ID: 810-109396-3

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104328	CA	EA SB	06/28/24 11:31

Client Sample ID: SJBH - 4 Sink

Lab Sample ID: 810-109396-4

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104328	CA	EA SB	06/28/24 11:33

Client Sample ID: SJBH - 5 Sink

Lab Sample ID: 810-109396-5

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104328	CA	EA SB	06/28/24 11:35

Client Sample ID: SJBH - 6 Sink

Lab Sample ID: 810-109396-6

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104328	CA	EA SB	06/28/24 11:37

Client Sample ID: SJBH - 7 Sink

Lab Sample ID: 810-109396-7

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104364	NB	EA SB	06/28/24 17:18

Eurofins Eaton Analytical South Bend

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 8 WF

Lab Sample ID: 810-109396-8

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104364	NB	EA SB	06/28/24 17:21

Client Sample ID: SJBH - 9 WF

Lab Sample ID: 810-109396-9

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104364	NB	EA SB	06/28/24 17:23

Client Sample ID: SJBH - 10 WF

Lab Sample ID: 810-109396-10

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104364	NB	EA SB	06/28/24 17:31

Client Sample ID: SJBH - 11 WF

Lab Sample ID: 810-109396-11

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104364	NB	EA SB	06/28/24 17:39

Client Sample ID: SJBH - 12 WF

Lab Sample ID: 810-109396-12

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104364	NB	EA SB	06/28/24 17:42

Client Sample ID: SJBH - 13 Sink

Lab Sample ID: 810-109396-13

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104364	NB	EA SB	06/28/24 17:44

Client Sample ID: SJBH - 14 ICE

Lab Sample ID: 810-109396-14

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104364	NB	EA SB	06/28/24 17:47

Eurofins Eaton Analytical South Bend

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 15 Sink

Lab Sample ID: 810-109396-15

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104364	NB	EA SB	06/28/24 17:49

Client Sample ID: SJBH - 16 WF

Lab Sample ID: 810-109396-16

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104364	NB	EA SB	06/28/24 17:52

Client Sample ID: SJBH - 17 WF

Lab Sample ID: 810-109396-17

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104364	NB	EA SB	06/28/24 17:54

Client Sample ID: SJBH - 18 WF

Lab Sample ID: 810-109396-18

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104364	NB	EA SB	06/28/24 17:57

Client Sample ID: SJBH - 19 Sink

Lab Sample ID: 810-109396-19

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104364	NB	EA SB	06/28/24 18:00

Client Sample ID: SJBH - 20 Sink

Lab Sample ID: 810-109396-20

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 08:48

Client Sample ID: SJBH - 21 Sink

Lab Sample ID: 810-109396-21

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 08:56

Eurofins Eaton Analytical South Bend

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 22 Sink

Lab Sample ID: 810-109396-22

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 08:59

Client Sample ID: SJBH - 23 Sink

Lab Sample ID: 810-109396-23

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 09:02

Client Sample ID: SJBH - 24 Sink

Lab Sample ID: 810-109396-24

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 09:05

Client Sample ID: SJBH - 25 Sink

Lab Sample ID: 810-109396-25

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 09:07

Client Sample ID: SJBH - 26 WF

Lab Sample ID: 810-109396-26

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 09:10

Client Sample ID: SJBH - 27 Sink

Lab Sample ID: 810-109396-27

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 09:13

Client Sample ID: SJBH - 28 Sink

Lab Sample ID: 810-109396-28

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 09:16

Eurofins Eaton Analytical South Bend

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 29 WF

Lab Sample ID: 810-109396-29

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 09:19

Client Sample ID: SJBH - 30 Sink

Lab Sample ID: 810-109396-30

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 10:06

Client Sample ID: SJBH - 32 Sink

Lab Sample ID: 810-109396-31

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 09:30

Client Sample ID: SJBH - 33 WF

Lab Sample ID: 810-109396-32

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 09:38

Client Sample ID: SJBH - 34 Sink

Lab Sample ID: 810-109396-33

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104482	CA	EA SB	07/01/24 09:33

Client Sample ID: SJBH - 35 Sink

Lab Sample ID: 810-109396-34

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 09:44

Client Sample ID: SJBH - 36 Sink

Lab Sample ID: 810-109396-35

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 09:47

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 37 Sink

Lab Sample ID: 810-109396-36

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 09:49

Client Sample ID: SJBH - 38 Sink

Lab Sample ID: 810-109396-37

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 09:52

Client Sample ID: SJBH - 39 Sink

Lab Sample ID: 810-109396-38

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 09:55

Client Sample ID: SJBH - 40 Sink

Lab Sample ID: 810-109396-39

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 09:58

Client Sample ID: SJBH - 41 Sink

Lab Sample ID: 810-109396-40

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104482	CA	EA SB	07/01/24 09:35

Client Sample ID: SJBH - 42 Sink

Lab Sample ID: 810-109396-41

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 10:23

Client Sample ID: SJBH - 43 Sink

Lab Sample ID: 810-109396-42

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 10:26

Eurofins Eaton Analytical South Bend

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 44 Sink

Lab Sample ID: 810-109396-43

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 10:34

Client Sample ID: SJBH - 45 Sink

Lab Sample ID: 810-109396-44

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 10:37

Client Sample ID: SJBH - 46 Sink

Lab Sample ID: 810-109396-45

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 10:40

Client Sample ID: SJBH - 47 WF

Lab Sample ID: 810-109396-46

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 10:43

Client Sample ID: SJBH - 48 Sink

Lab Sample ID: 810-109396-47

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 10:46

Client Sample ID: SJBH - 49 Sink

Lab Sample ID: 810-109396-48

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 10:49

Client Sample ID: SJBH - 50 Sink

Lab Sample ID: 810-109396-49

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 10:51

Eurofins Eaton Analytical South Bend

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Client Sample ID: SJBH - 51 Sink

Lab Sample ID: 810-109396-50

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 11:00

Client Sample ID: SJBH - 52 Sink

Lab Sample ID: 810-109396-51

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 11:03

Client Sample ID: SJBH - 53 Hose Bib

Lab Sample ID: 810-109396-52

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 11:05

Client Sample ID: SJBH - 54 ICE MACH

Lab Sample ID: 810-109396-53

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 11:08

Client Sample ID: SJBH - 55 WF

Lab Sample ID: 810-109396-54

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	104372	CA	EA SB	06/29/24 11:17

Client Sample ID: SJBH - 56

Lab Sample ID: 810-109396-55

Date Collected: 06/24/24 08:00

Matrix: Drinking Water

Date Received: 06/25/24 09:30

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total Recoverable	Prep	200.8			104187	NB	EA SB	06/27/24 13:06
Total Recoverable	Analysis	200.8		1	104362	NB	EA SB	06/28/24 17:48

Laboratory References:

EA SB = Eurofins Eaton Analytical South Bend, 110 S Hill Street, South Bend, IN 46617, TEL (574)233-4777

Accreditation/Certification Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Laboratory: Eurofins Eaton Analytical South Bend

The accreditations/certifications listed below are applicable to this report.

Authority	Program	Identification Number	Expiration Date
Missouri	State	880	09-30-24

1
2
3
4
5
6
7
8
9
10
11
12
13
14

Method Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Method	Method Description	Protocol	Laboratory
200.8	Metals (ICP/MS)	EPA	EA SB
200.8	Preparation, Total Recoverable Metals	EPA	EA SB

Protocol References:

EPA = US Environmental Protection Agency

Laboratory References:

EA SB = Eurofins Eaton Analytical South Bend, 110 S Hill Street, South Bend, IN 46617, TEL (574)233-4777

Sample Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Lab Sample ID	Client Sample ID	Matrix	Collected	Received
810-109396-1	SJBH - 1 ICE	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-2	SJBH - 2 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-3	SJBH - 3 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-4	SJBH - 4 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-5	SJBH - 5 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-6	SJBH - 6 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-7	SJBH - 7 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-8	SJBH - 8 WF	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-9	SJBH - 9 WF	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-10	SJBH - 10 WF	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-11	SJBH - 11 WF	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-12	SJBH - 12 WF	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-13	SJBH - 13 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-14	SJBH - 14 ICE	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-15	SJBH - 15 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-16	SJBH - 16 WF	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-17	SJBH - 17 WF	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-18	SJBH - 18 WF	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-19	SJBH - 19 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-20	SJBH - 20 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-21	SJBH - 21 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-22	SJBH - 22 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-23	SJBH - 23 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-24	SJBH - 24 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-25	SJBH - 25 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-26	SJBH - 26 WF	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-27	SJBH - 27 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-28	SJBH - 28 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-29	SJBH - 29 WF	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-30	SJBH - 30 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-31	SJBH - 32 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-32	SJBH - 33 WF	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-33	SJBH - 34 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-34	SJBH - 35 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-35	SJBH - 36 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-36	SJBH - 37 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-37	SJBH - 38 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-38	SJBH - 39 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-39	SJBH - 40 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-40	SJBH - 41 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-41	SJBH - 42 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-42	SJBH - 43 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-43	SJBH - 44 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-44	SJBH - 45 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-45	SJBH - 46 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-46	SJBH - 47 WF	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-47	SJBH - 48 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-48	SJBH - 49 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-49	SJBH - 50 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-50	SJBH - 51 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-51	SJBH - 52 Sink	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-52	SJBH - 53 Hose Bib	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-53	SJBH - 54 ICE MACH	Drinking Water	06/24/24 08:00	06/25/24 09:30
810-109396-54	SJBH - 55 WF	Drinking Water	06/24/24 08:00	06/25/24 09:30

Sample Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Benton High

Job ID: 810-109396-1

Lab Sample ID	Client Sample ID	Matrix	Collected	Received
810-109396-55	SJBH - 56	Drinking Water	06/24/24 08:00	06/25/24 09:30

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14

LUMINIS EATON ANALYTICAL: SOUTH BEND
110 South Hill Street
South Bend, IN 46617
Phone (574) 233-4777

Chain of Custody Record



Environment Testing
America

7/25

Client Information		Sampler: Ian St. John		Lab PM:	
Client Contact: Casey Housman		Phone: 314-853-4668		E-Mail: ian@stjohnenv.com	
Company: St. Joseph School District		Address: 1415 North 26th Street		City: St. Joseph	
State, Zip: Missouri 64506		Phone: 816-671-4000		Email: CaseyHousman@sjsd.k12.mo.us	
Project Name: St. Joseph School District		Site: Bendon High		SSOW#:	
Due Date Requested:		TAT Requested (days): Standard		Compliance Project: ☐ Yes ☒ No	
PO #:		WO #:		Project #:	
Sample Identification		Sample Date		Sample Time	
STBH-1 A/E		6/24/2024		G W	
STBH-2 Sink					
STBH-3 " "					
STBH-4 " "					
STBH-5 " "					
STBH-6 " "					
STBH-7 " "					
STBH-8 WF					
STBH-9 WF					
STBH-10 WF					
STBH-11 WF					
Possible Hazard Identification		☐ Non-Hazard ☐ Flammable ☐ Skin Irritant ☐ Poison B ☒ Unknown ☐ Radiological		Deliverable Requested: I, II, III, IV, Other (specify)	
Empty Kit Relinquished by:		Date:		Time:	
Relinquished by: <i>[Signature]</i>		Date/Time: April 14, 2024		Company	
Relinquished by:		Date/Time:		Company	
Relinquished by:		Date/Time:		Company	
Custody Seals Intact: ☐ Yes ☒ No		Custody Seal No.:		Cooler Temperature(s) °C and Other Remarks:	

Analysis Requested		Total Number of Containers		Special Instructions/Note:	
pH verified <2					
Preservation Codes:		A - HCL		M - Hexane	
B - NaOH		C - Zn Acetate		N - None	
D - Nitric Acid		E - NaHSO4		O - AsNaO2	
F - MeOH		G - Amchlor		P - Na2OAS	
H - Ascorbic Acid		I - Ice		Q - Na2SO3	
J - DI Water		K - EDTA		R - Na2SO4	
L - EDA		Other:		S - H2SO4	
				T - TSP Dodecahydrate	
				U - Acetone	
				V - MCAA	
				W - pH 4-5	
				Y - Trizma	
				Z - other (specify)	

Sample Disposal (A fee may be assessed if samples are retained longer than 1 month)

☐ Return To Client ☒ Disposal By Lab ☐ Archive For _____ Months

Special Instructions/QC Requirements:

Method of Shipment:

Date/Time: **6:25:24 4/25**

Company

Chain of Custody Record



Sampler: Ian St. John		Lab PIV:	Carrier Tracking No(s):		COC No:
Phone: 314-853-4668		E-Mail: ian@stjohnenv.com	State of Origin: MO		Page: 2 of 2
Company: Casey Housman		PWSID:	Job #:		
Address: St. Joseph School District		Analysis Requested			
City: 1415 North 26th Street		Due Date Requested:			
State, Zip: St. Joseph Missouri 64506		TAT Requested (days): Standard			
Phone: 816-671-4000		Compliance Project: ☐ Yes ☐ No			
Email: CaseyHousman@sjsd.k12.mo.us		PO #:			
Project Name: St. Joseph School District		WO #:			
Site: Benton High		Project #:			
SSOW#:		Sample Date: 6/24/2024			
Sample Identification		Sample Type (C=comp, G=grab)	Sample Time	Matrix (W=water, S=solid, O=other)	Field Filtered Sample (Yes or No)
STBH-12 WF		G	6/24/2024	W	
STBH-13 Snrk					
STBH-14 ICE					
STBH-15 Snrk					
STBH-16 WF					
STBH-17 WF					
STBH-18 WF					
STBH-19 Snrk					
STBH-20 " "					
STBH-21 " "					
STBH-22 " "					
Possible Hazard Identification		Preservation Code:			
☐ Non-Hazard ☐ Flammable ☐ Skin Irritant ☐ Poison B ☒ Unknown ☐ Radiological					
Deliverable Requested: I, II, III, IV, Other (specify)					
Empty Kit Relinquished by:		Date:			
Relinquished by: [Signature]		Date: April 14, 2024			
Relinquished by:		Date:			
Relinquished by:		Date:			
Custody Seals Intact: ☐ Yes ☐ No		Custody Seal No.:			

PH verified 42

Ab In Drinking Water

Special Instructions/Note:

Sample Disposal (A fee may be assessed if samples are retained longer than 1 month)

☐ Return To Client ☒ Disposal By Lab ☐ Archive For _____ Months

Special Instructions/QC Requirements:

Method of Shipment:

Date/Time: 11:35:24 430

Company:

Date/Time:

Company:

Date/Time:

Company:

Cooler Temperature(s) °C and Other Remarks:

Phone (574) 233-4777 Client Information Client Contact: Casey Housman Company: St. Joseph School District Address: 1415 North 26th Street City: St. Joseph State, Zip: Missouri 64506 Phone: 816-671-4000 Email: CaseyHousman@sjsd.k12.mo.us Project Name: St. Joseph School District Site: <u>Benton High</u>		Lab PM: Ian St. John Phone: 314-853-4668 E-Mail: ian@stjohnenv.com State of Origin: MO Page 3 of 3 Job #:	
Due Date Requested: TAT Requested (days): Standard Compliance Project: ☐ Yes ☒ No PO #: WO #: Project #: SSOW #:		Carrier Tracking No(s): State of Origin: MO Page 3 of 3 Job #:	
Analysis Requested pH verified <2 Total Number of containers:		Preservation Codes: A - HCL B - NaOH C - Zn Acetate D - Nitric Acid E - NaHSO4 F - MeOH G - Amchlor H - Ascorbic Acid I - Ice J - DI Water K - EDTA L - EDA Other:	
Special Instructions/Note: No Leaking Water		Special Instructions/Note: No Leaking Water	
Sample Identification SJ BH-23 Sink SJ BH-24 Sink SJ BH-25 Sink SJ BH-26 W/F SJ BH-27 Sink SJ BH-28 Sink SJ BH-29 W/F SJ BH-30 Sink SJ BH-31 Sink SJ BH-32 Sink SJ BH-33 W/F		Sample Date 6/24/2020 Sample Time 10:00 Sample Type G-grab Matrix W-water, S-solid, O-ore, A-ash, L-leachate, N-nitrate, A-air	
Possible Hazard Identification ☐ Non-Hazard ☐ Flammable ☐ Skin Irritant ☐ Poison B ☒ Unknown ☐ Radiological		Sample Disposal (A fee may be assessed if samples are retained longer than 1 month) ☐ Return To Client ☒ Disposal By Lab ☐ Archive For _____ Months	
Deliverable Requested: I, II, III, IV, Other (specify)		Special Instructions/QC Requirements:	
Empty Kit Relinquished by: Relinquished by: <u>Chad Johnson</u> Relinquished by:		Method of Shipment: Date/Time: <u>6/25/20 9:30</u> Date/Time:	
Custody Seal No.: A Yes ☐ No ☐		Cooler Temperature(s) °C and Other Remarks:	

Chain of Custody Record

Client Information

Client Contact: Casey Housman

Company: St. Joseph School District

Address: 1415 North 26th Street

City: St. Joseph

State, Zip: Missouri 64506

Phone: 816-671-4000

Email: CaseyHousman@sjsd.k12.mo.us

Project Name: St. Joseph School District

Site: Benton Hg

Sampler: Ian St. John

Phone: 314-853-4668

E-Mail: ian@stjohnenv.com

State of Origin: MO

COC No:

Page: 1 of 1

Job #:

Due Date Requested:

TAT Requested (days): Standard

Compliance Project: ☐ Yes ☒ No

PO #:

WO #:

Project #:

SSOW#:

Analysis Requested

pH verified <2

B In Drinking Water

Preservation Codes:

- A - HCL
- B - NaOH
- C - Zn Acetate
- D - Nitric Acid
- E - NaHSO4
- F - MeOH
- G - Amchlor
- H - Ascorbic Acid
- I - Ice
- J - DI Water
- K - EDTA
- L - EDA
- Other:
- M - Hexane
- N - None
- O - AsNaO2
- P - Na2O4S
- Q - Na2SO3
- R - Na2SO4
- S - H2SO4
- T - TSP Dodecahydrate
- U - Acetone
- V - MCAA
- W - pH 4-5
- Y - Trizma
- Z - other (specify)

Sample Identification

SJBH-34 Sink
SJBH-35 " "
SJBH-36 " "
SJBH-37 " "
SJBH-38 " "
SJBH-39 " "
SJBH-40 " "
SJBH-41 " "
SJBH-42 " "
SJBH-43 " "
SJBH-44 " "

Sample Date

Sample Time

Sample Type (C=Comp, G=grab)

Matrix (W=water, S=solid, O=other)

Preservation Code: W

Total Number of containers

Special Instructions/Note:

Possible Hazard Identification

☐ Non-Hazard ☐ Flammable ☐ Skin Irritant ☐ Poison B ☒ Unknown ☐ Radiological

Sample Disposal (A fee may be assessed if samples are retained longer than 1 month)

☐ Return To Client ☒ Disposal By Lab ☐ Archive For _____ Months

Special Instructions/QC Requirements:

Empty Kit Relinquished by:

Relinquished by:

Relinquished by:

Relinquished by:

Date:

Date/Time: April 14, 2024

Company

Received by:

Date/Time: 4/15/24 4:30

Company

Method of Shipment:

Custody Seal No.: ☐ Yes ☒ No

Cooler Temperature(s) °C and Other Remarks:

Eurofins Eaton Analytical: South Bend
110 South Hill Street
South Bend, IN 46617
Phone (574) 233-4777

Chain of Custody Record



Environment Testing
America

Client Information		Sampler: Ian St. John		Lab PM:		Carrier Tracking No(s):		COC No:	
Client Contact: Casey Housman		Phone: 314-853-4668		E-Mail: ian@stjohnenv.com		State of Origin: MO		Page: 5 of 5	
Company: St. Joseph School District		PWSID:		Analysis Requested		Job #:		Preservation Codes:	
Address: 1415 North 26th Street		Due Date Requested:		TAT Requested (days): Standard		Compliance Project: Δ Yes Δ No		A - HCL M - Hexane N - None O - AsNaO2 P - Na2CO3 Q - Na2SO3 R - NaHSO4 S - H2SO4 T - TSP Dodecahydrate U - Acetone V - MCAA W - pH 4-5 Y - Trizma Z - other (specify)	
City: St. Joseph		PO #:		WO #:		Project #:		Other:	
State, Zip: Missouri 64506		SSOW#:		Sample Date		Sample Time		Sample Type (C=comp, G=grab)	
Phone: 816-671-4000		Matrix (W=water, S=solid, O=soil)		Field Filtered Sample (Yes or No)		Preservation Code:		Special Instructions/Note:	
Email: CaseyHousman@sisd.k12.mo.us		Sample Date		Sample Time		Sample Type (C=comp, G=grab)		Matrix (W=water, S=solid, O=soil)	
Project Name: St. Joseph School District		Sample Date		Sample Time		Sample Type (C=comp, G=grab)		Matrix (W=water, S=solid, O=soil)	
Site: Benton High		Sample Date		Sample Time		Sample Type (C=comp, G=grab)		Matrix (W=water, S=solid, O=soil)	
Sample Identification		Sample Date		Sample Time		Sample Type (C=comp, G=grab)		Matrix (W=water, S=solid, O=soil)	
ST BH-45 Sink		6/24/24 0800		G		W			
ST BH-46 Sink									
ST BH-47 WF									
ST BH-48 Sink									
ST BH-49 Sink									
ST BH-50 Sink									
ST BH-51 - Sink									
ST BH-52 Sink									
ST BH-53 HOSE P1B									
ST BH-54 10E MACH									
ST BH-55 WF									
Possible Hazard Identification		Unknown		Radiological		Poison B		Skin Irritant	
Deliverable Requested: I, II, III, IV, Other (specify)		Flammable		Non-Hazard		Flammable		Non-Hazard	
Empty Kit Relinquished by:		Date:		Time:		Method of Shipment:		Company	
Relinquished by: [Signature]		April 14, 2024						Company	
Relinquished by:		Date/Time:		Date/Time:		Date/Time:		Company	
Relinquished by:		Date/Time:		Date/Time:		Date/Time:		Company	
Custody Seals Intact: Δ Yes Δ No		Custody Seal No.:		Cooler Temperature(s) °C and Other Remarks:					

[illegible]

Login Sample Receipt Checklist

Client: St. John Environmental Consulting

Job Number: 810-109396-1

Login Number: 109396

List Source: Eurofins Eaton Analytical South Bend

List Number: 1

Creator: Alfred, Robbin

Question	Answer	Comment
The cooler's custody seal, if present, is intact.	True	
Sample custody seals, if present, are intact.	True	
Samples were received on ice.	False	Thermal preservation not required.
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	False	Thermal preservation not required.
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	True	
Samples do not require splitting or compositing.	True	
Container provided by EEA	True	