

ANALYTICAL REPORT

PREPARED FOR

Attn: Ian St. John
St. John Environmental Consulting
5515 Grace Ave.
Saint Louis, Missouri 63116

Generated 8/15/2024 10:28:23 AM

JOB DESCRIPTION

St. Joseph School District - Spring Garden

JOB NUMBER

810-114632-1

Eurofins Eaton Analytical South Bend

Job Notes

This report may not be reproduced except in full, and with written approval from the laboratory. The results relate only to the samples tested. For questions please contact the Project Manager at the e-mail address or telephone number listed on this page.

The test results in this report relate only to the samples as received by the laboratory and will meet all requirements of the methodology, with any exceptions noted. This report shall not be reproduced except in full, without the express written approval of the laboratory. All questions should be directed to the Eurofins Eaton Analytical, LLC Project Manager.

Authorization



Generated
8/15/2024 10:28:23 AM

Authorized for release by
Pamela Brown, Project Manager
Pamela.Brown@et.eurofinsus.com
(574)233-4777

Table of Contents

Cover Page	1
Table of Contents	3
Definitions/Glossary	4
Case Narrative	5
Detection Summary	6
Client Sample Results	8
QC Sample Results	11
QC Association Summary	14
Lab Chronicle	16
Certification Summary	19
Method Summary	20
Sample Summary	21
Chain of Custody	22
Receipt Checklists	24



Definitions/Glossary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Qualifiers

Metals

Qualifier	Qualifier Description
J	Result is less than the RL but greater than or equal to the MDL and the concentration is an approximate value.

Glossary

Abbreviation	These commonly used abbreviations may or may not be present in this report.
α	Listed under the "D" column to designate that the result is reported on a dry weight basis
%R	Percent Recovery
CFL	Contains Free Liquid
CFU	Colony Forming Unit
CNF	Contains No Free Liquid
DER	Duplicate Error Ratio (normalized absolute difference)
Dil Fac	Dilution Factor
DL	Detection Limit (DoD/DOE)
DL, RA, RE, IN	Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample
DLC	Decision Level Concentration (Radiochemistry)
EDL	Estimated Detection Limit (Dioxin)
LOD	Limit of Detection (DoD/DOE)
LOQ	Limit of Quantitation (DoD/DOE)
MCL	EPA recommended "Maximum Contaminant Level"
MDA	Minimum Detectable Activity (Radiochemistry)
MDC	Minimum Detectable Concentration (Radiochemistry)
MDL	Method Detection Limit
ML	Minimum Level (Dioxin)
MPN	Most Probable Number
MQL	Method Quantitation Limit
NC	Not Calculated
ND	Not Detected at the reporting limit (or MDL or EDL if shown)
NEG	Negative / Absent
POS	Positive / Present
PQL	Practical Quantitation Limit
PRES	Presumptive
QC	Quality Control
RER	Relative Error Ratio (Radiochemistry)
RL	Reporting Limit or Requested Limit (Radiochemistry)
RPD	Relative Percent Difference, a measure of the relative difference between two points
TEF	Toxicity Equivalent Factor (Dioxin)
TEQ	Toxicity Equivalent Quotient (Dioxin)
TNTC	Too Numerous To Count

Case Narrative

Client: St. John Environmental Consulting
Project: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Job ID: 810-114632-1

Eurofins Eaton Analytical South Bend

Job Narrative 810-114632-1

Analytical test results meet all requirements of the associated regulatory program listed on the Accreditation/Certification Summary Page unless otherwise noted under the individual analysis. Data qualifiers and/or narrative comments are included to explain any exceptions, if applicable.

- Matrix QC may not be reported if insufficient sample is provided or site-specific QC samples were not submitted. In these situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD may be performed, unless otherwise specified in the method.
- Surrogate and/or isotope dilution analyte recoveries (if applicable) which are outside of the QC window are confirmed unless attributed to a dilution or otherwise noted in the narrative.

Regulated compliance samples (e.g. SDWA, NPDES) must comply with the associated agency requirements/permits.

Receipt

The samples were received on 8/5/2024 9:15 AM. Unless otherwise noted below, the samples arrived in good condition, and, where required, properly preserved and on ice.

Metals

No additional analytical or quality issues were noted, other than those described above or in the Definitions/ Glossary page.

Eurofins Eaton Analytical South Bend

Detection Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Client Sample ID: SJSG-3 Sink

Lab Sample ID: 810-114632-1

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	2.0		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-4 Sink

Lab Sample ID: 810-114632-2

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	3.4		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-5 Sink

Lab Sample ID: 810-114632-3

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	15		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-6 Sink

Lab Sample ID: 810-114632-4

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	36		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-7 Bubbler

Lab Sample ID: 810-114632-5

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	11		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-9 Sink

Lab Sample ID: 810-114632-6

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	8.4		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-10 Bubbler

Lab Sample ID: 810-114632-7

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	5.5		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-11 Sink

Lab Sample ID: 810-114632-8

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	4.5		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-12 Sink

Lab Sample ID: 810-114632-9

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	3.2		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-13 Sink

Lab Sample ID: 810-114632-10

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	3100		5.0		ug/L	10		200.8	Total Recoverable

Client Sample ID: SJSG-15 Sink

Lab Sample ID: 810-114632-11

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	24		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-16 Sink

Lab Sample ID: 810-114632-12

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	7.3		0.50		ug/L	1		200.8	Total/NA

This Detection Summary does not include radiochemical test results.

Eurofins Eaton Analytical South Bend

Detection Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Client Sample ID: SJSG-17 Bubbler

Lab Sample ID: 810-114632-13

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	4.5		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-26 Sink

Lab Sample ID: 810-114632-14

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	1.3		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-27 Bubbler

Lab Sample ID: 810-114632-15

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	1.7		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-28 WF

Lab Sample ID: 810-114632-16

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	79		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-29 Sink

Lab Sample ID: 810-114632-17

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	5.7		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-30 Bubbler

Lab Sample ID: 810-114632-18

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	2.7		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-32 Sink

Lab Sample ID: 810-114632-19

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	10		0.50		ug/L	1		200.8	Total/NA

Client Sample ID: SJSG-34 Sink

Lab Sample ID: 810-114632-20

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Lead	2.8		0.50		ug/L	1		200.8	Total/NA

This Detection Summary does not include radiochemical test results.

Eurofins Eaton Analytical South Bend

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Client Sample ID: SJSG-3 Sink

Date Collected: 08/01/24 08:00

Date Received: 08/05/24 09:15

Lab Sample ID: 810-114632-1

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	2.0		0.50		ug/L			08/13/24 18:40	1

Client Sample ID: SJSG-4 Sink

Date Collected: 08/01/24 08:00

Date Received: 08/05/24 09:15

Lab Sample ID: 810-114632-2

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	3.4		0.50		ug/L			08/13/24 20:26	1

Client Sample ID: SJSG-5 Sink

Date Collected: 08/01/24 08:00

Date Received: 08/05/24 09:15

Lab Sample ID: 810-114632-3

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	15		0.50		ug/L			08/14/24 10:55	1

Client Sample ID: SJSG-6 Sink

Date Collected: 08/01/24 08:00

Date Received: 08/05/24 09:15

Lab Sample ID: 810-114632-4

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	36		0.50		ug/L			08/14/24 11:01	1

Client Sample ID: SJSG-7 Bubbler

Date Collected: 08/01/24 08:00

Date Received: 08/05/24 09:15

Lab Sample ID: 810-114632-5

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	11		0.50		ug/L			08/14/24 11:03	1

Client Sample ID: SJSG-9 Sink

Date Collected: 08/01/24 08:00

Date Received: 08/05/24 09:15

Lab Sample ID: 810-114632-6

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	8.4		0.50		ug/L			08/14/24 11:16	1

Client Sample ID: SJSG-10 Bubbler

Date Collected: 08/01/24 08:00

Date Received: 08/05/24 09:15

Lab Sample ID: 810-114632-7

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	5.5		0.50		ug/L			08/14/24 11:08	1

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Client Sample ID: SJSG-11 Sink

Date Collected: 08/01/24 08:00

Date Received: 08/05/24 09:15

Lab Sample ID: 810-114632-8

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	4.5		0.50		ug/L			08/14/24 11:10	1

Client Sample ID: SJSG-12 Sink

Date Collected: 08/01/24 08:00

Date Received: 08/05/24 09:15

Lab Sample ID: 810-114632-9

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	3.2		0.50		ug/L			08/14/24 20:12	1

Client Sample ID: SJSG-13 Sink

Date Collected: 08/01/24 08:00

Date Received: 08/05/24 09:15

Lab Sample ID: 810-114632-10

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS) - Total Recoverable

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	3100		5.0		ug/L		08/13/24 13:45	08/14/24 21:39	10

Client Sample ID: SJSG-15 Sink

Date Collected: 08/01/24 08:00

Date Received: 08/05/24 09:15

Lab Sample ID: 810-114632-11

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	24		0.50		ug/L			08/14/24 20:15	1

Client Sample ID: SJSG-16 Sink

Date Collected: 08/01/24 08:00

Date Received: 08/05/24 09:15

Lab Sample ID: 810-114632-12

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	7.3		0.50		ug/L			08/14/24 20:18	1

Client Sample ID: SJSG-17 Bubbler

Date Collected: 08/01/24 08:00

Date Received: 08/05/24 09:15

Lab Sample ID: 810-114632-13

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	4.5		0.50		ug/L			08/14/24 20:21	1

Client Sample ID: SJSG-26 Sink

Date Collected: 08/01/24 08:00

Date Received: 08/05/24 09:15

Lab Sample ID: 810-114632-14

Matrix: Drinking Water

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.3		0.50		ug/L			08/14/24 20:24	1

Eurofins Eaton Analytical South Bend

Client Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Client Sample ID: SJSG-27 Bubbler

Lab Sample ID: 810-114632-15

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	1.7		0.50		ug/L			08/14/24 20:27	1

Client Sample ID: SJSG-28 WF

Lab Sample ID: 810-114632-16

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	79		0.50		ug/L			08/14/24 20:35	1

Client Sample ID: SJSG-29 Sink

Lab Sample ID: 810-114632-17

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	5.7		0.50		ug/L			08/14/24 20:38	1

Client Sample ID: SJSG-30 Bubbler

Lab Sample ID: 810-114632-18

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	2.7		0.50		ug/L			08/14/24 20:41	1

Client Sample ID: SJSG-32 Sink

Lab Sample ID: 810-114632-19

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	10		0.50		ug/L			08/14/24 20:44	1

Client Sample ID: SJSG-34 Sink

Lab Sample ID: 810-114632-20

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Method: EPA 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	2.8		0.50		ug/L			08/14/24 20:52	1

QC Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Method: 200.8 - Metals (ICP/MS)

Lab Sample ID: MB 810-109915/12

Matrix: Drinking Water

Analysis Batch: 109915

Client Sample ID: Method Blank

Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			08/13/24 18:14	1

Lab Sample ID: LCS 810-109915/13

Matrix: Drinking Water

Analysis Batch: 109915

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	50.0	53.5		ug/L		107	85 - 115

Lab Sample ID: LLCS 810-109915/11

Matrix: Drinking Water

Analysis Batch: 109915

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LLCS Result	LLCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	0.300	0.333	J	ug/L		111	50 - 150

Lab Sample ID: MB 810-109917/14

Matrix: Drinking Water

Analysis Batch: 109917

Client Sample ID: Method Blank

Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			08/13/24 19:26	1

Lab Sample ID: LCS 810-109917/15

Matrix: Drinking Water

Analysis Batch: 109917

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	50.0	51.1		ug/L		102	85 - 115

Lab Sample ID: LLCS 810-109917/11

Matrix: Drinking Water

Analysis Batch: 109917

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LLCS Result	LLCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	0.300	0.330	J	ug/L		110	50 - 150

Lab Sample ID: MB 810-110034/13

Matrix: Drinking Water

Analysis Batch: 110034

Client Sample ID: Method Blank

Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			08/14/24 09:11	1

Lab Sample ID: MB 810-110034/43

Matrix: Drinking Water

Analysis Batch: 110034

Client Sample ID: Method Blank

Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			08/14/24 10:13	1

Eurofins Eaton Analytical South Bend

QC Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Method: 200.8 - Metals (ICP/MS)

Lab Sample ID: LCS 810-110034/44

Matrix: Drinking Water

Analysis Batch: 110034

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	50.0	51.4		ug/L		103	85 - 115

Lab Sample ID: LLCS 810-110034/11

Matrix: Drinking Water

Analysis Batch: 110034

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LLCS Result	LLCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	0.300	0.332	J	ug/L		111	50 - 150

Lab Sample ID: 810-114632-3 MS

Matrix: Drinking Water

Analysis Batch: 110034

Client Sample ID: SJSG-5 Sink

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MS Result	MS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	15		50.0	70.1		ug/L		110	70 - 130

Lab Sample ID: 810-114632-3 MSD

Matrix: Drinking Water

Analysis Batch: 110034

Client Sample ID: SJSG-5 Sink

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MSD Result	MSD Qualifier	Unit	D	%Rec	%Rec Limits	RPD	RPD Limit
Lead	15		50.0	70.4		ug/L		111	70 - 130	0	20

Lab Sample ID: MB 810-110143/11

Matrix: Drinking Water

Analysis Batch: 110143

Client Sample ID: Method Blank

Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			08/14/24 13:09	1

Lab Sample ID: MB 810-110143/153

Matrix: Drinking Water

Analysis Batch: 110143

Client Sample ID: Method Blank

Prep Type: Total/NA

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L			08/14/24 19:49	1

Lab Sample ID: LCS 810-110143/154

Matrix: Drinking Water

Analysis Batch: 110143

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	50.0	48.5		ug/L		97	85 - 115

Lab Sample ID: LLCS 810-110143/10

Matrix: Drinking Water

Analysis Batch: 110143

Client Sample ID: Lab Control Sample

Prep Type: Total/NA

Analyte	Spike Added	LLCS Result	LLCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	0.300	0.310	J	ug/L		103	50 - 150

Eurofins Eaton Analytical South Bend

QC Sample Results

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Method: 200.8 - Metals (ICP/MS)

Lab Sample ID: 810-114632-19 MS

Matrix: Drinking Water

Analysis Batch: 110143

Client Sample ID: SJSG-32 Sink

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MS Result	MS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	10		50.0	57.2		ug/L		94	70 - 130

Lab Sample ID: 810-114632-19 MSD

Matrix: Drinking Water

Analysis Batch: 110143

Client Sample ID: SJSG-32 Sink

Prep Type: Total/NA

Analyte	Sample Result	Sample Qualifier	Spike Added	MSD Result	MSD Qualifier	Unit	D	%Rec	%Rec Limits	RPD	RPD Limit
Lead	10		50.0	56.8		ug/L		93	70 - 130	1	20

Lab Sample ID: MB 810-109913/1-A

Matrix: Drinking Water

Analysis Batch: 110130

Client Sample ID: Method Blank

Prep Type: Total Recoverable

Prep Batch: 109913

Analyte	MB Result	MB Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<0.50		0.50		ug/L		08/13/24 13:45	08/14/24 15:23	1

Lab Sample ID: LCS 810-109913/6-A

Matrix: Drinking Water

Analysis Batch: 110130

Client Sample ID: Lab Control Sample

Prep Type: Total Recoverable

Prep Batch: 109913

Analyte	Spike Added	LCS Result	LCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	50.0	52.9		ug/L		106	85 - 115

Lab Sample ID: LLCS 810-109913/2-A

Matrix: Drinking Water

Analysis Batch: 110130

Client Sample ID: Lab Control Sample

Prep Type: Total Recoverable

Prep Batch: 109913

Analyte	Spike Added	LLCS Result	LLCS Qualifier	Unit	D	%Rec	%Rec Limits
Lead	0.300	0.336	J	ug/L		112	50 - 150

QC Association Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Metals

Prep Batch: 109913

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-114632-10	SJSG-13 Sink	Total Recoverable	Drinking Water	200.8	
MB 810-109913/1-A	Method Blank	Total Recoverable	Drinking Water	200.8	
LCS 810-109913/6-A	Lab Control Sample	Total Recoverable	Drinking Water	200.8	
LLCS 810-109913/2-A	Lab Control Sample	Total Recoverable	Drinking Water	200.8	

Analysis Batch: 109915

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-114632-1	SJSG-3 Sink	Total/NA	Drinking Water	200.8	
MB 810-109915/12	Method Blank	Total/NA	Drinking Water	200.8	
LCS 810-109915/13	Lab Control Sample	Total/NA	Drinking Water	200.8	
LLCS 810-109915/11	Lab Control Sample	Total/NA	Drinking Water	200.8	

Analysis Batch: 109917

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-114632-2	SJSG-4 Sink	Total/NA	Drinking Water	200.8	
MB 810-109917/14	Method Blank	Total/NA	Drinking Water	200.8	
LCS 810-109917/15	Lab Control Sample	Total/NA	Drinking Water	200.8	
LLCS 810-109917/11	Lab Control Sample	Total/NA	Drinking Water	200.8	

Analysis Batch: 110034

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-114632-3	SJSG-5 Sink	Total/NA	Drinking Water	200.8	
810-114632-4	SJSG-6 Sink	Total/NA	Drinking Water	200.8	
810-114632-5	SJSG-7 Bubbler	Total/NA	Drinking Water	200.8	
810-114632-6	SJSG-9 Sink	Total/NA	Drinking Water	200.8	
810-114632-7	SJSG-10 Bubbler	Total/NA	Drinking Water	200.8	
810-114632-8	SJSG-11 Sink	Total/NA	Drinking Water	200.8	
MB 810-110034/13	Method Blank	Total/NA	Drinking Water	200.8	
MB 810-110034/43	Method Blank	Total/NA	Drinking Water	200.8	
LCS 810-110034/44	Lab Control Sample	Total/NA	Drinking Water	200.8	
LLCS 810-110034/11	Lab Control Sample	Total/NA	Drinking Water	200.8	
810-114632-3 MS	SJSG-5 Sink	Total/NA	Drinking Water	200.8	
810-114632-3 MSD	SJSG-5 Sink	Total/NA	Drinking Water	200.8	

Analysis Batch: 110130

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
MB 810-109913/1-A	Method Blank	Total Recoverable	Drinking Water	200.8	109913
LCS 810-109913/6-A	Lab Control Sample	Total Recoverable	Drinking Water	200.8	109913
LLCS 810-109913/2-A	Lab Control Sample	Total Recoverable	Drinking Water	200.8	109913

Analysis Batch: 110141

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-114632-10	SJSG-13 Sink	Total Recoverable	Drinking Water	200.8	109913

Analysis Batch: 110143

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-114632-9	SJSG-12 Sink	Total/NA	Drinking Water	200.8	
810-114632-11	SJSG-15 Sink	Total/NA	Drinking Water	200.8	
810-114632-12	SJSG-16 Sink	Total/NA	Drinking Water	200.8	
810-114632-13	SJSG-17 Bubbler	Total/NA	Drinking Water	200.8	
810-114632-14	SJSG-26 Sink	Total/NA	Drinking Water	200.8	

Eurofins Eaton Analytical South Bend

QC Association Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Metals (Continued)

Analysis Batch: 110143 (Continued)

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
810-114632-15	SJSG-27 Bubbler	Total/NA	Drinking Water	200.8	
810-114632-16	SJSG-28 WF	Total/NA	Drinking Water	200.8	
810-114632-17	SJSG-29 Sink	Total/NA	Drinking Water	200.8	
810-114632-18	SJSG-30 Bubbler	Total/NA	Drinking Water	200.8	
810-114632-19	SJSG-32 Sink	Total/NA	Drinking Water	200.8	
810-114632-20	SJSG-34 Sink	Total/NA	Drinking Water	200.8	
MB 810-110143/11	Method Blank	Total/NA	Drinking Water	200.8	
MB 810-110143/153	Method Blank	Total/NA	Drinking Water	200.8	
LCS 810-110143/154	Lab Control Sample	Total/NA	Drinking Water	200.8	
LLCS 810-110143/10	Lab Control Sample	Total/NA	Drinking Water	200.8	
810-114632-19 MS	SJSG-32 Sink	Total/NA	Drinking Water	200.8	
810-114632-19 MSD	SJSG-32 Sink	Total/NA	Drinking Water	200.8	

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Client Sample ID: SJSG-3 Sink

Lab Sample ID: 810-114632-1

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	109915	NB	EA SB	08/13/24 18:40

Client Sample ID: SJSG-4 Sink

Lab Sample ID: 810-114632-2

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	109917	NB	EA SB	08/13/24 20:26

Client Sample ID: SJSG-5 Sink

Lab Sample ID: 810-114632-3

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110034	CA	EA SB	08/14/24 10:55

Client Sample ID: SJSG-6 Sink

Lab Sample ID: 810-114632-4

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110034	CA	EA SB	08/14/24 11:01

Client Sample ID: SJSG-7 Bubbler

Lab Sample ID: 810-114632-5

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110034	CA	EA SB	08/14/24 11:03

Client Sample ID: SJSG-9 Sink

Lab Sample ID: 810-114632-6

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110034	CA	EA SB	08/14/24 11:16

Client Sample ID: SJSG-10 Bubbler

Lab Sample ID: 810-114632-7

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110034	CA	EA SB	08/14/24 11:08

Eurofins Eaton Analytical South Bend

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Client Sample ID: SJSG-11 Sink

Lab Sample ID: 810-114632-8

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110034	CA	EA SB	08/14/24 11:10

Client Sample ID: SJSG-12 Sink

Lab Sample ID: 810-114632-9

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110143	NB	EA SB	08/14/24 20:12

Client Sample ID: SJSG-13 Sink

Lab Sample ID: 810-114632-10

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total Recoverable	Prep	200.8			109913	NB	EA SB	08/13/24 13:45
Total Recoverable	Analysis	200.8		10	110141	NB	EA SB	08/14/24 21:39

Client Sample ID: SJSG-15 Sink

Lab Sample ID: 810-114632-11

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110143	NB	EA SB	08/14/24 20:15

Client Sample ID: SJSG-16 Sink

Lab Sample ID: 810-114632-12

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110143	NB	EA SB	08/14/24 20:18

Client Sample ID: SJSG-17 Bubbler

Lab Sample ID: 810-114632-13

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110143	NB	EA SB	08/14/24 20:21

Client Sample ID: SJSG-26 Sink

Lab Sample ID: 810-114632-14

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110143	NB	EA SB	08/14/24 20:24

Eurofins Eaton Analytical South Bend

Lab Chronicle

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Client Sample ID: SJSG-27 Bubbler

Lab Sample ID: 810-114632-15

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110143	NB	EA SB	08/14/24 20:27

Client Sample ID: SJSG-28 WF

Lab Sample ID: 810-114632-16

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110143	NB	EA SB	08/14/24 20:35

Client Sample ID: SJSG-29 Sink

Lab Sample ID: 810-114632-17

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110143	NB	EA SB	08/14/24 20:38

Client Sample ID: SJSG-30 Bubbler

Lab Sample ID: 810-114632-18

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110143	NB	EA SB	08/14/24 20:41

Client Sample ID: SJSG-32 Sink

Lab Sample ID: 810-114632-19

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110143	NB	EA SB	08/14/24 20:44

Client Sample ID: SJSG-34 Sink

Lab Sample ID: 810-114632-20

Date Collected: 08/01/24 08:00

Matrix: Drinking Water

Date Received: 08/05/24 09:15

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Analyst	Lab	Prepared or Analyzed
Total/NA	Analysis	200.8		1	110143	NB	EA SB	08/14/24 20:52

Laboratory References:

EA SB = Eurofins Eaton Analytical South Bend, 110 S Hill Street, South Bend, IN 46617, TEL (574)233-4777

Eurofins Eaton Analytical South Bend

Accreditation/Certification Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Laboratory: Eurofins Eaton Analytical South Bend

The accreditations/certifications listed below are applicable to this report.

Authority	Program	Identification Number	Expiration Date
Missouri	State	880	09-30-24

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14

Method Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Method	Method Description	Protocol	Laboratory
200.8	Metals (ICP/MS)	EPA	EA SB
200.8	Preparation, Total Recoverable Metals	EPA	EA SB

Protocol References:
EPA = US Environmental Protection Agency

Laboratory References:
EA SB = Eurofins Eaton Analytical South Bend, 110 S Hill Street, South Bend, IN 46617, TEL (574)233-4777

Sample Summary

Client: St. John Environmental Consulting
Project/Site: St. Joseph School District - Spring Garden

Job ID: 810-114632-1

Lab Sample ID	Client Sample ID	Matrix	Collected	Received
810-114632-1	SJSG-3 Sink	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-2	SJSG-4 Sink	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-3	SJSG-5 Sink	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-4	SJSG-6 Sink	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-5	SJSG-7 Bubbler	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-6	SJSG-9 Sink	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-7	SJSG-10 Bubbler	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-8	SJSG-11 Sink	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-9	SJSG-12 Sink	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-10	SJSG-13 Sink	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-11	SJSG-15 Sink	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-12	SJSG-16 Sink	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-13	SJSG-17 Bubbler	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-14	SJSG-26 Sink	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-15	SJSG-27 Bubbler	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-16	SJSG-28 WF	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-17	SJSG-29 Sink	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-18	SJSG-30 Bubbler	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-19	SJSG-32 Sink	Drinking Water	08/01/24 08:00	08/05/24 09:15
810-114632-20	SJSG-34 Sink	Drinking Water	08/01/24 08:00	08/05/24 09:15

South Bend, IN

110 S Hill Street

South Bend, IN 46617

Phone (574) 233-4777 Phone (574) 233-8207

Chain of Custody Record



Environment Testing
America

Client Information Client Contact: Casey Hausman Company: St. Joseph School District Address: 1415 North 26th Street City: St. Joseph State, Zip: Missburi 64506 Phone: 816-671-4000 Email: CaseyHausman@sisd.k12.mo.us Project Name: St. Joseph School District Site: Spring Garden		Sampler: Ian St. John Lab PM: 314-853-4668 E-Mail: lan@stjohnenv.com State of Origin: MO		CDC No: Page: Page 1 of 2 # KW Job #: 81514	
Due Date Requested: TAT Requested (days): Compliance Project: ☐ Yes ☒ No PO #: WO #: Project #: SSOW#:		Analysis Requested Preservation Codes: A - HCL B - NaOH C - Zn Acetate D - Nitric Acid E - NaHSO4 F - MeOH G - Amchlor H - Ascorbic Acid I - Ice J - DI Water K - EDTA L - EDA Other: M - Hexane N - None O - AsNaO2 P - Na2O4S Q - Na2SO3 R - Na2S2O8 S - H2SO4 T - TSP Dodecahydrate U - Acetone V - MCAA W - pH 4.5 Z - other (specify)			
Sample Identification Sample Date: 8/1/24 Sample Time: 0800 Sample Type (C=Comp, G=grab): G Matrix (W=water, S=solid, O=other, A=air): W		Total Number of containers: ☒			
Sample ID: STSG-3 SINK STSG-4 SINK STSG-5 SINK STSG-6 SINK STSG-7 BUBBLER STSG-9 SINK STSG-10 BUBBLER STSG-11 SINK STSG-12 SINK STSG-13 SINK STSG-15 SINK		Special Instructions/Note: #Rec'd unreserved Will preserve upon receipt. # per 8/5/24			
Possible Hazard Identification ☐ Non-Hazard ☐ Flammable ☐ Skin Irritant ☐ Poison B ☐ Unknown ☐ Radiological		Sample Disposal (A fee may be assessed if samples are retained longer than 1 month) ☐ Return To Client ☐ Disposal By Lab ☐ Archive For _____ Months			
Deliverable Requested: I, II, III, IV, Other (specify)		Special Instructions/QC Requirements:			
Empty Kit Relinquished by:		Method of Shipment:			
Relinquished by:		Received by: Kamron Williams 8/5/24 0915 Date/Time:			
Relinquished by:		Received by:			
Relinquished by:		Received by:			
Custody Seals Intact: ☐ Yes ☒ No		Cooler Temperature(s) °C and Other Remarks: Ambient			

Ver: 01/16/2019

South Bend, IN

110 S Hill Street

South Bend, IN 46617

Phone (574) 233-4777 Phone (574) 233-8207

Chain of Custody Record



Environment Testing
America

Client Information		Sampler:		Lab Pmt:		Carrier Tracking No(s):		COC No:	
Client Contact:		Phone:		E-Mail:		State of Origin:		Page: 3 of 2 # Kew	
Company:		PWSID:		Due Date Requested:		Analysis Requested		Job #: 8/5/24	
Address:		TAT Requested (days):		Compliance Project: ☐ Yes ☒ No		Perform MS/MSD (Yes or No)		Preservation Codes:	
City:		PO #:		WO #:		Field Filtered Sample (Yes or No)		A - HCL B - NaOH C - Zn Acetate D - Nitric Acid E - NaHSO4 F - MeOH G - Anchlor H - Ascorbic Acid I - Ice J - DI Water K - EDTA L - EDA Other:	
State, Zip:		Project #:		SSOW#:		Matrix (W=water, S=solid, O=soil, A=air)		M - Hexane N - None O - AsNaO2 P - Na2O4S Q - Na2SO3 R - Na2S2O8 S - H2SO4 T - TSP Dodecahydrate U - Acetone V - MCAA W - pH 4-5 Z - other (specify)	
Phone:		Sample Date		Sample Time		Sample Type (C=Comp, G=grab)		Total Number of Containers	
Email:		Sample Date		Sample Time		Sample Type (C=Comp, G=grab)		Special Instructions/Note:	
Project Name:		Sample Date		Sample Time		Sample Type (C=Comp, G=grab)			
Site:		Sample Date		Sample Time		Sample Type (C=Comp, G=grab)			
Sample Identification		Sample Date		Sample Time		Sample Type (C=Comp, G=grab)			
STSG-16 SINK		8/1/24		0800		G W			
STSG-17 BUBBLER									
STSG-26 SINK									
STSG-27 BUBBLER									
STSG-28 WF									
STSG-29 SINK									
STSG-30 BUBBLER									
STSG-32 SINK									
STSG-34 SINK									
Possible Hazard Identification		Sample Date		Sample Time		Sample Type (C=Comp, G=grab)			
☐ Non-Hazard ☐ Flammable ☐ Skin Irritant		Sample Date		Sample Time		Sample Type (C=Comp, G=grab)			
Deliverable Requested: I, II, III, IV, Other (specify)		Sample Date		Sample Time		Sample Type (C=Comp, G=grab)			
Empty Kit Relinquished by:		Date:		Time:		Method of Shipment:			
Relinquished by:		Date/Time:		Date/Time:		Date/Time:			
Relinquished by:		Date/Time:		Date/Time:		Date/Time:			
Relinquished by:		Date/Time:		Date/Time:		Date/Time:			
Custody Seals Intact: ☐ Yes ☒ No		Custody Seal No.:		Cooler Temperature(s) °C and Other Remarks: Ambient		Received by: Kamaron Williams		Date/Time: 8/5/24 0915	
						Received by:		Date/Time:	
						Received by:		Date/Time:	
						Company: ECA-SB		Company:	

Ver: 01/16/2019

Login Sample Receipt Checklist

Client: St. John Environmental Consulting

Job Number: 810-114632-1

Login Number: 114632

List Source: Eurofins Eaton Analytical South Bend

List Number: 1

Creator: Williams, Kameron

Question	Answer	Comment
The cooler's custody seal, if present, is intact.	True	
Sample custody seals, if present, are intact.	True	
Samples were received on ice.	False	Thermal preservation not required.
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	False	Thermal preservation not required.
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	True	
Samples do not require splitting or compositing.	True	
Container provided by EEA	True	