


John S. Hobart Elementary School



January 14, 2025



John S. Hobart Elementary School

Item #	Description	Comments
55	Pavements	Replacement of a large majority/needs full replacement
56	Sidewalks	Replace majority of curbing, sidewalks and walkways
57	Playground Equipment	Replacement of surface
66	Exterior Walls/Columns	Repairs, repointing, powerwashing, recoat, scrape and paint
69	Exterior Doors	Replace mullions, hollow metal doors/frames, harden vision/sidelights
74	Interior Bearing Walls and Fire Walls	Install fire/smoke dampers - wall between kitchen/serving line
77	Resilient Tiles or Sheet Flooring	Replacement of VCTs in mutiple locations
79	Wood Flooring	Replacement of gym floor
80	Ceilings	Replacement of ceilings multiple locations
88	Ventilation System	Improve ventilation small office spaces, install concrete pads
92	HVAC Control Systems	Complete update to DDC
97	Plumbing Fixtures	Renovate single stall toilets off main office, faculty, off kitchen/faculty rm.
107	Communication Systems	Replace entire PA/Intercom system

Elementary Libraries



January 14, 2025

