

Lead in School Drinking Water Report

Chloe Clark Elementary School



EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: leadfreekids@doh.wa.gov.

DEFINITIONS

Fixture Housing
Location

Room/space where
fixture is located
(i.e. room number,
gym, playground)

Fixture Housing Type

Structure that contains
the individual fixtures
where water samples
were collected from.
Fixture housing may
contain one or more
individual fixture for
sampling.

Fixture Location
Details

Location within a
room or space where
fixture housing is
located, starting to the
left of the entrance and
rotating clockwise, of
the total number of
fixture housings in a
room or space
(e.g. 1/5, 2/5)

Fixture Type

Tap, Sprayer, Water
Fountain, Water Bottle
Filler, Ice maker

Fixture Position

Left, Center, Right

Date(s) collected: 2024-10-30

Date(s) analyzed: 2024-11-22, 2024-11-26

.	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	401115	Main Building	Sink	Room 4	1 of 1	Water Fountain	right	32
2	401127	Main Building	Sink	Music Room	1 of 1	Tap	center	31
3	401069	Main Building	Sink	Room 16	1 of 1	Water Fountain	right	11
4	401134	Main Building	Sink	Room 13	1 of 1	Tap	center	11
5	401125	Main Building	Sink	Room 9	1 of 1	Water Fountain	right	8
6	401070	Main Building	Sink	Room 17	1 of 1	Tap	center	7
7	401072	Main Building	Sink	Room 14	1 of 1	Tap	center	7
8	401117	Main Building	Sink	Room 5	1 of 1	Water Fountain	right	6
9	401073	Main Building	Sink	Room 14	1 of 1	Water Fountain	right	5
10	401090	Main Building	Sink	Room 23	1 of 1	Tap	center	5
11	401137	Main Building	Sink	Room 159	1 of 1	Tap	center	5
12	401063	Main Building	Sink	Room 18	1 of 1	Tap	center	4
13	401066	Main Building	Sink	Room 19	1 of 1	Tap	center	4
14	401078	Main Building	Sink	Room 29	1 of 1	Tap	center	4
15	401082	Main Building	Sink	Room 27	1 of 1	Tap	center	4
16	401118	Main Building	Sink	Room 6	1 of 1	Tap	left	4

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
17	401061	Main Building	Sink	Room 20	1 of 1	Tap	center	3
18	401064	Main Building	Sink	Room 21	1 of 1	Tap	center	3
19	401068	Main Building	Sink	Room 16	1 of 1	Tap	center	3
20	401074	Main Building	Sink	Room 15	1 of 1	Tap	center	3
21	401076	Main Building	Sink	Room 28	1 of 1	Tap	center	3
22	401080	Main Building	Sink	Room 26	1 of 1	Tap	center	3
23	401086	Main Building	Sink	Room 25	1 of 1	Tap	center	3
24	401088	Main Building	Sink	Room 22	1 of 1	Tap	center	3
25	401136	Main Building	Sink	Room 12	1 of 1	Tap	center	3
26	401079	Main Building	Sink	Room 29	1 of 1	Water Fountain	right	2
27	401084	Main Building	Sink	Room 24	1 of 1	Tap	center	2
28	401103	Main Building	Sink - Multi-Compartment	Kitchen	1 of 2	Tap	center	2
29	401104	Main Building	Sink - Multi-Compartment	Kitchen	1 of 2	Sprayer	right	2
30	401109	Main Building	Sink	Room 1	1 of 1	Water Fountain	right	2
31	401119	Main Building	Sink	Room 6	1 of 1	Water Fountain	right	2
32	401121	Main Building	Sink	Room 7	1 of 1	Water Fountain	right	2

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
33	401133	Main Building	Sink	Room 10	1 of 1	Tap	center	2
34	401083	Main Building	Sink	Room 27	1 of 1	Water Fountain	right	1
35	401089	Main Building	Sink	Room 22	1 of 1	Water Fountain	right	1
36	401091	Main Building	Sink	Room 23	1 of 1	Water Fountain	right	1
37	401112	Main Building	Sink	Room 3	1 of 1	Tap	left	1
38	401060	Main Building	Fountain - Multi-Level with Bottle Filler	Hallway Next To Mechanical Room 161a	1 of 1	Water Fountain	right	<1
39	401062	Main Building	Sink	Room 20	1 of 1	Water Fountain	right	<1
40	401065	Main Building	Sink	Room 21	1 of 1	Water Fountain	right	<1
41	401067	Main Building	Sink	Room 19	1 of 1	Water Fountain	right	<1
42	401071	Main Building	Sink	Room 17	1 of 1	Water Fountain	right	<1
43	401075	Main Building	Sink	Room 15	1 of 1	Water Fountain	right	<1
44	401077	Main Building	Sink	Room 28	1 of 1	Water Fountain	right	<1
45	401081	Main Building	Sink	Room 26	1 of 1	Water Fountain	right	<1
46	401085	Main Building	Sink	Room 24	1 of 1	Water Fountain	right	<1
47	401087	Main Building	Sink	Room 25	1 of 1	Water Fountain	right	<1
48	401102	Main Building	Sink - Multi-Compartment	Kitchen	1 of 2	Tap	left	<1

.	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
49	401105	Main Building	Sink	Kitchen	2 of 2	Sprayer	center	<1
50	401106	Main Building	Fountain with Bottle Filler	Gym	1 of 1	Water Bottle Filler	center	<1
51	401107	Main Building	Fountain with Bottle Filler	Gym	1 of 1	Water Fountain	right	<1
52	401108	Main Building	Sink	Room 1	1 of 1	Tap	left	<1
53	401110	Main Building	Sink	Room 2	1 of 1	Tap	left	<1
54	401111	Main Building	Sink	Room 2	1 of 1	Water Fountain	right	<1
55	401113	Main Building	Sink	Room 3	1 of 1	Water Fountain	right	<1
56	401114	Main Building	Sink	Room 4	1 of 1	Tap	left	<1
57	401116	Main Building	Sink	Room 5	1 of 1	Tap	left	<1
58	401120	Main Building	Sink	Room 7	1 of 1	Tap	left	<1
59	401122	Main Building	Fountain with Bottle Filler	1st Grade Hallway Across From 117a	1 of 1	Water Bottle Filler	center	<1
60	401123	Main Building	Fountain with Bottle Filler	1st Grade Hallway Across From 117a	1 of 1	Water Fountain	right	<1
61	401124	Main Building	Sink	Room 9	1 of 1	Tap	left	<1
62	401126	Main Building	Sink	Nurses Office	1 of 1	Tap	center	<1

.	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
63	401128	Main Building	Fountain - Multi-Level	Hallway Next To Kiln Room	1 of 1. Higher fountain	Water Fountain	right	<1
64	401129	Main Building	Fountain - Multi-Level	Hallway Next To Kiln Room	1 of 1. Lower fountain.	Water Fountain	right	<1
65	401130	Main Building	Sink	Room 11	1 of 1	Tap	center	<1
66	401131	Main Building	Sink	Room 11	1 of 1	Water Fountain	right	<1
67	401132	Main Building	Sink	Staff Lounge	1 of 1	Tap	center	<1
68	401135	Main Building	Sink	Room 13	1 of 1	Water Fountain	right	<1
69	401138	Main Building	Fountain - Multi-Level with Bottle Filler	Hallway Next To Mechanical Room 161a	1 of 1	Water Bottle Filler	right	<1
70	401139	Main Building	Fountain - Multi-Level with Bottle Filler	Hallway Next To Mechanical Room 161a	1 of 1. Higher fountain	Water Fountain	right	<1