

Lead in School Drinking Water Report

Saltars Point Elementary School



EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: leadfreekids@doh.wa.gov.

DEFINITIONS

Fixture Housing
Location

Room/space where
fixture is located
(i.e. room number,
gym, playground)

Fixture Housing Type

Structure that contains
the individual fixtures
where water samples
were collected from.
Fixture housing may
contain one or more
individual fixture for
sampling.

Fixture Location
Details

Location within a
room or space where
fixture housing is
located, starting to the
left of the entrance and
rotating clockwise, of
the total number of
fixture housings in a
room or space
(e.g. 1/5, 2/5)

Fixture Type

Tap, Sprayer, Water
Fountain, Water Bottle
Filler, Ice maker

Fixture Position

Left, Center, Right

Date(s) collected: 2024-10-31

Date(s) analyzed: 2024-11-22, 2024-12-02

.	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	401093	Main Building	Sink - Multi-Compartment	Kitchen	2 of 3	Tap	left	9
2	401241	Main Building	Sink	Otter Zone Room 146	1 of 1	Water Fountain	left	7
3	401235	Main Building	Sink	Special Education Room	1 of 2	Water Fountain	left	5
4	401099	Main Building	Fountain	Wing 3 Fountains	2 of 2. Right fountain	Water Fountain	right	4
5	401193	Saltar's Point Modular	Sink	Room M2	1 of 1	Tap	center	4
6	401220	Main Building	Sink	Music Room	1 of 1	Tap	center	4
7	401094	Main Building	Sink - Multi-Compartment	Kitchen	2 of 3	Tap	right	3
8	401098	Main Building	Fountain	Wing 3 Fountains	1 of 2	Water Fountain	right	3
9	401224	Main Building	Sink	Room 17	1 of 1	Tap	center	3
10	401237	Main Building	Sink	Resource Room Number 141	1 of 1	Tap	center	3
11	401251	Main Building	Sink	Room 7	1 of 1	Tap	center	3

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
12	401092	Main Building	Sink	Kitchen	1 of 3	Tap	center	2
13	401180	Main Building	Sink	Room 3	1 of 1	Tap	center	2
14	401181	Main Building	Sink	Room 3	1 of 1	Water Fountain	left	2
15	401184	Main Building	Sink	Room 1	1 of 1	Tap	center	2
16	401185	Main Building	Sink	Room 1	1 of 1	Water Fountain	left	2
17	401186	Main Building	Sink - Multi-Compartment	Staff Lounge	1 of 1	Tap	center	2
18	401192	Salta's Point Modular	Sink	Room M1	1 of 1	Tap	center	2
19	401222	Main Building	Sink	Room 18	1 of 1	Tap	center	2
20	401225	Main Building	Sink	Room 17	1 of 1	Water Fountain	left	2
21	401229	Main Building	Sink	Room 16	1 of 1	Water Fountain	left	2
22	401232	Main Building	Sink	Room 14	1 of 1	Tap	center	2
23	401234	Main Building	Sink	Special Education Room	1 of 2	Tap	center	2
24	401239	Main Building	Sink	Resource Room 145	1 of 1	Water Fountain	left	2
25	401240	Main Building	Sink	Otter Zone Room 146	1 of 1	Tap	center	2
26	401248	Main Building	Sink	Room 9	1 of 1	Water Fountain	left	2

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
27	401256	Main Building	Sink	Room 5	1 of 1	Tap	center	2
28	401257	Main Building	Sink	Room 5	1 of 1	Water Fountain	left	2
29	401259	Main Building	Sink	Room 4	1 of 1	Water Fountain	left	2
30	401183	Main Building	Sink	Room 2	1 of 1	Water Fountain	left	1
31	401223	Main Building	Sink	Room 18	1 of 1	Water Fountain	left	1
32	401228	Main Building	Sink	Room 16	1 of 1	Tap	center	1
33	401233	Main Building	Sink	Room 14	1 of 1	Water Fountain	left	1
34	401236	Main Building	Sink - Multi-Compartment	Special Education Room	2 of 2	Tap	center	1
35	401238	Main Building	Sink	Resource Room 145	1 of 1	Tap	center	1
36	401245	Main Building	Sink	Room 10	1 of 1	Tap	center	1
37	401249	Main Building	Sink	Room 8	1 of 1	Tap	center	1
38	401250	Main Building	Sink	Room 8	1 of 1	Water Fountain	left	1
39	401252	Main Building	Sink	Room 7	1 of 1	Water Fountain	left	1
40	401253	Main Building	Sink	Nurses Office	1 of 1	Tap	center	1
41	401255	Main Building	Sink	Room 6	1 of 1	Water Fountain	left	1
42	401258	Main Building	Sink	Room 4	1 of 1	Tap	center	1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
43	401095	Main Building	Sink	Kitchen	3 of 3	Sprayer	center	<1
44	401096	Main Building	Fountain with Bottle Filler	Hallway Outside Of Gym Across From Kitchen	1 of 1	Water Bottle Filler	center	<1
45	401097	Main Building	Fountain with Bottle Filler	Hallway Outside Of Gym Across From Kitchen	1 of 1	Water Fountain	right	<1
46	401182	Main Building	Sink	Room 2	1 of 1	Tap	center	<1
47	401187	Main Building	Fountain - Multi-Level with Bottle Filler	Outside Of Staff Lounge	1 of 1. Higher fountain.	Water Fountain	right	<1
48	401188	Main Building	Fountain - Multi-Level with Bottle Filler	Outside Of Staff Lounge	1 of 1	Water Bottle Filler	left	<1
49	401189	Main Building	Fountain - Multi-Level with Bottle Filler	Outside Of Staff Lounge	1 of 1. Lower fountain	Water Fountain	right	<1
50	401190	Saltar's Point Modular	Fountain - Multi-Level	Hallway	1 of 1. Higher fountain	Water Fountain	right	<1
51	401191	Saltar's Point Modular	Fountain - Multi-Level	Hallway	1 of 1. Lower fountain	Water Fountain	right	<1
52	401221	Main Building	Sink	Music Room	1 of 1	Water Fountain	left	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
53	401226	Main Building	Sink	Room 15	1 of 1	Tap	center	<1
54	401227	Main Building	Sink	Room 15	1 of 1	Water Fountain	right	<1
55	401230	Main Building	Sink	Room 13	1 of 1	Tap	center	<1
56	401231	Main Building	Sink	Room 13	1 of 1	Water Fountain	left	<1
57	401242	Main Building	Sink	Room 12	1 of 1	Tap	center	<1
58	401243	Main Building	Sink	Room 11	1 of 1	Tap	center	<1
59	401244	Main Building	Sink	Room 11	1 of 1	Water Fountain	left	<1
60	401246	Main Building	Sink	Room 10	1 of 1	Water Fountain	left	<1
61	401247	Main Building	Sink	Room 9	1 of 1	Tap	center	<1
62	401254	Main Building	Sink	Room 6	1 of 1	Tap	center	<1