

July 3, 2024

Zach Nannestad Douglas County School District 2812 N. Highway 85 Castle Rock, CO 80109

**Re:** Echo Park Stadium

11901 Newlin Gulch Blvd, Parker, CO 80134

**Radon Sampling Assessment** 

Dear Mr. Nannestad:

Quality Environmental Services & Technologies Inc. (QUEST) is pleased to assist Douglas County School District with the ongoing radon survey of its schools. At your request, QUEST conducted radon testing at Echo Park Stadium, located at 11901 Newlin Gulch Boulevard in Parker, Colorado.

Nine (9) AirChek radon test kits were placed on June 18, 2024, and nine (9) were retrieved on June 20, 2024. The attached laboratory results specify radon concentrations to be all within the EPA guideline of 4 pCi/L for acceptable radon concentrations.

If you have any questions, or if we may be of additional assistance, please contact QUEST, Inc. at 303-935-1573. We look forward to our continued association.

Sincerely,

Robert A. Woellner

Robert W. M.

Founder/Industrial Hygienist

Attachment: Laboratory Report

NEHA: NRPP Certification #105324RT

Jake Gamble

Industrial Hygienist

Larry Head

CEO

## Radon test result report for: ECHO PARK STADIUM

Kit#	Room Id	Started	Ended	pCi/L	Analyzed
11551011	A108	2024-06-18 @ 9:00 an	2024-06-20 @ 10:00 am	< 0.3	2024-06-24
11551004	E106	2024-06-18 @ 9:00 an	2024-06-20 @ 10:00 am	< 0.3	2024-06-24
11551005	E107	2024-06-18 @ 9:00 an	2024-06-20 @ 10:00 am	< 0.3	2024-06-24
11551006	E109	2024-06-18 @ 9:00 an	2024-06-20 @ 10:00 am	0.6	2024-06-24
11551007	E111	2024-06-18 @ 9:00 an	2024-06-20 @ 10:00 am	< 0.3	2024-06-24
11551008	E113	2024-06-18 @ 9:00 an	2024-06-20 @ 10:00 am	< 0.3	2024-06-24
11551009	<b>HOME LOCKER - 18</b>	2024-06-18 @ 9:00 an	2024-06-20 @ 10:00 am	0.9	2024-06-24
11551003	PRESS BOX MAIN AREA	2024-06-18 @ 9:00 an	2024-06-20 @ 10:00 am	< 0.3	2024-06-24
11551010	VISITOR LOCKER OFFICE	2024-06-18 @ 9:00 an	2024-06-20 @ 10:00 am	0.7	2024-06-24

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498