

**Sayville Union Free School District**  
**Districtwide Lead in Drinking Water**  
**Sampling and Remediation Plan**

**2020**



**ENVIROSCIENCE**  
**CONSULTANTS INC.**

**2150 Smithtown Avenue**  
**Ronkonkoma, NY 11779**  
**(631) 580-3191**  
**[www.envirohealth.org](http://www.envirohealth.org)**

**Project #19238**

**Districtwide Lead in Drinking Water**  
**Sampling and Remediation Plan**

**Performed for:**

**Sayville Union Free School District**  
**99 Greeley Avenue**  
**Sayville, NY 11782**

**November 2020**

**Prepared by:**

**Enviroscience Consultants, Inc.**  
**2150 Smithtown Avenue**  
**Ronkonkoma, NY 11779**  
**(631) 580-3191**

**Project #19238**

**President**



---

**Glenn Neuschwender**

# Districtwide Lead in Drinking Water Sampling and Remediation Plan

## Table of Contents

I. Executive Summary

II. Sampling Methodology

III. Initial Results

Appendix A – Cherry Avenue Elementary School

Appendix B – Lincoln Avenue Elementary School

Appendix C – Sunrise Drive Elementary School

Appendix D – Sayville Middle School

Appendix E – Sayville High School

Appendix F – Old Junior High Building

January 13, 2021

Scott Saperstein  
Sayville UFSD  
99 Greeley Road  
Sayville NY, 11782

## **I. Executive Summary**

The Sayville Union Free School District has developed their 2020 Lead in Drinking Water Sampling and Analysis Program, as required by the New York State Department of Health (Public Health Law Sections 1370-a and 1110, Subpart 67-4 Lead Testing in School Drinking Water).

In accordance with the regulation, this Lead Remediation Plan is prepared to identify locations deemed as Applicable Drinking Water Sources and report first draw sample results, to mitigate locations where sample results exceed 15 parts per billion, to identify locations deemed as Non-Applicable Water Sources, communicate this designation to building occupants, and to develop strategies for monitoring locations deemed Non-Applicable Water Sources to insure building occupants do not consume water from these locations.

Within the Sayville Union Free School District, the following locations have been deemed Applicable Drinking Water Sources by the administration:

- 1) Water fountains and bottle filling stations;
- 2) Kitchen water faucets and pot fillers used in food preparation;
- 3) Ice machines
- 4) Elementary School classroom sinks
- 5) Bathroom sinks

First draw samples were collected from each of these locations within the District, and analyzed by a New York State Department of Health ELAP certified laboratory. For results at or below 15 ppb, no further action is required until 2025. For locations above 15 ppb, options include: second and third draw sample collection to determine source of lead, designation of the location as Non-applicable Water Source, or permanent removal of the fixture from the location. In either case, the result was communicated by Envirosience Consultants, and the fixture was shut off by the District immediately upon receipt of results.

The following locations within the Sayville Union Free School District were deemed Non-Applicable Water Sources by the administration:

- 1) Science Laboratory sinks;
- 2) Art Room sinks;
- 3) Other classroom sinks;
- 4) Outside spigots
- 5) Custodial Closet sinks

In these cases, the District has placed signs adjacent to the fixture to notify occupants that the water is not intended for consumption. To further support this protocol, the following management of the locations is required:

- 1) Science Laboratory sinks - communicate in writing with students that these locations are for science experiments and hand washing only, not for consumption. This is most easily accomplished by including this language in the laboratory safety paperwork distributed to students at the beginning of the school year. This program should be monitored by the respective science teachers, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.
- 2) Art Room sinks - communicate in writing to students that these locations are for cleaning of art supplies and hand washing only, not for consumption. This is most easily accomplished by including this language in the course paperwork distributed to students at the beginning of the school year. This program should be monitored by the respective art teachers, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.
- 3) Other classroom sinks - classrooms in this category often include classrooms, where students are to hand wash after bathroom usage or activities as part of a regular hygiene program. This program should be monitored by teachers and staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.
- 4) Outside spigots - all-weather signage will be installed at each location. Further, spigots will have a special key maintained by the custodial staff to ensure that non-authorized persons do not fill sports coolers or use hoses for consumption. This program should be monitored by custodial staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.
- 5) Custodial Closet sinks - these locations should be accessed by custodial personnel only, and locked when not in use. Access to others should be restricted. This program should be monitored by custodial staff to ensure consumption is not taking place, and any deficiencies reported for assessment and revision, if necessary, by the Facilities Department.

## **II. Sampling Procedures:**

In accordance with the regulation, Enviroscience Consultants, Inc. performed initial water sampling throughout the Sayville Union Free School District from November 19-25, 2021. Samples were collected in wide-mouth 250 milliliter containers and were collected in the morning hours before the facilities opened. The water sources were not used for at least 8 hours and not more than 18 hours prior to sampling. Unique source numbers and designations were assigned to each source location. Unique sample identification numbers

were assigned to each sample taken. The key to fixture type codes and the sampling location schematics are shown below.

### Fixture Type Codes

BF Bottle Filler  
 HB Hose Bib  
 IM Ice Machine  
 OS Other Source  
 PF Pot Filler  
 SK Sink  
 SL Supply Line  
 SP Spigot  
 SPY Spray  
 SS Slop Sink  
 V Valve  
 WC Water Cooler  
 WF Water Fountain

### Source Designations

App Applicable  
 N/A Non-applicable

### Remediation Type Codes

FR Fixture Replacement  
 FRSLV Fixture, supply line or valve replacement  
 FRSLVPA Fixture, supply line or valve replacement  
 plumbing assessment  
 SIGN Non-potable water sign posted  
 CAPPED Supply line capped or fixture removed



### III. Initial Results:

All water source locations in each of the school buildings were assessed. Water source locations identified as drinking water sources were considered Applicable, and first draw samples were collected. Water source locations identified as non-drinking water sources were considered Non-applicable and these locations were documented.

The results of the initial sampling and the use of signs warning against water use at Non-applicable sources is documented in the School Water Outlet Inventory for each building (Appendix A through F).

All elevated locations should be taken off line until the remediation is completed. Any other drinking water sources in these buildings that were not functional at the time of initial sampling and have not been tested should be tested. All locations deemed non-applicable, but do not have signs, should be taken off line until signs have been posted.

The following is a summary of results in parts per billion (ppb) of locations where sample results were found above 15 ppb:

#### Cherry Avenue Elementary School

Kitchen 1 - 3 Bay Left	SK	27.4
Room 101 - Bathroom	SK	18.8
Room 108 - Music	SK	35
Storage B - Bathroom off Gym - Right	SK	36.7
Boys Bathroom by Room 111 @ A	SK	22.5
Room 113	SK	38.6
Room 115	SK	20.1
Room 117	SK	29.2
Room 125	SK	15.7

#### Lincoln Avenue Elementary School

Men's Bathroom - Left	SK	15.4
Art Room Office	SK	167

### Sunrise Drive Elementary School

Kitchen Dishwasher Station @ A	SK	30.7
Kitchen Sanitizer Station @B	SK	31.3
Room 106	SK	38.9
Room 110	SK	15.8
Room 123A	WF	23
Room 125	WF	16.3
Room 125	SK	16
Room 129	SK	106
Speech Office Bathroom @A	SK	107
Speech Office Bathroom @B	SK	18

### Sayville Middle School

Room 117 Station 2	SK	16.8
Room 117 Station 5	SK	24.5
Pool - Girl's Locker Room	WF	32.9
Pool - Girl's Locker Room @ A	SK	23.1
Pool - Boy's Locker Room	WF	16.5
Room 106 Unit @ A	SK	35.3
Room 106 Unit @ B	SK	45
Room 105 /106 Office	SK	117
Room 104 Unit @ B	SK	18.2
Room 103 Unit @ A	SK	15.2
Room 103 Unit @ B	SK	15.8
Main Office Kitchenette	SK	21.2

## Sayville High School

Kitchen 4-Bay @ A	SK	54.4
Kitchen 4-Bay @ C	SK	29.1
Kitchen Pot filler Right	PF	29.9
Girl's Bathroom by Room 134 @ C	SK	40.2
Athletic Trainer @ A	SK	53.4
Athletic Trainer @ B	SK	68.3
Girl's Lower Locker Room @A	SK	108
Room 200A @ A	SK	46.9
Room 200A @ B	SK	19.7
Room 200A @ C	SK	47.1
Second Floor Faculty Room Women's Bathroom @ B	SK	19.4
Room 121	SK	16.9

## Old Junior High School

Room 211 @ B	SK	83.8
Lower Locker Room Bathroom Left	SK	33.5
Lower Locker Room Bathroom Right	SK	58.1
Upper Locker Room Spigot	OS	23.8

## Appendix A

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Kitchen 1 - Dishrinse	SPY	App	1.77	11/25/2020	-	-	-	None	-	-	-
1001-2	Kitchen 1 - Bathroom	SK	App	14.2	11/25/2020	-	-	-	None	-	-	-
1001-3	Kitchen 1 - 3 Bay Right	SK	App	5.26	11/25/2020	-	-	-	None	-	-	-
<b>1001-4</b>	<b>Kitchen 1 - 3 Bay Left</b>	<b>SK</b>	<b>App</b>	<b>27.4</b>	<b>11/25/2020</b>				<b>Additional Sampling Required</b>			
1001-5	Kitchen 1 - Island Hand Wash	SK	N/A		11/25/2020	-	-	-	Sign Required	-	-	-
1002-1	Faculty Bathroom by Kitchen 1 - Handicap	SK	App	1.94	11/25/2020	-	-	-	None	-	-	-
1003-1	Faculty Bathroom by Multi Purpose Room	SK	App	2.13	11/25/2020	-	-	-	None	-	-	-
1004-1	Faculty Room	SK	App	5.2	11/25/2020	-	-	-	None	-	-	-
1005-1	Hallway by Faculty Room	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1006-1	Cafeteria	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1006-2	Cafeteria - Portable Unit	SK	App	2.32	11/25/2020	-	-	-	None	-	-	-
1007-1	Staff Bathroom by Cafeteria	SK	App	<1.0	11/25/2020	-	-	-	None	-	-	-
1008-1	Principals Office - Bathroom	SK	App	3.21	11/25/2020	-	-	-	None	-	-	-
<b>1009-1</b>	<b>Room 101 - Bathroom</b>	<b>SK</b>	<b>App</b>	<b>18.8</b>	<b>11/25/2020</b>				<b>Additional Sampling Required</b>			
1009-2	Room 101	SK	App	3.35	12/2/2020	-	-	-	None	-	-	-
1009-3	Room 101	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1010-1	Room 102 - Bathroom	SK	App	9.04	11/25/2020	-	-	-	None	-	-	-
1010-2	Room 102	SK	App	3.78	12/2/2020	-	-	-	None	-	-	-
1010-3	Room 102	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1011-1	Room 103 - Bathroom	SK	App	2.68	11/25/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1011-2	Room 103	SK	App	14.1	12/2/2020	-	-	-	None	-	-	-
1011-3	Room 103	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1012-1	Room 104 - Bathroom	SK	App	11.3	11/25/2020	-	-	-	None	-	-	-
1012-2	Room 104	SK	App	3.8	11/25/2020	-	-	-	None	-	-	-
1012-3	Room 104	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1013-1	Custodial Closet by Room 104	SS	N/A		11/25/2020	-	-	-	Sign Required	-	-	-
1014-1	Hallway by Room 103	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1015-1	Room 105 - Bathroom	SK	App	4.81	11/25/2020	-	-	-	None	-	-	-
1015-2	Room 105	SK	App	<1.0	11/25/2020	-	-	-	None	-	-	-
1015-3	Room 105	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1016-1	Room 106 - Bathroom	SK	App	10	11/25/2020	-	-	-	None	-	-	-
1016-2	Room 106	SK	App	14.9	11/25/2020	-	-	-	None	-	-	-
1016-3	Room 106	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1017-1	Hallway By Kitchen 1	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1017-2	Hallway By Kitchen 1	BF	App	<1.0	11/25/2020	-	-	-	None	-	-	-
1018-1	Nurses Office	SK	App	7.28	11/25/2020	-	-	-	None	-	-	-
1018-2	Nurses Office - Bathroom	SK	App	5.36	11/25/2020	-	-	-	None	-	-	-
1019-1	Room 109 - Art - Left	SK	App	2.27	12/2/2020	-	-	-	None	-	-	-
1019-2	Room 109 - Art - Right	SK	App	2.08	12/2/2020	-	-	-	None	-	-	-
1020-1	Custodial Office Bathroom	SK	App	2.41	11/25/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1020-2	Custodial Office Bathroom	SS	N/A		11/25/2020	-	-	-	Sign Required	-	-	-
<b>1021-1</b>	<b>Room 108 - Music</b>	<b>SK</b>	<b>App</b>	<b>35</b>	<b>11/25/2020</b>				<b>Additional Sampling Required</b>			
1021-2	Room 108 - Music	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1022-1	Hallway by Gym	WF	App		11/12/2020	-	-	-	None	Removed From Service	-	-
1022-2	Hallway by Gym	BF	App	<1.0	11/12/2020	-	-	-	None	-	-	-
1023-1	Gym - Portable Unit	SK	App	7.06	11/25/2020	-	-	-	None	-	-	-
1024-1	Storage B - Bathroom Office Gym - Left	SK	App	15	11/25/2020	-	-	-	None	-	-	-
<b>1024-2</b>	<b>Storage B - Bathroom Office Gym - Right</b>	<b>SK</b>	<b>App</b>	<b>36.7</b>	<b>11/25/2020</b>				<b>Additional Sampling Required</b>			
1025-1	Coaches Office Bathroom	SK	App	7.54	11/25/2020	-	-	-	None	-	-	-
1026-1	Girls Bathroom by Room 111 @ A	SK	App	1.98	11/25/2020	-	-	-	None	-	-	-
1026-2	Girls Bathroom by Room 111 @ B	SK	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1026-3	Girls Bathroom by Room 111 @ C	SK	App	4.57	11/25/2020	-	-	-	None	-	-	-
1026-4	Girls Bathroom by Room 111 @ D	SK	App	4.7	11/25/2020	-	-	-	None	-	-	-
1027-1	Custodial Closet by Room 111	SS	N/A		11/25/2020	-	-	-	Sign Required	-	-	-
<b>1028-1</b>	<b>Boys Bathroom by Room 111 @ A</b>	<b>SK</b>	<b>App</b>	<b>22.5</b>	<b>11/25/2020</b>				<b>Additional Sampling Required</b>			
1028-2	Boys Bathroom by Room 111 @ B	SK	App	2.43	11/25/2020	-	-	-	None	-	-	-
1028-3	Boys Bathroom by Room 111 @ C	SK	App	8.7	11/25/2020	-	-	-	None	-	-	-
1028-4	Boys Bathroom by Room 111 @ D	SK	App	2.15	11/25/2020	-	-	-	None	-	-	-
1029-1	Room 111 / 111B	SK	App	6.27	11/25/2020	-	-	-	None	-	-	-
1029-2	Room 111 / 111B	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1030-1	Room 110	SK	App	2.87	11/25/2020	-	-	-	None	-	-	-
1030-2	Room 110	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
<b>1031-1</b>	<b>Room 113</b>	<b>SK</b>	<b>App</b>	<b>38.6</b>	<b>11/25/2020</b>				<b>Additional Sampling Required</b>			
1031-2	Room 113	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1032-1	Room 112	SK	App	5.95	11/25/2020	-	-	-	None	-	-	-
1032-2	Room 112	WF	App		12/2/2020	-	-	-	None	Removed From Service	-	-
<b>1033-1</b>	<b>Room 115</b>	<b>SK</b>	<b>App</b>	<b>20.1</b>	<b>11/25/2020</b>				<b>Additional Sampling Required</b>			
1033-2	Room 115	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1034-1	Room 114	SK	App	6.45	12/2/2020	-	-	-	None	-	-	-
1034-2	Room 114	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
<b>1035-1</b>	<b>Room 117</b>	<b>SK</b>	<b>App</b>	<b>29.2</b>	<b>11/25/2020</b>				<b>Additional Sampling Required</b>			
1035-2	Room 117	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1036-1	Room 116	SK	App	4.16	11/25/2020	-	-	-	None	-	-	-
1036-2	Room 116	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1037-1	Faculty Bathroom by Library	SK	App	4.08	11/25/2020	-	-	-	None	-	-	-
1038-1	Room 121	SK	App	6.01	11/25/2020	-	-	-	None	-	-	-
1038-2	Room 121	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1039-1	Room 120	SK	App	9.63	11/25/2020	-	-	-	None	-	-	-
1039-2	Room 120	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1040-1	Room 123	SK	App	4.36	11/25/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1040-2	Room 123	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1041-1	Girls Bathroom by Room 123 - Left	SK	App	2.94	11/25/2020	-	-	-	None	-	-	-
1041-2	Girls Bathroom by Room 123 - Middle	SK	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1041-3	Girls Bathroom by Room 123 - Right	SK	App	2.47	12/2/2020	-	-	-	None	-	-	-
1042-1	Hallway by Room 125	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1043-1	Custodial Closet by Room 125	SS	N/A		11/25/2020	-	-	-	Sign Required	-	-	-
1044-1	Boys Bathroom by Room 125 - Left	SK	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1044-2	Boys Bathroom by Room 125 - Middle	SK	App	4.1	11/25/2020	-	-	-	None	-	-	-
1044-3	Boys Bathroom by Room 125 - Right	SK	App	2.82	11/25/2020	-	-	-	None	-	-	-
<b>1045-1</b>	<b>Room 125</b>	<b>SK</b>	<b>App</b>	<b>15.7</b>	<b>11/25/2020</b>				<b>Additional Sampling Required</b>			
1045-2	Room 125	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1046-1	Room 122	SK	App	5.6	11/25/2020	-	-	-	None	-	-	-
1046-2	Room 122	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1047-1	Room 127	SK	App	6	11/25/2020	-	-	-	None	-	-	-
1047-2	Room 127	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1048-1	Room 124	SK	App	9.98	11/25/2020	-	-	-	None	-	-	-
1048-2	Room 124	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1049-1	Room 129	SK	App	9.63	11/25/2020	-	-	-	None	-	-	-
1049-2	Room 129	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1050-1	Room 126	SK	App	6.75	11/25/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1050-2	Room 126	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-
1051-1	Room 128	SK	App	12.4	11/25/2020	-	-	-	None	-	-	-
1051-2	Room 128	WF	App		11/25/2020	-	-	-	None	Removed From Service	-	-

## Laboratory Report

NYE Report #: 2204556-16196

November 16, 2020

Project Manager  
Enviroscience Consultants, Inc.  
2150 Smithtown Avenue  
Ronkonkoma, NY 11779

Project: Cherry Avenue Elementary School

Dear Project Manager,


Enclosed is the Laboratory Analytical Report for potable water sample(s) received on November 16, 2020. New York Environmental analyzed the samples on November 16, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



---

Li Tsang, Laboratory Director

Date Collected:	12 Nov 2020
Date Received:	16 Nov 2020
Date Analyzed:	16 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

<u>Lab ID</u>	<u>CID</u>	<u>Sample Location/Description</u>	<u>LOQ</u>	<u>Result</u>	<u>Units</u>	<u>Flag</u>
201116J025	1	Hall by Gym-BF; Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

## Laboratory Report

NYE Report #: 2204705-16303

December 2, 2020

Project Manager  
Enviroscience Consultants, Inc.  
2150 Smithtown Avenue  
Ronkonkoma, NY 11779

Project: Cherry Avenue Elementary School

Dear Project Manager,


Enclosed is the Laboratory Analytical Report for potable water sample(s) received on November 25, 2020. New York Environmental analyzed the samples on November 27, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



---

Li Tsang, Laboratory Director

Date Collected:	25 Nov 2020
Date Received:	25 Nov 2020
Date Analyzed:	27 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201125L001	1	Kitchen 1 - Dishrinse-SPY; Initial	1.00	1.77	µg/L	
201125L002	2	Kitchen 1 - Bathroom-SK; Initial	1.00	14.2	µg/L	
201125L003	3	Kitchen 1 - 3 Bay Right-SK; Initial	1.00	5.26	µg/L	
201125L004	4	Kitchen 1 - 3 Bay Left-SK; Initial	1.00	27.4	µg/L	H
201125L005	5	Faculty Bathroom by Kitchen 1 - Handicap-SK; Initial	1.00	1.94	µg/L	
201125L006	6	Faculty Bathroom by Multi Purpose Room-SK; Initial	1.00	2.13	µg/L	
201125L007	7	Faculty Room-SK; Initial	1.00	5.20	µg/L	
201125L008	8	Cafeteria - Portable Unit-SK; Initial	1.00	2.32	µg/L	
201125L009	9	Staff Bathroom by Cafeteria-SK; Initial	1.00	<1.00	µg/L	
201125L010	10	Principals Office - Bathroom-SK; Initial	1.00	3.21	µg/L	
201125L011	11	Room 101 - Bathroom-SK; Initial	1.00	18.8	µg/L	H
201125L012	12	Room 102 - Bathroom-SK; Initial	1.00	9.04	µg/L	
201125L013	13	Room 103 - Bathroom-SK; Initial	1.00	2.68	µg/L	
201125L014	14	Room 104 - Bathroom-SK; Initial	1.00	11.3	µg/L	
201125L015	15	Room 104-SK; Initial	1.00	3.80	µg/L	
201125L016	16	Room 105 - Bathroom-SK; Initial	1.00	4.81	µg/L	
201125L017	17	Room 105-SK; Initial	1.00	<1.00	µg/L	
201125L018	18	Room 106 - Bathroom-SK; Initial	1.00	10.0	µg/L	
201125L019	19	Room 106-SK; Initial	1.00	14.9	µg/L	
201125L020	20	Hallway By Kitchen 1-BF; Initial	1.00	<1.00	µg/L	
201125L021	21	Nurses Office-SK; Initial	1.00	7.28	µg/L	
201125L022	22	Nurses Office - Bathroom-SK; Initial	1.00	5.36	µg/L	
201125L023	23	Custodial Office Bathroom-SK; Initial	1.00	2.41	µg/L	
201125L024	24	Room 108 - Music-SK; Initial	1.00	35.0	µg/L	H
201125L025	25	Gym - Portable Unit-SK; Initial	1.00	7.06	µg/L	
201125L026	26	Storage B - Bathroom Office Gym - Left-SK; Initial	1.00	15.0	µg/L	



Date Collected:	25 Nov 2020
Date Received:	25 Nov 2020
Date Analyzed:	27 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201125L027	27	Storage B - Bathroom Office Gym - Right-SK; Initial	1.00	36.7	µg/L	H
201125L028	28	Coaches Office Bathroom-SK; Initial	1.00	7.54	µg/L	
201125L029	29	Girls Bathroom by Room 111 @ A-SK; Initial	1.00	1.98	µg/L	
201125L030	30	Girls Bathroom by Room 111 @ C-SK; Initial	1.00	4.57	µg/L	
201125L031	31	Girls Bathroom by Room 111 @ D-SK; Initial	1.00	4.70	µg/L	
201125L032	32	Boys Bathroom by Room 111 @ A-SK; Initial	1.00	22.5	µg/L	H
201125L033	33	Boys Bathroom by Room 111 @ B-SK; Initial	1.00	2.43	µg/L	
201125L034	34	Boys Bathroom by Room 111 @ C-SK; Initial	1.00	8.70	µg/L	
201125L035	35	Boys Bathroom by Room 111 @ D-SK; Initial	1.00	2.15	µg/L	
201125L036	36	Room 111 / 111B-SK; Initial	1.00	6.27	µg/L	
201125L037	37	Room 110-SK; Initial	1.00	2.87	µg/L	
201125L038	38	Room 113-SK; Initial	1.00	38.6	µg/L	H
201125L039	39	Room 115-SK; Initial	1.00	20.1	µg/L	H
201125L040	40	Room 117-SK; Initial	1.00	29.2	µg/L	H
201125L041	41	Room 116-SK; Initial	1.00	4.16	µg/L	
201125L042	42	Faculty Bathroom by Library-SK; Initial	1.00	4.08	µg/L	
201125L043	43	Room 121-SK; Initial	1.00	6.01	µg/L	
201125L044	44	Room 120-SK; Initial	1.00	9.63	µg/L	
201125L045	45	Room 123-SK; Initial	1.00	4.36	µg/L	
201125L046	46	Girls Bathroom by Room 123 - Left-SK; Initial	1.00	2.94	µg/L	
201125L047	47	Boys Bathroom by Room 125 - Middle-SK; Initial	1.00	4.10	µg/L	
201125L048	48	Boys Bathroom by Room 125 - Right-SK; Initial	1.00	2.82	µg/L	
201125L049	49	Room 125-SK; Initial	1.00	15.7	µg/L	H
201125L050	50	Room 122-SK; Initial	1.00	5.60	µg/L	
201125L051	51	Room 127-SK; Initial	1.00	6.00	µg/L	
201125L052	52	Room 124-SK; Initial	1.00	9.98	µg/L	
201125L053	53	Room 129-SK; Initial	1.00	9.63	µg/L	



Date Collected:	25 Nov 2020
Date Received:	25 Nov 2020
Date Analyzed:	27 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

<u>Lab ID</u>	<u>CID</u>	<u>Sample Location/Description</u>	<u>LOQ</u>	<u>Result</u>	<u>Units</u>	<u>Flag</u>
201125L054	54	Room 126-SK; Initial	1.00	6.75	µg/L	
201125L055	55	Room 128-SK; Initial	1.00	12.4	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

H: Sample result exceeds applicable regulatory limit.

## Laboratory Report

NYE Report #: 2204810-16342

December 7, 2020

Project Manager  
Enviroscience Consultants, Inc.  
2150 Smithtown Avenue  
Ronkonkoma, NY 11779

Project: Cherry Avenue Elementary School

Dear Project Manager,


Enclosed is the Laboratory Analytical Report for potable water sample(s) received on December 03, 2020. New York Environmental analyzed the samples on December 04, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



---

Li Tsang, Laboratory Director

Date Collected:	03 Dec 2020
Date Received:	03 Dec 2020
Date Analyzed:	04 Dec 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201203Q011	1	Room 101-SK; Initial	1.00	3.35	µg/L	
201203Q012	2	Room 102-SK; Initial	1.00	3.78	µg/L	
201203Q013	3	Room 103-SK; Initial	1.00	14.1	µg/L	
201203Q014	4	Room 109-Art-Left-SK; Initial	1.00	2.27	µg/L	
201203Q015	5	Room 109-Art-Right-SK; Initial	1.00	2.08	µg/L	
201203Q016	6	Room 112-SK; Initial	1.00	5.95	µg/L	
201203Q017	7	Room 114-SK; Initial	1.00	6.45	µg/L	
201203Q018	8	Girls Bathroom by Room 123-SK; Initial	1.00	2.47	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

## Appendix B

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Kitchen	SK	App	3.45	11/20/2020	-	-	-	None	-	-	-
1001-2	Kitchen 3-Bay - Left	SPY	App	6.6	11/20/2020	-	-	-	None	-	-	-
1001-3	Kitchen 3-Bay - Right	SK	App	2.57	11/20/2020	-	-	-	None	-	-	-
1001-4	Kitchen Dishwasher	SPY	App	4.81	11/20/2020	-	-	-	None	-	-	-
1001-5	Kitchen Prep Island	SK	App	12.1	11/20/2020	-	-	-	None	-	-	-
1002-1	Cafeteria	SK	App	3.68	11/20/2020	-	-	-	None	-	-	-
1002-2	Cafeteria	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1002-3	Cafeteria	BF	App	<1.0	11/20/2020	-	-	-	None	-	-	-
1003-1	Custodial Closet by Kitchen	SS	N/A		11/20/2020	-	-	-	None	Locked Door	-	-
<b>1004-1</b>	<b>Men's Bathroom - Left</b>	<b>SK</b>	<b>App</b>	<b>15.4</b>	<b>11/20/2020</b>				<b>Additional Sampling Required</b>	<b>SIGN</b>		
1004-2	Men's Bathroom - Right	SK	App	2.75	11/20/2020	-	-	-	None	-	-	-
1005-1	Room 110	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1005-2	Room 110	SK	App	3.07	11/20/2020	-	-	-	None	-	-	-
1006-1	Room 111	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1006-2	Room 111	SK	App	5.06	11/20/2020	-	-	-	None	-	-	-
1007-1	Room 112	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1007-2	Room 112	SK	App	2.73	11/20/2020	-	-	-	None	-	-	-
1008-1	Room 113	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1008-2	Room 113	SK	App	5.56	11/20/2020	-	-	-	None	-	-	-
1009-1	Room 114	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1009-2	Room 114	SK	App	9.23	11/20/2020	-	-	-	None	-	-	-
1010-1	Room 115	WF	App	1.45	11/20/2020	-	-	-	None	-	-	-
1010-2	Room 115	SK	App	4.87	11/20/2020	-	-	-	None	-	-	-
1011-1	Room 116	WF	App	<1.0	11/20/2020	-	-	-	None	-	-	-
1011-2	Room 116	SK	App	8.9	11/20/2020	-	-	-	None	-	-	-
1012-1	Room 117	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1012-2	Room 117	SK	App	4.02	11/20/2020	-	-	-	None	-	-	-
1013-1	Room 118	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1013-2	Room 118	SK	App	3.3	11/20/2020	-	-	-	None	-	-	-
1014-1	Room 119	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1014-2	Room 119	SK	App	2.96	11/20/2020	-	-	-	None	-	-	-
1015-1	Room 120	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1015-2	Room 120	SK	App	4.25	11/20/2020	-	-	-	None	-	-	-
1016-1	Room 121	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1016-2	Room 121	SK	App	4.96	11/20/2020	-	-	-	None	-	-	-
1017-1	Room 123	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1017-2	Room 123	SK	App	13.9	11/20/2020	-	-	-	None	-	-	-
1018-1	Boy's Locker Room Bathroom - Left	SK	App	7.97	11/20/2020	-	-	-	None	-	-	-
1018-2	Boy's Locker Room Bathroom - Right	SK	App	5.71	11/20/2020	-	-	-	None	-	-	-
1019-1	Room 124	SK	App	3.68	11/20/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1019-2	Room 124 Bathroom	SK	App	13.2	11/20/2020	-	-	-	None	-	-	-
1020-1	Room 125	SK	App	3.55	11/20/2020	-	-	-	None	-	-	-
1020-2	Room 125 Bathroom	SK	App	12.4	11/20/2020	-	-	-	None	-	-	-
1021-1	Gym	SK	App	8.36	11/20/2020	-	-	-	None	-	-	-
1022-1	Physical Education Office Bathroom	SK	App	14.7	11/20/2020	-	-	-	None	SIGN	-	-
1023-1	Girl's Locker Room	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1023-2	Girl's Locker Room Bathroom - Left	SK	App	6.49	11/20/2020	-	-	-	None	-	-	-
1023-3	Girl's Locker Room Bathroom - Right	SK	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1024-1	Women's Bathroom by Gym - Left	SK	App	10.8	11/20/2020	-	-	-	None	-	-	-
1024-2	Women's Bathroom by Gym - Right	SK	App	10.2	11/20/2020	-	-	-	None	-	-	-
1025-1	Unisex Handicap Bathroom by Gym	SK	App	1.98	11/20/2020	-	-	-	None	-	-	-
1026-1	Room 151	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1026-2	Room 151 @ A	SK	App	6.94	11/20/2020	-	-	-	None	-	-	-
1026-3	Room 151 @ B	SK	App	11.4	11/20/2020	-	-	-	None	SIGN	-	-
1027-1	Room 152	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1027-2	Room 152	SK	App	5.59	11/20/2020	-	-	-	None	-	-	-
1027-3	Room 152 Bathroom	SK	App	5.1	11/20/2020	-	-	-	None	-	-	-
1028-1	Room 153	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1028-2	Room 153	SK	App	<1.0	11/20/2020	-	-	-	None	-	-	-
1029-1	Kindergarten Common Area	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1029-2	Kindergarten Common Area	SK	App	<1.0	11/20/2020	-	-	-	None	-	-	-
1030-1	Custodial Closet in Kindergarten Area	SS	N/A		11/20/2020	-	-	-	None	Locked Door	-	-
1031-1	Room 154	SK	App	<1.0	11/20/2020	-	-	-	None	-	-	-
1031-2	Room 154 Bathroom	SK	App	4.41	11/20/2020	-	-	-	None	-	-	-
1032-1	Room 155	SK	App	<1.0	11/20/2020	-	-	-	None	-	-	-
1032-2	Room 155 Bathroom	SK	App	<1.0	11/20/2020	-	-	-	None	-	-	-
1033-1	Room 142	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1033-2	Room 142	SK	App	7.5	11/20/2020	-	-	-	None	-	-	-
1034-1	Room 141	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1034-2	Room 141	SK	App	5.18	11/20/2020	-	-	-	None	-	-	-
1035-1	Room 140	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1035-2	Room 140	SK	App	3.89	11/20/2020	-	-	-	None	-	-	-
1036-1	Room 139	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1036-2	Room 139	SK	App	11.9	11/20/2020	-	-	-	None	-	-	-
1037-1	Room 138	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1037-2	Room 138	SK	App	7.73	11/20/2020	-	-	-	None	-	-	-
1038-1	Room 137	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1038-2	Room 137	SK	App	8.99	11/20/2020	-	-	-	None	-	-	-
1039-1	Room 136	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1039-2	Room 136	SK	App	3.76	11/20/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1040-1	Room 135	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1040-2	Room 135	SK	App	3.99	11/20/2020	-	-	-	None	-	-	-
1041-1	Room 134	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1041-2	Room 134	SK	App	1.66	11/20/2020	-	-	-	None	-	-	-
1042-1	Room 133	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1042-2	Room 133	SK	App	5.7	11/20/2020	-	-	-	None	-	-	-
1043-1	Room 132	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1043-2	Room 132	SK	App	6.72	11/20/2020	-	-	-	None	SIGN	-	-
1044-1	Room 131	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1044-2	Room 131	SK	App	12.8	11/20/2020	-	-	-	None	-	-	-
1045-1	Girl's Bathroom by Room 129 (Linear) @ A	SK	App	5.48	11/20/2020	-	-	-	None	-	-	-
1045-2	Girl's Bathroom by Room 129 (Linear) @ B	SK	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1045-3	Girl's Bathroom by Room 129 (Linear) @ C	SK	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1045-4	Girl's Bathroom by Room 129 (Linear) @ D	SK	App	4.48	11/20/2020	-	-	-	None	-	-	-
1046-1	Custodial Closet by Room 129	SS	N/A		11/20/2020	-	-	-	None	Locked Door	-	-
1047-1	Boy's Bathroom by Room 129 - Left	SK	App	2.98	11/20/2020	-	-	-	None	-	-	-
1047-2	Boy's Bathroom by Room 129 - Middle	SK	App	6.63	11/20/2020	-	-	-	None	-	-	-
1047-3	Boy's Bathroom by Room 129 - Right	SK	App	4.56	11/20/2020	-	-	-	None	-	-	-
1048-1	Hallway by Room 130	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1048-2	Hallway by Room 130	BF	App	<1.0	11/12/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1049-1	Room 130 @ A	SK	App	3.22	11/20/2020	-	-	-	None	-	-	-
1049-2	Room 130 @ B	SK	App	5.45	11/20/2020	-	-	-	None	-	-	-
1050-1	Main Office Kitchenette	SK	App	6.69	11/20/2020	-	-	-	None	-	-	-
1050-2	Main Office Bathroom	SK	App	7.82	11/20/2020	-	-	-	None	-	-	-
1051-1	Nurse's Office	SK	App	3.91	11/20/2020	-	-	-	None	-	-	-
1051-2	Nurse's Office Bathroom	SK	App	5.29	11/20/2020	-	-	-	None	-	-	-
<b>1052-1</b>	<b>Art Room Office</b>	<b>SK</b>	<b>App</b>	<b>167</b>	<b>11/20/2020</b>				<b>Additional Sampling Required</b>			
1052-2	Art Room @ A	SK	App	4.47	11/20/2020	-	-	-	None	-	-	-
1052-3	Art Room @ A	SPY	App	6.79	11/20/2020	-	-	-	None	-	-	-
1052-4	Art Room @ B	SK	App	2.93	11/20/2020	-	-	-	None	-	-	-
1052-5	Art Room @ B	SPY	App	<1.0	11/20/2020	-	-	-	None	-	-	-
1052-6	Art Room @ C	SK	App	1.4	11/20/2020	-	-	-	None	-	-	-
1052-7	Art Room @ C	SPY	App	2.15	11/20/2020	-	-	-	None	-	-	-
1053-1	Room 106	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1053-2	Room 106	SK	App	9.91	11/20/2020	-	-	-	None	-	-	-
1054-1	Faculty Room Kitchenette	SK	App	5.53	11/20/2020	-	-	-	None	-	-	-
1055-1	Room 109	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1055-2	Room 109	SK	App	7.76	11/20/2020	-	-	-	None	-	-	-
1056-1	Women's Bathroom by Auditorium - Left	SK	App	3.33	11/20/2020	-	-	-	None	-	-	-
1056-2	Women's Bathroom by Auditorium - Right	SK	App	7.2	11/20/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1057-1	Library Faculty Bathroom	SK	App	3.12	11/20/2020	-	-	-	None	-	-	-
1057-2	Library Student Bathroom	SK	App	1.24	11/20/2020	-	-	-	None	-	-	-
1057-3	Library	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1058-1	Boiler Room	SS	N/A		11/20/2020	-	-	-	None	Locked Door	-	-
1059-1	Custodial Office Right Bathroom	SK	App	1.47	11/20/2020	-	-	-	None	-	-	-
1059-2	Custodial Office Left Bathroom	SK	App	1.47	11/20/2020	-	-	-	None	-	-	-

## Laboratory Report

NYE Report #: 2204557-16197

November 16, 2020

Project Manager  
Enviroscience Consultants, Inc.  
2150 Smithtown Avenue  
Ronkonkoma, NY 11779

Project: Lincoln Avenue Elementary School

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on November 16, 2020. New York Environmental analyzed the samples on November 16, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



---

Li Tsang, Laboratory Director

Date Collected:	12 Nov 2020
Date Received:	16 Nov 2020
Date Analyzed:	16 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

<u>Lab ID</u>	<u>CID</u>	<u>Sample Location/Description</u>	<u>LOQ</u>	<u>Result</u>	<u>Units</u>	<u>Flag</u>
201116J026	1	Hallway Room 130-BF; Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

## Laboratory Report

NYE Report #: 2204647-16265

November 24, 2020

Project Manager  
Enviroscience Consultants, Inc.  
2150 Smithtown Avenue  
Ronkonkoma, NY 11779

Project: Lincoln Avenue Elementary

Dear Project Manager,


Enclosed is the Laboratory Analytical Report for potable water sample(s) received on November 23, 2020. New York Environmental analyzed the samples on November 23, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



Li Tsang, Laboratory Director

Date Collected:	20 Nov 2020
Date Received:	23 Nov 2020
Date Analyzed:	23 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201123J188	1	Kitchen - SK; Initial	1.00	3.45	µg/L	
201123J189	2	Kitchen 3-Bay - Left - SPY; Initial	1.00	6.60	µg/L	
201123J190	3	Kitchen 3-Bay - Right - SK; Initial	1.00	2.57	µg/L	
201123J191	4	Kitchen Dishwasher - SPY; Initial	1.00	4.81	µg/L	
201123J192	5	Kitchen Prep Island - SK; Initial	1.00	12.1	µg/L	
201123J193	6	Cafeteria - SK; Initial	1.00	3.68	µg/L	
201123J194	7	Cafeteria - BF; Initial	1.00	<1.00	µg/L	
201123J195	8	Men's Bathroom - Left - SK; Initial	1.00	15.4	µg/L	H
201123J196	9	Men's Bathroom - Right - SK; Initial	1.00	2.75	µg/L	
201123J197	10	Room 110 - SK; Initial	1.00	3.07	µg/L	
201123J198	11	Room 111 - SK; Initial	1.00	5.06	µg/L	
201123J199	12	Room 112 - SK; Initial	1.00	2.73	µg/L	
201123J200	13	Room 113 - SK; Initial	1.00	5.56	µg/L	
201123J201	14	Room 114 - SK; Initial	1.00	9.23	µg/L	
201123J202	15	Room 115 - WF; Initial	1.00	1.45	µg/L	
201123J203	16	Room 115 - SK; Initial	1.00	4.87	µg/L	
201123J204	17	Room 116 - WF; Initial	1.00	<1.00	µg/L	
201123J205	18	Room 116 - SK; Initial	1.00	8.90	µg/L	
201123J206	19	Room 117 - SK; Initial	1.00	4.02	µg/L	
201123J207	20	Room 118 - SK; Initial	1.00	3.30	µg/L	
201123J208	21	Room 119 - SK; Initial	1.00	2.96	µg/L	
201123J209	22	Room 120 - SK; Initial	1.00	4.25	µg/L	
201123J210	23	Room 121 - SK; Initial	1.00	4.96	µg/L	
201123J211	24	Room 123 - SK; Initial	1.00	13.9	µg/L	
201123J212	25	Boy's Locker Room Bathroom - Left - SK; Initial	1.00	7.97	µg/L	
201123J213	26	Boy's Locker Room Bathroom - Right- SK; Initial	1.00	5.71	µg/L	



Date Collected:	20 Nov 2020
Date Received:	23 Nov 2020
Date Analyzed:	23 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201123J214	27	Room 124 - SK; Initial	1.00	3.68	µg/L	
201123J215	28	Room 124 Bathroom - SK; Initial	1.00	13.2	µg/L	
201123J216	29	Room 125 - SK; Initial	1.00	3.55	µg/L	
201123J217	30	Room 125 Bathroom - SK; Initial	1.00	12.4	µg/L	
201123J218	31	Gym - SK; Initial	1.00	8.36	µg/L	
201123J219	32	Physical Education Office Bathroom - SK; Initial	1.00	14.7	µg/L	
201123J220	33	Girl's Locker Room Bathroom - Left - SK; Initial	1.00	6.49	µg/L	
201123J221	34	Women's Bathroom by Gym - Left - SK; Initial	1.00	10.8	µg/L	
201123J222	35	Women's Bathroom by Gym - Right - SK; Initial	1.00	10.2	µg/L	
201123J223	36	Unisex Handicap Bathroom by Gym - SK; Initial	1.00	1.98	µg/L	
201123J224	37	Room 151 @ A - SK; Initial	1.00	6.94	µg/L	
201123J225	38	Room 151 @ B - SK; Initial	1.00	11.4	µg/L	
201123J226	39	Room 152 - SK; Initial	1.00	5.59	µg/L	
201123J227	40	Room 152 Bathroom - SK; Initial	1.00	5.10	µg/L	
201123J228	41	Room 153 - SK; Initial	1.00	<1.00	µg/L	
201123J229	42	Kindergarten Common Area - SK; Initial	1.00	<1.00	µg/L	
201123J230	43	Room 154 - SK; Initial	1.00	<1.00	µg/L	
201123J231	44	Room 154 Bathroom - SK; Initial	1.00	4.41	µg/L	
201123J232	45	Room 155 - SK; Initial	1.00	<1.00	µg/L	
201123J233	46	Room 155 Bathroom - SK; Initial	1.00	<1.00	µg/L	
201123J234	47	Room 142 - SK; Initial	1.00	7.50	µg/L	
201123J235	48	Room 141 - SK; Initial	1.00	5.18	µg/L	
201123J236	49	Room 140 - SK; Initial	1.00	3.89	µg/L	
201123J237	50	Room 139 - SK; Initial	1.00	11.9	µg/L	
201123J238	51	Room 138 - SK; Initial	1.00	7.73	µg/L	
201123J239	52	Room 137 - SK; Initial	1.00	8.99	µg/L	
201123J240	53	Room 136 - SK; Initial	1.00	3.76	µg/L	



Date Collected:	20 Nov 2020
Date Received:	23 Nov 2020
Date Analyzed:	23 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201123J241	54	Room 135 - SK; Initial	1.00	3.99	µg/L	
201123J242	55	Room 134 - SK; Initial	1.00	1.66	µg/L	
201123J243	56	Room 133 - SK; Initial	1.00	5.70	µg/L	
201123J244	57	Room 132 - SK; Initial	1.00	6.72	µg/L	
201123J245	58	Room 131 - SK; Initial	1.00	12.8	µg/L	
201123J246	59	Girl's Bathroom by Room 129 (Linear) @ A - SK; Initial	1.00	5.48	µg/L	
201123J247	60	Girl's Bathroom by Room 129 (Linear) @ D - SK; Initial	1.00	4.48	µg/L	
201123J248	61	Boy's Bathroom by Room 129 - Left - SK; Initial	1.00	2.98	µg/L	
201123J249	62	Boy's Bathroom by Room 129 - Middle - SK; Initial	1.00	6.63	µg/L	
201123J250	63	Boy's Bathroom by Room 129 - Right- SK; Initial	1.00	4.56	µg/L	
201123J251	64	Hallway by Room 129 - BF; Initial	1.00	<1.00	µg/L	
201123J252	65	Room 130 @ A - SK; Initial	1.00	6.22	µg/L	
201123J253	66	Room 130 @ B - SK; Initial	1.00	5.45	µg/L	
201123J254	67	Main Office Kitchenette - SK; Initial	1.00	6.69	µg/L	
201123J255	68	Main Office Bathroom - SK; Initial	1.00	7.82	µg/L	
201123J256	69	Nurse's Office - SK; Initial	1.00	3.91	µg/L	
201123J257	70	Nurse's Office Bathroom - SK; Initial	1.00	5.29	µg/L	
201123J258	71	Art Room Office - SK; Initial	1.00	167	µg/L	E,H
201123J259	72	Art Room @ A - SK; Initial	1.00	4.47	µg/L	
201123J260	73	Art Room @ A - SPY; Initial	1.00	6.79	µg/L	
201123J261	74	Art Room @ B - SK; Initial	1.00	2.93	µg/L	
201123J262	75	Art Room @ B - SPY; Initial	1.00	<1.00	µg/L	
201123J263	76	Art Room @ C - SK; Initial	1.00	1.40	µg/L	
201123J264	77	Art Room @ C - SPY; Initial	1.00	2.15	µg/L	
201123J265	78	Room 106 - SK; Initial	1.00	9.91	µg/L	
201123J266	79	Faculty Room Kitchenette - SK; Initial	1.00	5.53	µg/L	
201123J267	80	Room 109 - SK; Initial	1.00	7.76	µg/L	



Date Collected:	20 Nov 2020
Date Received:	23 Nov 2020
Date Analyzed:	23 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

<u>Lab ID</u>	<u>CID</u>	<u>Sample Location/Description</u>	<u>LOQ</u>	<u>Result</u>	<u>Units</u>	<u>Flag</u>
201123J268	81	Women's Bathroom by Auditorium - Left - SK; Initial	1.00	3.33	µg/L	
201123J269	82	Women's Bathroom by Auditorium - Right - SK; Initial	1.00	7.20	µg/L	
201123J270	83	Library Faculty Bathroom - SK; Initial	1.00	3.12	µg/L	
201123J271	84	Custodial Office Right Bathroom - SK; Initial	1.00	1.24	µg/L	
201123J272	85	Custodial Office Left Bathroom - SK; Initial	1.00	1.47	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.

## Appendix C

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-1	Kitchen Dishwasher Station @ A	SK	App	30.7	11/20/2020				Additional Sampling Required			
1001-2	Kitchen Dishwasher Station @ A	SPY	App	<1.0	11/20/2020	-	-	-	None	-	-	-
1001-3	Kitchen Dishwasher Station @ B	SK	App		11/20/2020	-	-	-	None	-	-	-
1001-4	Kitchen Prep	SK	App	6.53	11/20/2020	-	-	-	None	-	-	-
1001-5	Kitchen Sanitizer Station @A	SK	App	3.39	11/20/2020	-	-	-	None	-	-	-
1001-6	Kitchen Sanitizer Station @B	SK	App	31.3	11/20/2020				Additional Sampling Required			
1001-7	Kitchen Island	SK	App	3.54	11/20/2020	-	-	-	None	-	-	-
1002-1	Kitchen Bathroom	SK	App	11.2	11/20/2020	-	-	-	None	-	-	-
1003-1	Faculty Left Bathroom by Cafeteria	SK	App	<1.0	11/20/2020	-	-	-	None	-	-	-
1004-1	Faculty Right Bathroom by Cafeteria	SK	App	<1.0	11/20/2020	-	-	-	None	-	-	-
1005-1	Faculty Room (Room 100)	SK	App	4.5	11/20/2020	-	-	-	None	-	-	-
1006-1	Room 101	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1006-2	Room 101	SK	App	8.12	11/20/2020	-	-	-	None	-	-	-
1006-3	Room 101 Bathroom	SK	App	7.13	11/20/2020	-	-	-	None	-	-	-
1007-1	Room 102	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1007-2	Room 102	SK	App	6.14	11/20/2020	-	-	-	None	-	-	-
1007-3	Room 102 Bathroom	SK	App	1.86	11/20/2020	-	-	-	None	-	-	-
1008-1	Room 103	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1008-2	Room 103	SK	App	3.45	11/20/2020	-	-	-	None	-	-	-
1008-3	Room 103 Bathroom	SK	App	2.57	11/20/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1009-1	Room 104	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1009-2	Room 104	SK	App	13.7	11/20/2020	-	-	-	None	-	-	-
1009-3	Room 104 Bathroom	SK	App	2.52	11/20/2020	-	-	-	None	-	-	-
1010-1	Room 105	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1010-2	Room 105	SK	App	6.63	11/20/2020	-	-	-	None	-	-	-
1010-3	Room 105 Bathroom	SK	App	4.16	11/20/2020	-	-	-	None	-	-	-
1011-1	Room 106	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
<b>1011-2</b>	<b>Room 106</b>	<b>SK</b>	<b>App</b>	<b>38.9</b>	<b>11/20/2020</b>				<b>Additional Sampling Required</b>			
1011-3	Room 106 Bathroom	SK	App	7.19	11/20/2020	-	-	-	None	-	-	-
1012-1	Room 107	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1012-2	Room 107	SK	App	<1.0	11/20/2020	-	-	-	None	-	-	-
1012-3	Room 107 Bathroom	SK	App	4.23	11/20/2020	-	-	-	None	-	-	-
1013-1	Room 108	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1013-2	Room 108	SK	App	7.55	11/20/2020	-	-	-	None	-	-	-
1013-3	Room 108 Bathroom	SK	App	2.56	11/20/2020	-	-	-	None	-	-	-
1014-1	Custodial Closet by Room 110	SS	N/A		11/20/2020	-	-	-	None	Locked Door	-	-
1015-1	Room 110	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
<b>1015-2</b>	<b>Room 110</b>	<b>SK</b>	<b>App</b>	<b>15.8</b>	<b>11/20/2020</b>				<b>Additional Sampling Required</b>			
1015-3	Room 110 Bathroom	SK	App	4.4	11/20/2020	-	-	-	None	-	-	-
1016-1	Room 112	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1016-2	Room 112	SK	App	6.36	11/20/2020	-	-	-	None	-	-	-
1016-3	Room 112 Bathroom	SK	App	4.57	11/20/2020	-	-	-	None	-	-	-
1017-1	Room 109	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1017-2	Room 109	SK	App	7.06	11/20/2020	-	-	-	None	-	-	-
1017-3	Room 109 Bathroom	SK	App	1.62	11/20/2020	-	-	-	None	-	-	-
1018-1	Main Office Kitchenette	SK	App	6.26	11/20/2020	-	-	-	None	-	-	-
1019-1	Custodial Office	SS	N/A		11/20/2020	-	-	-	None	Locked Door	-	-
1020-1	Hallway by Main Office	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1021-1	Mens Bathroom by Room 116 @A	SK	App	8.76	11/20/2020	-	-	-	None	-	-	-
1021-2	Mens Bathroom by Room 116 @B	SK	App	10.2	11/20/2020	-	-	-	None	-	-	-
1022-1	Womens Bathroom by Nurse's Office @A	SK	App	2.88	11/20/2020	-	-	-	None	-	-	-
1022-2	Womens Bathroom by Nurse's Office @B	SK	App	4.82	11/20/2020	-	-	-	None	-	-	-
1023-1	Nurse's Office	SK	App	6.99	11/20/2020	-	-	-	None	-	-	-
1023-2	Nurse's Office Bathroom	SK	App	6.37	11/20/2020	-	-	-	None	-	-	-
1024-1	Room 119 Art	SK	App	4.99	11/20/2020	-	-	-	None	-	-	-
1025-1	Custodial Closet by Room 121	SS	N/A		11/20/2020	-	-	-	Sign Required	-	-	-
1026-1	Room 121	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1026-2	Room 121	SK	App	7.63	11/20/2020	-	-	-	None	-	-	-
1027-1	Boys Bathroom by Room 121 @A	SK	App	<1.0	11/20/2020	-	-	-	None	-	-	-
1027-2	Boys Bathroom by Room 121 @B	SK	App		11/20/2020	-	-	-	None	Removed From Service	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1027-3	Boys Bathroom by Room 121 @C	SK	App	1.57	11/20/2020	-	-	-	None	-	-	-
1028-1	Girls Bathroom by Room 121 @A	SK	App	1.21	11/20/2020	-	-	-	None	-	-	-
1028-2	Girls Bathroom by Room 121 @B	SK	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1028-3	Girls Bathroom by Room 121 @C	SK	App	2.01	11/20/2020	-	-	-	None	-	-	-
<b>1029-1</b>	<b>Room 123A</b>	<b>WF</b>	<b>App</b>	<b>23</b>	<b>11/20/2020</b>				<b>Additional Sampling Required</b>			
1029-2	Room 123A	SK	App	5.82	11/20/2020	-	-	-	None	-	-	-
1030-1	Room 122	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1030-2	Room 122	SK	App	1.92	11/20/2020	-	-	-	None	-	-	-
<b>1031-1</b>	<b>Room 125</b>	<b>WF</b>	<b>App</b>	<b>16.3</b>	<b>11/20/2020</b>				<b>Additional Sampling Required</b>	<b>Removed From Service</b>		
<b>1031-2</b>	<b>Room 125</b>	<b>SK</b>	<b>App</b>	<b>16</b>	<b>11/20/2020</b>				<b>Additional Sampling Required</b>			
1032-1	Room 124	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1032-2	Room 124	SK	App	10.7	11/20/2020	-	-	-	None	-	-	-
1033-1	Room 127	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1033-2	Room 127	SK	App		11/20/2020	-	-	-	Non-functional Sampling Required	-	-	-
1034-1	Room 126	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1034-2	Room 126	SK	App	7.83	11/20/2020	-	-	-	None	-	-	-
1035-1	Room 129	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
<b>1035-2</b>	<b>Room 129</b>	<b>SK</b>	<b>App</b>	<b>106</b>	<b>11/20/2020</b>				<b>None</b>			
1036-1	Room 128	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1036-2	Room 128	SK	App	13.8	11/20/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1037-1	Girls Locker Room Bathroom @A	SK	App		11/20/2020	-	-	-	None	-	-	-
1037-2	Girls Locker Room Bathroom @B	SK	App		11/20/2020	-	-	-	None	-	-	-
1038-1	Speech Office Bathroom @A	SK	App	107	11/20/2020				Additional Sampling Required			
1038-2	Speech Office Bathroom @B	SK	App	18	11/20/2020				Additional Sampling Required			
1039-1	Hallway by Room 120B (right unit)	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1039-2	Hallway by Room 120A (left unit)	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1039-3	Hallway by Room 120A	BF	App	<1.0	11/20/2020	-	-	-	None	-	-	-
1040-1	Library Office	SK	App	8.61	11/20/2020	-	-	-	None	-	-	-
1041-1	Womens Bathroom by Room 130	SK	App	1	11/20/2020	-	-	-	None	-	-	-
1042-1	Mens Bathroom by Room 130	SK	App	1.9	11/20/2020	-	-	-	None	-	-	-
1043-1	Room 130	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1043-2	Room 130	SK	App	8.89	11/20/2020	-	-	-	None	-	-	-
1044-1	Boys Bathroom by Room 130 @A	SK	App	4	11/20/2020	-	-	-	None	-	-	-
1044-2	Boys Bathroom by Room 130 @B	SK	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1044-3	Boys Bathroom by Room 130 @C	SK	App	4.77	11/20/2020	-	-	-	None	-	-	-
1045-1	Custodial Closet by Room 130	SS	N/A		11/20/2020	-	-	-	None	Locked Door	-	-
1046-1	Girls Bathroom by Room 132 @A	SK	App	2.93	11/20/2020	-	-	-	None	-	-	-
1046-2	Girls Bathroom by Room 132 @B	SK	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1046-3	Girls Bathroom by Room 132 @C	SK	App	4.85	11/20/2020	-	-	-	None	-	-	-
1047-1	Hallway by Room 132	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1048-1	Room 132	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1048-2	Room 132	SK	App	2.56	11/20/2020	-	-	-	None	-	-	-
1049-1	Room 134	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1049-2	Room 134	SK	App	2.74	11/20/2020	-	-	-	None	-	-	-
1050-1	Room 133	WF	App	2.95	11/20/2020	-	-	-	None	-	-	-
1050-2	Room 133	SK	App	13.5	11/20/2020	-	-	-	None	-	-	-
1051-1	Room 136	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1051-2	Room 136	SK	App	6.07	11/20/2020	-	-	-	None	-	-	-
1052-1	Room 135	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1052-2	Room 135	SK	App	9.87	11/20/2020	-	-	-	None	-	-	-
1053-1	Room 138	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1053-2	Room 138	SK	App	10.6	11/20/2020	-	-	-	None	-	-	-
1054-1	Room 137	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1054-2	Room 137	SK	App	7.29	11/20/2020	-	-	-	None	-	-	-
1055-1	Room 140	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1055-2	Room 140	SK	App	8.08	11/20/2020	-	-	-	None	-	-	-
1056-1	Room 139	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1056-2	Room 139	SK	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1057-1	Room 142	WF	App		11/20/2020	-	-	-	None	Removed From Service	-	-
1057-2	Room 142	SK	App	6.68	11/20/2020	-	-	-	None	-	-	-

## Laboratory Report

NYE Report #: 2204645-16263

November 24, 2020

Project Manager  
Enviroscience Consultants, Inc.  
2150 Smithtown Avenue  
Ronkonkoma, NY 11779

Project: Sunrise Elementary School

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on November 23, 2020. New York Environmental analyzed the samples on November 23, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



---

Li Tsang, Laboratory Director

Date Collected:	20 Nov 2020
Date Received:	23 Nov 2020
Date Analyzed:	23 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201123J046	1	Kitchen Dishwasher Station @ A-SK; Initial	1.00	30.7	µg/L	H
201123J047	2	Kitchen Dishwasher Station @ A-SPY; Initial	1.00	<1.00	µg/L	
201123J048	3	Kitchen Prep-SK; Initial	1.00	6.53	µg/L	
201123J049	4	Kitchen Sanitizer Station @A-SK; Initial	1.00	3.39	µg/L	
201123J050	5	Kitchen Sanitizer Station @B-SK; Initial	1.00	31.3	µg/L	H
201123J051	6	Kitchen Island-SK; Initial	1.00	3.54	µg/L	
201123J052	7	Kitchen Bathroom-SK; Initial	1.00	11.2	µg/L	
201123J053	8	Faculty Left Bathroom by Cafeteria-SK; Initial	1.00	<1.00	µg/L	
201123J054	9	Faculty Right Bathroom by Cafeteria-SK; Initial	1.00	<1.00	µg/L	
201123J055	10	Faculty Room (Room 100)-SK; Initial	1.00	4.50	µg/L	
201123J056	11	Room 101-SK; Initial	1.00	8.12	µg/L	
201123J057	12	Room 101 Bathroom-SK; Initial	1.00	7.13	µg/L	
201123J058	13	Room 102-SK; Initial	1.00	6.14	µg/L	
201123J059	14	Room 102 Bathroom-SK; Initial	1.00	1.86	µg/L	
201123J060	15	Room 103-SK; Initial	1.00	3.45	µg/L	
201123J061	16	Room 103 Bathroom-SK; Initial	1.00	2.57	µg/L	
201123J062	17	Room 104-SK; Initial	1.00	13.7	µg/L	
201123J063	18	Room 104 Bathroom-SK; Initial	1.00	2.52	µg/L	
201123J064	19	Room 105-SK; Initial	1.00	6.63	µg/L	
201123J065	20	Room 105 Bathroom-SK; Initial	1.00	4.16	µg/L	
201123J066	21	Room 106-SK; Initial	1.00	38.9	µg/L	H
201123J067	22	Room 106 Bathroom-SK; Initial	1.00	7.19	µg/L	
201123J068	23	Room 107-SK; Initial	1.00	<1.00	µg/L	
201123J069	24	Room 107 Bathroom-SK; Initial	1.00	4.23	µg/L	
201123J070	25	Room 108-SK; Initial	1.00	7.55	µg/L	
201123J071	26	Room 108 Bathroom-SK; Initial	1.00	2.56	µg/L	



Date Collected:	20 Nov 2020
Date Received:	23 Nov 2020
Date Analyzed:	23 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201123J072	27	Room 110-SK; Initial	1.00	15.8	µg/L	H
201123J073	28	Room 110 Bathroom-SK; Initial	1.00	4.40	µg/L	
201123J074	29	Room 112-SK; Initial	1.00	6.36	µg/L	
201123J075	30	Room 112 Bathroom-SK; Initial	1.00	4.57	µg/L	
201123J076	31	Room 109-SK; Initial	1.00	7.06	µg/L	
201123J077	32	Room 109 Bathroom-SK; Initial	1.00	1.62	µg/L	
201123J078	33	Main Office Kitchenette-SK; Initial	1.00	6.26	µg/L	
201123J079	34	Mens Bathroom by Room 116 @A-SK; Initial	1.00	8.76	µg/L	
201123J080	35	Mens Bathroom by Room 116 @B-SK; Initial	1.00	10.2	µg/L	
201123J081	36	Womens Bathroom by Nurse's Office @A-SK; Initial	1.00	2.88	µg/L	
201123J082	37	Womens Bathroom by Nurse's Office @B-SK; Initial	1.00	4.82	µg/L	
201123J083	38	Nurse's Office -SK; Initial	1.00	6.99	µg/L	
201123J084	39	Nurse's Office Bathroom-SK; Initial	1.00	6.37	µg/L	
201123J085	40	Room 119 Art-SK; Initial	1.00	4.99	µg/L	
201123J086	41	Room 121-SK; Initial	1.00	7.63	µg/L	
201123J087	42	Boys Bathroom by Room 121 @A-SK; Initial	1.00	<1.00	µg/L	
201123J088	43	Boys Bathroom by Room 121 @C-SK; Initial	1.00	1.57	µg/L	
201123J089	44	Girls Bathroom by Room 121 @A-SK; Initial	1.00	1.21	µg/L	
201123J090	45	Girls Bathroom by Room 121 @C-SK; Initial	1.00	2.01	µg/L	
201123J091	46	Room 123A-WF; Initial	1.00	23.0	µg/L	H
201123J092	47	Room 123A-SK; Initial	1.00	5.82	µg/L	
201123J093	48	Room 122-SK; Initial	1.00	1.92	µg/L	
201123J094	49	Room 125-WF; Initial	1.00	16.3	µg/L	H
201123J095	50	Room 125-SK; Initial	1.00	16.0	µg/L	H
201123J096	51	Room 124-SK; Initial	1.00	10.7	µg/L	
201123J097	52	Room 126-SK; Initial	1.00	7.83	µg/L	
201123J098	53	Room 129-SK; Initial	1.00	106	µg/L	E,H



Date Collected:	20 Nov 2020
Date Received:	23 Nov 2020
Date Analyzed:	23 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201123J099	54	Room 128-SK; Initial	1.00	13.8	µg/L	
201123J100	55	Speech Office Bathroom @A-SK; Initial	1.00	107	µg/L	E,H
201123J101	56	Speech Office Bathroom @B-SK; Initial	1.00	18.0	µg/L	H
201123J102	57	Hallway by Room 120A-BF; Initial	1.00	<1.00	µg/L	
201123J103	58	Library Office -SK; Initial	1.00	8.61	µg/L	
201123J104	59	Womens Bathroom by Room 130-SK; Initial	1.00	1.00	µg/L	
201123J105	60	Mens Bathroom by Room 130 -SK; Initial	1.00	1.90	µg/L	
201123J106	61	Room 130-SK; Initial	1.00	8.89	µg/L	
201123J107	62	Boys Bathroom by Room 130 @A-SK; Initial	1.00	4.00	µg/L	
201123J108	63	Boys Bathroom by Room 130 @C-SK; Initial	1.00	4.77	µg/L	
201123J109	64	Girls Bathroom by Room 132 @A-SK; Initial	1.00	2.93	µg/L	
201123J110	65	Girls Bathroom by Room 132 @C-SK; Initial	1.00	4.85	µg/L	
201123J111	66	Room 132-SK; Initial	1.00	2.56	µg/L	
201123J112	67	Room 134-SK; Initial	1.00	2.74	µg/L	
201123J113	68	Room 133-WF; Initial	1.00	2.95	µg/L	
201123J114	69	Room 133-SK; Initial	1.00	13.5	µg/L	
201123J115	70	Room 136-SK; Initial	1.00	6.07	µg/L	
201123J116	71	Room 135-SK; Initial	1.00	9.87	µg/L	
201123J117	72	Room 138-SK; Initial	1.00	10.6	µg/L	
201123J118	73	Room 137-SK; Initial	1.00	7.29	µg/L	
201123J119	74	Room 140-SK; Initial	1.00	8.08	µg/L	
201123J120	75	Room 142-SK; Initial	1.00	6.68	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.



## Appendix D

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-01	Serving Line A	SK	App	1.23	11/19/2020	-	-	-	None	-	-	-
1001-02	Kitchen Handwash by Serving Line A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1001-03	Kitchen by Serving Line A	SPY	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1001-04	Kitchen Handwash by Serving Line B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1001-05	Kitchen by Serving Line B	SPY	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1001-06	Kitchen by Ice Machine	SK	App	4.03	11/19/2020	-	-	-	None	-	-	-
1001-07	Kitchen	IM	App	<1.0	11/19/2020	-	-	-	None	-	-	-
1001-08	Serving Line B	SK	App	5.57	11/19/2020	-	-	-	None	-	-	-
1001-09	Kitchen by Pizza Oven	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1001-10	Kitchen Island Left	SK	App	1.17	11/19/2020	-	-	-	None	-	-	-
1001-11	Kitchen Island Right	SPY	App	<1.0	11/19/2020	-	-	-	None	-	-	-
1001-12	Kitchen	PF	App	3.85	11/19/2020	-	-	-	None	-	-	-
1002-01	Cafeteria by Serving Line A	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
1002-02	Cafeteria by Serving Line A	BF	App	<1.0	11/19/2020	-	-	-	None	-	-	-
1002-03	Cafeteria by Serving Line B	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
1002-04	Cafeteria by Serving Line B	BF	App	<1.0	11/19/2020	-	-	-	None	-	-	-
1003-01	Custodial Area Bathroom	SK	App	<1.0	11/19/2020	-	-	-	None	-	-	-
1003-02	Custodial Area	SS	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1004-01	Room 116 Station 1	SK	App	9.22	11/19/2020	-	-	-	None	-	-	-
1004-02	Room 116 Station 2	SK	App	13.2	11/19/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1004-03	Room 116 Station 3	SK	App	9.67	11/19/2020	-	-	-	None	-	-	-
1004-04	Room 116 Station 4	SK	App	8.08	11/19/2020	-	-	-	None	-	-	-
1004-05	Room 116 Station 5	SK	App	11.1	11/19/2020	-	-	-	None	-	-	-
1005-01	Room 117 Station 1	SK	App	8.1	11/19/2020	-	-	-	None	-	-	-
<b>1005-02</b>	<b>Room 117 Station 2</b>	<b>SK</b>	<b>App</b>	<b>16.8</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
1005-03	Room 117 Station 3	SK	App	14	11/19/2020	-	-	-	None	-	-	-
1005-04	Room 117 Station 4	SK	App	11.4	11/19/2020	-	-	-	None	-	-	-
<b>1005-05</b>	<b>Room 117 Station 5</b>	<b>SK</b>	<b>App</b>	<b>24.5</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
1006-01	Room 118	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1007-01	Women's Bathroom by Cafeteria @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1007-02	Women's Bathroom by Cafeteria @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1007-03	Women's Bathroom by Cafeteria @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1007-04	Women's Bathroom by Cafeteria @ D	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1007-05	Women's Bathroom by Cafeteria @ E	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1007-06	Women's Bathroom by Cafeteria @ F	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1008-01	Hall by Large Group Instruction Left	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
1008-02	Hall by Large Group Instruction Left	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
1009-01	Men's Bathroom by Cafeteria @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1009-02	Men's Bathroom by Cafeteria @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1009-03	Men's Bathroom by Cafeteria @ C	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1009-04	Men's Bathroom by Cafeteria @ D	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1009-05	Men's Bathroom by Cafeteria @ E	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1009-06	Men's Bathroom by Cafeteria @ F	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1010-01	Girl's Coach's Office	IM	App	6.2	1/4/2020	-	-	-	None	-	-	-
1010-02	Girl's Coach's Office Bathroom	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1010-03	Girl's Locker Room by Coach's Office	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
1010-04	Girl's Locker Room Left	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
1010-05	Girl's Locker Room Right	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
1010-06	Girl's Locker Room Bathroom @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1010-07	Girl's Locker Room Bathroom @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1011-01	Boy's Gym Office	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1011-02	Boy's Locker Room	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
1011-03	Boy's Locker Room Bathroom @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1011-04	Boy's Locker Room Bathroom @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1012-01	Girl's Bathroom by Auditorium ADA	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1012-02	Girl's Bathroom by Auditorium @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1012-03	Girl's Bathroom by Auditorium @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1013-01	Boy's Bathroom by Auditorium ADA	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1013-02	Boy's Bathroom by Auditorium @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1013-03	Boy's Bathroom by Auditorium @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1014-01	Custodial Closet by Room 112	SS	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1015-01	Room 112	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1016-01	Unisex Bathroom by Room 112 @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1016-02	Unisex Bathroom by Room 112 @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1017-01	Hall by Room 111 Left	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
1017-02	Hall by Room 111 Right	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
1018-01	Room 110	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1019-01	Room 108	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
<b>1020-01</b>	<b>Pool Girl's Locker Room</b>	<b>WF</b>	<b>App</b>	<b>32.9</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
<b>1020-02</b>	<b>Pool Girl's Locker Room @ A</b>	<b>SK</b>	<b>App</b>	<b>23.1</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
1020-03	Pool Girl's Locker Room @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
<b>1021-01</b>	<b>Pool Boy's Locker Room</b>	<b>WF</b>	<b>App</b>	<b>16.5</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
1021-02	Pool Boy's Locker Room @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1021-03	Pool Boy's Locker Room @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1022-01	Pool Office Bathroom	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1023-01	Pool Deck Bathroom	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1024-01	Pool Filter Room	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-
1025-01	Men's Bathroom in Music Hallway	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1026-01	Women's Bathroom in Music Hallway	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
<b>1027-01</b>	<b>Room 106 Unit @ A</b>	<b>SK</b>	<b>App</b>	<b>35.3</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1027-02	Room 106 Unit @ B	SK	App	45	11/19/2020				Additional Sampling Required			
1028-01	Room 105 /106 Office	SK	App	117	11/19/2020				Additional Sampling Required			
1029-01	Room 105 Unit @ A	SK	App	12.8	11/19/2020	-	-	-	None	-	-	-
1029-02	Room 105 Unit @ B	SK	App	11	11/19/2020	-	-	-	None	-	-	-
1030-01	Room 104 Unit @ A	SK	App	13.3	11/19/2020	-	-	-	None	-	-	-
1030-02	Room 104 Unit @ B	SK	App	18.2	11/19/2020				Additional Sampling Required			
1031-01	Room 104 / 103 Office	SK	N/A		11/19/2020	-	-	-	None	Removed From Service	-	-
1032-01	Room 103 Unit @ A	SK	App	15.2	11/19/2020				Additional Sampling Required			
1032-02	Room 103 Unit @ B	SK	App	15.8	11/19/2020				Additional Sampling Required			
1033-01	Hall by Room 103 Left	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
1033-02	Hall by Room 103 Right	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
1034-01	Custodial Closet by Room 102	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-
1035-01	Room 102	SK	App	6.27	11/19/2020	-	-	-	None	-	-	-
1036-01	Main Office Kitchenette	SK	App	21.2	11/19/2020				Additional Sampling Required			
1037-01	Men's Faculty Bathroom by Serving Line A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1038-01	Women's Faculty Bathroom by Serving Line A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1039-01	Hall by Teacher's Dining Room - Right	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
1039-02	Hall by Teacher's Dining Room - Right	BF	App	<1.0	11/19/2020	-	-	-	None	-	-	-
1039-03	Hall by Teacher's Dining Room - Left	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
1040-01	Teacher's Dining Room	SK	App	1.18	11/19/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1041-01	Nurse's Office	SK	App	7.42	11/19/2020	-	-	-	None	-	-	-
1041-02	Nurse's Office Right Bathroom	SK	App	1.41	11/19/2020	-	-	-	None	-	-	-
1041-03	Nurse's Office Left Bathroom	SK	App	2.19	11/19/2020	-	-	-	None	-	-	-
1042-01	Boiler Room	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-
1043-01	Room 101	SK	N/A		11/19/2020	-	-	-	None	Removed From Service	-	-
2001-01	Men's Faculty Bathroom by Room 238 @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2001-02	Men's Faculty Bathroom by Room 238 @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2001-03	Men's Faculty Bathroom by Room 238 @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2001-04	Men's Faculty Bathroom by Room 238 @ D	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2002-01	Women's Faculty Bathroom by Room 238 @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2002-02	Women's Faculty Bathroom by Room 238 @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2002-03	Women's Faculty Bathroom by Room 238 @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2002-04	Women's Faculty Bathroom by Room 238 @ D	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2003-01	Room 239 Table 1 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2003-02	Room 239 Table 1 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2003-03	Room 239 Table 2 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2003-04	Room 239 Table 2 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2003-05	Room 239 Table 3 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2003-06	Room 239 Table 3 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2003-07	Room 239 Table 4 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2003-08	Room 239 Table 4 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2004-01	Science Prep Counter by Room 239	SK	App	5.26	11/19/2020	-	-	-	None	-	-	-
2004-02	Science Prep Counter by Room 207	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2004-03	Science Prep Counter by Room 243	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2004-04	Science Prep Table by Room 232	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2004-05	Science Prep Table by Room 206	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2005-01	Room 232 Table 1 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2005-02	Room 232 Table 1 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2005-03	Room 232 Table 2 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2005-04	Room 232 Table 2 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2005-05	Room 232 Table 3 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2005-06	Room 232 Table 3 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2005-07	Room 232 Table 4 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2005-08	Room 232 Table 4 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2006-01	Room 231 Table 1 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2006-02	Room 231 Table 1 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2006-03	Room 231 Table 2 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2006-04	Room 231 Table 2 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2006-05	Room 231 Table 3 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2006-06	Room 231 Table 3 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2006-07	Room 231 Table 4 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2006-08	Room 231 Table 4 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2007-01	Room 246 Table 1 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2007-02	Room 246 Table 1 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2007-03	Room 246 Table 2 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2007-04	Room 246 Table 2 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2007-05	Room 246 Table 3 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2007-06	Room 246 Table 3 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2007-07	Room 246 Table 4 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2007-08	Room 246 Table 4 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2008-01	Room 245 Teacher's Station	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2008-02	Room 245 Table 1 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2008-03	Room 245 Table 1 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2008-04	Room 245 Table 2 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2008-05	Room 245 Table 2 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2008-06	Room 245 Table 3 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2008-07	Room 245 Table 3 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2008-08	Room 245 Table 4 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2008-09	Room 245 Table 4 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2009-01	Room 207 Table 1 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2009-02	Room 207 Table 1 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2009-03	Room 207 Table 2 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2009-04	Room 207 Table 2 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2009-05	Room 207 Table 3 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2009-06	Room 207 Table 3 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2010-01	Room 206 Teacher's Station	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2010-02	Room 206 Table 1 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2010-03	Room 206 Table 1 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2010-04	Room 206 Table 2 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2010-05	Room 206 Table 2 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2010-06	Room 206 Table 3 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2010-07	Room 206 Table 3 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2010-08	Room 206 Table 4 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2010-09	Room 206 Table 4 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2011-01	Room 243 Teacher's Station	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2011-02	Room 243 Table 1 @ A	SK	N/A		11/19/2020	-	-	-	None	Removed From Service	-	-
2011-03	Room 243 Table 1 @ B	SK	N/A		11/19/2020	-	-	-	None	Removed From Service	-	-
2011-04	Room 243 Table 2 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2011-05	Room 243 Table 2 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2011-06	Room 243 Table 3 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2011-07	Room 243 Table 3 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2011-08	Room 243 Table 4 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2011-09	Room 243 Table 4 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2012-01	Room 240 Table 1 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2012-02	Room 240 Table 1 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2012-03	Room 240 Table 2 @ A	SK	N/A		11/19/2020	-	-	-	None	Removed From Service	-	-
2012-04	Room 240 Table 2 @ B	SK	N/A		11/19/2020	-	-	-	None	Removed From Service	-	-
2012-05	Room 240 Table 3 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2012-06	Room 240 Table 3 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2012-07	Room 240 Table 4 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2012-08	Room 240 Table 4 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2013-01	Hall by Room 234 Left	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
2013-02	Hall by Room 234 Right	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
2014-01	Custodial Closet by Room 233	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-
2015-01	Room 247	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2016-01	Library Office	SK	App	<1.0	11/19/2020	-	-	-	None	-	-	-
2017-01	Custodial Closet by Library Office	SS	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2018-01	Unisex Left BR by Library Office	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2019-01	Unisex Right BR by Library Office	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2019-02	Unisex Right BR by Library Office	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2020-01	Boy's Bathroom by Room 229	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2021-01	Hall by Room 229 Left	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
2021-02	Hall by Room 229 Right	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
2022-01	Hall by Room 214 Left	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
2022-02	Hall by Room 214 Right	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
2023-01	Girl's Bathroom by Room 214 @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2023-02	Girl's Bathroom by Room 214 @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2024-01	Women's Bathroom by Room 213 @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2024-02	Women's Bathroom by Room 213 @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2025-01	Men's Bathroom by Room 213	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2026-01	Custodial Closet by Room 212	SS	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2027-01	Custodial Closet by Room 205	SS	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
2028-01	Hall by Room 204 Left	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
2028-02	Hall by Room 204 Right	WF	App		11/19/2020	-	-	-	None	Removed From Service	-	-
2029-01	Boy's Bathroom by Room 244 @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2029-02	Boy's Bathroom by Room 244 @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2029-03	Boy's Bathroom by Room 244 @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2029-04	Boy's Bathroom by Room 244 @ D	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2029-05	Girl's Bathroom by Room 244 @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2029-06	Girl's Bathroom by Room 244 @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2029-07	Girl's Bathroom by Room 244 @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2029-08	Girl's Bathroom by Room 244 @ D	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-

## Laboratory Report

NYE Report #: 2204644-16262

November 24, 2020

Project Manager  
Enviroscience Consultants, Inc.  
2150 Smithtown Avenue  
Ronkonkoma, NY 11779

Project: Sayville Middle School

Dear Project Manager,


Enclosed is the Laboratory Analytical Report for potable water sample(s) received on November 23, 2020. New York Environmental analyzed the samples on November 23, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



---

Li Tsang, Laboratory Director

Date Collected:	19 Nov 2020
Date Received:	23 Nov 2020
Date Analyzed:	23 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201123J005	1	Serving Line A -SK; Initial	1.00	1.23	µg/L	
201123J006	2	Kitchen by Ice Machine-SK; Initial	1.00	4.03	µg/L	
201123J007	3	Serving Line B-SK; Initial	1.00	5.57	µg/L	
201123J008	4	Kitchen Island Left-SK; Initial	1.00	1.17	µg/L	
201123J009	5	Kitchen Island Right-SPY; Initial	1.00	<1.00	µg/L	
201123J010	6	Kitchen-PF; Initial	1.00	3.85	µg/L	
201123J011	7	Kitchen-IM; Initial	1.00	<1.00	µg/L	
201123J012	8	Room 116 Station 1-SK; Initial	1.00	9.22	µg/L	
201123J013	9	Room 116 Station 2-SK; Initial	1.00	13.2	µg/L	
201123J014	10	Room 116 Station 3-SK; Initial	1.00	9.67	µg/L	
201123J015	11	Room 116 Station 4-SK; Initial	1.00	8.08	µg/L	
201123J016	12	Room 116 Station 5-SK; Initial	1.00	11.1	µg/L	
201123J017	13	Room 117 Station 1-SK; Initial	1.00	8.10	µg/L	
201123J018	14	Room 117 Station 2-SK; Initial	1.00	16.8	µg/L	H
201123J019	15	Room 117 Station 3-SK; Initial	1.00	14.0	µg/L	
201123J020	16	Room 117 Station 4-SK; Initial	1.00	11.4	µg/L	
201123J021	17	Room 117 Station 5-SK; Initial	1.00	24.5	µg/L	H
201123J022	18	Room 106 Unit @ A-SK; Initial	1.00	35.3	µg/L	H
201123J023	19	Room 106 Unit @ B-SK; Initial	1.00	45.0	µg/L	H
201123J024	20	Room 105 /106 Office-SK; Initial	1.00	117	µg/L	E,H
201123J025	21	Room 105 Unit @ A-SK; Initial	1.00	12.8	µg/L	
201123J026	22	Room 105 Unit @ B-SK; Initial	1.00	11.0	µg/L	
201123J027	23	Room 104 Unit @ A-SK; Initial	1.00	13.3	µg/L	
201123J028	24	Room 104 Unit @ B-SK; Initial	1.00	18.2	µg/L	H
201123J029	25	Room 103 Unit @ A-SK; Initial	1.00	15.2	µg/L	H
201123J030	26	Room 103 Unit @ B-SK; Initial	1.00	15.8	µg/L	H



Date Collected:	19 Nov 2020
Date Received:	23 Nov 2020
Date Analyzed:	23 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201123J031	27	Room 102-SK; Initial	1.00	6.27	µg/L	
201123J032	28	Main Office Kitchenette-SK; Initial	1.00	21.2	µg/L	H
201123J033	29	Hall by Teacher's Dining Room - Right-BF; Initial	1.00	<1.00	µg/L	
201123J034	30	Teacher's Dining Room-SK; Initial	1.00	1.18	µg/L	
201123J035	31	Nurse's Office-SK; Initial	1.00	7.42	µg/L	
201123J036	32	Nurse's Office Right Bathroom-SK; Initial	1.00	1.41	µg/L	
201123J037	33	Nurse's Office Left Bathroom-SK; Initial	1.00	2.19	µg/L	
201123J038	34	Cafeteria by Serving Line A-BF; Initial	1.00	<1.00	µg/L	
201123J039	35	Cafeteria by Serving Line B-BF; Initial	1.00	<1.00	µg/L	
201123J040	36	Custodial Area Bathroom-SK; Initial	1.00	<1.00	µg/L	
201123J041	37	Science Prep Counter by Room 239-SK; Initial	1.00	5.26	µg/L	
201123J042	38	Library Office-SK; Initial	1.00	<1.00	µg/L	
201123J043	39	Pool Girl's Locker Room-WF; Initial	1.00	32.9	µg/L	H
201123J044	40	Pool Girl's Locker Room @ A-SK; Initial	1.00	23.1	µg/L	H
201123J045	41	Pool Boy's Locker Room-WF; Initial	1.00	16.5	µg/L	H

Comment:

CID: Client ID LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.

## Appendix E

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
0001-1	Room L10A Trough @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
0001-2	Room L10A Trough @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
0001-3	Room L10A Trough @ C	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
0001-4	Room L10A Trough @ D	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
0002-1	Room L60 Birdbath	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
0003-1	Men's Faculty Bathroom by Room L40	SK	App	1.83	11/19/2020	-	-	-	None	-	-	-
0004-1	Custodial Closet by L30	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-
0005-1	Women's Faculty Bathroom by Room L40	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
0006-1	Hall by Room L30	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
0007-1	Room L30 Teacher's Station	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
0007-2	Room L30 Counter 1 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
0007-3	Room L30 Counter 1 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
0007-4	Room L30 Counter 1 @ C	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
0007-5	Room L30 Counter 2	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1001-1	Kitchen Handwash @A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
<b>1001-2</b>	<b>Kitchen 4-Bay @ A</b>	<b>SK</b>	<b>App</b>	<b>54.4</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
1001-3	Kitchen 4-Bay @ B	SPY	App	7.99	11/19/2020	-	-	-	None	-	-	-
1001-4	Kitchen 4-Bay @ B	SK	App	6.29	11/19/2020	-	-	-	None	-	-	-
<b>1001-5</b>	<b>Kitchen 4-Bay @ C</b>	<b>SK</b>	<b>App</b>	<b>29.1</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
1001-6	Kitchen 4-Bay @ D	SK	App	12.7	11/19/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1001-7	Kitchen Dishwasher Room @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1001-8	Kitchen Dishwasher Room @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1001-9	Kitchen Handwash @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1001-10	Kitchen 2-Bay @ A	SK	App	5.73	11/19/2020	-	-	-	None	-	-	-
1001-11	Kitchen 2-Bay @ B	SK	App	11.5	11/19/2020	-	-	-	None	-	-	-
1001-12	Kitchen Island Prep	SK	App	12.2	11/19/2020	-	-	-	None	-	-	-
<b>1001-13</b>	<b>Kitchen Potfiller Right</b>	<b>PF</b>	<b>App</b>	<b>29.9</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
1001-14	Kitchen Potfiller Left	PF	App	14.6	11/19/2020	-	-	-	None	-	-	-
1001-15	Serving Line Handwash @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1001-16	Serving Line Handwash @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1001-17	Serving Line Handwash @ C	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1001-18	Kitchen Lunch Room	SK	App	1.6	11/19/2020	-	-	-	None	-	-	-
1002-1	Cafeteria-left	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1002-2	Cafeteria-left	BF	App	<1.0	11/16/2020	-	-	-	None	-	-	-
1002-3	Cafeteria-right	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1003-1	Senior Lounge	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1003-2	Senior Lounge	BF	App	<1.0	11/19/2020	-	-	-	None	-	-	-
1004-1	Kitchen C-Snack Room	SK	App	5.8	11/19/2020	-	-	-	None	-	-	-
1005-1	Attendance Office Bathroom	SK	App	2.13	11/19/2020	-	-	-	None	-	-	-
1006-1	Principal's Office Bathroom	SK	App	<1.0	11/19/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1007-1	Custodial Closet by Security Office	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-
1008-1	Boy's Bathroom by Security Office@ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1008-2	Boy's Bathroom by Security Office@ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1009-1	Girl's Bathroom by Security Office @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1009-2	Girl's Bathroom by Security Office @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1010-1	Stage Crew Closet	SS	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1011-1	Room 128	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1012-1	Men's Bathroom by Auditorium	SK	App	3.5	11/19/2020	-	-	-	None	-	-	-
1013-1	Women's Bathroom by Auditorium	SK	App	4.24	11/19/2020	-	-	-	None	-	-	-
1014-1	Hall by Storage K - left	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1014-2	Hall by Storage K - right	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1015-1	Nurse's Office	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1015-2	Nurse's Office Right Bathroom	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1015-3	Nurse's Office Left Bathroom	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1016-1	Room 101 - Special Education	SK	App	3.83	11/19/2020	-	-	-	None	-	-	-
1017-1	Men's Bathroom by Room 98	SK	App	<1.0	11/19/2020	-	-	-	None	-	-	-
1018-1	Women's Bathroom by Room 98	SK	App	<1.0	11/19/2020	-	-	-	None	-	-	-
1019-1	Custodial Closet by Room 98	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-
1020-1	Hall by Room 98-left	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1020-2	Hall by Room 98-left	BF	App	<1.0	12/3/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1020-3	Hall by Room 98-right	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1021-1	Room 98 Teacher's Station	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1021-2	Room 98 Pod 1	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1021-3	Room 98 Pod 2	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1021-4	Room 98 Pod 3	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1021-5	Room 98 Pod 4	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1021-6	Room 98 Pod 5	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1021-7	Room 98 Pod 6 @A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1021-8	Room 98 Pod 6 @B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1021-9	Room 98 Fume Hood spigot	SP	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1021-10	Room 98 Prep Room	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1022-1	Room 96 Teacher's Station	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1022-2	Room 96 Counter @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1022-3	Room 96 Counter @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1022-4	Room 96 Counter @ C	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1022-5	Room 96 Counter @ D	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1022-6	Room 96 Pod 1 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1022-7	Room 96 Pod 1 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1022-8	Room 96 Pod 2 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1022-9	Room 96 Pod 2 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1022-10	Room 96 Pod 3 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1022-11	Room 96 Pod 3 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1022-12	Room 96 Pod 4 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1022-13	Room 96 Pod 4 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1023-1	Room 102 Teacher's Station	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1023-2	Room 102 Counter 1	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1023-3	Room 102 Counter 2	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1024-1	Hall by Room 102-left	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1024-2	Hall by Room 102-right	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1025-1	Room 104 Teacher's Station	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1025-2	Room 104 Counter 1 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1025-3	Room 104 Counter 1 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1025-4	Room 104 Counter 2 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1025-5	Room 104 Counter 2 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1025-6	Room 104 Back Counter	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1025-7	Room 104 Side Counter	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1026-1	Room 103 Pod 1 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1026-2	Room 103 Pod 1 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1026-3	Room 103 Pod 2 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1026-4	Room 103 Pod 2 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1026-5	Room 103 Pod 3 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1026-6	Room 103 Pod 3 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1027-1	Room 107 Pod 1 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1027-2	Room 107 Pod 1 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1027-3	Room 107 Pod 2 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1027-4	Room 107 Pod 2 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1027-5	Room 107 Pod 3 @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1027-6	Room 107 Pod 3 @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1027-7	Room 107 Counter	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1028-1	Room 108 Teacher's Station @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1028-2	Room 108 Teacher's Station @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1028-3	Room 108 Center Wall @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1028-4	Room 108 Center Wall @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1028-5	Room 108 Rear Counter @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1028-6	Room 108 Rear Counter @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1028-7	Room 108 Side Counter @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1028-8	Room 108 Side Counter @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1029-1	Room 110 Teacher's Station	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1029-2	Room 110 Counter	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1029-3	Room 110 Pod 1 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1029-4	Room 110 Pod 1 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1029-5	Room 110 Pod 2 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1029-6	Room 110 Pod 2 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1029-7	Room 110 Pod 3 @ A	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1029-8	Room 110 Pod 3 @ B	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1030-1	Room 111 Teacher's Station @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1030-2	Room 111 Teacher's Station @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1030-3	Room 111 Counter @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1030-4	Room 111 Counter @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1031-1	Hall by Room 110 - left	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1031-1	Hall by Room 110 - right	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1032-1	Room 112 Counter	SK	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1032-2	Room 112 Pod 1 @ A	SK	N/A		11/19/2020	-	-	-	None	Removed from service	-	-
1032-3	Room 112 Pod 1 @ B	SK	N/A		11/19/2020	-	-	-	None	Removed from service	-	-
1032-4	Room 112 Pod 2 @A	SK	N/A		11/19/2020	-	-	-	None	Removed from service	-	-
1032-5	Room 112 Pod 2 @B	SK	N/A		11/19/2020	-	-	-	None	Removed from service	-	-
1032-6	Room 112 Prep Room	SK	App	7.69	11/19/2020	-	-	-	None	-	-	-
1033-1	Custodial Closet by Room 112	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-
1034-1	Library Office	SK	App	6.37	11/19/2020	-	-	-	None	-	-	-
1035-1	Boy's Bathroom by Room 113 @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1035-2	Boy's Bathroom by Room 113 @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1035-3	Boy's Bathroom by Room 113 @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1035-4	Boy's Bathroom by Room 113 @ D	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1035-5	Boy's Bathroom by Room 113 @ E	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1036-1	Girl's Bathroom by Room 113 @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1036-2	Girl's Bathroom by Room 113 @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1036-3	Girl's Bathroom by Room 113 @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1036-4	Girl's Bathroom by Room 113 @ D	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1036-5	Girl's Bathroom by Room 113 @ E	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1037-1	Hall by Room 113 - left	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1037-2	Hall by Room 113 - right	WF	App		11/19/2020	-	-	-	None	-	-	-
1038-1	Hall by Room 122 - left	WF	App		11/19/2020	-	-	-	None	-	-	-
1038-2	Hall by Room 122 - left	BF	App	<1.0	11/19/2020	-	-	-	None	-	-	-
1038-3	Hall by Room 122 - right	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1039-1	First Floor Faculty Room	SK	App	1.41	11/19/2020	-	-	-	None	-	-	-
1040-1	Unisex Faculty Bathroom - right	SK	N/A	7.41	11/19/2020	-	-	-	None	SIGN	-	-
1041-1	Unisex Faculty Bathroom - left	SK	App		11/19/2020	-	-	-	None	-	-	-
1042-1	Boy's Bathroom by Room 134 @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1042-2	Boy's Bathroom by Room 134 @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1042-3	Boy's Bathroom by Room 134 @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1042-4	Boy's Bathroom by Room 134 @ D	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1043-1	Custodial Closet by Room 134	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-
1044-1	Girl's Bathroom by Room 134 @ A	SK	App	9.31	11/19/2020	-	-	-	None	-	-	-
1044-2	Girl's Bathroom by Room 134 @ B	SK	App	13.9	11/19/2020	-	-	-	None	-	-	-
<b>1044-3</b>	<b>Girl's Bathroom by Room 134 @ C</b>	<b>SK</b>	<b>App</b>	<b>40.2</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
1044-4	Girl's Bathroom by Room 134 @ D	SK	App		11/19/2020	-	-	-	None	Removed from service	-	-
1045-1	Hall by Room 134	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1046-1	Art Room 135 @ A	SK	App	1.55	11/19/2020	-	-	-	None	-	-	-
1046-2	Art Room 135 @ B	SK	App	2.24	11/19/2020	-	-	-	None	-	-	-
1047-1	Art Room 137 @ A	SK	App	2.9	11/19/2020	-	-	-	None	-	-	-
1047-2	Art Room 137 @ B	SK	App	2.34	11/19/2020	-	-	-	None	-	-	-
1048-1	Art Room 138 @ A	SK	App	<1.0	11/19/2020	-	-	-	None	-	-	-
1048-2	Art Room 138 @ B	SK	App	1.33	11/19/2020	-	-	-	None	-	-	-
1049-1	Athletic Trainer Ice Machine	IM	App		11/19/2020	-	-	-	None	Removed from service	-	-
<b>1049-2</b>	<b>Athletic Trainer @ A</b>	<b>SK</b>	<b>App</b>	<b>53.4</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
<b>1049-3</b>	<b>Athletic Trainer @ B</b>	<b>SK</b>	<b>App</b>	<b>68.3</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
1050-1	Boy's Locker Room	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1050-2	Boy's Locker Room @A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1050-3	Boy's Locker Room @B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1051-1	Custodial Closet by Athletic Trainer	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1052-1	Men's Bathroom in Gym Lobby	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1053-1	Gym Lobby	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1053-2	Gym Lobby	BF	App	<1.0	11/19/2020	-	-	-	None	-	-	-
1054-1	Women's Bathroom in Gym Lobby	SK	App	11	11/19/2020	-	-	-	None	-	-	-
1055-1	Girl's Locker Room	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1055-2	Girl's Locker Room @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1055-3	Girl's Locker Room @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1055-4	Girl's Locker Room @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1056-1	Girl's Physical Education Office	SK	App		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1057-1	Girl's Locker Room Back Lobby	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
<b>1058-1</b>	<b>Girl's Lower Locker Room @A</b>	<b>SK</b>	<b>App</b>	<b>108</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
1058-2	Girl's Lower Locker Room @B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1059-1	Wellness Center - left	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1059-2	Wellness Center - left	BF	App	<1.0	11/16/2020	-	-	-	None	-	-	-
1059-3	Wellness Center - right	WF	App		11/19/2020	-	-	-	None	-	-	-
1059-4	Wellness Center Women's Bathroom @ A	SK	App	5.11	11/19/2020	-	-	-	None	-	-	-
1059-5	Wellness Center Women's Bathroom @ B	SK	App	6.99	11/19/2020	-	-	-	None	-	-	-
1059-6	Wellness Center Women's Bathroom @ C	SK	App	9.59	11/19/2020	-	-	-	None	-	-	-
1059-7	Wellness Center Men's Bathroom @ A	SK	App	3.51	11/19/2020	-	-	-	None	-	-	-
1059-8	Wellness Center Men's Bathroom @ B	SK	App	4.5	11/19/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1059-9	Wellness Center Men's Bathroom @ C	SK	App	5.51	11/19/2020	-	-	-	None	-	-	-
1060-1	Boy's Physical Education Office	SK	App	7.09	11/19/2020	-	-	-	None	-	-	-
1061-1	Boy's Locker Room Back Lobby	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1062-1	Boy's Lower Locker Room	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
1062-2	Boy's Lower Locker Room @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1062-3	Boy's Lower Locker Room @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2001-1	English Department Faculty Room	SK	App	2.17	11/19/2020	-	-	-	None	-	-	-
2002-1	Women's Faculty Bathroom by Room 234	SK	App	7.41	11/19/2020	-	-	-	None	-	-	-
2003-1	Men's Faculty Bathroom by Room 234	SK	App	1.82	11/19/2020	-	-	-	None	-	-	-
2004-1	Boy's Bathroom by Room 234 @ A	SK	App	7.43	11/19/2020	-	-	-	None	-	-	-
2004-2	Boy's Bathroom by Room 234 @ B	SK	App	11.4	11/19/2020	-	-	-	None	-	-	-
2004-3	Boy's Bathroom by Room 234 @ C	SK	App	11	11/19/2020	-	-	-	None	-	-	-
2005-1	Girl's Bathroom by Room 234 @ A	SK	App	8.08	11/19/2020	-	-	-	None	-	-	-
2005-2	Girl's Bathroom by Room 234 @ B	SK	App	14.4	11/19/2020	-	-	-	None	-	-	-
2005-3	Girl's Bathroom by Room 234 @ C	SK	App	14.6	11/19/2020	-	-	-	None	-	-	-
2006-1	Hall by Room 234 - left	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
2006-2	Hall by Room 234 - right	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
2007-1	Custodial Closet by Room 234	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-
2008-1	Hall by Room 208 - left	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
2008-2	Hall by Room 208 - right	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2009-1	Room 200C Life Skills	SK	App	1.66	11/19/2020	-	-	-	None	-	-	-
2010-1	Hall by Room 200B - left	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
2010-2	Hall by Room 200B - right	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
2011-1	Room 200A @ A	SK	App	46.9	11/19/2020				Additional Sampling Required			
2011-2	Room 200A @ B	SK	App	19.7	11/19/2020				Additional Sampling Required			
2011-3	Room 200A @ C	SK	App	47.1	11/19/2020				Additional Sampling Required			
2012-1	Boy's Bathroom by Room 211A @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2012-2	Boy's Bathroom by Room 211A @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2012-3	Boy's Bathroom by Room 211A @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2012-4	Boy's Bathroom by Room 211A @ D	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2012-5	Boy's Bathroom by Room 211A @ E	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2012-6	Boy's Bathroom by Room 211A @ F	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2013-1	Girl's Bathroom by Room 211A @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2013-2	Girl's Bathroom by Room 211A @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2013-3	Girl's Bathroom by Room 211A @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2013-4	Girl's Bathroom by Room 211A @ D	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2013-5	Girl's Bathroom by Room 211A @ E	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2013-6	Girl's Bathroom by Room 211A @ F	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2013-7	Girl's Bathroom by Room 211A @ G	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2014-1	Second Floor Faculty Room	SK	App	6.7	11/19/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2014-2	Second Floor Faculty Room Men's Bathroom	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2014-3	Second Floor Faculty Room Women's Bathroom @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
<b>2014-2</b>	<b>Second Floor Faculty Room Women's Bathroom @ B</b>	<b>SK</b>	<b>App</b>	<b>19.4</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
2015-1	Hall by Room 220 - left	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
2015-2	Hall by Room 220 - left	BF	App	<1.0	11/19/2020	-	-	-	None	-	-	-
2015-3	Hall by Room 220 - right	WF	App		11/19/2020	-	-	-	None	Removed from service	-	-
<b>2015-4</b>	<b>Room 121</b>	<b>SK</b>	<b>App</b>	<b>16.9</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
2015-5	Custodial Office Bathroom	SK	App	1.42	11/19/2020	-	-	-	None	-	-	-
2015-6	Kitchen Bathroom @ A	SK	App	5.3	11/19/2020	-	-	-	None	-	-	-
2015-7	Kitchen Bathroom @ B	SK	App	2.76	11/19/2020	-	-	-	None	-	-	-

## Laboratory Report

NYE Report #: 2204555-16195

November 16, 2020

Project Manager  
Enviroscience Consultants, Inc.  
2150 Smithtown Avenue  
Ronkonkoma, NY 11779

Project: Sayville High School

Dear Project Manager,


Enclosed is the Laboratory Analytical Report for potable water sample(s) received on November 16, 2020. New York Environmental analyzed the samples on November 16, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



---

Li Tsang, Laboratory Director

Date Collected:	16 Nov 2020
Date Received:	16 Nov 2020
Date Analyzed:	16 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

<u>Lab ID</u>	<u>CID</u>	<u>Sample Location/Description</u>	<u>LOQ</u>	<u>Result</u>	<u>Units</u>	<u>Flag</u>
201116J023	1	Cafeteria, Left-BF; Initial	1.00	<1.00	µg/L	
201116J024	2	Wellness Center, Left-BF; Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

## Laboratory Report

NYE Report #: 2204646-16264

November 24, 2020

Project Manager  
Enviroscience Consultants, Inc.  
2150 Smithtown Avenue  
Ronkonkoma, NY 11779

Project: Sayville High School

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on November 23, 2020. New York Environmental analyzed the samples on November 23, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



---

Li Tsang, Laboratory Director

Date Collected:	19 Nov 2020
Date Received:	23 Nov 2020
Date Analyzed:	23 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201123J121	1	Kitchen 4-Bay @ A-SK; Initial	1.00	54.4	µg/L	E,H
201123J122	2	Kitchen 4-Bay @ B-SPY; Initial	1.00	7.99	µg/L	
201123J123	3	Kitchen 4-Bay @ B-SK; Initial	1.00	6.29	µg/L	
201123J124	4	Kitchen 4-Bay @ C-SK; Initial	1.00	29.1	µg/L	H
201123J125	5	Kitchen 4-Bay @ D-SK; Initial	1.00	12.7	µg/L	
201123J126	6	Kitchen 2-Bay @ A-SK; Initial	1.00	5.73	µg/L	
201123J127	7	Kitchen 2-Bay @ B-SK; Initial	1.00	11.5	µg/L	
201123J128	8	Kitchen Island Prep-SK; Initial	1.00	12.2	µg/L	
201123J129	9	Kitchen Potfiller Right-PF; Initial	1.00	29.9	µg/L	H
201123J130	10	Kitchen Potfiller Left-PF; Initial	1.00	14.6	µg/L	
201123J131	11	Kitchen Lunch Room-SK; Initial	1.00	1.60	µg/L	
201123J132	12	Senior Lounge-BF; Initial	1.00	<1.00	µg/L	
201123J133	13	Kitchen C-Snack Room-SK; Initial	1.00	5.80	µg/L	
201123J134	14	Attendance Office Bathroom-SK; Initial	1.00	2.13	µg/L	
201123J135	15	Principal's Office Bathroom-SK; Initial	1.00	<1.00	µg/L	
201123J136	16	Men's Bathroom by Auditorium-SK; Initial	1.00	3.50	µg/L	
201123J137	17	Women's Bathroom by Auditorium-SK; Initial	1.00	4.24	µg/L	
201123J138	18	Room 101 - Special Education-SK; Initial	1.00	3.83	µg/L	
201123J139	19	Men's Bathroom by Room 98-SK; Initial	1.00	<1.00	µg/L	
201123J140	20	Women's Bathroom by Room 98-SK; Initial	1.00	<1.00	µg/L	
201123J141	21	Room 112 Prep Room-SK; Initial	1.00	7.69	µg/L	
201123J142	22	Library Office-SK; Initial	1.00	6.37	µg/L	
201123J143	23	Hall by Room 122 - left-BF; Initial	1.00	<1.00	µg/L	
201123J144	24	First Floor Faculty Room -SK; Initial	1.00	1.41	µg/L	
201123J145	25	Unisex Faculty Bathroom - left-SK; Initial	1.00	7.41	µg/L	
201123J146	26	Girl's Bathroom by Room 134 @ A-SK; Initial	1.00	9.31	µg/L	



Date Collected:	19 Nov 2020
Date Received:	23 Nov 2020
Date Analyzed:	23 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201123J147	27	Girl's Bathroom by Room 134 @ B-SK; Initial	1.00	13.9	µg/L	
201123J148	28	Girl's Bathroom by Room 134 @ C-SK; Initial	1.00	40.2	µg/L	H
201123J149	29	Art Room 135 @ A-SK; Initial	1.00	1.55	µg/L	
201123J150	30	Art Room 135 @ B-SK; Initial	1.00	2.24	µg/L	
201123J151	31	Art Room 137 @ A-SK; Initial	1.00	2.90	µg/L	
201123J152	32	Art Room 137 @ B-SK; Initial	1.00	2.34	µg/L	
201123J153	33	Art Room 138 @ A-SK; Initial	1.00	<1.00	µg/L	
201123J154	34	Art Room 138 @ B-SK; Initial	1.00	1.33	µg/L	
201123J155	35	Athletic Trainer @ A-SK; Initial	1.00	53.4	µg/L	E,H
201123J156	36	Athletic Trainer @ B-SK; Initial	1.00	68.3	µg/L	E,H
201123J157	37	Gym Lobby-BF; Initial	1.00	<1.00	µg/L	
201123J158	38	Women's Bathroom in Gym Lobby-SK; Initial	1.00	11.0	µg/L	
201123J159	39	Girl's Lower Locker Room @A-SK; Initial	1.00	108	µg/L	E,H
201123J160	40	Wellness Center Women's Bathroom @ A-SK; Initial	1.00	5.11	µg/L	
201123J161	41	Wellness Center Women's Bathroom @ B-SK; Initial	1.00	6.99	µg/L	
201123J162	42	Wellness Center Women's Bathroom @ C-SK; Initial	1.00	9.59	µg/L	
201123J163	43	Wellness Center Men's Bathroom @ A-SK; Initial	1.00	3.51	µg/L	
201123J164	44	Wellness Center Men's Bathroom @ B-SK; Initial	1.00	4.50	µg/L	
201123J165	45	Wellness Center Men's Bathroom @ C-SK; Initial	1.00	5.51	µg/L	
201123J166	46	Boy's Physical Education Office-SK; Initial	1.00	7.09	µg/L	
201123J167	47	English Department Faculty Room-SK; Initial	1.00	2.17	µg/L	
201123J168	48	Women's Faculty Bathroom by Room 234-SK; Initial	1.00	7.41	µg/L	
201123J169	49	Men's Faculty Bathroom by Room 234-SK; Initial	1.00	1.82	µg/L	
201123J170	50	Boy's Bathroom by Room 234 @ A-SK; Initial	1.00	7.43	µg/L	
201123J171	51	Boy's Bathroom by Room 234 @ B-SK; Initial	1.00	11.4	µg/L	
201123J172	52	Boy's Bathroom by Room 234 @ C-SK; Initial	1.00	11.0	µg/L	
201123J173	53	Girl's Bathroom by Room 234 @ A-SK; Initial	1.00	8.08	µg/L	



Date Collected:	19 Nov 2020
Date Received:	23 Nov 2020
Date Analyzed:	23 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201123J174	54	Girl's Bathroom by Room 234 @ B-SK; Initial	1.00	14.4	µg/L	
201123J175	55	Girl's Bathroom by Room 234 @ C-SK; Initial	1.00	14.6	µg/L	
201123J176	56	Room 200C Life Skills-SK; Initial	1.00	1.66	µg/L	
201123J177	57	Room 200A @ A-SK; Initial	1.00	46.9	µg/L	H
201123J178	58	Room 200A @ B-SK; Initial	1.00	19.7	µg/L	H
201123J179	59	Room 200A @ C-SK; Initial	1.00	47.1	µg/L	H
201123J180	60	Second Floor Faculty Room-SK; Initial	1.00	6.70	µg/L	
201123J181	61	Second Floor Faculty Room Women's Bathroom @ B-SK; Initial	1.00	19.4	µg/L	H
201123J182	62	Hall by Room 220 - left-BF; Initial	1.00	<1.00	µg/L	
201123J183	63	Men's Faculty Bathroom by Room L40-SK; Initial	1.00	1.83	µg/L	
201123J184	64	Room 121-SK; Initial	1.00	16.9	µg/L	H
201123J185	65	Custodial Office Bathroom-SK; Initial	1.00	1.42	µg/L	
201123J186	66	Kitchen Bathroom @ A-SK; Initial	1.00	5.30	µg/L	
201123J187	67	Kitchen Bathroom @ B-SK; Initial	1.00	2.76	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.

## Laboratory Report

NYE Report #: 2204808-16340

December 7, 2020

Project Manager  
Enviroscience Consultants, Inc.  
2150 Smithtown Avenue  
Ronkonkoma, NY 11779

Project: Sayville High School

Dear Project Manager,

Enclosed is the Laboratory Analytical Report for potable water sample(s) received on December 03, 2020. New York Environmental analyzed the samples on December 04, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



---

Li Tsang, Laboratory Director

Date Collected:	03 Dec 2020
Date Received:	03 Dec 2020
Date Analyzed:	04 Dec 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

<u>Lab ID</u>	<u>CID</u>	<u>Sample Location/Description</u>	<u>LOQ</u>	<u>Result</u>	<u>Units</u>	<u>Flag</u>
201203Q002	1	Hall by Room 98-Left-BF; Initial	1.00	<1.00	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

## Appendix F

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
0001-1	Basement	SK	App	1.08	11/19/2020	-	-	-	None	-	-	-
1001-1	Hall across from Auditorium	WF	App		11/19/2020	-	-	-	None	Removed from Service	-	-
1001-2	Hall across from Auditorium	BF	App	<1.0	11/19/2020	-	-	-	None	-	-	-
1002-1	1st Floor Custodial Closet	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-
1003-1	Men's Bathroom 1st Floor @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1003-2	Men's Bathroom 1st Floor @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1003-3	Men's Bathroom 1st Floor @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1004-1	Room 130	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1004-2	Room 130 BR	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1005-1	Women's Bathroom 1st Floor @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1005-2	Women's Bathroom 1st Floor @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1005-3	Women's Bathroom 1st Floor @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1006-1	Hall by Room 119	WF	App		11/19/2020	-	-	-	None	Removed from Service	-	-
1007-1	Lower Locker Room Storage Ice Machine	SL	App	24.7	1/5/2020				None		7.39	2/12/20
1007-1	Lower Locker Room Storage	IM	App	<1.0	11/19/2020	-	-	-	None	-	-	-
<b>1008-1</b>	<b>Lower Locker Room Bathroom Left</b>	<b>SK</b>	<b>App</b>	<b>33.5</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
<b>1008-2</b>	<b>Lower Locker Room Bathroom Right</b>	<b>SK</b>	<b>App</b>	<b>58.1</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
1008-3	Lower Locker Room Custodial Closet	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-
1009-1	Upper Locker Room Coach's Office	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
1009-2	Upper Locker Room	WF	App	15	11/19/2020	-	-	-	None		-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
1009-3	Upper Locker Room	OS	App	23.8	11/19/2020				Additional Sampling Required			
1009-3	Upper Locker Room Bathroom	SK	App	12.5	11/19/2020	-	-	-	None	-	-	-
1010-1	Restroom right of WF by Room 156	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1010-2	Restroom right of WF by Room 156 Custodial Closet	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-
1011-1	Hall by Room 156	WF	App		11/19/2020	-	-	-	None	Removed from Service	-	-
1012-1	Restroom left of WF by Room 156	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1013-1	IMC Rear Bathroom	SK	App	6.51	11/19/2020	-	-	-	None	-	-	-
1014-1	Concession Stand Women's Bathroom @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1014-2	Concession Stand Women's Bathroom @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1014-3	Concession Stand Women's Bathroom @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1015-1	Concession Stand Men's Bathroom @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1015-2	Concession Stand Men's Bathroom @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1015-3	Concession Stand Men's Bathroom @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
1016-1	Concession Stand Custodial Closet	SS	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1017-1	Concession Stand Kitchen 3-Bay Left	SK	App	3.36	11/19/2020	-	-	-	None	-	-	-
1017-2	Concession Stand Kitchen 3-Bay Right	SK	App	7.46	11/19/2020	-	-	-	None	-	-	-
1017-3	Concession Stand Kitchen	SK	App	<1.0	11/19/2020	-	-	-	None	-	-	-
1017-4	Concession Stand Kitchen Custodial Closet	SS	N/A		11/19/2020	-	-	-	Sign Required	-	-	-
1018-1	West Team Room Bathroom	SK	App	2.53	11/19/2020	-	-	-	None	-	-	-
1019-1	East Team Room Bathroom	SK	App	1.18	11/19/2020	-	-	-	None	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2001-1	Women's Bathroom 2nd Floor @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2001-2	Women's Bathroom 2nd Floor @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2001-3	Women's Bathroom 2nd Floor @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2002-1	Hall by Room 211A	WF	App		11/19/2020	-	-	-	None	Removed from Service	-	-
2003-1	Custodial Men's Bathroom	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2003-2	Custodial Women's Bathroom @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2003-3	Custodial Women's Bathroom @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2004-1	Room 224 Teacher's Station	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2004-2	Room 224 Counter @ A	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2004-3	Room 224 Counter @ B	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2004-4	Room 224 Counter @ C	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2004-5	Room 224 Counter @ D	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2005-1	Room 210 Science Prep	SK	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2005-2	Room 210 Science Prep	IM	N/A		11/19/2020	-	-	-	None	SIGN	-	-
2006-1	Room 211 @ A	SK	App	11.6	11/19/2020	-	-	-	None	-	-	-
<b>2006-2</b>	<b>Room 211 @ B</b>	<b>SK</b>	<b>App</b>	<b>83.8</b>	<b>11/19/2020</b>				<b>Additional Sampling Required</b>			
2007-1	Room 211A - Nurse Prep	SK	App	13.6	11/19/2020	-	-	-	None	-	-	-
2008-1	Men's Bathroom 2nd Floor @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2008-2	Men's Bathroom 2nd Floor @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
2008-3	Men's Bathroom 2nd Floor @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-

Space #	Sample Location	Fixture Type	App or N/A	Latest 1 <sup>st</sup> Draw Results (ppb)	Latest 1st Draw Sampling Date	15 Second Draw Results (ppb)	60 Second Draw Results (ppb)	Flush Sampling Date	Remedial Recommendation	Remedial Response	Post Remedial Results (ppb)	Post Remedial Sampling Date
2009-1	2nd Floor Custodial Closet	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-
2010-1	Hall by Room 204	WF	App		11/19/2020	-	-	-	None	Removed from Service	-	-
3001-1	Women's Bathroom 3rd Floor @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
3001-2	Women's Bathroom 3rd Floor @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
3001-3	Women's Bathroom 3rd Floor @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
3002-1	Hall by Room 311	WF	App		11/19/2020	-	-	-	None	Removed from Service	-	-
3003-1	Room 320 Faculty Room	SK	App	4.54	11/19/2020	-	-	-	None	-	-	-
3004-1	Men's Bathroom 3rd Floor @ A	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
3004-2	Men's Bathroom 3rd Floor @ B	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
3004-3	Men's Bathroom 3rd Floor @ C	SK	N/A		11/19/2020	-	-	-	Mixed Valve Sampling Not Required	-	-	-
3005-1	Hall by Room 303	WF	App		11/19/2020	-	-	-	None	Removed from Service	-	-
3006-1	3rd Floor Custodial Closet	SS	N/A		11/19/2020	-	-	-	None	Locked Door	-	-

## Laboratory Report

NYE Report #: 2204706-16304

November 30, 2020

Project Manager  
Enviroscience Consultants, Inc.  
2150 Smithtown Avenue  
Ronkonkoma, NY 11779

Project: Sayville Old Junior High School

Dear Project Manager,


Enclosed is the Laboratory Analytical Report for potable water sample(s) received on November 25, 2020. New York Environmental analyzed the samples on November 27, 2020 for Lead (Pb) by EPA Method 200.9 Rev. 2.2.

If there are any questions regarding the analyses, please feel free to contact us at your convenience. New York Environmental is a NELAP accredited laboratory. Attached reported results meet the requirements of the NELAP standards unless otherwise noted.

Samples' analytical results relate only to the samples tested, in the condition received by the laboratory. This report shall not be reproduced except in its entirety without written approval of the laboratory.

We sincerely thank you for your business, and look forward to being of service for your future environmental testing needs.

Sincerely,



---

Li Tsang, Laboratory Director

Date Collected:	19 Nov 2020
Date Received:	25 Nov 2020
Date Analyzed:	27 Nov 2020

Analytical Method:	EPA 200.9 Rev. 2.2
Analyte, Matrix:	Lead, Potable Water

Lab ID	CID	Sample Location/Description	LOQ	Result	Units	Flag
201125L056	1	Room 320 Faculty Room-SK; Initial	1.00	4.54	µg/L	
201125L057	2	Hall across from Auditorium-BF; Initial	1.00	<1.00	µg/L	
201125L058	3	Lower Locker Room Storage-IM; Initial	1.00	<1.00	µg/L	
201125L059	4	Lower Locker Room Bathroom Left-SK; Initial	1.00	33.5	µg/L	H
201125L060	5	Lower Locker Room Bathroom Right-SK; Initial	1.00	58.1	µg/L	E,H
201125L061	6	Upper Locker Room-WF; Initial	1.00	15.0	µg/L	
201125L062	7	Upper Locker Room-OS; Initial	1.00	23.8	µg/L	H
201125L063	8	Upper Locker Room Bathroom-SK; Initial	1.00	12.5	µg/L	
201125L064	9	IMC Rear Bathroom-SK; Initial	1.00	6.51	µg/L	
201125L065	10	Concession Stand Kitchen 3-Bay Left-SK; Initial	1.00	3.36	µg/L	
201125L066	11	Concession Stand Kitchen 3-Bay Right-SK; Initial	1.00	7.46	µg/L	
201125L067	12	Concession Stand Kitchen-SK; Initial	1.00	<1.00	µg/L	
201125L068	13	West Team Room Bathroom-SK; Initial	1.00	2.53	µg/L	
201125L069	14	East Team Room Bathroom-SK; Initial	1.00	1.18	µg/L	
201125L070	15	Basement-SK; Initial	1.00	1.08	µg/L	
201125L071	16	Room 211 @ A-SK; Initial	1.00	11.6	µg/L	
201125L072	17	Room 211 @ B-SK; Initial	1.00	83.8	µg/L	E,H
201125L073	18	Room 211A-Nurse Prep-SK; Initial	1.00	13.6	µg/L	

Comment:

CID: Client ID LOQ: Limit of Quantitation

E: Sample result exceeds instrument calibration, value is estimated.

H: Sample result exceeds applicable regulatory limit.

