

NELAC NY 11769
NRPP 101193 AL
NRSB ARL0017

EPA Method #402-R-92-004
Liquid Scintillation
NRPP Device Code 8088
NRSB Device Code 12193

Laboratory Report for:

Property Tested: Project # 11652-X

Catey Bourne
14026 Thunderbolt PI Suite 100
Chantilly VA 20151

Minnie Howard Campus
3775 W Braddock Rd
Alexandria VA 22302


Log Number	Device Number	Test Exposure	Duration	Area Tested	Result pCi/L
8676292	5167133	01/22/2025 10:05 am	01/24/2025 12:11 pm	Floor 1 Main Office	1.3
8676293	5167134	01/22/2025 10:06 am	01/24/2025 12:12 pm	Floor 1 Main Office - 1001K	1.1
8676294	5167135	01/22/2025 10:07 am	01/24/2025 12:13 pm	Floor 1 Main Office - 1001J	1.6
8676295	5167136	01/22/2025 10:08 am	01/24/2025 12:13 pm	Floor 1 Main Office - 1001I	1.6
8676296	5167137	01/22/2025 10:09 am	01/24/2025 12:13 pm	Floor 1 Main Office - 1001E	1.4
8676297	5167138	01/22/2025 10:09 am	01/24/2025 12:14 pm	Floor 1 Main Office - 1001F	1.6
8676298	5167139	01/22/2025 10:10 am	01/24/2025 12:14 pm	Floor 1 Main Office - 1001G	1.4
8676299	5167140	01/22/2025 10:10 am	01/24/2025 12:15 pm	Floor 1 Main Office - 1001H	1.4
8676300	5167141	01/22/2025 10:11 am	01/24/2025 12:15 pm	Floor 1 Main Office - 1001L	1.1
8676301	5167142	01/22/2025 10:12 am	01/24/2025 12:15 pm	Floor 1 Main Office - 1001D	1.4
8676302	5167143	01/22/2025 10:14 am	01/24/2025 12:16 pm	Floor 1 Main Office - 1001C	1.9

Comment: ANSI/AARST MA-MFLB standards: Requirement for test was not met; *device moved during testing; **your test results may have been influenced by an improper testing environment (Kitchen). Results are for informational purposes only.

Test Performed By: Placed: William Sargent 24MS088 Retrieved: William Sargent 24MS088

Distributed by: Environmental Hazards Services

Date Received: 01/28/2025 Date Logged: 01/28/2025 Date Analyzed: 01/29/2025 Date Reported: 01/29/2025

Report Reviewed By: 

Report Approved By: 

Disclaimer:

Shawn Price, Director of Laboratory Operations, AccuStar Labs

The counting uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Laboratory personnel were not involved in the placement or retrieval of the samples. Analytical results relate to the samples as received by the laboratory. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NELAC NY 11769
NRPP 101193 AL
NRSB ARL0017

EPA Method #402-R-92-004
Liquid Scintillation
NRPP Device Code 8088
NRSB Device Code 12193

Laboratory Report for:

Property Tested: Project # 11652-X

Catey Bourne
14026 Thunderbolt PI Suite 100
Chantilly VA 20151

Minnie Howard Campus
3775 W Braddock Rd
Alexandria VA 22302


Log Number	Device Number	Test Exposure	Duration	Area Tested	Result pCi/L
8676303	5167144	01/22/2025 10:17 am	01/24/2025 12:16 pm	Floor 1 Main Office - 1001 A	1.5
8676304	5167145	01/22/2025 10:20 am	01/24/2025 12:18 pm	Floor 1 Preschool - 1105	1.3
8676305	5167146	01/22/2025 10:21 am	01/24/2025 12:19 pm	*Floor 1 Preschool - 1106	0.9
8676306	5167147	01/22/2025 10:22 am	01/24/2025 12:19 pm	*Floor 1 Preschool - 1107	0.9
8676307	5167148	01/22/2025 10:23 am	01/24/2025 12:20 pm	Floor 1 Preschool - 1109	0.8
8676308	5167149	01/22/2025 10:24 am	01/24/2025 12:22 pm	Floor 1 Preschool - 1110	1.0
8676309	5167150	01/22/2025 10:25 am	01/24/2025 12:23 pm	Floor 1 Preschool - 1113	0.9
8676310	5167151	01/22/2025 10:25 am	01/24/2025 12:24 pm	Floor 1 Preschool - 1111	0.7
8676311	5167152	01/22/2025 10:26 am	01/24/2025 12:24 pm	Floor 1 Preschool - 1115	1.0
8676312	5167153	01/22/2025 10:26 am	01/24/2025 12:24 pm	Floor 1 Preschool - 1115 Duplicate	0.9
8676313	5167154	01/22/2025 10:27 am	01/24/2025 12:25 pm	Floor 1 Preschool - 1114	0.9

Comment: ANSI/AARST MA-MFLB standards: Requirement for test was not met; *device moved during testing; **your test results may have been influenced by an improper testing environment (Kitchen). Results are for informational purposes only.

Test Performed By: Placed: William Sargent 24MS088 Retrieved: William Sargent 24MS088

Distributed by: Environmental Hazards Services

Date Received: 01/28/2025 Date Logged: 01/28/2025 Date Analyzed: 01/29/2025 Date Reported: 01/29/2025

Report Reviewed By: 

Report Approved By: 

Disclaimer:

Shawn Price, Director of Laboratory Operations, AccuStar Labs

The counting uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Laboratory personnel were not involved in the placement or retrieval of the samples. Analytical results relate to the samples as received by the laboratory. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NELAC NY 11769
NRPP 101193 AL
NRSB ARL0017

EPA Method #402-R-92-004
Liquid Scintillation
NRPP Device Code 8088
NRSB Device Code 12193

Laboratory Report for:

Property Tested: Project # 11652-X

Catey Bourne
14026 Thunderbolt PI Suite 100
Chantilly VA 20151

Minnie Howard Campus
3775 W Braddock Rd
Alexandria VA 22302


Log Number	Device Number	Test Exposure	Duration	Area Tested	Result pCi/L
8676314	5167155	01/22/2025 10:28 am	01/24/2025 12:26 pm	Floor 1 Preschool - 1103	1.1
8676315	5167156	01/22/2025 10:32 am	01/24/2025 12:28 pm	Floor 1 Room 1204	2.2
8676316	5167157	01/22/2025 10:32 am	01/24/2025 12:28 pm	Floor 1 Room 1204 Blank	< 0.4
8676317	5167158	01/22/2025 10:33 am	01/24/2025 12:29 pm	Floor 1 Room 1205B	2.8
8676318	5167159	01/22/2025 10:34 am	01/24/2025 12:29 pm	Floor 1 Room 1205C	2.6
8676319	5167160	01/22/2025 10:34 am	01/24/2025 12:30 pm	Floor 1 Room 1205D	3.2
8676320	5167161	01/22/2025 10:35 am	01/24/2025 12:30 pm	Floor 1 Room 1205E	2.9
8676321	5167162	01/22/2025 10:36 am	01/24/2025 12:31 pm	Floor 1 Room 1205F	2.1
8676322	5167163	01/22/2025 10:37 am	01/24/2025 12:32 pm	Floor 1 Room 1205G	2.1
8676323	5167164	01/22/2025 10:37 am	01/24/2025 12:32 pm	Floor 1 Room 1205G Duplicate	2.2
8676324	5167165	01/22/2025 10:38 am	01/24/2025 12:34 pm	Floor 1 Room 1205H	2.6

Comment: ANSI/AARST MA-MFLB standards: Requirement for test was not met; *device moved during testing; **your test results may have been influenced by an improper testing environment (Kitchen). Results are for informational purposes only.

Test Performed By: Placed: William Sargent 24MS088 Retrieved: William Sargent 24MS088

Distributed by: Environmental Hazards Services

Date Received: 01/28/2025 Date Logged: 01/28/2025 Date Analyzed: 01/29/2025 Date Reported: 01/29/2025

Report Reviewed By: 

Report Approved By: 

Disclaimer:

Shawn Price, Director of Laboratory Operations, AccuStar Labs

The counting uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Laboratory personnel were not involved in the placement or retrieval of the samples. Analytical results relate to the samples as received by the laboratory. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NELAC NY 11769
NRPP 101193 AL
NRSB ARL0017

EPA Method #402-R-92-004
Liquid Scintillation
NRPP Device Code 8088
NRSB Device Code 12193

Laboratory Report for:

Property Tested: Project # 11652-X

Catey Bourne
14026 Thunderbolt PI Suite 100
Chantilly VA 20151

Minnie Howard Campus
3775 W Braddock Rd
Alexandria VA 22302


Log Number	Device Number	Test Exposure	Duration	Area Tested	Result pCi/L
8676325	5167166	01/22/2025 10:38 am	01/24/2025 12:34 pm	Floor 1 Resource Center	2.5
8676326	5167167	01/22/2025 10:39 am	01/24/2025 12:34 pm	Floor 1 Teen Wellness - Main	0.8
8676327	5167168	01/22/2025 10:39 am	01/24/2025 12:35 pm	Floor 1 Room 1206F	0.5
8676328	5167169	01/22/2025 10:40 am	01/24/2025 12:35 pm	Floor 1 Room 1206E	0.9
8676329	5167170	01/22/2025 10:40 am	01/24/2025 12:35 pm	Floor 1 Room 1206D	0.8
8676330	5167171	01/22/2025 10:41 am	01/24/2025 12:36 pm	Floor 1 Room 1206C	0.9
8676331	5167172	01/22/2025 10:41 am	01/24/2025 12:36 pm	Floor 1 Room 1206B	1.0
8676332	5167173	01/22/2025 10:41 am	01/24/2025 12:37 pm	Floor 1 Room 1206A	0.7
8676333	5167174	01/22/2025 10:43 am	01/24/2025 12:38 pm	Floor 1 Room 1203	0.7
8676334	5167175	01/22/2025 10:43 am	01/24/2025 12:38 pm	Floor 1 Room 1203 Duplicate	0.4
8676335	5167176	01/22/2025 10:43 am	01/24/2025 12:38 pm	Floor 1 Room 1202F	0.5

Comment: ANSI/AARST MA-MFLB standards: Requirement for test was not met; *device moved during testing; **your test results may have been influenced by an improper testing environment (Kitchen). Results are for informational purposes only.

Test Performed By: Placed: William Sargent 24MS088 Retrieved: William Sargent 24MS088

Distributed by: Environmental Hazards Services

Date Received: 01/28/2025 Date Logged: 01/28/2025 Date Analyzed: 01/29/2025 Date Reported: 01/29/2025

Report Reviewed By: 

Report Approved By: 

Disclaimer:

Shawn Price, Director of Laboratory Operations, AccuStar Labs

The counting uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Laboratory personnel were not involved in the placement or retrieval of the samples. Analytical results relate to the samples as received by the laboratory. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NELAC NY 11769
NRPP 101193 AL
NRSB ARL0017

EPA Method #402-R-92-004
Liquid Scintillation
NRPP Device Code 8088
NRSB Device Code 12193

Laboratory Report for:

Property Tested: Project # 11652-X

Catey Bourne
14026 Thunderbolt PI Suite 100
Chantilly VA 20151

Minnie Howard Campus
3775 W Braddock Rd
Alexandria VA 22302


Log Number	Device Number	Test Exposure	Duration	Area Tested	Result pCi/L
8676336	5167177	01/22/2025 10:44 am	01/24/2025 12:39 pm	Floor 1 Room 1202E	0.7
8676337	5167178	01/22/2025 10:45 am	01/24/2025 12:39 pm	Floor 1 Room 1202D	1.4
8676338	5167179	01/22/2025 10:45 am	01/24/2025 12:40 pm	Floor 1 Room 1202C	0.5
8676339	5167180	01/22/2025 10:45 am	01/24/2025 12:40 pm	Floor 1 Room 1202C Duplicate	0.7
8676340	5167182	01/22/2025 10:47 am	01/24/2025 12:43 pm	Floor 1 Health Clinic - Main	0.9
8676341	5167183	01/22/2025 10:47 am	01/24/2025 12:43 pm	Floor 1 Room 1207A	0.4
8676342	5167184	01/22/2025 10:49 am	01/24/2025 12:44 pm	Floor 1 Room 1207C	0.8
8676343	5167185	01/22/2025 10:49 am	01/24/2025 12:44 pm	Floor 1 Room 1207D	0.9
8676344	5167186	01/22/2025 10:49 am	01/24/2025 12:44 pm	Floor 1 Room 1207E	0.9
8676345	5167187	01/22/2025 10:49 am	01/24/2025 12:45 pm	Floor 1 Room 1207E Blank	< 0.4
8676346	5167188	01/22/2025 10:50 am	01/24/2025 12:46 pm	Floor 1 Room 1208	2.2


Comment: ANSI/AARST MA-MFLB standards: Requirement for test was not met; *device moved during testing; **your test results may have been influenced by an improper testing environment (Kitchen). Results are for informational purposes only.

Test Performed By: Placed: William Sargent 24MS088 Retrieved: William Sargent 24MS088

Distributed by: Environmental Hazards Services

Date Received: 01/28/2025 Date Logged: 01/28/2025 Date Analyzed: 01/29/2025 Date Reported: 01/29/2025

Report Reviewed By: 

Report Approved By: 

Disclaimer:

Shawn Price, Director of Laboratory Operations, AccuStar Labs

The counting uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Laboratory personnel were not involved in the placement or retrieval of the samples. Analytical results relate to the samples as received by the laboratory. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NELAC NY 11769
NRPP 101193 AL
NRSB ARL0017

EPA Method #402-R-92-004
Liquid Scintillation
NRPP Device Code 8088
NRSB Device Code 12193

Laboratory Report for:

Property Tested: Project # 11652-X

Catey Bourne
14026 Thunderbolt PI Suite 100
Chantilly VA 20151

Minnie Howard Campus
3775 W Braddock Rd
Alexandria VA 22302


Log Number	Device Number	Test Exposure	Duration	Area Tested	Result pCi/L
8676347	5167189	01/22/2025 10:50 am	01/24/2025 12:47 pm	Floor 1 Room 1201	< 0.4
8676348	5167190	01/22/2025 10:50 am	01/24/2025 12:49 pm	Floor 1 Room 1200	0.4
8676349	5167191	01/22/2025 10:52 am	01/24/2025 12:49 pm	Floor 1 1st Floor Commons	0.7
8676350	5167192	01/22/2025 10:52 am	01/24/2025 12:49 pm	*Floor 1 1st Floor Commons	0.4
8676351	5167193	01/22/2025 10:54 am	01/24/2025 12:50 pm	*Floor 1 Room 1209	2.6
8676352	5167194	01/22/2025 10:54 am	01/24/2025 12:50 pm	*Floor 1 Room 1209 Duplicate	2.2
8676353	5167195	01/22/2025 10:56 am	01/24/2025 12:51 pm	*Floor 1 Room 1st Floor Forum	0.7
8676354	5167196	01/22/2025 10:58 am	01/24/2025 12:53 pm	*Floor 1 Room 1305 - Lifeguard	< 0.4
8676355	5167197	01/22/2025 10:59 am	01/24/2025 12:54 pm	Floor 1 Room 1307 - Break Room	0.5
8676356	5167198	01/22/2025 10:59 am	01/24/2025 12:54 pm	Floor 1 Room 1308	< 0.4
8676357	5167199	01/22/2025 10:59 am	01/24/2025 12:55 pm	*Floor 1 Room 1304	< 0.4

Comment: ANSI/AARST MA-MFLB standards: Requirement for test was not met; *device moved during testing; **your test results may have been influenced by an improper testing environment (Kitchen). Results are for informational purposes only.

Test Performed By: Placed: William Sargent 24MS088 Retrieved: William Sargent 24MS088

Distributed by: Environmental Hazards Services

Date Received: 01/28/2025 Date Logged: 01/28/2025 Date Analyzed: 01/29/2025 Date Reported: 01/29/2025

Report Reviewed By: 

Report Approved By: 

Disclaimer:

Shawn Price, Director of Laboratory Operations, AccuStar Labs

The counting uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Laboratory personnel were not involved in the placement or retrieval of the samples. Analytical results relate to the samples as received by the laboratory. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NELAC NY 11769
NRPP 101193 AL
NRSB ARL0017

EPA Method #402-R-92-004
Liquid Scintillation
NRPP Device Code 8088
NRSB Device Code 12193

Laboratory Report for:

Property Tested: Project # 11652-X

Catey Bourne
14026 Thunderbolt PI Suite 100
Chantilly VA 20151

Minnie Howard Campus
3775 W Braddock Rd
Alexandria VA 22302


Log Number	Device Number	Test Exposure	Duration	Area Tested	Result pCi/L
8676358	5167200	01/22/2025 11:02 am	01/24/2025 12:56 pm	Floor 1 Room 1003	0.8
8676359	5167201	01/22/2025 11:04 am	01/24/2025 12:57 pm	Floor 1 1st Floor Serving	1.0
8676360	5167202	01/22/2025 11:06 am	01/24/2025 12:57 pm	**Floor 1 Kitchen	0.7
8676361	5167203	01/22/2025 11:06 am	01/24/2025 12:58 pm	*Floor 1 Kitchen Office 1313	0.9
8676362	5167204	01/22/2025 11:06 am	01/24/2025 12:58 pm	*Floor 1 Kitchen Office 1313 Duplicate	0.7
8676363	5167205	01/22/2025 11:17 am	01/24/2025 1:01 pm	Floor 2 Room 2110	1.3
8676364	5167206	01/22/2025 11:17 am	01/24/2025 1:01 pm	Floor 2 Room 2110 Duplicate	1.0
8676365	5167207	01/22/2025 11:18 am	01/24/2025 1:02 pm	Floor 2 Room 2108	0.8
8676366	5167208	01/22/2025 11:18 am	01/24/2025 1:02 pm	Floor 2 Room 2107	1.2
8676367	5167209	01/22/2025 11:19 am	01/24/2025 1:03 pm	Floor 2 Room 2106	1.1
8676368	5167210	01/22/2025 11:20 am	01/24/2025 1:03 pm	*Floor 2 Room 2105	1.4


Comment: ANSI/AARST MA-MFLB standards: Requirement for test was not met; *device moved during testing; **your test results may have been influenced by an improper testing environment (Kitchen). Results are for informational purposes only.

Test Performed By: Placed: William Sargent 24MS088 Retrieved: William Sargent 24MS088

Distributed by: Environmental Hazards Services

Date Received: 01/28/2025 Date Logged: 01/28/2025 Date Analyzed: 01/29/2025 Date Reported: 01/29/2025

Report Reviewed By: 

Report Approved By: 

Disclaimer:

Shawn Price, Director of Laboratory Operations, AccuStar Labs

The counting uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Laboratory personnel were not involved in the placement or retrieval of the samples. Analytical results relate to the samples as received by the laboratory. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NELAC NY 11769
NRPP 101193 AL
NRSB ARL0017

EPA Method #402-R-92-004
Liquid Scintillation
NRPP Device Code 8088
NRSB Device Code 12193

Laboratory Report for:

Property Tested: Project # 11652-X

Catey Bourne
14026 Thunderbolt PI Suite 100
Chantilly VA 20151

Minnie Howard Campus
3775 W Braddock Rd
Alexandria VA 22302


Log Number	Device Number	Test Exposure	Duration	Area Tested	Result pCi/L
8676369	5167211	01/22/2025 11:20 am	01/24/2025 1:03 pm	*Floor 2 Room 2105 Blank	< 0.4
8676370	5167212	01/22/2025 11:22 am	01/24/2025 1:04 pm	Floor 2 Room 2102	1.1
8676371	5167213	01/22/2025 11:22 am	01/24/2025 1:04 pm	Floor 2 Room 2101	1.0
8676372	5167214	01/22/2025 11:22 am	01/24/2025 1:04 pm	Floor 2 Room 2101 Duplicate	1.2
8676373	5167215	01/22/2025 11:22 am	01/24/2025 1:05 pm	Floor 2 Room 2104	0.9
8676374	5167216	01/22/2025 11:23 am	01/24/2025 1:07 pm	*Floor 2 Room 2103	1.1
8676375	5167217	01/22/2025 11:27 am	01/24/2025 1:09 pm	Floor 2 Room 2303 - Bailey Office	< 0.4
8676376	5167218	01/22/2025 11:27 am	01/24/2025 1:10 pm	Floor 2 Room 2301 - Aquatics Office	< 0.4
8676377	5167219	01/22/2025 11:27 am	01/24/2025 1:10 pm	Floor 2 Room 2301 - Aquatics Office Duplicate	0.4
8676378	5167220	01/22/2025 11:35 am	01/24/2025 1:13 pm	Floor 2 Room 2117	0.9
8676379	5167221	01/22/2025 11:36 am	01/24/2025 1:15 pm	Floor 2 Room 2216	0.6

Comment: ANSI/AARST MA-MFLB standards: Requirement for test was not met; *device moved during testing; **your test results may have been influenced by an improper testing environment (Kitchen). Results are for informational purposes only.

Test Performed By: Placed: William Sargent 24MS088 Retrieved: William Sargent 24MS088

Distributed by: Environmental Hazards Services

Date Received: 01/28/2025 Date Logged: 01/28/2025 Date Analyzed: 01/29/2025 Date Reported: 01/29/2025

Report Reviewed By: 

Report Approved By: 

Disclaimer:

Shawn Price, Director of Laboratory Operations, AccuStar Labs

The counting uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Laboratory personnel were not involved in the placement or retrieval of the samples. Analytical results relate to the samples as received by the laboratory. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NELAC NY 11769
NRPP 101193 AL
NRSB ARL0017

EPA Method #402-R-92-004
Liquid Scintillation
NRPP Device Code 8088
NRSB Device Code 12193

Laboratory Report for:

Property Tested: Project # 11652-X

Catey Bourne
14026 Thunderbolt PI Suite 100
Chantilly VA 20151

Minnie Howard Campus
3775 W Braddock Rd
Alexandria VA 22302


Log Number	Device Number	Test Exposure	Duration	Area Tested	Result pCi/L
8676380	5167222	01/22/2025 11:38 am	01/24/2025 1:22 pm	Floor 2 Room 2310	0.5
8676381	5167223	01/22/2025 11:40 am	01/24/2025 1:24 pm	Floor 2 2nd Floor Career Cen.	1.0
8676382	5167224	01/22/2025 11:45 am	01/24/2025 1:26 pm	Floor 3 3rd Floor Media Cen.	0.5
8676383	5167225	01/22/2025 11:46 am	01/24/2025 1:27 pm	Floor 3 Room 3119	0.8
8676384	5167226	01/22/2025 11:46 am	01/24/2025 1:28 pm	Floor 3 Room 3113	0.8
8676385	5167227	01/22/2025 11:47 am	01/24/2025 1:30 pm	Floor 3 Room 3213	< 0.4
8676386	5167228	01/22/2025 11:50 am	01/24/2025 1:32 pm	Floor 3 Room 3008 - Main Recep.	0.8
8676387	5167229	01/22/2025 11:53 am	01/24/2025 1:35 pm	Floor 4 Room 4303	0.4
8676388	5167231	01/22/2025 11:55 am	01/24/2025 1:42 pm	Floor 4 Room 4112	0.8
8676389	5167232	01/22/2025 11:56 am	01/24/2025 1:44 pm	Floor 4 Room 4001	0.6
8676390	5167233	01/22/2025 11:57 am	01/24/2025 1:46 pm	Floor 4 Room 4215	< 0.4

Comment: ANSI/AARST MA-MFLB standards: Requirement for test was not met; *device moved during testing; **your test results may have been influenced by an improper testing environment (Kitchen). Results are for informational purposes only.

Test Performed By: Placed: William Sargent 24MS088 Retrieved: William Sargent 24MS088

Distributed by: Environmental Hazards Services

Date Received: 01/28/2025 Date Logged: 01/28/2025 Date Analyzed: 01/29/2025 Date Reported: 01/29/2025

Report Reviewed By: 

Report Approved By: 

Disclaimer:

Shawn Price, Director of Laboratory Operations, AccuStar Labs

The counting uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Laboratory personnel were not involved in the placement or retrieval of the samples. Analytical results relate to the samples as received by the laboratory. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.

NELAC NY 11769
NRPP 101193 AL
NRSB ARL0017

EPA Method #402-R-92-004
Liquid Scintillation
NRPP Device Code 8088
NRSB Device Code 12193

Laboratory Report for:

Property Tested: Project # 11652-X

Catey Bourne
14026 Thunderbolt PI Suite 100
Chantilly VA 20151

Minnie Howard Campus
3775 W Braddock Rd
Alexandria VA 22302


Log Number	Device Number	Test Date	Exposure Start	Exposure End	Duration	Area Tested	Result pCi/L
8676391	5167234	01/22/2025	11:59 am	01/24/2025	1:48 pm	Floor 5 Room 5004	0.5
8676392	5167236	01/22/2025	12:02 pm	01/24/2025	1:51 pm	Floor 5 Room 5208	0.6
8676393	5167237	01/22/2025	12:02 pm	01/24/2025	1:51 pm	Floor 5 Room 5208 Duplicate	0.5
8676394	5167238	01/22/2025	12:04 pm	01/24/2025	1:53 pm	Floor 5 Room 5003	0.4


Comment: ANSI/AARST MA-MFLB standards: Requirement for test was not met; *device moved during testing; **your test results may have been influenced by an improper testing environment (Kitchen). Results are for informational purposes only.

Test Performed By: Placed: William Sargent 24MS088 Retrieved: William Sargent 24MS088

Distributed by: Environmental Hazards Services

Date Received: 01/28/2025 Date Logged: 01/28/2025 Date Analyzed: 01/29/2025 Date Reported: 01/29/2025

Report Reviewed By: 

Report Approved By: 

Disclaimer:

Shawn Price, Director of Laboratory Operations, AccuStar Labs

The counting uncertainty of this radon measurement is +/- 10 %. Factors contributing to uncertainty include statistical variations, daily and seasonal variations in radon concentrations, sample collection techniques and operation of the dwelling. Interference with test conditions may influence the test results.

This report may only be transferred to a third party in its entirety. Laboratory personnel were not involved in the placement or retrieval of the samples. Analytical results relate to the samples as received by the laboratory. Results shown on this report represent levels of radon gas measured between the dates shown in the room or area of the site identified above as "Property Tested". Incorrect information will affect results. The results may not be construed as either predictive or supportive of measurements conducted in any area of this structure at any other time. AccuStar Labs, its employees and agents are not responsible for the consequences of any action taken or not taken based upon the results reported or any verbal or written interpretation of the results.