

Water Sampling Log

Name of Building Memorial Junior School
 Building Owner Hanover Township Bd of Educ

Date Collected: 20-Mar-25
 Sample Collected by: PD McGuinness

Sample No.	Tap No.	Sample Type	Type of Outlet	Manufacturer		Time	Lead Results	
							mg/L	%AL
--	1	1st	Bubbler		Hallway - across from Art Room 619, left side		Removed	
--	2	1st	Sink		Hallway, across from Room 619, right side		Removed	
--	3	1st	Bubbler		Hallway - across from Nurse's Office, left side		Removed	
--	4	1st	Bubbler		Hallway - across from Nurse's Office, right side		Removed	
RK-032025-01	5	1st	Sink		Nurse's Office	06:13	0.0055	37%
--	6	1st	Chiller		6th Grade Corridor, outside Asst Principal Office		Removed	
RK-032025-02	7	1st	Sink		Home Economics - far left sink	06:16	0.0082	54%
RK-032025-03	8	1st	Sink		Home Economics - left-center sink	06:17	0.0037	25%
RK-032025-04	9	1st	Sink		Home Economics - center sink	06:17	0.0028	19%
RK-032025-05	10	1st	Sink		Home Economics - center-right sink	06:18	0.0032	21%
RK-032025-06	11	1st	Sink		Home Economics - far right sink	06:18	ND	-
RK-032025-07	12	1st	Sink		Main Office Kitchen	06:20	0.0044	30%
RK-032025-08	13	1st	Sink		Board Office Kitchen	06:22	0.0026	17%
RK-032025-09	14	1st	Bottle Filler	Elkay	Main Entrance Hallway	06:26	ND	-
--	15	1st	Bubbler		Room 710		Removed	
--	16	1st	Bubbler		Room 711		Removed	
--	17	1st	Bubbler		Hallway, across from Room 711		Inoperable	
--	18	1st	Bubbler		Room 713		Turned Off	
--	19	1st	Bubbler		Room 712		Turned Off	
--	20	1st	Bubbler		Room 715		Turned Off	

Sample Type: **1st:** First Draw sample collected after water sat in pipe between 8 and 18 hours

FL: Water flushed through tap for at least 2 minutes

ND: means Not Detected at or above the Reliability Detection Limit (RDL) of 1.0 µg/L for Lead.

Water Sampling Log

Name of Building Memorial Junior School
 Building Owner Hanover Township Bd of Educ

Date Collected: 20-Mar-25
 Sample Collected by: PD McGuinness

Sample No.	Tap No.	Sample Type	Type of Outlet	Manufacturer		Time	Lead Results	
							mg/L	%AL
--	21	1st	Bubbler		Room 714	Removed		
--	22	1st	Bubbler		Room 716	Removed		
--	23	1st	Bubbler		Room 718	Removed		
RK-032025-10	24	1st	Bottle Filler	Elkay	Hallway between bathrooms, opposite Room 815	06:29	ND	-
--	25	1st	Bubbler		Hallway - across from Room 812	Turned Off		
--	26	1st	Bubbler		Hallway - outside Room 818, left side	Turned Off		
--	27	1st	Bubbler		Hallway - outside Room 818, right side	Turned Off		
RK-032025-11	28	1st	Bottle Filler	Elkay	Hallway - outside Auditorium	06:31	ND	-
--	29	1st	Bubbler		8th Grade Hallway - across from Room 824	Turned Off		
RK-032025-12	30	1st	Sink		Faculty Lounge	06:34	0.0026	17%
--	31	1st	Chiller		Hallway - next to Maintenance Office	Turned Off		
RK-032025-13	32	1st	Bottle Filler	Elkay	Cafeteria	06:37	ND	-
RK-032025-14	33	1st	Sink		Main Kitchen, left side	06:39	0.0071	47%
RK-032025-15	34	1st	Sink		Main Kitchen, right side	06:39	0.0304	203%
RK-032025-16	35	1st	Sink		Maintenance Kitchen Sink	06:39	0.0037	25%
--	36	1st	Chiller	Elkay	Viking Hallway	Turned Off		
RK-032025-17	37	1st	Bottle Filler	Elkay	Viking Hallway	06:42	ND	-
--	38	1st	Chiller		Viking Hallway	Turned Off		
RK-032025-18	39	1st	Bubbler		Boy's Locker Room	06:44	0.0069	46%
RK-032025-19	40	1st	Bubbler		Girl's Locker Room	06:46	0.0106	71%

Sample Type: **1st:** First Draw sample collected after water sat in pipe between 8 and 18 hours

FL: Water flushed through tap for at least 2 minutes

ND: means Not Detected at or above the Reliability Detection Limit (RDL) of 1.0 µg/L for Lead.

Water Sampling Log

Name of Building Bee Meadow School
 Building Owner Hanover Township Bd of Educ

Date Collected: 20-Mar-25
 Sample Collected by: PD McGuinness

Sample No.	Tap No.	Sample Type	Type of Outlet	Manufacturer	Location	Time	Lead Results	
							mg/L	%AL
RK-032025-31	1	1st	Sink		Faculty Room Kitchen	06:58	0.0028	19%
RK-032025-32	2	1st	Sink		Main Kitchen Sink	06:59	ND	-
RK-032025-33	3	1st	Bottle Filler	Elkay	Hallway - across from Cafeteria	07:00	ND	-
RK-032025-34	4	1st	Sink		Main Office Sink	07:02	0.0065	44%
RK-032025-35	5	1st	Sink		Nurse's Office	07:03	ND	-
--	6	1st	Sink Fountain		Room 8		Turned Off	
--	7	1st	Sink Fountain		Room 9		Turned Off	
--	8	1st	Sink Fountain		Room 10		Turned Off	
--	9	1st	Sink Fountain		Room 11		Turned Off	
--	10	1st	Sink Fountain		Room 12		Turned Off	
--	11	1st	Sink Fountain		Room 13		Turned Off	
--	12	1st	Chiller	Elkay	Hallway - next to Room 29, left side		Turned Off	
--	13	1st	Chiller	Elkay	Hallway - next to Room 29, right side		Turned Off	
--	14	1st	Sink Fountain		Room 16		Turned Off	
--	15	1st	Sink Fountain		Room 17		Turned Off	
--	16	1st	Sink Fountain		Room 18		Turned Off	
--	17	1st	Sink Fountain		Room 19		Turned Off	
--	18	1st	Bubbler		Hallway, next to Room 20, right side		Turned Off	
	19	1st	Chiller		Hallway - across from Gym		Turned Off	
--	20	1st	Chiller		Hallway - across from Gym		Turned Off	

Sample Type: **1st:** First Draw sample collected after water sat in pipe between 8 and 18 hours
FL: Water flushed through tap for at least 2 minutes
ND: means Not Detected at or above the Reliability Detection Limit (RDL) of 1.0 µg/L for Lead.

Water Sampling Log

Name of Building Bee Meadow School
 Building Owner Hanover Township Bd of Educ

Date Collected: 20-Mar-25
 Sample Collected by: PD McGuinness

Sample No.	Tap No.	Sample Type	Type of Outlet	Manufacturer		Time	Lead Results	
							mg/L	%AL
RK-032025-35	11	1st	Bottle Filler	Elkay	Hallway - next to Room 34	07:06	ND	-
RK-032025-36	18	1st	Bottle Filler	Elkay	Hallway - across from Gym	07:06	ND	-
--	21	1st	Sink Fountain		Room 5		Turned Off	
--	22	1st	Sink Fountain		Room 6		Turned Off	
--	23	1st	Sink Fountain		Room 4		Turned Off	
--	24	1st	Sink Fountain		Room 4		Turned Off	
--	25	1st	Chiller	Elkay	Hallway - next to Room 2		Turned Off	
--	26	1st	Sink Fountain		Room 2		Turned Off	
--	27	1st	Sink Fountain		Room 1		Turned Off	

Sample Type: **1st:** First Draw sample collected after water sat in pipe between 8 and 18 hours
FL: Water flushed through tap for at least 2 minutes
ND: means Not Detected at or above the Reliability Detection Limit (RDL) of 1.0 µg/L for Lead.

Water Sampling Log

Name of Building Salem Drive School
 Building Owner Hanover Township Bd of Educ

Date Collected: 20-Mar-25
 Sample Collected by: PD McGuinness

Sample No.	Tap No.	Sample Type	Type of Outlet	Manufacturer		Time	Lead Results	
							mg/L	%AL
RK-032025-41	1	1st	Sink		Library Office	07:22	0.0021	14%
RK-032025-42	2	1st	Bottle Filler	Elkay	Hallway - by Boiler Room	07:23	ND	-
RK-032025-43	3	1st	Sink		Nurse's Office	07:25	ND	-
--	4	1st	Bubbler		Room 4	Turned Off		
--	5	1st	Bubbler		Room 1 - Kindergarten	Turned Off		
--	6	1st	Bubbler		Room 2 - Kindergarten	Turned Off		
RK-032025-44	7	1st	Sink		Faculty Room	07:27	ND	-
--	8	1st	Bubbler		Hallway by bathrooms, across from Room 11, left side	Delete - does not exist		
--	9	1st	Bubbler		Hallway by bathrooms, across from Room 11, right side	Delete - does not exist		
--	10	1st	Bubbler		Room 11	Turned Off		
RK-032025-45	11	1st	Bottle Filler	Elkay	Hallway - across from Gym	07:29	ND	-
--	12	1st	Bubbler		Room 17	Turned Off		
--	13	1st	Chiller	Elkay	Hallway - across from Cafeteria, left side	Turned Off		
--	14	1st	Chiller	Elkay	Hallway - across from Cafeteria, middle	Turned Off		
RK-032025-46	15	1st	Bottle Filler	Elkay	Hallway - across from Cafeteria, middle	07:29	ND	-
--	16	1st	Chiller	Elkay	Hallway - across from Cafeteria, right side	Turned Off		
--	17	1st	Chiller	Elkay	Cafeteria - left side	Turned Off		
RK-032025-47	18	1st	Bottle Filler	Elkay	Cafeteria - right side	07:31	ND	-
RK-032025-48	19	1st	Sink		Main Kitchen Sink	07:32	0.0269	179%
								-

Sample Type: **1st:** First Draw sample collected after water sat in pipe between 8 and 18 hours

FL: Water flushed through tap for at least 2 minutes

ND: means Not Detected at or above the Reliability Detection Limit (RDL) of 1.0 µg/L for Lead.

Water Sampling Log

Name of Building Mountain View School
 Building Owner Hanover Township Bd of Educ

Date Collected: 20-Mar-25
 Sample Collected by: PD McGuinness

Sample No.	Tap No.	Sample Type	Type of Outlet	Manufacturer		Time	Lead Results	
							mg/L	%AL
RK-041822-61	1	1st	Bottle Filler		Hallway - next to Main Office	07:50	ND	-
RK-041822-62	2	1st	Sink		Nurse	07:51	0.0021	14%
RK-041822-63	3	1st	Sink		Faculty Room	07:53	ND	-
--	4	1st	Bubbler		Room 13	Turned Off		
--	5	1st	Bubbler		Room 5	Turned Off		
RK-041822-64	6	1st	Bottle Filler		Hallway - next to Room 12	07:55	ND	-
--	7	1st	Bubbler		Room 12	Turned Off		
--	8	1st	Bubbler		Room 11	Turned Off		
--	9	1st	Bubbler		Room 6	Turned Off		
--	10	1st	Bubbler		Room 7	Turned Off		
--	11	1st	Bubbler		Room 8	Turned Off		
--	12	1st	Bubbler		Room 10	Turned Off		
--	13	1st	Bubbler		Room 9	Turned Off		
RK-041822-65	14	1st	Bottle Filler	Elkay	Hallway - across from Teacher's Lounge	07:56	ND	-
RK-041822-66	15	1st	Sink		Main Kitchen	07:58	ND	-
--	16	1st	Bubbler		Room 15	Turned Off		
--	17	1st	Bubbler		Room 16	Turned Off		
--	18	1st	Bubbler		Room 19	Turned Off		
--	19	1st	Bubbler		Room 17	Turned Off		
--	20	1st	Bubbler		Room 20 new bubbler	Turned Off		

Sample Type: **1st:** First Draw sample collected after water sat in pipe between 8 and 18 hours

FL: Water flushed through tap for at least 2 minutes

ND: means Not Detected at or above the Reliability Detection Limit (RDL) of 1.0 µg/L for Lead.

