

Letchworth Elementary - Remediation

LEAD TESTING 2025

Location: ELEMENTARY

S=Staff E=Elementary

H=Hall

K=Kitchen

Flush Date/Time:

M=Middle

O=Office

C=Café

Performed by: Todd Brant

H=High School

G=Gym

L=Lav

Sample Date/Time: _____

DF=Drink'g Fountain

M=Maint.

Gr=Girls

Collected by: Todd Brant

F=Faucet

BR=Break Rm

B=Boys

* Denotes row in box

Location	Type	Remediation
Elem Gym Lobby Girls Lav Sink-Right	F	Posted. Not to drink water
Elem Gym Lobby Girls Lav Sink-Center	F	Posted. Not to drink water
Elem Gym Lobby Girls Lav Sink-Left	F	Posted. Not to drink water
Elem Gym Lobby Boys Lav sink-Far right	F	Posted. Not to drink water
Elem Gym Lobby Boys Lav sink- Right	F	Posted. Not to drink water
Elem Gym Lobby Boys Lav sink-Center	F	Posted. Not to drink water
Elem Gym Lobby Boys Lav sink-Left	F	Posted. Not to drink water
Elem Gym Lobby Drinking fountain - Left	DF	
Elem Gym Lobby Drinking Fountain - Right	DF	
Elem Gym Lobby Bottle Filler	BF	
Elem room 1	F	
Elem room 2	F	
Elem room 3	F	
Elem room 4	F	
Elem Café Lav Girls	F #1	
"	F #2	
Elem Café Lav Boys	F #1	
"	F #2	
Elem Café Drinking Fountain	DF	
Elem room 5 Lav sink	F	Posted. Not to drink water
Elem Office Staff Lav	F	
Elem room 10	F	
Elem room 15	F	
Elem room 15 - office	F	
Elem room 16	F	
Elem room 16 Lav Sink	F	
Elem boys locker room	F	Posted. Not to drink water
Elem boys Locker room Lav Sink	F	
Elem room 18	F	
Elem room 19	F	
Elem room 20	F	
Elem room 21	F	
Elem room 23 (1 sink) Faucet-Right	F	
Elem room 23 (1 sink) Faucet - Center	F	
Elem room 23 (1 sink) Faucet - Left	F	
Elem room 23 (single)	F	
Elem Short Hall Boys Lav - Left	F	
Elem Short Hall Boys Lav - Middle	F	

