

Portland Public Schools
Lead and Copper Water Sampling Results
Initial and Follow Up Flush Sample Data
Alameda Elementary - 3rd Site Visit

Sample Identification #	Location	Date Collected	Date Analyzed	Lab ID	Analyte	Results	Detection Limit	PPS Action Level*	Units
230-3901-A-003-A	Bubbler (left one of two) - Hallway near Room 140B	11/28/2018	12/3/2018	A8K0847-01	Copper	0.433	0.00400	1.3	ppm
230-3901-A-003-A	Bubbler (left one of two) - Hallway near Room 140B	11/28/2018	12/3/2018	A8K0847-01	Lead	0.521	0.200	15	ppb
230-3901-A-003-B	Bubbler (left one of two) - Hallway near Room 140B	11/28/2018	12/3/2018	A8K0847-02	Copper	0.538	0.00400	1.3	ppm
230-3901-A-003-B	Bubbler (left one of two) - Hallway near Room 140B	11/28/2018	12/3/2018	A8K0847-02	Lead	0.235	0.200	15	ppb
230-3901-B-003-A	Bubbler (right one of two) - Hallway near room 140B	11/28/2018	12/3/2018	A8K0847-03	Copper	0.564	0.00400	1.3	ppm
230-3901-B-003-A	Bubbler (right one of two) - Hallway near room 140B	11/28/2018	12/3/2018	A8K0847-03	Lead	0.406	0.200	15	ppb
230-3901-B-003-B	Bubbler (right one of two) - Hallway near room 140B	11/28/2018	12/3/2018	A8K0847-04	Copper	0.524	0.00400	1.3	ppm
230-3901-B-003-B	Bubbler (right one of two) - Hallway near room 140B	11/28/2018	12/3/2018	A8K0847-04	Lead	0.206	0.200	15	ppb