

Portland Public Schools
Lead and Copper Water Sampling Results
A (Initial) and B (Follow-Up) Sample Data
East Sylvan School

Sample Identification # and Location	Date/Time Collected	Date/Time Analyzed	Container ID	Analyte	Results	PPS Action Level*	Units
372-2038-B-002A Hallway	09/28/18 6:26 AM	10/03/18 12:24 AM	18024700	Copper	< 0.1	1.3	ppm
372-2038-B-002A Hallway	09/28/18 6:26 AM	10/03/18 12:24 AM	18024700	Lead	5	15	ppb
372-2038-B-002B Hallway	09/28/18 6:26 AM	10/03/18 12:29 AM	18024707	Copper	< 0.1	1.3	ppm
372-2038-B-002B Hallway	09/28/18 6:26 AM	10/03/18 12:29 AM	18024707	Lead	< 1	15	ppb
372-2044-A-002A Hallway	09/28/18 6:31 AM	10/03/18 12:34 AM	18024706	Copper	< 0.1	1.3	ppm
372-2044-A-002A Hallway	09/28/18 6:31 AM	10/03/18 12:34 AM	18024706	Lead	16	15	ppb
372-2044-A-002B Hallway	09/28/18 6:31 AM	10/03/18 12:39 AM	18024701	Copper	< 0.1	1.3	ppm
372-2044-A-002B Hallway	09/28/18 6:31 AM	10/03/18 12:39 AM	18024701	Lead	1	15	ppb
372-2040-A-002A Classroom 19	09/28/18 6:07 AM	10/03/18 12:44 AM	18024705	Copper	0.6	1.3	ppm
372-2040-A-002A Classroom 19	09/28/18 6:07 AM	10/03/18 12:44 AM	18024705	Lead	91	15	ppb
372-2040-A-002B Classroom 19	09/28/18 6:07 AM	10/03/18 12:48 AM	18024704	Copper	0.2	1.3	ppm
372-2040-A-002B Classroom 19	09/28/18 6:07 AM	10/03/18 12:48 AM	18024704	Lead	19	15	ppb

Results highlighted indicate a value at or above the PPS Action Level and that the fixture is under further review. During review, the highlighted fixture(s) will remain out of service.