

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
Brentwood Ross High School							
BRTWD-0414	1064	Corridor Near Room 1103 (1060)	Water Fountain-No Chiller	Potable	6/7/2025	7.4	Removed From Service, Pending Remediation
BRTWD-0415	1064	Corridor Near Room 1110 (1057)	Water Fountain-No Chiller	Potable	6/7/2025	6.6	Removed From Service, Pending Remediation
BRTWD-0590	1074	Kitchen	Pasta Pot/Steam Kettle	Potable	6/7/2025	16.1	Removed From Service, Pending Remediation
BRTWD-0594	N/A	Kitchen	Hand Wash Only	Non-Potable	6/12/2025	32.6	Placarded for Non-Drinking Use Until Remediated
BRTWD-0602	1074	Kitchen	Kitchen Faucet (Cold)	Potable	6/7/2025	20.7	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
Brentwood Sonderling High School							
BRTWD-0046	N/A	Kitchen (New Construction)	Hand Wash Only	Non-Potable	6/7/2025	9.5	Placarded for Non-Drinking Use Until Remediated
BRTWD-0050	N/A	Kitchen (New Construction)	Hand Wash Only	Non-Potable	6/7/2025	14.5	Placarded for Non-Drinking Use Until Remediated
BRTWD-0238	2054	Corridor Room 2500 To Room 2537	Water Fountain-No Chiller	Potable	6/7/2025	9.4	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
East Kindergarten Center							
BRTWD-2577	1005	Room 10	Water Fountain-No Chiller	Potable	6/10/2025	14.1	Removed From Service, Pending Remediation
BRTWD-2579	1006	Room 11	Water Fountain-No Chiller	Potable	6/10/2025	7.2	Removed From Service, Pending Remediation
BRTWD-2589	1015	Room 20	Water Fountain-No Chiller	Potable	6/10/2025	12.1	Removed From Service, Pending Remediation
BRTWD-2628	1055	Room 33	Water Fountain-No Chiller	Potable	6/10/2025	13.5	Removed From Service, Pending Remediation
BRTWD-2638	1061	Room 39	Water Fountain-No Chiller	Potable	6/10/2025	6.3	Removed From Service, Pending Remediation
BRTWD-2640	1062	Room 42	Water Fountain-No Chiller	Potable	6/10/2025	5.1	Removed From Service, Pending Remediation
BRTWD-3271	1041	Kitchen	Pasta Pot/Steam Kettle	Potable	6/10/2025	7.0	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
East Middle School							
BRTWD-1476	1036	Kitchen	Hand Wash Only	Non-Potable	6/7/2025	11.7	Placarded for Non-Drinking Use Until Remediated
BRTWD-3240	1048A	Room 106 Laundry Room	Home Economics Faucet (Cold)	Potable	6/7/2025	15.5	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
Freshman Center							
BRTWD-1501	1010	Health Suite	Nurse's Office Sink	Potable	6/7/2025	6.3	Removed From Service, Pending Remediation
BRTWD-1517	1036	Cafeteria (Area Reconstructed)	Hand Wash Only	Non-Potable	6/7/2025	16.8	Placarded for Non-Drinking Use Until Remediated
BRTWD-1518	1036	Cafeteria (Area Reconstructed)	Kitchen Faucet (Cold)	Potable	6/7/2025	12.1	Removed From Service, Pending Remediation
BRTWD-1520	1038	Kitchen	Hand Wash Only	Non-Potable	6/7/2025	10.2	Placarded for Non-Drinking Use Until Remediated
BRTWD-1546	1071	Boys Locker Room	Water Fountain-No Chiller	Potable	6/7/2025	20.2	Removed From Service, Pending Remediation
BRTWD-1614	2014	Corridor Near Room 209 (2008)	Water Fountain-No Chiller	Potable	6/7/2025	13.8	Removed From Service, Pending Remediation
BRTWD-3108	1071	Boys Locker Room	Water Fountain-No Chiller	Potable	6/7/2025	19.6	Removed From Service, Pending Remediation
BRTWD-3366	1028A	Home Ec. Kitchen	Home Economics Faucet (Cold)	Potable	6/7/2025	40.9	Removed From Service, Pending Remediation
BRTWD-3367	1028A	Home Ec. Kitchen	Home Economics Faucet (Cold)	Potable	6/7/2025	119	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
Hemlock Park Elementary School							
BRTWD-2246	1025A	Nurse Sick Room	Nurse's Office Sink	Potable	6/5/2025	79.8	Removed From Service, Pending Remediation
BRTWD-2259	1040	Room 18	Water Fountain-No Chiller	Potable	6/5/2025	34.5	Removed From Service, Pending Remediation
BRTWD-2261	1041	Room 17	Water Fountain-No Chiller	Potable	6/5/2025	7.3	Removed From Service, Pending Remediation
BRTWD-2267	1045	Room 24	Water Fountain-No Chiller	Potable	6/5/2025	7.0	Removed From Service, Pending Remediation
BRTWD-2269	1046	Room 23	Water Fountain-No Chiller	Potable	6/5/2025	7.5	Removed From Service, Pending Remediation
BRTWD-2275	1049	Room 28	Water Fountain-No Chiller	Potable	6/5/2025	23.5	Removed From Service, Pending Remediation
BRTWD-3558	1033	Kitchen	Pasta Pot/Steam Kettle	Potable	6/5/2025	31.6	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
Laurel Park Elementary School							
BRTWD-2447	1004	Room 2	Water Fountain-No Chiller	Potable	6/4/2025	6.2	Removed From Service, Pending Remediation
BRTWD-2472	1017	Room 14	Water Fountain-No Chiller	Potable	6/4/2025	9.0	Removed From Service, Pending Remediation
BRTWD-2478	1020	Room 15	Water Fountain-No Chiller	Potable	6/4/2025	6.9	Removed From Service, Pending Remediation
BRTWD-2487	1030A	Speech Therapist Office	Office Faucet	Potable	6/4/2025	5.9	Removed From Service, Pending Remediation
BRTWD-2501	1038	Kitchen	Hand Wash Only	Non-Potable	6/4/2025	15.3	Placarded for Non-Drinking Use Until Remediated
BRTWD-2505	1041	Room 20	Water Fountain-No Chiller	Potable	6/4/2025	8.7	Removed From Service, Pending Remediation
BRTWD-2514	1047	Room 17	Water Fountain-No Chiller	Potable	6/4/2025	6.2	Removed From Service, Pending Remediation
BRTWD-2516	1048	Room 19	Water Fountain-No Chiller	Potable	6/4/2025	17.3	Removed From Service, Pending Remediation
BRTWD-2532	1057	Room 30	Water Fountain-No Chiller	Potable	6/4/2025	15.1	Removed From Service, Pending Remediation
BRTWD-2534	1058	Room 29	Water Fountain-No Chiller	Potable	6/4/2025	6.2	Removed From Service, Pending Remediation
BRTWD-3183	1038	Kitchen	Pasta Pot/Steam Kettle	Potable	6/4/2025	7.9	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
Loretta Park Elementary School							
BRTWD-2352	1001	Room 2	Water Fountain-No Chiller	Potable	6/4/2025	9.3	Removed From Service, Pending Remediation
BRTWD-2359	1004	Room 5	Water Fountain-No Chiller	Potable	6/4/2025	10.9	Removed From Service, Pending Remediation
BRTWD-2365	1007	Room 8	Water Fountain-No Chiller	Potable	6/4/2025	13.2	Removed From Service, Pending Remediation
BRTWD-2373	1011	Room 12	Water Fountain-No Chiller	Potable	6/4/2025	6.5	Removed From Service, Pending Remediation
BRTWD-2375	1013	Room 14	Water Fountain-No Chiller	Potable	6/4/2025	9.5	Removed From Service, Pending Remediation
BRTWD-2376	1014	Faculty Room	Kitchen Faucet (Cold)	Potable	6/4/2025	6.6	Removed From Service, Pending Remediation
BRTWD-2384	1035	Kitchen	Kitchen Faucet (Cold)	Potable	6/4/2025	9.4	Removed From Service, Pending Remediation
BRTWD-2391	1035	Kitchen	Kitchen Faucet (Cold)	Potable	6/4/2025	5.9	Removed From Service, Pending Remediation
BRTWD-2415	1052	Room 24	Water Fountain-No Chiller	Potable	6/4/2025	26.3	Removed From Service, Pending Remediation
BRTWD-2417	1053	Room 25	Water Fountain-No Chiller	Potable	6/4/2025	9.4	Removed From Service, Pending Remediation
BRTWD-3202	1002	Room 3	Water Fountain-No Chiller	Potable	6/4/2025	7.3	Removed From Service, Pending Remediation
BRTWD-3204	1035	Kitchen	Pasta Pot/Steam Kettle	Potable	6/4/2025	11.4	Removed From Service, Pending Remediation
BRTWD-3211	1050	Room 22	Water Fountain-No Chiller	Potable	6/4/2025	6.9	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
North Elementary School							
BRTWD-1086	2014	Room A-20	Water Fountain-No Chiller	Potable	6/4/2025	5.2	Removed From Service, Pending Remediation
BRTWD-1088	2015	Room A-21	Water Fountain-No Chiller	Potable	6/4/2025	6.6	Removed From Service, Pending Remediation
BRTWD-1095	1026	Kitchen (Annex)	Kitchen Faucet (Cold)	Potable	6/4/2025	28.0	Removed From Service, Pending Remediation
BRTWD-1128	1056	Nurse's Office	Nurse's Office Sink	Potable	6/4/2025	8.3	Removed From Service, Pending Remediation

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
BRTWD-3212	1055	Room 27	Water Fountain-No Chiller	Potable	6/4/2025	30.6	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
North Middle School							
BRTWD-1776	2023A	Library Work Room	Office Faucet	Non-Potable	6/11/2025	10.0	Placarded for Non-Drinking Use Until Remediated
BRTWD-3412	N/A	Teacher Center Kitchen (exterior access)	Kitchen Faucet (Cold)	Potable	6/11/2025	18.1	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
Northeast Elementary School							
BRTWD-1238	1050	Room 24	Water Fountain-No Chiller	Potable	6/4/2025	7.7	Removed From Service, Pending Remediation
BRTWD-1272	1067	Annex Kitchen	Kitchen Faucet (Cold)	Potable	6/4/2025	7.0	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
Oak Park Elementary School							
BRTWD-2789	1026A	Nurse's Office Exam Room	Nurse's Office Sink	Potable	6/6/2025	171	Removed From Service, Pending Remediation
BRTWD-2793	1038	Kitchen	Kitchen Faucet (Cold)	Potable	6/6/2025	5.2	Removed From Service, Pending Remediation
BRTWD-2795	1038	Kitchen	Hand Wash Only	Non-Potable	6/6/2025	10.6	Placarded for Non-Drinking Use Until Remediated
BRTWD-3137	1015	Room 14	Water Fountain-No Chiller	Potable	6/6/2025	6.7	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
Pine Park Elementary School							
BRTWD-2101	2005A	Room 32 Bathroom	Water Fountain-No Chiller	Potable	6/6/2025	5.9	Removed From Service, Pending Remediation
BRTWD-2125	1012	Room 11	Water Fountain-No Chiller	Potable	6/6/2025	7.0	Removed From Service, Pending Remediation
BRTWD-2133	1016	Room 15	Water Fountain-No Chiller	Potable	6/6/2025	11.2	Removed From Service, Pending Remediation
BRTWD-2144	1036	Kitchen	Kitchen Faucet (Cold)	Potable	6/6/2025	19.5	Removed From Service, Pending Remediation
BRTWD-2152	1036	Kitchen	Hand Wash Only	Non-Potable	6/6/2025	12.7	Placarded for Non-Drinking Use Until Remediated
BRTWD-2177	1052	Room 24	Water Fountain-No Chiller	Potable	6/6/2025	16.3	Removed From Service, Pending Remediation
BRTWD-2179	1053	Room 25	Water Fountain-No Chiller	Potable	6/6/2025	7.4	Removed From Service, Pending Remediation
BRTWD-2183	1054	Room 26	Water Fountain-No Chiller	Potable	6/6/2025	6.2	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
Southeast Elementary School							
BRTWD-2668	1002	Room 102	Water Fountain-No Chiller	Potable	6/5/2025	5.1	Removed From Service, Pending Remediation
BRTWD-2687	1012	Room 3	Water Fountain-No Chiller	Potable	6/5/2025	14.9	Removed From Service, Pending Remediation
BRTWD-2691	1014	Room 1	Water Fountain-No Chiller	Potable	6/5/2025	6.4	Removed From Service, Pending Remediation
BRTWD-2705	1029	Kitchen	Hand Wash Only	Non-Potable	6/5/2025	32.5	Placarded for Non-Drinking Use Until Remediated
BRTWD-2723	1043	Room 15	Water Fountain-No Chiller	Potable	6/5/2025	7.8	Removed From Service, Pending Remediation
BRTWD-2731	1047	Room 19	Water Fountain-No Chiller	Potable	6/5/2025	16.7	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
Southwest Elementary School							
BRTWD-0765	1045	Room 34	Water Fountain-No Chiller	Potable	6/5/2025	45.0	Removed From Service, Pending Remediation
BRTWD-0793	1074	Room 18	Water Fountain-No Chiller	Potable	6/5/2025	71.2	Removed From Service, Pending Remediation
BRTWD-0797	1076	Room 20	Water Fountain-No Chiller	Potable	6/5/2025	75.3	Removed From Service, Pending Remediation
BRTWD-0801	1079	Room 21	Water Fountain-No Chiller	Potable	6/5/2025	11.3	Removed From Service, Pending Remediation
BRTWD-0856	2023	Room 44	Water Fountain-No Chiller	Potable	6/5/2025	6.3	Removed From Service, Pending Remediation
BRTWD-0886	1028	Room 5	Water Fountain-No Chiller	Potable	6/5/2025	6.3	Removed From Service, Pending Remediation
BRTWD-3583	1029B	Speech Room 6 Work Room 2 (Interior Wall Removed)	Bottled Water Dispenser (Cold)	Potable	6/5/2025	32.0	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
South Middle School							
BRTWD-1834	1025	Nurse's Office	Nurse's Office Sink	Potable	6/7/2025	8.8	Removed From Service, Pending Remediation
BRTWD-1896	2021A	Library Work Room	Office Faucet	Potable	6/7/2025	8.8	Removed From Service, Pending Remediation
BRTWD-3846	1021	Kitchen	Hand Wash Only	Non-Potable	6/7/2025	9.6	Placarded for Non-Drinking Use Until Remediated

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
Twin Pines Elementary School							
BRTWD-0966	1053	Room 17	Water Fountain-No Chiller	Potable	6/6/2025	5.3	Removed From Service, Pending Remediation
BRTWD-0978	1059	Room 23	Water Fountain-No Chiller	Potable	6/6/2025	12.8	Removed From Service, Pending Remediation
BRTWD-1015	1043	Kitchen	Kitchen Faucet (Cold)	Potable	6/6/2025	7.9	Removed From Service, Pending Remediation
BRTWD-1017	1043	Kitchen	Kitchen Faucet (Cold)	Potable	6/6/2025	5.1	Removed From Service, Pending Remediation
BRTWD-1018	1043	Kitchen	Kitchen Faucet (Cold)	Potable	6/6/2025	41.5	Removed From Service, Pending Remediation
BRTWD-2999	1038	Nurse's Office Back Office	Nurse's Office Sink	Potable	6/6/2025	13.5	Removed From Service, Pending Remediation

Brentwood Union Free School District

23-53744

Outlet Number	AHERA Number	Common Room Name	Outlet Type	Potable/ Non-Potable	Sample Date	Result ppb	Current Status
West Middle School							
BRTWD-1942	1002	Corridor Near Auditorium	Water Fountain-No Chiller	Potable	6/10/2025	11.3	Removed From Service, Pending Remediation
BRTWD-1975	1050	Corridor Near Faculty Room (1027)	Water Fountain-No Chiller	Potable	6/10/2025	5.1	Removed From Service, Pending Remediation
BRTWD-1978	1029C	Nurse's Office - Inner Office	Nurse's Office Sink	Potable	6/10/2025	19.0	Removed From Service, Pending Remediation
BRTWD-1987	1033	Kitchen	Kitchen Faucet (Cold)	Potable	6/10/2025	6.2	Removed From Service, Pending Remediation
BRTWD-2039	2043	Corridor Near Room 210 (2031)	Water Fountain-No Chiller	Potable	6/10/2025	99.7	Removed From Service, Pending Remediation
BRTWD-2042	2019	Corridor Near Room 220 (2016)	Water Fountain-No Chiller	Potable	6/10/2025	14.5	Removed From Service, Pending Remediation
BRTWD-3512	1043	Room 106	Home Economics Faucet (Cold)	Potable	6/10/2025	5.2	Removed From Service, Pending Remediation
BRTWD-3513	1043	Room 106	Home Economics Faucet (Cold)	Potable	6/10/2025	6.3	Removed From Service, Pending Remediation
BRTWD-3515	1047	Room 104	Home Economics Faucet (Cold)	Potable	6/10/2025	19.8	Removed From Service, Pending Remediation
BRTWD-3516	1047	Room 104	Home Economics Faucet (Cold)	Potable	6/10/2025	52.8	Removed From Service, Pending Remediation
BRTWD-3517	1047	Room 104	Home Economics Faucet (Cold)	Potable	6/10/2025	28.5	Removed From Service, Pending Remediation
BRTWD-3518	1047	Room 104	Home Economics Faucet (Cold)	Potable	6/10/2025	12.4	Removed From Service, Pending Remediation
BRTWD-3519	1047A	Room 104 Laundry Room	Home Economics Faucet (Cold)	Potable	6/10/2025	7.4	Removed From Service, Pending Remediation