

2025 LEAD WATER TESTING REMEDIATION PLAN

SCHOOL	SAMPLE NUMBER	ITEM DESCRIPTION / LOCATION	DATE	RESULT	ACTION
High School	138.1-11	Kitchen Hand Wash Sink in Serving Area Close to Windows	7/16/2025	Tested Above Threshold	Retest
	138.1-37	Room 316 - Left Sink	7/16/2025	Tested Below Threshold	Retest
	138.1-38	Room 316 - Right Sink	7/16/2025	Tested Above Threshold	Retest
	138.1-50	Girls Varsity Locker Room Drinking Fountain	7/16/2025	Tested Above Threshold	Retest
Middle School	138.2-01	Kitchen Side-by-Side Double Sink by Window Sink	7/16/2025	Tested Above Threshold	Retest
	138.2-08	Boys South Gym Locker Room Drinking Fountain	7/16/2025	Tested Above Threshold	Outlet to be taken out of service
	138.2-12	Boys Pool Locker Room Drinking Fountain	7/16/2025	Tested Above Threshold	Outlet to be taken out of service
	138.2-13	Girls Pool Locker Room Drinking Fountain	7/16/2025	Tested Above Threshold	Outlet to be taken out of service
	138.2-16	Nurses Office Sink	7/16/2025	Tested Above Threshold	Retest
	138.2-20	Drinking Fountain by Room 113	7/16/2025	Tested Above Threshold	Outlet to be taken out of service
	138.2-21	Drinking Fountain by Room 121	7/16/2025	Tested Above Threshold	Outlet to be taken out of service
	138.2-25	Drinking Fountain by Room 149	7/16/2025	Tested Above Threshold	Outlet to be taken out of service
	138.2-26	Drinking Fountain by 151	7/16/2025	Tested Above Threshold	Outlet to be taken out of service
	138.2-27	Room 153 - Left Sink	7/16/2025	Tested Above Threshold	Retest
	138.2-29	Room 153 - Side Room Sink	7/16/2025	Tested Above Threshold	Retest
	138.2-34	Drinking Fountain by Room 221	7/16/2025	Tested Above Threshold	Outlet to be taken out of service
	138.2-36	Drinking Fountain by Room 213	7/16/2025	Tested Above Threshold	Outlet to be taken out of service
	138.2-38	Drinking Fountain by Room 201	7/16/2025	Tested Above Threshold	Outlet to be taken out of service
	138.2-40	Room 218 - Left Sink (closest to door)	7/16/2025	Tested Above Threshold	Retest
	138.2-42	Room 218 - Right Sink	7/16/2025	Tested Above Threshold	Retest
	138.2-43	Room 218 - Back Wall Sink	7/16/2025	Tested Above Threshold	Retest
	138.2-45	Room 214 - Far Sink	7/16/2025	Tested Above Threshold	Retest
	138.2-47	Room 212 - Back Left Sink	7/16/2025	Tested Above Threshold	Retest
	138.2-48	Room 212 - Back Right Sink	7/16/2025	Tested Above Threshold	Retest
	138.2-49	Room 212 - Hall Side Left Sink	7/16/2025	Tested Above Threshold	Retest
	138.2-50	Room 212 - Hall Side Right Sink	7/16/2025	Tested Above Threshold	Retest
	138.2-51	Room 210 - Back Left Sink	7/16/2025	Tested Above Threshold	Retest
	138.2-52	Room 210 - Back Right Sink	7/16/2025	Tested Above Threshold	Retest
	138.2-53	Room 210 - Hall Side Left Sink	7/16/2025	Tested Above Threshold	Retest
	138.2-54	Room 210 - Hall Side Right Sink	7/16/2025	Tested Above Threshold	Retest
Smallwood	138.3-01	Kitchen Dishwashing Sink	7/16/2025	Tested Above Threshold	Retest
	138.3-04	Kitchen Prep Sink	7/16/2025	Tested Above Threshold	Retest
	138.3-05	Kitchen Triple Left Sink	7/16/2025	Tested Above Threshold	Retest
	138.3-06	Kitchen Triple Right Sink	7/16/2025	Tested Above Threshold	Retest
	138.3-10	Kitchen Pot Filler	7/16/2025	Tested Above Threshold	Retest
	138.3-12	Room 126 - Sink	7/16/2025	Tested Above Threshold	Retest
	138.3-38	Room 150 - Bubbler Drinking Fountain	7/16/2025	Tested Above Threshold	Retest
	138.3-46	Room 162 - Bubbler Drinking Fountain	7/16/2025	Tested Above Threshold	Retest
	138.3-52	Room 159 - Bubbler Drinking Fountain	7/16/2025	Tested Above Threshold	Retest
Windermere	138.4-09	Kitchen Kettle Filler Right	7/22/2025	Tested Above Threshold	Retest
	138.4-33	Classroom 252 Sink by Window	7/22/2025	Tested Above Threshold	Retest
Field House	138.5-04	Track Spigot	8/4/2025	Tested Above Threshold	Sign Posted Non-Potable Water