

2025 LEAD WATER TESTING REMEDIATION PLAN (Second Round)

SCHOOL	SAMPLE NUMBER	ITEM DESCRIPTION / LOCATION	DATE	RESULT	ACTION
High School	138.1-37	Room 316 - Left Sink	8/11/2025	Tested Below Threshold	Sign Posted Non-Potable Water
	138.1-38	Room 316 - Right Sink	8/11/2025	Tested Above Threshold	Sign Posted Non-Potable Water
	138.1-50	Girls Varsity Locker Room Drinking Fountain	8/11/2025	Tested Above Threshold	Replace Faucet/and/or Install Filter
Middle School	138.2-29	Room 153 - Side Room Sink	8/11/2025	Tested Above Threshold	Replace Faucet/and/or Install Filter
	138.2-42	Room 218 - Right Sink	8/11/2025	Tested Above Threshold	Replace Faucet/and/or Install Filter
	138.2-43	Room 218 - Back Wall Sink	8/11/2025	Tested Above Threshold	Replace Faucet/and/or Install Filter
	138.2-49	Room 212 - Hall Side Left Sink	8/11/2025	Tested Above Threshold	Replace Faucet/and/or Install Filter
	138.2-50	Room 212 - Hall Side Right Sink	8/11/2025	Tested Above Threshold	Replace Faucet/and/or Install Filter
	138.2-51	Room 210 - Back Left Sink	8/11/2025	Tested Above Threshold	Replace Faucet/and/or Install Filter
	138.2-52	Room 210 - Back Right Sink	8/11/2025	Tested Above Threshold	Replace Faucet/and/or Install Filter
	138.2-53	Room 210 - Hall Side Left Sink	8/11/2025	Tested Above Threshold	Replace Faucet/and/or Install Filter
Smallwood	138.3-06	Kitchen Triple Right Sink	8/11/2025	Tested Above Threshold	Replace Faucet/and/or Install Filter
	138.3-10	Kitchen Pot Filler	8/11/2025	Tested Above Threshold	Replace Faucet/and/or Install Filter
	138.3-12	Room 126 - Sink	8/11/2025	Tested Above Threshold	Sign Posted Non-Potable Water
	138.3-46	Room 162 - Bubbler Drinking Fountain	8/11/2025	Tested Above Threshold	Outlet to be Taken Out of Service
	138.3-52	Room 159 - Bubbler Drinking Fountain	8/11/2025	Tested Above Threshold	Outlet to be Taken Out of Service
Windermere	138.4-09	Kitchen Kettle Filler Right	8/11/2025	Tested Above Threshold	Replace Faucet/and/or Install Filter