



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

July 18, 2025

Andy Chasteen
Medford School District
900 Kenyon St
Medford, OR 97501
TEL: 541-842-3646
FAX 541-842-1160

RE: Griffin Creek School Leads-AMENDED

Order No.: 25050575

Dear Andy Chasteen:

Neilson Research Corporation received 27 sample(s) on 5/13/2025 for the analyses presented in the following report.

The results relate only to the parameters tested or to the sample as received by the laboratory. This report shall not be reproduced except in full, without the written approval of Neilson Research Corporation. If you have any questions regarding these test results, please feel free to call.

Sincerely,
Neilson Research Corporation

Tamra Schmedemann
Director of Project Management
245 S Grape St
Medford, OR 97501



Revision v1



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Case Narrative

WO#: 25050575
Date: 7/18/2025

CLIENT: Medford School District

Project: Griffin Creek School Leads-AMENDED

The analyses were performed according to the guidelines in the Neilson Research Corporation Quality Assurance Program. This report contains analytical results for the sample(s) as received by the laboratory.

Neilson Research Corporation certifies that this report is in compliance with the requirements of NELAP. No unusual difficulties were experienced during analysis of this batch except as noted below or qualified with data flags on the reports.

The report has been amended to include the accreditation status, which was omitted from the original version due to a clerical error. Neilson Research Corporation is, and has been, accredited by ORELAP for the analysis of lead in drinking water.

Revision v1



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 25050575
Date Reported: 7/18/2025

Medford School District
900 Kenyon St
Medford, OR 97501

Lab Order: 25050575
Received Date: 5/13/2025 9:18:00 AM
Reported Date: 7/18/2025 4:07:32 PM

Sample Information:

Lab ID: 25050575-01 **Client Sample ID:** Room 24-DF
Collection Date: 5/13/2025 6:14:00 AM **Collected By:** Mike Medel
Matrix: Drinking Water **Sample Location:** Room 24-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	6/4/2025	15.0	A

Lab ID: 25050575-02 **Client Sample ID:** Room 24-Sink
Collection Date: 5/13/2025 6:14:00 AM **Collected By:** Mike Medel
Matrix: Drinking Water **Sample Location:** Room 24-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	6/4/2025	15.0	A

Lab ID: 25050575-03 **Client Sample ID:** Room 25-DF
Collection Date: 5/13/2025 6:12:00 AM **Collected By:** Mike Medel
Matrix: Drinking Water **Sample Location:** Room 25-DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	6/4/2025	15.0	A

QUALIFIERS	*	Value exceeds Maximum or Minimum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcode
	DF	Dilution Factor	E	Value above quantitation range
	H	Holding times for preparation or analysis exceeded	J	Analyte detected below quantitation limits
	MI	Recovery outside control limits due to Matrix Interference	ND	Not Detected at the Reporting Limit
	R	RPD outside accepted recovery limits	RL	Reporting Limit

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Revision v1



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 25050575

Date Reported: 7/18/2025

Medford School District
900 Kenyon St
Medford, OR 97501

Lab Order: 25050575
Received Date: 5/13/2025 9:18:00 AM
Reported Date: 7/18/2025 4:07:32 PM

Sample Information:

Lab ID: 25050575-04 Client Sample ID: Room 25-Sink
Collection Date: 5/13/2025 6:12:00 AM Collected By: Mike Medel
Matrix: Drinking Water Sample Location: Room 25-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.629		0.515	ppb	1	6/4/2025	15.0	A

Lab ID: 25050575-05 Client Sample ID: Boys RR Adj Room 25- Sink (1) Left
Collection Date: 5/13/2025 6:11:00 AM Collected By: Mike Medel
Matrix: Drinking Water Sample Location: Boys RR Adj Room 25- Sink (1) Left

Trace Metals by EPA 200.8 ICP-MS						Analyst: CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.01		0.515	ppb	1	6/4/2025	15.0	A

Lab ID: 25050575-06 Client Sample ID: Boys RR Adj Room 25- Sink (2)
Collection Date: 5/13/2025 6:11:00 AM Collected By: Mike Medel
Matrix: Drinking Water Sample Location: Boys RR Adj Room 25- Sink (2)

Trace Metals by EPA 200.8 ICP-MS						Analyst: CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.902		0.515	ppb	1	6/4/2025	15.0	A

QUALIFIERS	*	Value exceeds Maximum or Minimum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcode
	DF	Dilution Factor	E	Value above quantitation range
	H	Holding times for preparation or analysis exceeded	J	Analyte detected below quantitation limits
	MI	Recovery outside control limits due to Matrix Interference	ND	Not Detected at the Reporting Limit
	R	RPD outside accepted recovery limits	RL	Reporting Limit

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Revision v1



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 25050575

Date Reported: 7/18/2025

Medford School District
900 Kenyon St
Medford, OR 97501

Lab Order: 25050575
Received Date: 5/13/2025 9:18:00 AM
Reported Date: 7/18/2025 4:07:32 PM

Sample Information:

Lab ID: 25050575-07 **Client Sample ID:** Boys RR Adj Room 25- Sink (3)
Collection Date: 5/13/2025 6:10:00 AM **Collected By:** Mike Medel
Matrix: Drinking Water **Sample Location:** Boys RR Adj Room 25- Sink (3)

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.27		0.515	ppb	1	6/4/2025	15.0	A

Lab ID: 25050575-08 **Client Sample ID:** Boys RR Adj Room 25- Sink (4)
Collection Date: 5/13/2025 6:09:00 AM **Collected By:** Mike Medel
Matrix: Drinking Water **Sample Location:** Boys RR Adj Room 25- Sink (4)

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.799		0.515	ppb	1	6/4/2025	15.0	A

Lab ID: 25050575-09 **Client Sample ID:** Boys RR Adj Room 25- Sink (5) Right
Collection Date: 5/13/2025 6:08:00 AM **Collected By:** Mike Medel
Matrix: Drinking Water **Sample Location:** Boys RR Adj Room 25- Sink (5) Right

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.558		0.515	ppb	1	6/4/2025	15.0	A

QUALIFIERS	*	Value exceeds Maximum or Minimum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcode
	DF	Dilution Factor	E	Value above quantitation range
	H	Holding times for preparation or analysis exceeded	J	Analyte detected below quantitation limits
	MI	Recovery outside control limits due to Matrix Interference	ND	Not Detected at the Reporting Limit
	R	RPD outside accepted recovery limits	RL	Reporting Limit

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Revision v1



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 25050575

Date Reported: 7/18/2025

Medford School District
900 Kenyon St
Medford, OR 97501

Lab Order: 25050575
Received Date: 5/13/2025 9:18:00 AM
Reported Date: 7/18/2025 4:07:32 PM

Sample Information:

Lab ID: 25050575-10 **Client Sample ID:** Girls RR Adj Room 25- Sink (1) Left
Collection Date: 5/13/2025 6:06:00 AM **Collected By:** Mike Medel
Matrix: Drinking Water **Sample Location:** Girls RR Adj Room 25- Sink (1) Left

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	6/4/2025	15.0	A

Lab ID: 25050575-11 **Client Sample ID:** Girls RR Adj Room 25- Sink (2)
Collection Date: 5/13/2025 6:05:00 AM **Collected By:** Mike Medel
Matrix: Drinking Water **Sample Location:** Girls RR Adj Room 25- Sink (2)

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.808		0.515	ppb	1	6/4/2025	15.0	A

Lab ID: 25050575-12 **Client Sample ID:** Girls RR Adj Room 25- Sink (3)
Collection Date: 5/13/2025 6:04:00 AM **Collected By:** Mike Medel
Matrix: Drinking Water **Sample Location:** Girls RR Adj Room 25- Sink (3)

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	6/4/2025	15.0	A

QUALIFIERS	*	Value exceeds Maximum or Minimum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcode
	DF	Dilution Factor	E	Value above quantitation range
	H	Holding times for preparation or analysis exceeded	J	Analyte detected below quantitation limits
	MI	Recovery outside control limits due to Matrix Interference	ND	Not Detected at the Reporting Limit
	R	RPD outside accepted recovery limits	RL	Reporting Limit

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Revision v1



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 25050575
Date Reported: 7/18/2025

Medford School District
900 Kenyon St
Medford, OR 97501

Lab Order: 25050575
Received Date: 5/13/2025 9:18:00 AM
Reported Date: 7/18/2025 4:07:32 PM

Sample Information:

Lab ID: 25050575-13 **Client Sample ID:** Girls RR Adj Room 25- Sink (4)
Collection Date: 5/13/2025 6:03:00 AM **Collected By:** Mike Medel
Matrix: Drinking Water **Sample Location:** Girls RR Adj Room 25- Sink (4)

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	6/4/2025	15.0	A

Lab ID: 25050575-14 **Client Sample ID:** Girls RR Adj Room 25- Sink (5) Right
Collection Date: 5/13/2025 6:02:00 AM **Collected By:** Mike Medel
Matrix: Drinking Water **Sample Location:** Girls RR Adj Room 25- Sink (5) Right

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	6/4/2025	15.0	A

Lab ID: 25050575-15 **Client Sample ID:** Gym-DF (North)
Collection Date: 5/13/2025 5:50:00 AM **Collected By:** Mike Medel
Matrix: Drinking Water **Sample Location:** Gym-DF (North)

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.49		0.515	ppb	1	6/4/2025	15.0	A

QUALIFIERS	*	Value exceeds Maximum or Minimum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcode
	DF	Dilution Factor	E	Value above quantitation range
	H	Holding times for preparation or analysis exceeded	J	Analyte detected below quantitation limits
	MI	Recovery outside control limits due to Matrix Interference	ND	Not Detected at the Reporting Limit
	R	RPD outside accepted recovery limits	RL	Reporting Limit

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Revision v1



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 25050575

Date Reported: 7/18/2025

Medford School District
900 Kenyon St
Medford, OR 97501

Lab Order: 25050575
Received Date: 5/13/2025 9:18:00 AM
Reported Date: 7/18/2025 4:07:32 PM

Sample Information:

Lab ID: 25050575-16
Collection Date: 5/13/2025 5:51:00 AM
Matrix: Drinking Water
Client Sample ID: Gym-DF (South)
Collected By: Mike Medel
Sample Location: Gym-DF (South)

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.954		0.515	ppb	1	6/4/2025	15.0	A

Lab ID: 25050575-17
Collection Date: 5/13/2025 5:44:00 AM
Matrix: Drinking Water
Client Sample ID: Gym Womens RR-Sink
Collected By: Mike Medel
Sample Location: Gym Womens RR-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.697		0.515	ppb	1	6/4/2025	15.0	A

Lab ID: 25050575-18
Collection Date: 5/13/2025 5:42:00 AM
Matrix: Drinking Water
Client Sample ID: Gym Mens RR-Sink
Collected By: Mike Medel
Sample Location: Gym Mens RR-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	1.09		0.515	ppb	1	6/4/2025	15.0	A

QUALIFIERS	*	Value exceeds Maximum or Minimum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcode
	DF	Dilution Factor	E	Value above quantitation range
	H	Holding times for preparation or analysis exceeded	J	Analyte detected below quantitation limits
	MI	Recovery outside control limits due to Matrix Interference	ND	Not Detected at the Reporting Limit
	R	RPD outside accepted recovery limits	RL	Reporting Limit

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Revision v1



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 25050575

Date Reported: 7/18/2025

Medford School District
900 Kenyon St
Medford, OR 97501

Lab Order: 25050575
Received Date: 5/13/2025 9:18:00 AM
Reported Date: 7/18/2025 4:07:32 PM

Sample Information:

Lab ID: 25050575-19 **Client Sample ID:** Stage-Sink (Utility)
Collection Date: 5/13/2025 5:46:00 AM **Collected By:** Mike Medel
Matrix: Drinking Water **Sample Location:** Stage-Sink (Utility)

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	6/4/2025	15.0	A

Lab ID: 25050575-20 **Client Sample ID:** Room Above Stage (South) DF
Collection Date: 5/13/2025 5:47:00 AM **Collected By:** Mike Medel
Matrix: Drinking Water **Sample Location:** Room Above Stage (South) DF

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	0.654		0.515	ppb	1	6/4/2025	15.0	A

Lab ID: 25050575-21 **Client Sample ID:** Room Above Stage (South)-Sink
Collection Date: 5/13/2025 5:48:00 AM **Collected By:** Mike Medel
Matrix: Drinking Water **Sample Location:** Room Above Stage (South)-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst; CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	2.92		0.515	ppb	1	6/6/2025	15.0	A

QUALIFIERS	*	Value exceeds Maximum or Minimum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcode
	DF	Dilution Factor	E	Value above quantitation range
	H	Holding times for preparation or analysis exceeded	J	Analyte detected below quantitation limits
	MI	Recovery outside control limits due to Matrix Interference	ND	Not Detected at the Reporting Limit
	R	RPD outside accepted recovery limits	RL	Reporting Limit

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Revision v1



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 25050575

Date Reported: 7/18/2025

Medford School District
900 Kenyon St
Medford, OR 97501

Lab Order: 25050575
Received Date: 5/13/2025 9:18:00 AM
Reported Date: 7/18/2025 4:07:32 PM

Sample Information:

Lab ID: 25050575-22 Client Sample ID: Cafeteria-Bottle Filler (Upper)
Collection Date: 5/13/2025 5:36:00 AM Collected By: Mike Medel
Matrix: Drinking Water Sample Location: Cafeteria-Bottle Filler (Upper)

Trace Metals by EPA 200.8 ICP-MS						Analyst: CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	6/6/2025	15.0	A

Lab ID: 25050575-23 Client Sample ID: Cafeteria (Lower) Bottle Filler
Collection Date: 5/13/2025 5:38:00 AM Collected By: Mike Medel
Matrix: Drinking Water Sample Location: Cafeteria (Lower) Bottle Filler

Trace Metals by EPA 200.8 ICP-MS						Analyst: CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	6/6/2025	15.0	A

Lab ID: 25050575-24 Client Sample ID: Kitchen-Sink (Food Prep-North)
Collection Date: 5/13/2025 5:35:00 AM Collected By: Mike Medel
Matrix: Drinking Water Sample Location: Kitchen-Sink (Food Prep-North)

Trace Metals by EPA 200.8 ICP-MS						Analyst: CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	6/6/2025	15.0	A

QUALIFIERS	*	Value exceeds Maximum or Minimum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcode
	DF	Dilution Factor	E	Value above quantitation range
	H	Holding times for preparation or analysis exceeded	J	Analyte detected below quantitation limits
	MI	Recovery outside control limits due to Matrix Interference	ND	Not Detected at the Reporting Limit
	R	RPD outside accepted recovery limits	RL	Reporting Limit

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Revision v1



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

Analytical Report

WO#: 25050575

Date Reported: 7/18/2025

Medford School District
900 Kenyon St
Medford, OR 97501

Lab Order: 25050575
Received Date: 5/13/2025 9:18:00 AM
Reported Date: 7/18/2025 4:07:32 PM

Sample Information:

Lab ID: 25050575-25 Client Sample ID: Kitchen-Sink (Hand/Eye Wash)
Collection Date: 5/13/2025 5:30:00 AM Collected By: Mike Medel
Matrix: Drinking Water Sample Location: Kitchen-Sink (Hand/Eye Wash)

Trace Metals by EPA 200.8 ICP-MS						Analyst: CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	6/6/2025	15.0	A

Lab ID: 25050575-26 Client Sample ID: Kitchen-Sink(Pre-rinse/Dishwasher)
Collection Date: 5/13/2025 5:33:00 AM Collected By: Mike Medel
Matrix: Drinking Water Sample Location: Kitchen-Sink(Pre-rinse/Dishwasher)

Trace Metals by EPA 200.8 ICP-MS						Analyst: CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	6/6/2025	15.0	A

Lab ID: 25050575-27 Client Sample ID: Cafeteria Staff RR-Sink
Collection Date: 5/13/2025 5:33:00 AM Collected By: Mike Medel
Matrix: Drinking Water Sample Location: Cafeteria Staff RR-Sink

Trace Metals by EPA 200.8 ICP-MS						Analyst: CJS		
Analyses	Result	Qual	MRL	Units	DF	Date Analyzed	MCL	NELAP Status
Lead	ND		0.515	ppb	1	6/6/2025	15.0	A

QUALIFIERS	*	Value exceeds Maximum or Minimum Contaminant Level.	C1	Sample container temperature is out of limit as specified at testcode
	DF	Dilution Factor	E	Value above quantitation range
	H	Holding times for preparation or analysis exceeded	J	Analyte detected below quantitation limits
	MI	Recovery outside control limits due to Matrix Interference	ND	Not Detected at the Reporting Limit
	R	RPD outside accepted recovery limits	RL	Reporting Limit

NELAP A Accredited in accordance with NELAP ORELAP 100016, OR-028

Revision v1



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

QC SUMMARY REPORT

WO#: 25050575
18-Jul-25

Client: Medford School District
Project: Griffin Creek School Leads-AMENDED

TestCode: LEAD_SCHOOLS

Sample ID: MB-31530	SampType: MBLK	TestCode: LEAD_SCHO	Units: ppb	Prep Date: 6/3/2025	RunNo: 60046
Client ID: PBW	Batch ID: 31530	TestNo: E200.8	E200.8	Analysis Date: 6/5/2025	SeqNo: 983164
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead ND 0.515

Sample ID: LCS-31530	SampType: LCS	TestCode: LEAD_SCHO	Units: ppb	Prep Date: 6/3/2025	RunNo: 60046
Client ID: LCSW	Batch ID: 31530	TestNo: E200.8	E200.8	Analysis Date: 6/6/2025	SeqNo: 983165
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 101 0.520 100 0 101 85 115

Sample ID: 25050575-21AMS	SampType: MS	TestCode: LEAD_SCHO	Units: ppb	Prep Date: 6/3/2025	RunNo: 60046
Client ID: Room Above Stage (	Batch ID: 31530	TestNo: E200.8	E200.8	Analysis Date: 6/6/2025	SeqNo: 983167
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 101 0.520 100 2.92 97.7 70 130

Sample ID: 25050575-21AMSD	SampType: MSD	TestCode: LEAD_SCHO	Units: ppb	Prep Date: 6/3/2025	RunNo: 60046
Client ID: Room Above Stage (	Batch ID: 31530	TestNo: E200.8	E200.8	Analysis Date: 6/6/2025	SeqNo: 983168
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC LowLimit HighLimit RPD Ref Val %RPD RPDLimit Qual

Lead 96.8 0.520 100 2.92 93.9 70 130 101 3.89 20

Qualifiers: C1 Sample container temperature is out of limit as specified at testcode DF Dilution Factor H Holding times for preparation or analysis exceed
MI Recovery outside control limits due to Matrix Interference ND Not Detected at the Reporting Limit RL Reporting Limit

Revision v1



Neilson Research Corporation
245 S Grape St
Medford, OR 97501
TEL: (541) 770-5678 FAX: (541) 770-2901
Website: www.nrclabs.com

QC SUMMARY REPORT

WO#: 25050575
18-Jul-25

Client: Medford School District
Project: Griffin Creek School Leads-AMENDED

TestCode: LEAD_SCHOOLS

Sample ID: MB-31529	SampType: MBLK	TestCode: LEAD_SCHO	Units: ppb	Prep Date: 6/3/2025	RunNo: 60091						
Client ID: PBW	Batch ID: 31529	TestNo: E200.8	E200.8	Analysis Date: 6/4/2025	SeqNo: 984109						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	ND	0.515									
------	----	-------	--	--	--	--	--	--	--	--	--

Sample ID: LCS-31529	SampType: LCS	TestCode: LEAD_SCHO	Units: ppb	Prep Date: 6/3/2025	RunNo: 60091						
Client ID: LCSW	Batch ID: 31529	TestNo: E200.8	E200.8	Analysis Date: 6/4/2025	SeqNo: 984110						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	101	0.520	100	0	101	85	115				
------	-----	-------	-----	---	-----	----	-----	--	--	--	--

Sample ID: 25050575-01AMS	SampType: MS	TestCode: LEAD_SCHO	Units: ppb	Prep Date: 6/3/2025	RunNo: 60091						
Client ID: Room 24-DF	Batch ID: 31529	TestNo: E200.8	E200.8	Analysis Date: 6/4/2025	SeqNo: 984112						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	98.4	0.520	100	0.206	98.2	70	130				
------	------	-------	-----	-------	------	----	-----	--	--	--	--

Sample ID: 25050575-01AMSD	SampType: MSD	TestCode: LEAD_SCHO	Units: ppb	Prep Date: 6/3/2025	RunNo: 60091						
Client ID: Room 24-DF	Batch ID: 31529	TestNo: E200.8	E200.8	Analysis Date: 6/4/2025	SeqNo: 984113						
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	RPD Ref Val	%RPD	RPDLimit	Qual

Lead	100	0.520	100	0.206	100	70	130	98.4	1.88	20	
------	-----	-------	-----	-------	-----	----	-----	------	------	----	--

Qualifiers:	C1	Sample container temperature is out of limit as specified at testcode	DF	Dilution Factor	H	Holding times for preparation or analysis exceed
	MI	Recovery outside control limits due to Matrix Interference	ND	Not Detected at the Reporting Limit	RL	Reporting Limit

Revision v1

Sample Log-In Check List

Client Name: MedfordSchoolDist

Work Order Number: 25050575

RcptNo: 1

Logged by: Ashley Spiegelberg 5/13/2025 9:18:00 AM

Completed By: Coni Boyko 5/16/2025 12:38:49 PM

Reviewed By: Dorie Evans 6/10/2025 9:00:39 AM

Am
Coni Boyko
Dorie Evans

Chain of Custody

1. Is Chain of Custody complete? Yes ☒ No ☐ Not Present ☐
2. How was the sample delivered? Client

Log In

3. Coolers are present? Yes ☐ No ☐ NA ☒
4. Shipping container/cooler in good condition? Yes ☒ No ☐
Custody seals intact on shipping container/cooler? Yes ☐ No ☐ Not Present ☒ NA ☐
No. Seal Date: Signed By:
5. Was an attempt made to cool the samples? Yes ☐ No ☐ NA ☒
6. Were all samples received at a temperature of >0° C to 6.0°C Yes ☐ No ☐ NA ☒
7. Sample(s) in proper container(s)? Yes ☒ No ☐
8. Sufficient sample volume for indicated test(s)? Yes ☒ No ☐
9. Are samples (except VOA and ONG) properly preserved? Yes ☒ No ☐
10. Was preservative added to bottles? Yes ☐ No ☒ NA ☐
11. Is the headspace in the VOA vials less than 1/4 inch or 6 mm? Yes ☐ No ☐ No VOA Vials ☒
12. Were any sample containers received broken? Yes ☐ No ☒
13. Does paperwork match bottle labels? Yes ☒ No ☐
(Note discrepancies on chain of custody)
14. Are matrices correctly identified on Chain of Custody? Yes ☒ No ☐
15. Is it clear what analyses were requested? Yes ☒ No ☐
16. Were all holding times able to be met? Yes ☒ No ☐
(If no, notify customer for authorization.)

Special Handling (if applicable)

17. Was client notified of all discrepancies with this order? Yes ☐ No ☐ NA ☒

Person Notified: Date:
By Whom: Via: ☐ eMail ☐ Phone ☐ Fax ☐ In Person
Regarding:
Client Instructions:

18. Additional remarks:

Cooler Information

Cooler No	Temp °C	Condition	Seal Intact	Seal No	Seal Date	Signed By
-----------	---------	-----------	-------------	---------	-----------	-----------

Chain of Custody Record

Page 1 of 3

This Chain of Custody is a LEGAL DOCUMENT and must be filled out accurately.

Section A Required Client Information		Section B Required Project Information		Section C Invoice Information		Section D Rush Status (Subject to Scheduling)	
Company: MSD 549C		Project Name: <u>Griffin Creek</u>		Attention: Accounting		☐ Standard 10-14 Days ☐ 5 Business Days (50% surcharge) ☐ 3 Business Days (75% surcharge) ☐ 24 - 48 hours (100% surcharge) ☐ Other _____	
Address: 900 Kenyon Medford, OR 97501		Project Number:		Company Name: Medford School District			
Email: <u>andy.chasteen@medford.k12.or.us</u>		Report <u>andy.chasteen@medford.k12.or.us</u>		Address: 900 Kenyon Medford, OR 97501			
Phone: 541-840-4315 Fax:		Copy T <u>seth.barry@medford.k12.or.us</u>		P.O. #			
Collected By (Print): <u>Mike Medel</u>						Authorized ☐ Yes ☐ No	
Collected By (Sign): <u>[Signature]</u>							
Email Report ☐ Yes ☐ No Mail Report ☐ Yes ☐ No							
Fax Report ☐ Yes ☐ No							

Section E Sample Information				Analysis Requested										NRC Workorder # (Lab Use Only) <u>25050575</u>		
Sample ID	Matrix *	Date Collected	Time Collected	No. of Containers											Remarks/Field Data	NRC Sample # (Lab Use Only)
Room 24 - Drinking Fountain	DW	5/13/25	6:14	1												01
Room 24 - Sink	DW	5/13/25	6:14	1												02
Room 25 - Drinking Fountain	DW	5/13/25	6:12	1												03
Room 25 - Sink	DW	5/13/25	6:12	1												04
Boy's Restroom Adjacent To Room 25 -Sink (1) Left side	DW	5/13/25	6:11	1												05
Boy's Restroom Adjacent To Room 25 -Sink (2)	DW	5/13/25	6:11	1												06
Boy's Restroom Adjacent To Room 25 -Sink (3)	DW	5/13/25	6:10	1												07
Boy's Restroom Adjacent To Room 25 -Sink (4)	DW	5/13/25	6:09	1												08
Boy's Restroom Adjacent To Room 25 -Sink (5) Right side	DW	5/13/25	6:08	1												09
Girl's Restroom Adjacent To Room 25 -Sink (1) Left side	DW	5/13/25	6:06	1												10
Girl's Restroom Adjacent To Room 25 -Sink (2)	DW	5/13/25	6:05	1												11
Girl's Restroom Adjacent To Room 25 -Sink (3)	DW	5/13/25	6:04	1												12
Girl's Restroom Adjacent To Room 25 -Sink (4)	DW	5/13/25	6:03	1												13
Girl's Restroom Adjacent To Room 25 -Sink (5) Right side	DW	5/13/25	6:02	1												14
	DW			1												
Gym - Drinking Fountain (North)	DW	5/13/25	5:50	1												15
Gym - Drinking Fountain (South)	DW	5/13/25	5:51	1												16
Gym Women's Restroom - Sink	DW	5/13/25	5:44	1												17
Gym Men's Restroom - Sink	DW	5/13/25	5:42	1												18
Stage - Sink (Utility)	DW	5/13/25	5:46	1												19
Room Above The Stage (South) - Drinking Fountain	DW	5/13/25	5:47	1												20
Room Above The Stage (South) - Sink	DW	5/13/25	5:48	1												21
	DW			1												22

