

Lead Tests - North Medford High Main Building - # 20481700											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results (PPB)	Filtering For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481700-001WB	20481700-001WB26A	(A) Main Office - Bottle Filler	05/14/25	ND	Lead	09/24/06	10/05/22	Elkay (51300C)	Ferguson	Shared Filter with Fountain.
2	20481700-002DW	20481700-002DW26A	(A) Main Office - Drinking Fountain	05/14/25	ND	Lead	09/24/06	10/05/22	Elkay (51300C)	Ferguson	Shared Filter with Bottle Filler
3	20481700-003SF	20481700-003SF26A	(A) Tornado Conference Room - Sink	05/14/25	1.0						None.
4	20481700-004DW	20481700-004DW26A	(A) Courtyard Behind Main Office - Drinking Fountain (Upper)	05/14/25	ND						None.
5	20481700-005DW	20481700-005DW26A	(A) Courtyard Behind Main Office - Drinking Fountain (Lower)	05/14/25	ND						None.
6	20481700-006BF	20481700-006BF26A	(A) West Men's Rest Room - Sink	05/21/25	ND						None.
7	20481700-007BF	20481700-007BF26A	(A) West Women's Rest Room - Sink (Left)	05/21/25	ND						None.
8	20481700-008BF	20481700-008BF26A	(A) West Women's Rest Room - Sink (Right)	05/21/25	ND						None.
			(A) Health Room Sink	05/14/25	ND						Discovered 05/14/2025
9	20481700-009BF	20481700-009BF26A	(A) Health Room Unisex Rest Room - Sink	05/21/25	ND						None.
10	20481700-010BF	20481700-010BF26A	(A) South Unisex Rest Room - Sink	05/21/25	0.7						None.
11	20481700-011BF	20481700-011BF26A	(A) South Unisex Rest Room - Sink	05/21/25	ND						None.
12	20481700-012BF	20481700-012BF26A	(A) East Men's Rest Room - Sink	05/21/25	ND						None.
13	20481700-013BF	20481700-013BF26A	(A) East Women's Rest Room - Sink	05/21/25	ND						None.
14	20481700-014SF	20481700-014SF26A	(A) Staff Break Room - Sink	05/21/25	ND						None.
15	20481700-015IM	20481700-015IM26A	(A) Staff Break Room - Ice Maker	05/14/25	4.8						None.
Lead Tests - North Medford High Fine Arts Building - # 20481701											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filtering For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
NA	20481701-001DW	20481701-001DW26A	FA - Lobby - Drinking Fountain	06/18/18	0.8						11/6/24 Removed and replaced with Elkay unit.
1			FA - Lobby - Bottle Filler	05/14/25	ND	Sediment	11/06/24	11/06/24	Elkay	Ferguson	
2			FA - Lobby - Drinking Fountain	05/14/25	ND	Sediment	11/06/24	11/06/24	Elkay	Ferguson	
3	20481701-002BF	20481701-002BF26A	FA - Lobby - Men's Restroom - Sink (Left)	05/21/25	ND						None.
4	20481701-003BF	20481701-003BF26A	FA - Lobby - Men's Restroom - Sink (Right)	05/21/25	ND						None.
5	20481701-004BF	20481701-004BF26A	FA - Lobby - Women's Restroom - Sink (Left)	05/21/25	ND						None.
6	20481701-005BF	20481701-005BF26A	FA - Lobby - Women's Restroom - Sink (Right)	05/21/25	ND						None.
7	20481701-006BF	20481701-006BF26A	FA - Lobby - Unisex Restroom - Sink	05/21/25	1.5						None.
8	20481701-007CF	20481701-007CF26A	IDF Room Next to FA-3 - Sink	05/14/25	3.0						None.
9	20481701-008OT	20481701-008OT26A	IDF Room Next to FA-3 - Spray Nozzle	06/27/25	12.1						None.
10	20481701-009DW	20481701-009DW26A	Outside FA-3 - Drinking Fountain	05/14/25	0.8						None.
11	20481701-010BF	20481701-010BF26A	Outside FA-3 - Unisex Restroom - Sink	05/21/25	1.0						None.
12	20481701-011CF	20481701-011CF26A	FA-5 - Sink (South Wall)	05/14/25	1.3						None.
13	20481701-012CF	20481701-012CF26A	FA-5 - Sink (North Wall)	05/14/25	ND						None.
N/A	N/A	N/A	FA-5 - North Wall Trough Sink (Left Fixture 1)	05/08/19	35.4						Technical education classroom (Pottery) - Fixtures are not operational.
N/A	N/A	N/A	FA-5 - North Wall Trough Sink (Fixture 2)	05/08/19	31.0						Technical education classroom (Pottery) - Fixtures are not operational.
N/A	N/A	N/A	FA-5 - North Wall Trough Sink (Fixture 3)	05/08/19	113.0						Technical education classroom (Pottery) - Fixtures are not operational.
N/A	N/A	N/A	FA-5 - North Wall Trough Sink (Fixture 4)	05/08/19	39.6						Technical education classroom (Pottery) - Fixtures are not operational.
N/A	N/A	N/A	FA-5 - North Wall Trough Sink (Fixture 5)	05/08/19	268.0						Technical education classroom (Pottery) - Fixtures are not operational.
N/A	N/A	N/A	FA-5 - North Wall Trough Sink (Right Fixture 6)	05/08/19	733.0						Technical education classroom (Pottery) - Fixtures are not operational.
14	20481701-013CF	20481701-013CF26A	FA-5 - Kiln Area - Sink (Left Fixture)	05/14/25	ND						None.
15	20481701-014CF	20481701-014CF26A	FA-5 - Kiln Area - Sink (Right Fixture)	05/14/25	ND						None.
16	20481701-015CF	20481701-015CF26A	FA-6 - NE Island Sink (1)	05/14/25	0.6						None.
17	20481701-016CF	20481701-016CF26A	FA-6 - SE Island Sink (2)	05/14/25	ND						None.
18	20481701-017CF	20481701-017CF26A	FA-6 - NW Island Sink (3)	05/14/25	0.9						None.
19	20481701-018CF	20481701-018CF26A	FA-6 - SW Island Sink (4)	05/14/25	ND						None.
20	20481701-019CF	20481701-019CF26A	FA-6 - Sink (South Wall)	05/14/25	8.8						None.
21	20481701-020BF	20481701-020BF26A	FA-7 - Entrance - Men's Restroom - Sink	05/21/25	1.8						None.
22	20481701-021BF	20481701-021BF26A	FA-7 - Entrance - Women's Restroom - Sink	05/21/25	4.8						None.
23	20481701-022DW	20481701-022DW26A	FA-7 - Entrance - Drinking Fountain	05/14/25	1.8	Lead	01/01/12	06/25/25	3US-MAX-F01H	Lowes	
24	20481701-023CF	20481701-023CF26A	FA-8 - Sink	05/14/25	4.7						None.
25	20481701-024OT	20481701-024OT26A	FA - Outside Dressing Rooms - Paint Sink	06/27/25	ND						None.
26	20481701-025CF	20481701-025CF26A	FA - Girl's Dressing Room - Sink	06/27/25	10.7						None.
27	20481701-026BF	20481701-026BF26A	FA - Girl's Dressing Room Restroom - Sink	05/21/25	0.6						None.
28	20481701-027CF	20481701-027CF26A	FA - Boy's Dressing Room - Sink	05/21/25	ND						None.
29	20481701-028BF	20481701-028BF26A	FA - Boy's Dressing Room Restroom - Sink	05/21/25	1.2						None.

Lead Tests - North Medford High Cafeteria - # 20481702											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filtering For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	A	20481702-001KF	20481702-001KF26A	Dish Washer (DW) Area - East Wall - Pre-rinse Sink	05/14/25	7.0					None.
2	B	20481702-002KF	20481702-002KF26A	DW Area - East Wall - Pre-rinse Spray Nozzle (Left)	05/14/25	1.1					None.
3	C	20481702-003KF	20481702-003KF26A	DW Area - East Wall - Pre-rinse Spray Nozzle (Right)	05/14/25	4.7					None.
4	D	20481702-004KF	20481702-004KF26A	DW Area - West Wall - Hand Wash Sink (South West Corner)	05/14/25	ND					None.
5	E	20481702-005KF	20481702-005KF26A	DW Area - West Wall - Pre-rinse Sink (Left)	05/14/25	ND					None.
6	F	20481702-006KF	20481702-006KF26A	DW Area - West Wall - Spray Nozzle (Left)	05/14/25	1.2					None.
7	G	20481702-007KF	20481702-007KF26A	DW Area - West Wall - Pre-rinse Sink (Right)	05/14/25	1.6					None.
8		20481702-008BF	20481702-008BF26A	Kitchen Hall - Unisex Restroom - Sink	05/21/25	ND					None.
9		20481702-009BF	20481702-009BF26A	Kitchen Storage (Break Room) - Women's (Unisex) Restroom - Sink	05/21/25	ND					None.
10	H	20481702-010KF	20481702-010KF26A	Kitchen - East Wall - Hand Wash Sink (Left)	05/14/25	1.4					None.
11	I	20481702-011KF	20481702-011KF26A	Kitchen - East Wall - Hand Wash Sink (Right)	05/14/25	2.7					None.
12	J	20481702-012KF	20481702-012KF26A	Kitchen - East Wall - Food Prep Sink	05/14/25	ND					None.
13	K	20481702-013KF	20481702-013KF26A	Kitchen - East Island - Hand Wash Sink (Eye Wash)	05/14/25	ND					None.
14	L	20481702-014KF	20481702-014KF26A	Kitchen - East Island - Food Prep - Sink	05/14/25	0.6					None.
15	M	20481702-015KF	20481702-015KF26A	Kitchen - North West Wall - Food Prep - Sink	05/14/25	ND					None.
16	N	20481702-016KF	20481702-016KF26A	Kitchen - NW Hand Wash Sink By Hall	05/14/25	ND					Added to tracker 09/15/21.
17	O	20481702-017KF	20481702-017KF26A	Kitchen - North East Wall - Food Prep - Sink (Left)	05/14/25	0.9					None.
18	P	20481702-018KF	20481702-018KF26A	Kitchen - North East Wall - Food Prep - Sink (Right)	05/14/25	2.1					None.
19	Q	20481702-019KF	20481702-019KF26A	Kitchen - Small Kettle - Faucet	05/14/25	1.3					None.
20	R	20481702-020KF	20481702-020KF26A	Kitchen - Large Kettle - Faucet	05/14/25	ND					None.
21	S	20481702-021KF	20481702-021KF26A	Kitchen - Spray Nozzle To Right of Large Kettle	05/14/25	1.5					None.
22	T	20481702-022KF	20481702-022KF26A	Kitchen - Steam Oven (Upper - Filtered)	06/18/18	1.4	Sediment	12/12/15	06/15/18	EV 9618-11; EV979902SS Sediment	No lead test necessary. 3 x filters installed in series serving the upper and lower ovens.
N/A	N/A	N/A	N/A	Kitchen - Steam Oven (Upper - Un-filtered)	06/18/18	18.5	Sediment	12/12/15	06/15/18	EV 9618-11; EV979902SS Sediment	No lead test necessary. 3 x filters installed in series serving the upper and lower ovens.
23	U	20481702-023KF	20481702-023KF26A	Kitchen - Steam Oven (Lower)	06/18/18	7.1	Sediment	12/12/15	06/15/18	EV 9618-11; EV979902SS Sediment	No lead test necessary. 3 x filters installed in series serving the upper and lower ovens.
24	V	20481702-024KF	20481702-024KF26A	Kitchen - West Wall - Hand Wash Sink	05/14/25	ND					None.
25	W	20481702-025KF	20481702-025KF26A	Kitchen - Coffee Machine (North West Corner)	05/14/25	9.8					None.
26	X	20481702-026KF	20481702-026KF26A	Kitchen - Wok Faucet	05/14/25	0.6					None.
27		20481702-027KF	20481702-027KF26A	Kitchen - Soda Machine (East)	06/18/18	0.2					Removed as of 5/14/2025.
28		20481702-028IM	20481702-028IM26A	Kitchen - Soda Machine Ice Maker (East)	06/18/18	ND					Removed as of 5/14/2025.
29		20481702-029KF	20481702-029KF26A	Kitchen - Soda Machine (West)	06/18/18	0.2					Removed as of 5/14/2025.
30		20481702-030IM	20481702-030IM26A	Kitchen - Soda Machine Ice Maker (West)	06/18/18	ND					Removed as of 5/14/2025.
31		20481702-031IM	20481702-031IM26A	Kitchen - Pizza Area (West Side) - Ice Machine	05/14/25	ND					None.
32		20481702-032KF	20481702-032KF26A	Kitchen - Pizza Area (West Side) - Food Prep Sink	05/14/25	ND					None.
33		20481702-033KF	20481702-033KF26A	Kitchen - Pizza Area (West Side) - Hand Wash Sink	05/14/25	3.2					None.
NA		20481702-034DW	20481702-034DW26A	Cafeteria - Drinking Fountain (Upper)	06/29/17	2.2					This DF was taken out of commission due to complaints of smells.
NA		20481702-035DW	20481702-035DW26A	Cafeteria - Drinking Fountain (Lower)	07/29/16	1.7					This DF was taken out of commission due to complaints of smells.
				Cafeteria - Bottle Filler (Upper)	05/14/25	ND	Sediment	08/01/24	08/01/24	Elkay	Discovered 5/14/2025.
				Cafeteria - Drinking Fountain (Lower)	05/14/25	ND	Sediment	08/01/24	08/01/24	Elkay	Discovered 5/14/2025.
34		20481702-036BF	20481702-036BF26A	Cafeteria - Men's Restroom - Sink (Left)	05/21/25	1.4					None.
35		20481702-037BF	20481702-037BF26A	Cafeteria - Men's Restroom - Sink (Center)	05/21/25	12.1					None.
36		20481702-038BF	20481702-038BF26A	Cafeteria - Men's Restroom - Sink (Right)	05/21/25	4.5					None.
37		20481702-039BF	20481702-039BF26A	Cafeteria - Women's Restroom - Left Sink (1)	05/21/25	3.5					None.
38		20481702-040BF	20481702-040BF26A	Cafeteria - Women's Restroom - Sink (2)	05/21/25	3.7					None.
39		20481702-041BF	20481702-041BF26A	Cafeteria - Women's Restroom - Sink (3)	05/21/25	1.8					None.
40		20481702-042BF	20481702-042BF26A	Cafeteria - Women's Restroom - Right Sink (4)	05/21/25	3.2					None.
41		20481702-043CF	20481702-043CF26A	Room C-1 - Sink	05/14/25	ND					None.
42		20481702-001KF	20481702-044BF26A	Room C-1 Staff Unisex Restroom - Sink	05/21/25	0.8					None.
				Cafeteria - Bar Sink SW Corner	05/14/25	ND					Discovered 5/14/2025.

Lead Tests - North Medford High Science Building - # 20481704											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filtering For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481704-001DW	20481704-001DW26A	Outside S-6 - Drinking Fountain	05/14/25	4.1	Lead	08/15/16	06/26/25	3US-MAX-F01H	Lowes	
2	20481704-002DW	20481704-002DW26A	Outside Planetarium - Drinking Fountain	05/14/25	1.3						None.
3	20481704-003BF	20481704-003BF26A	Outside Planetarium Men's Restroom - Sink (Left)	08/07/25	4.0	Lead	08/06/25	08/06/25	Percola		None.
4	20481704-004BF	20481704-004BF26A	Outside Planetarium Men's Restroom - Sink (Center)	05/21/25	0.5						None.
5	20481704-005BF	20481704-005BF26A	Outside Planetarium Men's Restroom - Sink (Right)	05/21/25	ND						None.
6	20481704-006BF	20481704-006BF26A	Outside Planetarium Women's Restroom - Sink (Left)	05/21/25	1.3						None.
7	20481704-007BF	20481704-007BF26A	Outside Planetarium Women's Restroom - Sink (Center)	05/21/25	0.6						None.
8	20481704-008BF	20481704-008BF26A	Outside Planetarium Women's Restroom - Sink (Right)	05/21/25	0.7						None.
9	20481704-009DW	20481704-009DW26A	Outside S4 - Drinking Fountain	05/14/25	ND	Lead	08/15/16	05/23/18	3US-MAX-F01H	Lowes	
10	20481704-010BF	20481704-010BF26A	Outside S2 Men's Restroom - Sink	05/21/25	2.6						None.
11	20481704-011BF	20481704-011BF26A	Outside S2 Women's Restroom - Sink	05/21/25	ND						None.
N/A	N/A	N/A	S-8 - Sink (1 - With Eye Wash)	N/A	N/A						Water should not be consumed from the eye wash.
N/A	N/A	N/A	S-8 - Sink (2)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - Sink (3)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - Sink (4)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - Sink (5)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - Sink (6)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - Sink (7)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - Sink (8)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - Sink (9)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - Sink (10 - Island)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - North Lab Room - Sink (1)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - North Lab Room - Sink (2)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - North Lab Room - Sink (3)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - North Lab Room - Sink (4)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-8 - South Storage Room - Sink	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-9 - Island Sink (Left Fixture)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-9 - Island Sink (Right Fixture)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-9 - Sink (1 - South)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
12			S-9 - Sink (2 - North)	05/14/25	0.7	Lead	12/11/24	12/11/24	3US-MAX-F01H	Lowes	
N/A	N/A	N/A	S-9 - Eyewash (on south sink)	N/A	N/A						Water should not be consumed from the eye wash.
N/A	N/A	N/A	S-7 - Sink (1)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-7 - Sink (2)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-7 - Sink (2 - With Eye Wash)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-7 - Sink (3 - Island Left Fixture)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-7 - Sink (3 - Island Center Fixture)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-7 - Sink (3 - Island Right Fixture)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-7 - Sink (4)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-7 - Sink (5)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-7 - Sink (6)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-7 - Sink (7)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
13			Inbetween S-7/S-5 Break/Storage Room - Sink	05/14/25	2.9	Sediment	12/26/24	12/26/24	3US-MAX-F01H	Lowes	Now Break Room of sorts. Filter installed.
N/A	N/A	N/A	S-7 Storage Room (North) - Sink	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	Outside S-4/S-6 Storage Room - Sink	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-6 - Sink (West Island - Fixture Left)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-6 - Sink (West Island - Fixture Right)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-6 - Sink (Northwest Corner)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-6 - Sink (Northwest Corner - Eyewash)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-6 - Sink (Northwest Corner - Spray Nozzle)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-6 - Sink (1)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-6 - Sink (2)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-6 - Sink (3)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-6 - Sink (4 - East Island)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-6 - Sink (5)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-6 - Sink (6)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-6 - Sink (7)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-4 - West Island Sink	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-4 - Sink (1)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-4 - Sink (2)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.

N/A	N/A	N/A	S-4 - Sink (3)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-4 - East Island Sink	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-4 - Sink (5)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-4 - Sink (6)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-4 - Sink (7)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-4 - Sink (8)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-4 - Sink (8 - Eye Wash)	N/A	N/A						Water should not be consumed from the eye wash.
N/A	N/A	N/A	S-4 - Sink (8 - Spray Nozzle)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-1 Island Sink	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-1 Island Sink Spray Nozzle	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-1 - Sink (1)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-1 - Sink (2)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-1 - Sink (3)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-1 - Sink (4)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-1 - Sink (5)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-1 - Sink (5 - Eyewash)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-1 - Sink (6)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-1 - Sink (7)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-2 - Island Sink	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-2 - Island Sink Spray Nozzle	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-2 - Sink (1)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-2 - Sink (2)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-2 - Sink (3)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-2 - Sink (4)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-2 - Sink (5)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-2 - Sink (6)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-2 - Sink (7)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Island Sink	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (1)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (2)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (3)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (3 - Eye Wash)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (4)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (5)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (6)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.
N/A	N/A	N/A	S-3 - Sink (7)	N/A	N/A						"Non-Potable Water" Sign Installed 12 Dec 2019.

Lead Tests - North Medford High Observatory - # 20481705											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filtering For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
N/A	No Fixtures in this building			N/A	N/A						
Lead Tests - North Medford High Technical Arts 1-10 Building - # 20481706											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filtering For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481706-001CF	20481706-001CF26A	TA-10 - Trough Sink (Left Fixture 1)	05/14/25	ND						None.
2	20481706-002CF	20481706-002CF26A	TA-10 - Trough Sink (Fixture 2)	05/14/25	ND						None.
3	20481706-003CF	20481706-003CF26A	TA-10 - Trough Sink (Fixture 3)	05/14/25	ND						None.
4	20481706-004CF	20481706-004CF26A	TA-10 - Trough Sink (Right Fixture 4)	05/14/25	ND						None.
5	20481706-005DW	20481706-005DW26A	TA-10 - Drinking Fountain	05/14/25	8.1						None.
6	20481706-006BF	20481706-006BF26A	Outside TA-9 Girl's Restroom - Left Sink (1)	07/24/25	0.7						None.
7	20481706-007BF	20481706-007BF26A	Outside TA-9 Girl's Restroom - Sink (2)	07/24/25	2.5						None.
8	20481706-008BF	20481706-008BF26A	Outside TA-9 Girl's Restroom - Right Sink (3)	07/24/25	2.1						None.
9	20481706-009BF	20481706-009BF26A	Outside TA-9 Girl's Restroom - North Sink (4)	07/24/25	3.8						None.
10	20481706-010CF	20481706-010CF26A	TA-9 - Trough Sink (NE Fixture 1)	05/14/25	0.9						None.
11	20481706-011CF	20481706-011CF26A	TA-9 - Trough Sink (SE Fixture 2)	05/14/25	1.0						None.
12	20481706-012CF	20481706-012CF26A	TA-9 - Trough Sink (SW Fixture 3)	05/14/25	5.6						None.
13	20481706-013CF	20481706-013CF26A	TA-9 - Trough Sink (Fixture 4)	05/14/25	1.0						None.
14	20481706-014CF	20481706-014CF26A	TA-9 - Trough Sink (NW Right Fixture 5)	05/14/25	0.7						None.
15	20481706-015DW	20481706-015DW26A	TA-9 - Drinking Fountain	05/14/25	1.4						None.
N/A	N/A	N/A	TA-9 - Eye Wash	N/A	N/A						Water should not be consumed from the eye wash.
16	20481706-016BF	20481706-016BF26A	Adjacent To TA-1 Men's Restroom - NE Sink (1)	07/24/25	0.8						None.
17	20481706-017BF	20481706-017BF26A	Adjacent To TA-1 Men's Restroom - NW Sink (2)	07/24/25	ND						None.
18	20481706-018BF	20481706-018BF26A	Adjacent To TA-1 Men's Restroom - SW Sink (3)	07/24/25	ND						None.
19	20481706-019BF	20481706-019BF26A	Adjacent To TA-1 Men's Restroom - SE Sink (4)	07/24/25	1.0						None.
20	20481706-020CF	20481706-020CF26A	TA-8 - Sink	05/14/25	ND						None.
21	20481706-021CF	20481706-021CF26A	TA-8 - Sink (Utility)	05/14/25	1.2						None.
22	20481706-022CF	20481706-022CF26A	TA-7 - Sink	05/14/25	ND						None.
23	20481706-023DW	20481706-023DW26A	Outside TA-1 - Drinking Fountain (Upper)	05/14/25	ND	Lead	08/15/16	05/23/18	3US-MAX-F01H	Lowes	The upper and lower DF share the same filter.
24	20481706-024DW	20481706-024DW26A	Outside TA-1 - Drinking Fountain (Lower)	05/14/25	ND	Lead	08/15/16	05/23/18	3US-MAX-F01H	Lowes	The upper and lower DF share the same filter.
25	20481706-025CF	20481706-025CF26A	TA-5 - NW Sink (1)	05/08/19	2.7						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.
26	20481706-026CF	20481706-026CF26A	TA-5 - NE Sink (2)	05/08/19	2.0						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.
27	20481706-027CF	20481706-027CF26A	TA-5 - SE Sink (3)	05/08/19	2.2						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.
28	20481706-028CF	20481706-028CF26A	TA-5 - Sink (4)	05/08/19	3.1						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.
29	20481706-029CF	20481706-029CF26A	TA-5 - Sink (5)	05/08/19	4.1						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.
30	20481706-030CF	20481706-030CF26A	TA-5 - Sink (6)	05/08/19	1.3						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.
31	20481706-031CF	20481706-031CF26A	TA-5 - SW Sink (7)	05/08/19	4.7						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.
32	20481706-032CF	20481706-032CF26A	TA-5 - Sink (Island)	05/08/19	7.5						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.
33	20481706-033SF	20481706-033SF26A	Inbetween TA-5/6 - Sink (West)	05/14/25	2.5						None.
N/A	N/A	N/A	Inbetween TA-5/6 (Science) - Sink (East)	05/14/25	1.0						"Not For Consumption" Sign Installed 24 July 2019.
N/A	N/A	N/A	Inbetween TA-5/6 - Eyewash	N/A	N/A						Water should not be consumed from the eye wash.
34	20481706-034CF	20481706-034CF26A	TA-6 - NW Sink (1)	05/08/19	1.2						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.
35	20481706-035CF	20481706-035CF26A	TA-6 - NE Sink (2)	05/08/19	0.9						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.
36	20481706-036CF	20481706-036CF26A	TA-6 - SE Sink (3)	05/08/19	2.4						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.
37	20481706-037CF	20481706-037CF26A	TA-6 - Sink (4)	05/08/19	2.0						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.
38	20481706-038CF	20481706-038CF26A	TA-6 - Sink (5)	05/08/19	0.8						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.
39	20481706-039CF	20481706-039CF26A	TA-6 - Sink (6)	05/08/19	2.9						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.
40	20481706-040CF	20481706-040CF26A	TA-6 - SW Sink (7)	05/08/19	2.3						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.

41	20481706-041CF	20481706-041CF26A	TA-6 - Sink (Island)	05/08/19	4.8						Science. "Non-Potable Water" Sign Installed 12 Dec 2019.
Lead Tests - North Medford High Technical Arts 11-12 Building - # 20481707											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filtering For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481707-001DW	20481707-001DW26A	TA-11 - Drinking Fountain	05/14/25	1.1						None.
2	20481707-002CF	20481707-002CF26A	TA-11 - Sink	05/14/25	1.7						None.
3	20481707-003DW	20481707-003DW26A	TA-12 - Drinking Fountain	05/14/25	4.2						None.
4	20481707-004CF	20481707-004CF26A	TA-12 - Sink	05/14/25	1.6						None.
5	20481707-005BF	20481707-005BF26A	Outside TA-11 Men's Restroom - Sink	05/21/25	2.0	Lead	01/22/20	01/27/23	American Plumber 600R	Ferguson	
6	20481707-006BF	20481707-006BF26A	Outside TA-11 Women's Restroom - Sink	05/21/25	6.2						None.
Lead Tests - North Medford High Child Development Center - # 20481708											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filtering For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481708-001KF	20481708-001KF26A	CDC - Kitchen - Sink	05/14/25	ND						None.
2	20481708-002SF	20481708-002SF26A	CDC - Infant Area - Sink (Immediately Outside Kitchen Door)	05/14/25	ND						None.
3	20481708-003SF	20481708-003SF26A	CDC - Toddler Area - Sink (Left)	05/14/25	2.5						None.
4	20481708-004SF	20481708-004SF26A	CDC - Toddler Area - Sink (Right)	05/14/25	1.3						None.
5	20481708-005SF	20481708-005SF26A	CDC - Toddler Hallway Near Washer/Dryer - Sink (Left)	05/14/25	0.7						None.
6	20481708-006SF	20481708-006SF26A	CDC - Toddler Hallway Near Washer/Dryer - Sink (Right)	05/14/25	1.6						None.
7	20481708-007BF	20481708-007BF26A	CDC - Toddler Unisex Restroom - Sink	05/21/25	ND						None.
8	20481708-008BF	20481708-008BF26A	CDC - Pre-School Unisex Restroom - Sink (Left)	05/21/25	0.8						None.
9	20481708-009BF	20481708-009BF26A	CDC - Pre-School Unisex Restroom - Sink (Right)	05/21/25	ND						None.
10	20481708-010DW	20481708-010DW26A	CDC - Pre-School Classroom 1 - Drinking Fountain	05/14/25	0.7						None.
11	20481708-011CF	20481708-011CF26A	CDC - Pre-School Classroom 1 - Sink	05/14/25	0.6						None.
12	20481708-012CF	20481708-012CF26A	CDC - Pre-School Classroom 2 - Sink	05/14/25	ND						None.
			CDC - Preschool Classroom NE Sink	05/14/25	3.7						Discovered 05/14/2025.
13	20481708-013DW	20481708-013DW26A	CDC - Pre-School Playground - Drinking Fountain (Outside)	05/21/25	0.7	Lead	08/15/16	05/23/18	3US-MAX-F01H	Lowes	

Lead Tests - North Medford High Health - Culinary Building - # 20481709											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filtering For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481709-001CF	20481709-001CF26A	HC-8 - Sink	05/14/25	1.8						None.
2	20481709-002IM	20481709-002IM26A	HC-6 - Ice-o-matic	05/14/25	ND	Lead	08/22/16	05/23/18	3US-MAX-F01H	Lowes	This ice machine has a lead filter on it.
3	20481709-003CF	20481709-003CF26A	HC-6 - Island Sink Triple (Left Fixture)	05/14/25	ND						None.
4	20481709-004CF	20481709-004CF26A	HC-6 - Island Sink Triple (Right Fixture)	05/14/25	0.5						None.
5	20481709-005CF	20481709-005CF26A	HC-6 - Hand Wash - Sink	05/14/25	0.6						None.
6	20481709-006CF	20481709-006CF26A	HC-7 - Sink (1) West	05/14/25	ND						None.
7	20481709-007CF	20481709-007CF26A	HC-7 - Sink (2)	05/14/25	ND						None.
8	20481709-008CF	20481709-008CF26A	HC-7 - Sink (3)	05/14/25	ND						None.
9	20481709-009CF	20481709-009CF26A	HC-7 - Sink (4)	05/14/25	ND						None.
10	20481709-010CF	20481709-010CF26A	HC-7 - Sink (5)	05/14/25	ND						None.
11	20481709-011CF	20481709-011CF26A	HC-7 - Sink (6)	05/14/25	ND						None.
12	20481709-012CF	20481709-012CF26A	HC-7 - Sink (7)	05/14/25	ND						None.
13	20481709-013CF	20481709-013CF26A	HC-7 - Sink (8) East	05/14/25	0.6						None.
14	20481709-014CF	20481709-014CF26A	HC-5 - Sink	06/27/25	ND	Lead	06/26/25	06/26/25	Percola Lead Taste		None.
15	20481709-015CF	20481709-015CF26A	HC-4 - Sink	05/14/25	1.9						None.
16	20481709-016WB	20481709-016WB26A	Across From HC-4 - Bottle Filler (Upper)	05/14/25	ND	Sediment	12/15/22	12/15/22	Elkay	Ferguson	Elkay Bottle Filler Unit with filter installed.
17	20481709-028DW	20481709-028DW26A	Across From HC-4 - Drinking Fountain (Lower)	05/14/25	ND	Sediment	12/15/22	12/15/22	Elkay	Ferguson	Elkay Bottle Filler Unit with filter installed.
18	20481709-017BF	20481709-017BF26A	HC Women's Restroom - Sink (Left)	05/14/25	ND						NRC lost 5/21/25 sample.
19	20481709-018BF	20481709-018BF26A	HC Women's Restroom - Sink (Center)	05/21/25	ND						None.
20	20481709-019BF	20481709-019BF26A	HC Women's Restroom - Sink (Right)	05/21/25	0.9						05/14/2025 Found off.
21	20481709-020BF	20481709-020BF26A	HC Men's Restroom - Left Sink (1)	05/21/25	ND						05/14/2025 Found off.
22	20481709-021BF	20481709-021BF26A	HC Men's Restroom - Sink (2)	05/21/25	1.9						None.
23	20481709-022BF	20481709-022BF26A	HC Men's Restroom - Sink (3)	05/21/25	0.9						None.
24	20481709-023BF	20481709-023BF26A	HC Men's Restroom - Right Sink (4)	05/21/25	2.0						None.
25	20481709-024CF	20481709-024CF26A	HC-3 - Sink	05/14/25	0.9						None.
26	20481709-027BF	20481709-027BF26A	HC - Staff Restroom - Sink	05/21/25	ND						None.
N/A	N/A	N/A	HC-2 - Sink (1)	06/18/18	0.2						This sink was removed as part of the CTE classroom construction.
N/A	N/A	N/A	HC-2 - Sink (2)	06/18/18	ND						This sink was removed as part of the CTE classroom construction.
N/A	N/A	N/A	HC-2 - Sink (3)	06/18/18	0.2						This sink was removed as part of the CTE classroom construction.
N/A	N/A	N/A	HC-2 - Sink (4)	06/18/18	ND						This sink was removed as part of the CTE classroom construction.
N/A	N/A	N/A	HC-2 - Sink (5)	06/18/18	0.2						This sink was removed as part of the CTE classroom construction.
N/A	N/A	N/A	HC-2 - Sink (6)	06/18/18	1.9						This sink was removed as part of the CTE classroom construction.
N/A	N/A	N/A	HC-2 - Sink (7)	06/18/18	2.8						This sink was removed as part of the CTE classroom construction.

Lead Tests - North Medford High Humanities Building - # 20481710											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filtering For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481710-001DW	20481710-001DW26A	Outside H-21 - Drinking Fountain	05/14/25	0.7						None.
2	20481710-002DW	20481710-002DW26A	Outside H-13 - Drinking Fountain	05/14/25	ND						None.
3	20481710-003BF	20481710-003BF26A	Outside H-9 Women's Restroom - Sink	05/21/25	0.5						None.
4	20481710-004BF	20481710-004BF26A	Outside H-4 Men's Restroom - Sink	05/21/25	ND						None.
5	20481710-005BF	20481710-005BF26A	Across From H-38 Men's Restroom - Left North Sink (1)	05/21/25	ND						None.
6	20481710-006BF	20481710-006BF26A	Across From H-38 Men's Restroom - Sink (2)	05/21/25	ND						None.
7	20481710-007BF	20481710-007BF26A	Across From H-38 Men's Restroom - Sink (3)	05/21/25	ND						None.
8	20481710-008BF	20481710-008BF26A	Across From H-38 Men's Restroom - Right North Sink (4)	05/21/25	ND						None.
9	20481710-009BF	20481710-009BF26A	Across From H-38 Men's Restroom - Left South Sink (5)	05/21/25	ND						None.
10	20481710-010BF	20481710-010BF26A	Across From H-38 Men's Restroom - Sink (6)	05/21/25	ND						None.
11	20481710-011BF	20481710-011BF26A	Across From H-38 Men's Restroom - Sink (7)	05/21/25	ND						None.
12	20481710-012BF	20481710-012BF26A	Across From H-38 Men's Restroom - Right South Sink (8)	05/21/25	ND						None.
13	20481710-013BF	20481710-013BF26A	Across From H-38 Women's Restroom - Right West Sink (1)	05/21/25	0.6						None.
14	20481710-014BF	20481710-014BF26A	Across From H-38 Women's Restroom - Sink (2)	05/21/25	ND						None.
15	20481710-015BF	20481710-015BF26A	Across From H-38 Women's Restroom - Sink (3)	05/21/25	ND						None.
16	20481710-016BF	20481710-016BF26A	Across From H-38 Women's Restroom - Left West Sink (4)	05/21/25	1.9						None.
17	20481710-017BF	20481710-017BF26A	Across From H-38 Women's Restroom - Right East Sink (5)	05/21/25	0.6						None.
18	20481710-018BF	20481710-018BF26A	Across From H-38 Women's Restroom - Sink (6)	05/21/25	ND						None.
19	20481710-019BF	20481710-019BF26A	Across From H-38 Women's Restroom - Sink (7)	05/21/25	ND						None.
20	20481710-020BF	20481710-020BF26A	Across From H-38 Women's Restroom - Left East Sink (8)	05/21/25	0.6						None.
21	20481710-021DW	20481710-021DW26A	Outside H-38 - Drinking Fountain (Left Fixture)	05/14/25	1.3						None.
22	20481710-022DW	20481710-022DW26A	Outside H-38 - Drinking Fountain (Right Fixture)	05/14/25	ND						None.
Lead Tests - North Medford High Media Center - Commons Building - # 20481711											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filtering For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481711-001BF	20481711-001BF26A	Common's Men's Restroom - Sink (Left)	05/21/25	1.5						None.
2	20481711-002BF	20481711-002BF26A	Common's Men's Restroom - Sink (Center)	05/21/25	ND						None.
3	20481711-003BF	20481711-003BF26A	Common's Men's Restroom - Sink (Right)	05/21/25	ND						None.
4	20481711-004BF	20481711-004BF26A	Common's Women's Restroom - Sink (Left)	05/21/25	ND						None.
5	20481711-005BF	20481711-005BF26A	Common's Women's Restroom - Sink (Center)	05/21/25	0.8						None.
6	20481711-006BF	20481711-006BF26A	Common's Women's Restroom - Sink (Right)	05/21/25	ND						None.
7	20481711-007WB	20481711-007WB26A	Common's - Bottle Filler (Upper)	05/14/25	ND	Sediment	07/28/16	01/20/20	Elkay (51299C)	Ferguson	This drinking fountain has a lead/sediment filter on it.
8	20481711-008DW	20481711-008DW26A	Common's - Drinking Fountain (Lower)	05/14/25	ND	Sediment	07/28/16	01/20/20	Elkay (51299C)	Ferguson	This drinking fountain has a lead/sediment filter on it.
			Common's - Drinking Fountain on Left of Bottle Filler	05/14/25	0.6						Discovered 05/14/2025.
9	20481711-009SF	20481711-009SF26A	Common's - Sink (South West Corner)	05/14/25	1.3						None.
10	20481711-010SF	20481711-010SF26A	Common's - Sink (South East Corner)	05/14/25	2.7						None.
11	20481711-011BF	20481711-011BF26A	Media Center Staff Unisex Restroom - Sink	05/21/25	0.6						None.
12	20481711-012SF	20481711-012SF26A	Media Center Work Room - Sink	05/14/25	ND						None.
Lead Tests - North Medford High Tennis Court - # 20481712											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filtering For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481712-001DW	20481712-001DW26A	Tennis Court - Drinking Fountain	05/14/25	0.9						None.
2	20481712-002DW	20481712-002DW26A	JV Softball Field - Drinking Fountain (Behind Backstop)	05/14/25	1.2						None.

Lead Tests - North Medford High Varsity Baseball Building - # 20481713											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filtering For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481713-001DW	20481713-001DW26A	Baseball Field - Drinking Fountain (Visitors Dugout)	05/14/25	4.2						None.
NA	20481713-002OT	20481713-002OT26A	Baseball Field - Concession Stand - Soda Machine	07/29/16	1.5						Machine removed after 2018.
2	20481713-003IM	20481713-003IM26A	Baseball Field - Concession Stand - Ice Machine	05/14/25	ND						No filter.
			Baseball Field - Concession Stand - Sink	05/14/25	0.9						Discovered on 5/14/2025.
3	20481713-004BF	20481713-004BF26A	Baseball Field - Men's Restroom - Sink	05/21/25	1.4						None.
4	20481713-005BF	20481713-005BF26A	Baseball Field - Women's Restroom - Sink	05/21/25	1.4						None.
5	20481713-006DW	20481713-006DW26A	Baseball Field - Outside Restrooms - Drinking Fountain	05/14/25	0.8						None.
Lead Tests - North Medford High Track Building - # 20481714											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filtering For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481714-001IM	20481714-001IM26A	Bowerman Track Concession Stand - Ice Machine	05/14/25	12.9	Sediment	04/04/23	08/08/25	3US-MAX-F01H	Lowes	
2	20481714-002OT	20481714-002OT26A	Bowerman Concession Stand - Sink	05/14/25	ND						None.
3	20481714-003DW	20481714-003DW26A	Outside Bowerman Concession Stand - Drinking Fountain	05/14/25	0.6						None.
Lead Tests - North Medford High Bathrooms Near (SW) - Track Building - # 20481715											
#	Fixture ID #	Sample ID #	Location/Type	Date Tested	Lead Test Results	Filtering For	Date Filter Installed	Date of Last Filter Change	Filter Type	Supplier	Remarks
1	20481715-001BF	20481715-001BF26A	Near Track Men's Restroom (South East) - Sink	05/21/25	2.2						
2	20481715-002BF	20481715-002BF26A	Near Track Men's Restroom (North East) - Sink	05/21/25	2.0						
3	20481715-003BF	20481715-003BF26A	Near Track Unisex Restroom (South West) - Sink	05/21/25	1.5						
4	20481715-004BF	20481715-004BF26A	Near Track Unisex Restroom (North West) - Sink	05/21/25	1.4						
NA	N/A	N/A	Near Track Training Room (Spa In It) - Sink (Utility)	08/20/19	0.4						Converted to custodial sink. Testing not required.
5	20481715-005OS	20481715-005OS26A	Water Horse # 1 (West)	05/14/25	ND						
6	20481715-006OS	20481715-006OS26A	Water Horse # 2 (East)	06/18/18	0.7						Removed as of 5/14/2025.

*None Detected (ND) = 0.515 Or Less PPB
= Fixture Where Water Has The Potential of Being Consumed (All of These Will Be Tested When Testing The Whole School)

*ODE's required action level is 15 parts per billion (PPB)

*The E.P.A.'s recommended action level for lead in schools is 20 PPB. Oregon's action level for schools changed to 15 PPB in 2019 in accordance with OAR 333-061-0400. In 2021, ODE changed the unit of measurement for reporting to parts per billion (PPB).

*The E.P.A. action level for copper is 1.30

*Lead test results will be posted on the MSD/Facilities website within 5 days minus the school map for security purposes.