

Lead in School Drinking Water Report

Carl Cozier Elementary School



Date(s) collected: 2024-01-26

Date(s) analyzed: 2024-02-16

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
386458	Main Building	Fountain/ Tap Combo	Rm25	1 of 1	Water Fountain	17
386456	Main Building	Fountain/ Tap Combo	Rm26	1 of 1	Water Fountain	12
386676	Main Building	Fountain	Rm5	1 of 2	Water Fountain	8
386454	Main Building	Sink	Kitchen	Non-dishwashing/handwashing sink	Tap	7
386690	Main Building	Fountain/ Tap Combo	Rm13	1 of 1	Water Fountain	7
386457	Main Building	Fountain/ Tap Combo	Rm25	1 of 1	Tap	6

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
386660	Main Building	Fountain/ Tap Combo	Rm24	1 of 1	Water Fountain	6
386664	Main Building	Fountain/ Tap Combo	Rm22	1 of 1	Water Fountain	6
386672	Main Building	Fountain	Rm7	1 of 2	Water Fountain	6
386678	Main Building	Fountain	Rm4	1 of 2	Water Fountain	6
386680	Main Building	Fountain	Rm3	1 of 2	Water Fountain	6
386671	Main Building	Sink	Rm8	2 of 2 (fountain not working)	Tap	5
386683	Main Building	Fountain	Rm2	2 of 2	Water Fountain	5
386692	Main Building	Fountain/ Tap Combo	Rm14	1 of 1	Water Fountain	5
386459	Main Building	Fountain/ Tap Combo	Rm24	1 of 1	Tap	4
386662	Main Building	Fountain/ Tap Combo	Rm23	1 of 1	Water Fountain	4
386684	Main Building	Sink	Rm9	1 of 1	Tap	4
386685	Main Building	Sink	Rm10	2 of 2 (fountain off limits)	Tap	4
386455	Main Building	Fountain/ Tap Combo	Rm26	1 of 1	Tap	3
386661	Main Building	Fountain/ Tap Combo	Rm23	1 of 1	Tap	3
386673	Main Building	Sink	Rm7	2 of 2	Tap	3

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
38667 4	Main Building	Fountain	Rm6	1 of 2	Water Fountain	3
38667 7	Main Building	Sink	Rm5	2 of 2	Tap	3
38667 9	Main Building	Sink	Rm4	2 of 2	Tap	3
38668 1	Main Building	Sink	Rm3	2 of 2	Tap	3
38668 2	Main Building	Sink	Rm2	1 of 2	Tap	3
38667 5	Main Building	Sink	Rm6	2 of 2	Tap	2
38668 7	Main Building	Sink	Rm12	2 of 2 (fountain inaccessible)	Tap	2
38669 1	Main Building	Fountain/ Tap Combo	Rm14	1 of 1	Tap	2
38668 9	Main Building	Fountain/ Tap Combo	Rm13	1 of 1	Tap	1
38666 3	Main Building	Fountain/ Tap Combo	Rm22	1 of 1	Tap	<1
38666 5	Main Building	Fountain/ Tap Combo	Rm21	1 of 1	Tap	<1
38666 6	Main Building	Fountain/ Tap Combo	Rm21	1 of 1	Water Fountain	<1
38666 7	Main Building	Fountain - Multi- Level with Bottle Filler	Cafeteri a	1 of 2	Water Fountain	<1
38666 8	Main Building	Fountain - Multi- Level with Bottle	Cafeteri a	2 of 2	Water Bottle Filler	<1

Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Lead Test Result (ppb)
		Filler				
386669	Main Building	Fountain - Multi-Level with Bottle Filler	Cafeteria	2 of 2	Water Fountain	<1
386670	Main Building	Fountain	1st Hallway From Entrance	1 of 1	Water Fountain	<1
386686	Main Building	Sink	Rm11	1 of 1	Tap	<1
386688	Main Building	Fountain	Gym	1 of 1	Water Fountain	<1

EXPLANATION OF TESTING AND RESULTS:

Results in this report represent sampling conducted by Washington State Department of Health. Per **RCW 28A.210.410** sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols. Above is information related to lead sampling for your school(s). For questions regarding testing and result, please email: leadfreekids@doh.wa.gov