PC2504010109

RTCA RADON TESTING CORPORATION OF AMERICA

Site Radon Inspection Report

Date : 04/01/2025

Ms. Catey Bourne
ECS MID-ATLANTIC, LLC
14026 Thunderbolt Place
Suite 100
Chantilly, VA 20151-

Client: Mt. Vernon Community School
Test Location: 2601 Commonwealth Avenue
Alexandria, VA 22301-
Individual Canister Results

Canister ID# : 4994046
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Main Office
Radon Level : 0.5 pCi/L
Error for Measurement is: ± 0.3 pCi/L
Test Start : 03/26/2025 @ 15:51
Test Stop : 03/28/2025 @ 16:55
Received: 04/01/2025 @ 11:27
Analyzed: 04/01/2025 @ 15:12

Canister ID# : 4994005
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Principal's Off/DP
Radon Level : 0.4 pCi/L
Error for Measurement is: ± 0.3 pCi/L
Test Start : 03/26/2025 @ 15:52
Test Stop : 03/28/2025 @ 16:55
Received: 04/01/2025 @ 11:27
Analyzed: 04/01/2025 @ 15:27

Canister ID# : 4994038
Canister Type : Charcoal Canister 3 inch
Location : 1st FL=Principal's Off/DP
Radon Level : 0.2 pCi/L
Test Start : 03/26/2025 @ 15:52
Test Stop : 03/28/2025 @ 16:55
Received: 04/01/2025 @ 11:27
Analyzed: 04/01/2025 @ 15:08

Average of Side by Side Canisters 0.3 pCi/L

Error for Measurement is: ± 0.3 pCi/L

Canister ID# : 4994027
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Conf. Rm
Radon Level : 0.9 pCi/L
Error for Measurement is: ± 0.3 pCi/L
Test Start : 03/26/2025 @ 15:54
Test Stop : 03/28/2025 @ 16:56
Received: 04/01/2025 @ 11:27
Analyzed: 04/01/2025 @ 14:41

Canister ID# : 4994019
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Conf. Rm/BL
Radon Level : 0.1 pCi/L
Error for Measurement is: ± 0.2 pCi/L
Test Start : 03/26/2025 @ 15:54
Test Stop : 03/28/2025 @ 16:56
Received: 04/01/2025 @ 11:27
Analyzed: 04/01/2025 @ 15:39

Canister ID# : 4994029
Canister Type : Charcoal Canister 3 inch
Location : 1st FL = Asst. Princ./1
Radon Level : 0.2 pCi/L
Test Start : 03/26/2025 @ 15:55
Test Stop : 03/28/2025 @ 16:57
Received: 04/01/2025 @ 11:27
Analyzed: 04/01/2025 @ 15:08

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546
2 Hayes Street, Elmsford, NY 10523
www.rtca.com

RTCA RADON TESTING CORPORATION OF AMERICA

PC2504010109

Site Radon Inspection Report

Date : 04/01/2025

Ms. Catey Bourne
ECS MID-ATLANTIC, LLC
14026 Thunderbolt Place
Suite 100
Chantilly, VA 20151-

Client: Mt. Vernon Community School
Test Location: 2601 Commonwealth Avenue
Alexandria, VA 22301-

Individual Canister Results

Error for Measurement is: ± 0.3 pCi/L

Canister ID# :	4994034	Test Start :	03/26/2025 @ 15:56
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 16:57
Location :	1st FL = Asst. Princ./2	Received:	04/01/2025 @ 11:27
Radon Level :	0.4 pCi/L	Analyzed:	04/01/2025 @ 15:08

Error for Measurement is: ± 0.3 pCi/L

Canister ID# :	4995050	Test Start :	03/26/2025 @ 15:58
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 16:58
Location :	1st FL = Rm 100	Received:	04/01/2025 @ 11:27
Radon Level :	0.4 pCi/L	Analyzed:	04/01/2025 @ 14:56

Error for Measurement is: ± 0.3 pCi/L

Canister ID# :	4994047	Test Start :	03/26/2025 @ 16:01
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 16:58
Location :	1st FL = Rm 102/DP	Received:	04/01/2025 @ 11:27
Radon Level :	0.2 pCi/L	Analyzed:	04/01/2025 @ 15:59

Error for Measurement is: ± 0.3 pCi/L

Canister ID# :	4994076	Test Start :	03/26/2025 @ 16:01
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 16:58
Location :	1st FL = Rm 102/DP	Received:	04/01/2025 @ 11:27
Radon Level :	0.2 pCi/L	Analyzed:	04/01/2025 @ 15:39

Average of Side by Side Canisters 0.2 pCi/L

Error for Measurement is: ± 0.3 pCi/L

Canister ID# :	4995055	Test Start :	03/26/2025 @ 16:03
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 16:59
Location :	1st FL = Rm 103	Received:	04/01/2025 @ 11:27
Radon Level :	0.1 pCi/L	Analyzed:	04/01/2025 @ 15:08

Error for Measurement is: ± 0.3 pCi/L

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546
2 Hayes Street, Elmsford, NY 10523
www.rtca.com

PC2504010109

RTCA RADON TESTING CORPORATION OF AMERICA

Site Radon Inspection Report

Date : 04/01/2025

Ms. Catey Bourne
ECS MID-ATLANTIC, LLC
14026 Thunderbolt Place
Suite 100
Chantilly, VA 20151-

Client: Mt. Vernon Community School
Test Location: 2601 Commonwealth Avenue
Alexandria, VA 22301-

Individual Canister Results

Canister ID# :	4994853	Test Start :	03/26/2025 @ 16:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 16:59
Location :	1st FL = Rm 104/DP	Received:	04/01/2025 @ 11:27
Radon Level :	0.4 pCi/L	Analyzed:	04/01/2025 @ 15:50
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4995060	Test Start :	03/26/2025 @ 16:04
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 16:59
Location :	1st FL = Rm 104/DP	Received:	04/01/2025 @ 11:27
Radon Level :	0.3 pCi/L	Analyzed:	04/01/2025 @ 15:11

Average of Side by Side Canisters 0.4 pCi/L

Error for Measurement is: ± 0.3 pCi/L

Canister ID# :	4994086	Test Start :	03/26/2025 @ 16:06
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:00
Location :	1st FL = Rm 105	Received:	04/01/2025 @ 11:27
Radon Level :	0.2 pCi/L	Analyzed:	04/01/2025 @ 14:57
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	4993957	Test Start :	03/26/2025 @ 16:07
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:00
Location :	1st FL = Rm 107	Received:	04/01/2025 @ 11:27
Radon Level :	0.1 pCi/L	Analyzed:	04/01/2025 @ 15:50
Error for Measurement is: ±	0.6 pCi/L		

Canister ID# :	4994022	Test Start :	03/26/2025 @ 16:07
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:01
Location :	1st FL = Rm 106	Received:	04/01/2025 @ 11:27
Radon Level :	0.3 pCi/L	Analyzed:	04/01/2025 @ 14:55
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	4995045	Test Start :	03/26/2025 @ 16:10
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:02
Location :	1st FL = Library Office	Received:	04/01/2025 @ 11:27
Radon Level :	0.5 pCi/L	Analyzed:	04/01/2025 @ 15:24

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546

2 Hayes Street, Elmsford, NY 10523
www.rtca.com

RTCA RADON TESTING CORPORATION OF AMERICA

PC2504010109

Site Radon Inspection Report

Date : 04/01/2025

Ms. Catey Bourne
ECS MID-ATLANTIC, LLC
14026 Thunderbolt Place
Suite 100
Chantilly, VA 20151-

Client: Mt. Vernon Community School
Test Location: 2601 Commonwealth Avenue
Alexandria, VA 22301-

Individual Canister Results

Error for Measurement is: ± 0.4 pCi/L

Canister ID# :	4994840	Test Start :	03/26/2025 @ 16:11
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:02
Location :	1st FL = Staff Work Rm	Received:	04/01/2025 @ 11:27
Radon Level :	0.4 pCi/L	Analyzed:	04/01/2025 @ 15:50

Error for Measurement is: ± 0.4 pCi/L

Canister ID# :	4994052	Test Start :	03/26/2025 @ 16:13
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:03
Location :	1st FL = Rm 114/DP	Received:	04/01/2025 @ 11:27
Radon Level :	0.4 pCi/L	Analyzed:	04/01/2025 @ 14:56

Error for Measurement is: ± 0.3 pCi/L

Canister ID# :	4995030	Test Start :	03/26/2025 @ 16:13
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:03
Location :	1st FL = Rm 114/DP	Received:	04/01/2025 @ 11:27
Radon Level :	0.2 pCi/L	Analyzed:	04/01/2025 @ 14:55

Average of Side by Side Canisters 0.3 pCi/L

Error for Measurement is: ± 0.4 pCi/L

Canister ID# :	4993946	Test Start :	03/26/2025 @ 16:16
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:03
Location :	1st FL = Rm 114-A	Received:	04/01/2025 @ 11:27
Radon Level :	0.5 pCi/L	Analyzed:	04/01/2025 @ 15:08

Error for Measurement is: ± 0.4 pCi/L

Canister ID# :	4993943	Test Start :	03/26/2025 @ 16:19
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:04
Location :	1st FL = Auditorium	Received:	04/01/2025 @ 11:27
Radon Level :	0.4 pCi/L	Analyzed:	04/01/2025 @ 14:56

Error for Measurement is: ± 0.3 pCi/L

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546
2 Hayes Street, Elmsford, NY 10523
www.rtca.com

RTCA RADON TESTING CORPORATION OF AMERICA

PC2504010109

Site Radon Inspection Report

Date : 04/01/2025

Ms. Catey Bourne
ECS MID-ATLANTIC, LLC
14026 Thunderbolt Place
Suite 100
Chantilly, VA 20151-

Client: Mt. Vernon Community School
Test Location: 2601 Commonwealth Avenue
Alexandria, VA 22301-

Individual Canister Results

Canister ID# :	4993955	Test Start :	03/26/2025 @ 16:19
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:04
Location :	1st FL = Auditorium	Received:	04/01/2025 @ 11:27
Radon Level :	0.6 pCi/L	Analyzed:	04/01/2025 @ 15:59
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	4994064	Test Start :	03/26/2025 @ 16:21
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:05
Location :	1st FL = Rm 116/DP	Received:	04/01/2025 @ 11:27
Radon Level :	0.2 pCi/L	Analyzed:	04/01/2025 @ 15:24
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	4995040	Test Start :	03/26/2025 @ 16:21
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:05
Location :	1st FL = Rm 116/DP	Received:	04/01/2025 @ 11:27
Radon Level :	0.3 pCi/L	Analyzed:	04/01/2025 @ 15:27

Average of Side by Side Canisters 0.3 pCi/L

Error for Measurement is: ± 0.3 pCi/L

Canister ID# :	4994073	Test Start :	03/26/2025 @ 16:22
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:06
Location :	1st FL = Rm 117	Received:	04/01/2025 @ 11:27
Radon Level :	0.7 pCi/L	Analyzed:	04/01/2025 @ 15:27
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	4993947	Test Start :	03/26/2025 @ 16:24
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:06
Location :	1st FL = Rm 118	Received:	04/01/2025 @ 11:27
Radon Level :	0.4 pCi/L	Analyzed:	04/01/2025 @ 15:24
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	4993948	Test Start :	03/26/2025 @ 16:24
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:06
Location :	1st FL = Rm 118/BL	Received:	04/01/2025 @ 11:27
Radon Level :	0.1 pCi/L	Analyzed:	04/01/2025 @ 15:27

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546

2 Hayes Street, Elmsford, NY 10523
www.rtca.com

RTCA RADON TESTING CORPORATION OF AMERICA

PC2504010109

Site Radon Inspection Report

Date : 04/01/2025

Ms. Catey Bourne
ECS MID-ATLANTIC, LLC
14026 Thunderbolt Place
Suite 100
Chantilly, VA 20151-

Client: Mt. Vernon Community School
Test Location: 2601 Commonwealth Avenue
Alexandria, VA 22301-

Individual Canister Results

Error for Measurement is: ± 0.4 pCi/L

Canister ID# :	4995041	Test Start :	03/26/2025 @ 16:26
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:07
Location :	1st FL = Rm 119	Received:	04/01/2025 @ 11:27
Radon Level :	0.5 pCi/L	Analyzed:	04/01/2025 @ 15:27

Error for Measurement is: ± 0.3 pCi/L

Canister ID# :	4994055	Test Start :	03/26/2025 @ 16:28
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:08
Location :	1st FL = Rm 120	Received:	04/01/2025 @ 11:27
Radon Level :	0.1 pCi/L	Analyzed:	04/01/2025 @ 15:50

Error for Measurement is: ± 0.3 pCi/L

Canister ID# :	4994077	Test Start :	03/26/2025 @ 16:30
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:10
Location :	1st FL = Rm 122/DP	Received:	04/01/2025 @ 11:27
Radon Level :	0.3 pCi/L	Analyzed:	04/01/2025 @ 15:39

Error for Measurement is: ± 0.4 pCi/L

Canister ID# :	4994088	Test Start :	03/26/2025 @ 16:30
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:10
Location :	1st FL = Rm 122/DP	Received:	04/01/2025 @ 11:27
Radon Level :	0.5 pCi/L	Analyzed:	04/01/2025 @ 14:56

Average of Side by Side Canisters 0.4 pCi/L

Error for Measurement is: ± 0.3 pCi/L

Canister ID# :	4994066	Test Start :	03/26/2025 @ 16:31
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:10
Location :	1st FL = Rm 123	Received:	04/01/2025 @ 11:27
Radon Level :	0.5 pCi/L	Analyzed:	04/01/2025 @ 14:41

Error for Measurement is: ± 0.3 pCi/L

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546

2 Hayes Street, Elmsford, NY 10523
www.rtca.com

RTCA RADON TESTING CORPORATION OF AMERICA

PC2504010109

Site Radon Inspection Report

Date : 04/01/2025

Ms. Catey Bourne
ECS MID-ATLANTIC, LLC
14026 Thunderbolt Place
Suite 100
Chantilly, VA 20151-

Client: Mt. Vernon Community School
Test Location: 2601 Commonwealth Avenue
Alexandria, VA 22301-

Individual Canister Results

Canister ID# :	4994065	Test Start :	03/26/2025 @ 16:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:11
Location :	1st FL = Cafeteria	Received:	04/01/2025 @ 11:27
Radon Level :	0.3 pCi/L	Analyzed:	04/01/2025 @ 15:12
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	4994067	Test Start :	03/26/2025 @ 16:32
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:11
Location :	1st FL = Cafeteria	Received:	04/01/2025 @ 11:27
Radon Level :	0.4 pCi/L	Analyzed:	04/01/2025 @ 15:08
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4994082	Test Start :	03/26/2025 @ 16:38
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:08
Location :	1st FL = Rm 121	Received:	04/01/2025 @ 11:27
Radon Level :	0.6 pCi/L	Analyzed:	04/01/2025 @ 14:56
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	4994061	Test Start :	03/26/2025 @ 16:40
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:14
Location :	1st FL = Rm 113	Received:	04/01/2025 @ 11:27
Radon Level :	0.4 pCi/L	Analyzed:	04/01/2025 @ 15:12
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	4994016	Test Start :	03/26/2025 @ 16:40
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:25
Location :	1st FL = Gym	Received:	04/01/2025 @ 11:27
Radon Level :	0.3 pCi/L	Analyzed:	04/01/2025 @ 14:55
Error for Measurement is: ±	0.4 pCi/L		

Canister ID# :	4994031	Test Start :	03/26/2025 @ 16:40
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:25
Location :	1st FL = Gym	Received:	04/01/2025 @ 11:27
Radon Level :	0.4 pCi/L	Analyzed:	04/01/2025 @ 14:41
Error for Measurement is: ±	0.3 pCi/L		

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546

2 Hayes Street, Elmsford, NY 10523
www.rtca.com

RTCA RADON TESTING CORPORATION OF AMERICA

Site Radon Inspection Report

Date : 04/01/2025

Ms. Catey Bourne
ECS MID-ATLANTIC, LLC
14026 Thunderbolt Place
Suite 100
Chantilly, VA 20151-

Client: Mt. Vernon Community School
Test Location: 2601 Commonwealth Avenue
Alexandria, VA 22301-
Individual Canister Results

Canister ID# :	4994063	Test Start :	03/26/2025 @ 16:42
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:14
Location :	1st FL = Rm 112	Received:	04/01/2025 @ 11:27
Radon Level :	0.3 pCi/L	Analyzed:	04/01/2025 @ 14:42
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	4994071	Test Start :	03/26/2025 @ 16:44
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:15
Location :	1st FL = 111 Non-Fiction	Received:	04/01/2025 @ 11:27
Radon Level :	0.6 pCi/L	Analyzed:	04/01/2025 @ 16:00
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	4994042	Test Start :	03/26/2025 @ 16:45
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:15
Location :	1st FL = 111 Fiction	Received:	04/01/2025 @ 11:27
Radon Level :	0.1 pCi/L	Analyzed:	04/01/2025 @ 15:27
Error for Measurement is: ±	0.2 pCi/L		

Canister ID# :	4995059	Test Start :	03/26/2025 @ 16:49
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:18
Location :	2nd FL = Rm 211	Received:	04/01/2025 @ 11:27
Radon Level :	0.2 pCi/L	Analyzed:	04/01/2025 @ 15:11
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	4995056	Test Start :	03/26/2025 @ 16:49
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:18
Location :	2nd FL = Rm 213	Received:	04/01/2025 @ 11:27
Radon Level :	0.1 pCi/L	Analyzed:	04/01/2025 @ 15:39
Error for Measurement is: ±	0.3 pCi/L		

Canister ID# :	4993961	Test Start :	03/26/2025 @ 16:49
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:24
Location :	3rd FL = Rm 321	Received:	04/01/2025 @ 11:27
Radon Level :	0.3 pCi/L	Analyzed:	04/01/2025 @ 15:24
Error for Measurement is: ±	0.4 pCi/L		

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546
2 Hayes Street, Elmsford, NY 10523
www.rtca.com

RTCA RADON TESTING CORPORATION OF AMERICA

PC2504010109

Site Radon Inspection Report

Date : 04/01/2025

Ms. Catey Bourne
ECS MID-ATLANTIC, LLC
14026 Thunderbolt Place
Suite 100
Chantilly, VA 20151-

Client: Mt. Vernon Community School
Test Location: 2601 Commonwealth Avenue
Alexandria, VA 22301-

Individual Canister Results

Canister ID# :	4994049	Test Start :	03/26/2025 @ 16:54
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:20
Location :	2nd FL = Rm 228	Received:	04/01/2025 @ 11:27
Radon Level :	0.4 pCi/L	Analyzed:	04/01/2025 @ 15:45
Error for Measurement is:	± 0.3 pCi/L		

Canister ID# :	4993944	Test Start :	03/26/2025 @ 16:55
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:21
Location :	2nd FL = Rm 227	Received:	04/01/2025 @ 11:27
Radon Level :	0.4 pCi/L	Analyzed:	04/01/2025 @ 15:11
Error for Measurement is:	± 0.4 pCi/L		

Canister ID# :	4993949	Test Start :	03/26/2025 @ 16:56
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:21
Location :	2nd FL = Rm 226	Received:	04/01/2025 @ 11:27
Radon Level :	0.2 pCi/L	Analyzed:	04/01/2025 @ 15:08
Error for Measurement is:	± 0.4 pCi/L		

Canister ID# :	4994021	Test Start :	03/26/2025 @ 16:57
Canister Type :	Charcoal Canister 3 inch	Test Stop :	03/28/2025 @ 17:23
Location :	3rd FL = Rm 320	Received:	04/01/2025 @ 11:27
Radon Level :	0.3 pCi/L	Analyzed:	04/01/2025 @ 15:08
Error for Measurement is:	± 0.4 pCi/L		

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546

2 Hayes Street, Elmsford, NY 10523
www.rtca.com

PC2504010109

RTCA RADON TESTING CORPORATION OF AMERICA

Site Radon Inspection Report

Date : 04/01/2025

Ms. Catey Bourne
ECS MID-ATLANTIC, LLC
14026 Thunderbolt Place
Suite 100
Chantilly, VA 20151-

Client: Mt. Vernon Community School
Test Location: 2601 Commonwealth Avenue
Alexandria, VA 22301-

Individual Canister Results

The reported results indicate that radon levels in the building tested are below the United States Environmental Protection Agency (EPA) action level of 4.0 picoCuries per liter of air (pCi/L). The EPA recommends retesting if your living patterns change and you begin occupying a lower level of the building, such as a basement or if major remodeling is done.

General radon information may be obtained by consulting the EPA booklet: A Citizen's Guide to Radon (www.epa.gov/radon/pubs/citguide.html). To request a copy or for further information, please contact your state health department. The EPA maintains a radon information website, including copies of its publications, at www.epa.gov/iaq/radon.

For New Jersey clients: Please see the attached guidance document entitled Radon Testing and Mitigation: The Basics for further information.

For New York clients: If the radon level of one or more testing devices is equal to or exceeds 20 pCi/L please contact the New York State Department of Health, Bureau of Environmental Radiation Protection, for technical advice and assistance at 518-402-7556 or toll free1-800-458-1158.

PLEDGE OF ASSURED QUALITY

All procedures used for generating this report are in complete accordance with the current EPA protocols for the analysis of radon in air (EPA 402-R-92-004). The analytical results relate only to the samples tested, in the condition received by the lab, and that calculations were based upon the information supplied by client. RTCA and its personnel do not assume responsibility or liability , collectively and individually, for analysis results when detectors have been improperly handled or placed by the consumer, nor does RTCA and its personnel accept responsibility for any financial or health consequences of subsequent action or lack of action, taken by the customer or it's consultants based on RTCA-provided results.

National Radon Safety Board NRSB Certified Radon Professionals

Andreas C. George

Andreas C. George
Radon Measurement Specialist
NJ MES 11089

Dante Galan
Laboratory Director

NRSB ARL0001
NYS ELAP ID: 10806
PADEP ID: 0346
NJDEP ID: NY933
NJ MEB 90036
FL DOH RB1609
IL RNL2000201

(914)345-3380
FAX (914)345-8546

2 Hayes Street, Elmsford, NY 10523
www.rtca.com