

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
FROM ENTERANCE	CEILING PLASTER	TESTED NON ACM APRIL 2017	2,440 FT2	TESTED NON ACM APRIL 2017	TESTED NON ACM APRIL 2017	TESTED NON ACM APRIL 2+12:112017	TESTED NON ACM APRIL 2+12:112017
F-6 AUDITORIUM	TROWLED ON CEILING	17	3,000 FT2	TESTED 2022 NON ACM	TESTED 2022 NON ACM	TESTED 2022 NON ACM	TESTED 2022 NON ACM
	ASBESTOS WIRING	13	300 LF	NO DAMAGE	NO DAMAGE	MONITOR/CONTINUE O+M	MONITOR/CONTINUE O+M
	NEW FLOOR TILE AND CARPET		3,000 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/CONTINUE O+M	* MONITOR/CONTINUE O+M
				NO DAMAGE	NO DAMAGE	* MONITOR/CONTINUE O+M	* MONITOR/CONTINUE O+M
STAGE	EVTS	5	0	NO DAMAGE	NO DAMAGE	MONITOR/CONTINUE O+M	MONITOR/CONTINUE O+M
	FIRE DOOR	18	28 FT2	NO DAMAGE	NO DAMAGE	MONITOR/CONTINUE O+M	MONITOR/CONTINUE O+M
	ASBESTOS WIRING	13		NO DAMAGE	NO DAMAGE	MONITOR/CONTINUE O+M	MONITOR/CONTINUE O+M
ROOM M6	12" LT. ORANG FLOOR TILE AND MASTIC		160 FT2	NO DAMAGE	MODERATE 3 DAMAGED	MONITOR/CONTINUE O+M	MONITOR/CONTINUE O+M
CHORUS ROOM M10 FOYER AND CLOSET M10	12" WHITE WITH BEIGE SPEC FLOOR TILE AND MASTIC		300 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/CONTINUE O+M	* MONITOR/CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
PRACTICE ROOM M9 F4A	12" BROWN WITH WHITE SPEC FLOOR TILE AND MASTIC		100 FT2	MODERATE- 1 DAMAGED	MODERATE- 1 DAMAGED	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
	AIRCELL	4	8 LF	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	EVTS	5	1	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
M-13 F4D	12" BROWN WITH WHITE SPEC FLOOR TILE AND MASTIC		80 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
	AIRCELL	4	10 LF	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	EVTS	5	2	SEVERE- 2 DAMAGED	SEVERE- 2 DAMAGED	ENCAPSULATE WITH APPROVED MATERIAL	ENCAPSULATE WITH APPROVED MATERIAL
MUSIC ROOM M8 IN ROOM M7- MAIN AREA	12" BROWN WITH WHITE SPEC FLOOR TILE AND MASTIC		1,200 FT2	MODERATE- 5 DAMAGED	MODERATE- 5 DAMAGED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	PIPE INSULATION/ EVTS	4		TESTED JUNE 2021 NON ACM	TESTED JUNE 2021 NON ACM	TESTED JUNE 2021 NON ACM	TESTED JUNE 2021 NON ACM
M 12 F4E	12" BROWN WITH WHITE SPEC FLOOR TILE AND MASTIC		120 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
M 12A F4F	12" BROWN WITH WHITE SPEC FLOOR TILE AND MASTIC		112 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
	BREECHING	1	426 FT2	ABATED	ABATED	ABATED	ABATED

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
F-3 OLD BOILER ROOM AND BATH	WELL WATER TANK LAGGING	2	352 FT2	ABATED	ABATED	ABATED	ABATED
	HOT WATER TANK LAGGING	3	213 FT2	ABATED	ABATED	ABATED	ABATED
	AIRCELL	4	0	ABATED	ABATED	ABATED	ABATED
	EVTS IN BATH	5	4	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	FIRE DOOR	18	28 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	TROWLED ON CEILING	19	2,400 FT2	TESTED NON ACM	TESTED NON ACM	TESTED NON ACM	TESTED NON ACM
	INTERIOR BOILER INSULATION	20	120 FT2	ABATED	ABATED	ABATED	ABATED
	INTERIOR FIRE BRICKS	27	120 FT2	ABATED	ABATED	ABATED	ABATED
F-2	9" ORANGE SPEC FLOOR TILE AND MASTIC	12A	216 FT2	MODERATE- 1 DAMAGED WITH MASTIC EXPOSED	MODERATE- 1 DAMAGED WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
F-1C STORE ROOM	12" BEIGE WITH ROSE SPEC FLOOR TILE AND MASTIC		448 FT2	MODERATE- 1 DAMAGED	MODERATE- 2 DAMAGED	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
F 111 F-7	9" PALE BLUE WITH TAN SPEC FLOOR TILE AND MASTIC		120 FT2	MODERATE- 4 DAMAGED SOME /MASTIC EXPOSED	MODERATE- 4 DAMAGED SOME /MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
F-8	9" TAN FLOOR TILE AND MASTIC		216 FT2	MODERATE- NUMEROUS DAMAGED WITH SOME WITH MASTIC EXPOSED	MODERATE- NUMEROUS DAMAGED WITH SOME WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	EVTS	5	8	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
NO EVTS IN MUSIC HALL							
CAFÉ	VIBRATION CLOTH	NO EVTS	6 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
KITCHEN STORAGE #1	9" RED FLOOR TILE AND MASTIC		300 FT2	MODERATE- DAMAGED/ 1 WITH MASTIC EXPOSED	MODERATE 3 DAMAGED WITH MASTIC EXPOSED	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
	EVTS	5	16	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
KITCHEN OFFICE F 107	12" WHITE FLOOR TILE AND MASTIC	F107	144 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
KITCHEN STORAGE F121	12" BEIGE FLOOR TILE AND MASTIC	NO EVTS	144 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
KITCHEN	EVTS	5	8	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	2X4 CEILING TILES	7	1,404 FT2	MODERATE- 10 DAMAGED	MODERATE- 10 DAMAGED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
KITCHEN SINKS ROOM	EVTS	5	5	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
GIRLS BATH LT. OF B12	CEILING PLASTER	17	200 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
NO EVTS IN B HALL							
ROOM B-12 NURSES OFFICE	9" ORANGE SPEC FLOOR TILE AND MASTIC	12A	308 FT2	MODERATE- 2 DAMAGED WITH MASTIC EXPOSED	MODERATE- 2 DAMAGED WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
NURSES OFFICE	CEILING PLASTER		72 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM B-10	9" ORANGE SPEC FLOOR TILE AND MASTIC	12A	480 FT2	MODERATE- 1 DAMAGED WITH MASTIC EXPOSED	MODERATE- 1 DAMAGED WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	CHAULK BOARDS		64 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM B-9	9" ORANGE SPEC FLOOR TILE AND MASTIC	12A	840 FT2	NO DAMAGE	NO DAMAGE	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	CHAULK BOARDS		96 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM B-8	9" GRAY FLOOR TILE AND MASTIC	12B	840 FT2	MODERATE- 18 DAMAGED/ SOME WITH MASTIC EXPOSED	MODERATE- 18 DAMAGED/ SOME WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	CHAULK BOARDS		96 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM B-1	NEW FLOOR TILE AND CARPET	ABATED	896 FT2	NEW FLOOR TILE AND CARPET	NEW FLOOR TILE AND CARPET	NEW FLOOR TILE AND CARPET	NEW FLOOR TILE AND CARPET
ROOM B-7	9" GRAY FLOOR TILE AND MASTIC	12B	528 FT2	MODERATE- 3 DAMAGED/ SOME WITH MASTIC EXPOSED	MODERATE- 3 DAMAGED/ SOME WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	EVTS	5	0	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	CHAULK BOARDS		96 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
ROM B-6	9" GRAY FLOOR TILE AND MASTIC	12B	840 FT2	MODERATE- 6 DAMAGED/2 MISSING/ SOME WITH MASTIC EXPOSED	MODERATE DAMAGE/ LOOSE DEBRIS	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	CHAULK BOARDS		96 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM B-2	9" ORANGE FLOOR TILE AND MASTIC	12B	552 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
	CHAULK BOARDS		128 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM B-5	9" GRAY FLOOR TILE AND MASTIC	12B	528 FT2	MODERATE- 3 DAMAGED/ 3 MISSING/ SOME WITH MASTIC EXPOSED	MODERATE- 3 DAMAGED/ 3 MISSING/ SOME WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	CHAULK BOARDS		128 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM B-3	9" ORANGE SPEC FLOOR TILE AND MASTIC	12A		MODERATE- 6 DAMAGED/ SOME WITH MASTIC EXPOSED	MODERATE- 6 DAMAGED/ SOME WITH MASTIC	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	EVTS	5	4	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	CHAULK BOARDS		64 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM B-4	9" GRAY/ 12" RED FLOOR TILE AND MASTIC	12B	528 FT2	MODERATE- 2 DAMAGED/ 3 MISSING	MODERATE 2 DAMAGED/1 MISSING/ SOME WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
	CHAULK BOARDS		32 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
GO STRAIGHT/ TURN LEFT	B HALL TO C7 NO EVTS						
ROOM C-7	INTERIOR FUME HOOD	38	64 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM C-8	INTERIOR FUME HOOD	38	128 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM C-8B	12" WHITE FLOOR TILE AND MASTIC		400 FT2	MODERATE- 1 DAMAGED	MODERATE- 1 DAMAGED	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	LAB TABLE		24 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM C 6	CHAULK BOARDS/ GLUE DOTS		128 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM C 10	CHAULK BOARDS/ GLUE DOTS		128 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM C 11	CHAULK BOARDS/ GLUE DOTS		128 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM C 5	CHAULK BOARDS/ GLUE DOTS		128 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM C 12	CHAULK BOARDS/ GLUE DOTS		128 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM C-4	CHAULK BOARDS/ GLUE DOTS		128 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	9" ORANGE SPEC FLOOR TILE AND MASTIC	12A	600 FT2	MODERATE- 5 DAMAGED/ SOME WITH MASTIC EXPOSED	MODERATE 2 DAMAGED/ NUMEROUS PUNCTURES/ SOME WITH MASTIC EXPOSED	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
ROOM C-13	CHAULK BOARDS/ GLUE DOTS		128 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
ROOM C-14	CHAULK BOARDS/ GLUE DOTS		128 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM C-3	9" ORANGE SPEC FLOOR TILE AND MASTIC	12A		MODERATE- 1 DAMAGED	MODERATE- 1 DAMAGED	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
	EVTS	5	2	ABATED	ABATED	ABATED	ABATED
	CHAULK BOARDS/ GLUE DOTS		80 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM C-2	9" ORANGE SPEC FLOOR TILE AND MASTIC	12A	720 FT2	MODERATE- 3 DAMAGED WITH MASTIC EXPOSED	MODERATE- 1 DAMAGED WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	EVTS	5		NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	CHAULK BOARDS/ GLUE DOTS		128 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM C 15	CHAULK BOARDS/ GLUE DOTS		128 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM C 16	CHAULK BOARDS/ GLUE DOTS		128 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM C-1 AND CLOSET	9" ORANGE SPEC FLOOR TILE AND MASTIC	12A	720 FT2	MODERATE- 5 DAMAGED/ SOME WITH MASTIC EXPOSED	MODERATE- 5 DAMAGED/ SOME WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	CHAULK BOARDS/ GLUE DOTS		64 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
GIRLS BATH	CEILING PLASTER		200 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR
 TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
C-2 JC	9" RED FLOOR TILE AND MASTIC	12C	36 FT2	MODERATE- 3 DAMAGED	MODERATE- 3 DAMAGED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	EVTS		7	SEVERE- 1 DAMAGED	SEVERE- 1 DAMAGED	ENCAPSULATE WITH APPROVED MATERIAL	ENCAPSULATE WITH APPROVED MATERIAL
BOYS BATH	CEILING PLASTER		200 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
TURN LT.							
ELECTRIC PANEL B IN ROOM C1 AND ENTERANCE NEAR CAFE	9" ORANGE SPEC FLOOR TILE AND MASTIC	12A	240 FT2	MODERATE- 3 DAMAGED WITH MASTIC EXPOSED	MODERATE- 3 DAMAGED WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	EVTS		6	NO DAMAGE	SEVERE 1 DAMAGED	MONITOR/ CONTINUE O+M	REPAIR
GOTO ELECTRIC PANEL A/ SECURITY OFFICE OPP F1A	9" ORANGE SPEC FLOOR TILE AND MASTIC	12A	240 FT2	MODERATE- 2 DAMAGED	NO DAMAGE	REPLACE TILES * MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
E12A	12"BEIGE FLOOR TILE AND MASTIC		144 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
BOYS BATH OPP. E-13	CEILING PLASTER		100 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
D2 JANITOR CLOSET	NEW FLOOR		45 FT2	NEW FLOOR	NEW FLOOR	NEW FLOOR	NEW FLOOR
	EVTS		13	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM D-19	9" ORANGE SPEC FLOOR TILE AND MASTIC	12A	720 FT2	MODERATE- 23 DAMAGED/ PERIMETER	MODERATE- 23 DAMAGED/ PERIMETER	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
	EVTS	5	NO ACCESS	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
WOMENS FACILITY BATH	CEILING PLASTER		240 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM D-1	NEW 12" PINK FLOOR TILE AND MASTIC	ABATED	720 FT2	NO DAMAGE	NO DAMAGE	REPLACE 11 TILES * MONITOR/ CONTINUE O+M	REPLACE 11 TILES * MONITOR/ CONTINUE O+M
	CHAULK BOARDS/ GLUE DOTS		100 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	EVTS	5		NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM D-18	9" ORANGE SPEC FLOOR TILE AND MASTIC	12A	308 FT2	MODERATE- 4 DAMAGED	MODERATE- 4 DAMAGED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	CHAULK BOARDS/ GLUE DOTS		96 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	EVTS	5	NO ACCESS	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM D-2	9" GRAY FLOOR TILE AND MASTIC	12B	720 FT2	SEVERE DAMAGE	SEVERE DAMAGE	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	EVTS	5		NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
	BLACK BOARDS AND MATIC	33-34-36	100 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM D-17	9" GRAY FLOOR TILE AND MASTIC	12B	720 FT2	MODERATE- 3 DAMAGED	MODERATE- 3 DAMAGED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	BLACK BOARDS AND MATIC	33-34-36	100 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM D-3	9" GRAY FLOOR TILE AND MASTIC	12B	720 FT2	MODERATE- 1 DAMAGED/ SOME WITH MASTIC EXPOSED	MODERATE 3 DAMAGED WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	BLACK BOARDS AND MATIC	33-34	96 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM D-16	9" GRAY FLOOR TILE AND MASTIC	12B	720 FT2	MODERATE- 8 DAMAGED/ SOME WITH MASTIC EXPOSED	MODERATE 4 DAMAGED WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	BLACK BOARDS AND MATIC	33-34-36	96 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM D-1	ABATED 8/ 2023	12B	720 FT2	ABATED 8/ 2023	ABATED 8/ 2023	ABATED 8/ 2023	ABATED 8/ 2023

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
ROOM D-4	BLACK BOARDS AND MASTIC	33-34-36	96 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM D-15	9" GRAY FLOOR TILE AND MASTIC	12B	720 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	BLACK BOARDS AND MASTIC	33-34-36	100 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM D-5	9" GRAY FLOOR TILE AND MASTIC	12B	720 FT2	MODERATE- 13 DAMAGED/ 1 WITH MASTIC EXPOSED	MODERATE 17 DAMAGED/ SOME WITH MASTIC	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	EVTS	5		NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	BLACK BOARDS AND MASTIC	33-34-36	96 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM D 14	9" GRAY FLOOR TILE AND MASTIC	12B	308 FT2	MODERATE- 4 DAMAGED	MODERATE- 4 DAMAGED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	BLACK BOARDS AND MASTIC	33-34-36	88 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM D-6	9" GRAY FLOOR TILE AND MASTIC	12B	720 FT2	SEVERE NUMEROUS DAMAGED/ SOME WITH MASTIC EXPOSED	SEVERE NUMEROUS DAMAGED/ SOME WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
	BLACK BOARDS AND MASTIC	33-34-36	64 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM D-13	9" GRAY FLOOR TILE AND MASTIC	12B	720 FT2	MODERATE- 11 DAMAGED PERIMETER	MODERATE- 11 DAMAGED PERIMETER	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	EVTS	5	2	ABATED	ABATED	ABATED	ABATED
	BLACK BOARDS AND MASTIC	33-34-36	64 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM D-7	9" GRAY FLOOR TILE AND MASTIC	12B	720 FT2	MODERATE- NUMEROUS DAMAGED/ PERIMETER	MODERATE- NUMEROUS DAMAGED/ PERIMETER	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
ROOM D-12	9" GRAY FLOOR TILE AND MASTIC	12B	720 FT2	MODERATE- 2 DAMAGED/ SOME WITH MASTIC EXPOSED	MODERATE- 3 DAMAGED/ SOME WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
	BLACK BOARDS AND MASTIC	33-34-36	128 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
E WING							
BOYS BATH	CEILING PLASTER		100 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM E 12	VAPOR BARRIER UNDER CONCRETE			TESTED 2020 NON ACM	TESTED 2020 NON ACM	TESTED 2020 NON ACM	TESTED 2020 NON ACM
	CORK BOARD MASTIC	TAN		TESTED 2020 NON ACM	TESTED 2020 NON ACM	TESTED 2020 NON ACM	TESTED 2020 NON ACM
GIRLS BATH OPP. E-12	CEILING PLASTER		100 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
STORAGE	ROOF DRAIN EVTS		2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
GIRLS LOCKER ROOM ROOM E-2	EVTS	5		NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	ROOF DRAIN EVTS		4	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ELECTRIC PANEL GIRLS END OF GYM	EVTS	5	11	SEVERE- 1 DAMAGED	SEVERE- 1 DAMAGED	ENCAPSULATE WITH APPROVED MATERIAL	ENCAPSULATE WITH APPROVED MATERIAL
STORAGE A IN GYM	EVTS	5	4	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
GYM	EVTS- 20 FT OFF GROUND	5	29	SEVERE- 2 DAMAGED AT BOYS END	SEVERE- 2 DAMAGED AT BOYS END	ENCAPSULATE WITH APPROVED MATERIAL	ENCAPSULATE WITH APPROVED MATERIAL
WOOD SHOP E-9	9" LIGHT TAN FLOOR TILE AND MASTIC	12D	1,600 FT2	ABATED AUG 2019	ABATED AUG 2019	ABATED AUG 2019	ABATED AUG 2019
	EVTS	5	28	SEVERE- 1 DAMAGED/ 5 IN DUCT TAPE IN FINISH ROOM	SEVERE- 1 DAMAGED/ 5 IN DUCT TAPE IN FINISH ROOM	ENCAPSULATE WITH APPROVED MATERIAL	ENCAPSULATE WITH APPROVED MATERIAL
	FIRE DOOR	18		NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM E-8	EVTS	5		NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM E6- OLD BOYS LOCKER	AIRCELL	4	31 LF	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
ROOM AND COACHES OFFICE	12" WHITE FLOOR TILE AND MASTIC		144 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
	EVTS	5	4	SEVERE- 3 DAMAGED AREAS	SEVERE- 3 DAMAGED AREAS	ENCAPSULATE WITH APPROVED MATERIAL	ENCAPSULATE WITH APPROVED MATERIAL
	CEILING PLASTER	17		NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
BOYS BATH @ F HALL	CEILING PLASTER	17	200 FT2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM B20 NEAR CAFÉ F1	9" ORANGE SPEC FLOOR TILE AND MASTIC		144 FT2	NO DAMAGE	NO DAMAGE	* MONITOR/ CONTINUE O+M	* MONITOR/ CONTINUE O+M
ELECTRICAL ROOM OPP. NEW SENIOR CAFÉ	9" ORANGE SPEC FLOOR TILE AND MASTIC	12A	264 FT2	MODERATE- 1 DAMAGED WITH MASTIC EXPOSED	MODERATE- 1 DAMAGED WITH MASTIC EXPOSED	REPLACE TILES * MONITOR/ CONTINUE O+M	REPLACE TILES * MONITOR/ CONTINUE O+M
ROOM A-10 SERVER ROOM PREVIOUS A113	9" ORANGE SPEC FLOOR TILE AND MASTIC	12A		NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	AIRCELL	4		NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	EVTS	5		NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
ROOM A-11	EVTS	5	3	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
PRINCIPAL OFFICE ROOM OPP. A-2	EVTS	5	2	NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.

Building: Jefferson Twp. High School
 Address: 1010 Weldon Road RD2
 Owner: Jefferson Twp. BOE

EPA AHERA SIX MONTH SURVEILLANCE

Date: September 15, 2023
 Inspector: Daniel Schlosser

Functional Space	Material	Homo ID #	Amount	Previous Condition	Current Damage	Previous Response	Current Response
MAIN OFFICE/PRINCIPAL OFFICE	WALL BOARDS/ MASTIC	CARPET MASTIC TESTED 11/22 ALL NON ACM BY PLM/TEM		TESTED 2020 <1% ACM	TESTED 2020 <1% ACM	TESTED 2020 <1% ACM	TESTED 2020 <1% ACM
ENTIRE BUILDING	ALL COVE BASE AND MASTIC			NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	ALL EVI ELBOW/VALVES/ TRANSITIONS						
	BLACK AND GREEN BOARDS AND MASTIC			NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M
	TRANSITE PANELS ABOVE WINDOWS			NO DAMAGE	NO DAMAGE	MONITOR/ CONTINUE O+M	MONITOR/ CONTINUE O+M

* USE LIQUID WAX TO SEAL BROKEN OR DAMAGED FLOOR TILE UNTIL CONDITION WARRANTS REMOVAL.