

Building Inspected: Jefferson Twp. Middle School  
Address: 1010 Weldon Road  
Building Owner: Jefferson Twp. BOE

PEOSH INDOOR AIR QUALITY INSPECTION REPORT

Date: March 24, 2021  
Inspector: Dan Schlosser

<b>SAMPLE LOCATION</b>	<b>CO2 (PPM)</b>	<b>CO (PPM)</b>	<b>TEMPERATURE (F)</b>	<b>HUMIDITY (%)</b>
MAIN OFFICE	518	0	68.90	23
PRINCIPAL	514	0	69.10	22
CAFÉ	491	0	70.80	22
KITCHEN	487	0	71.20	22
GYM	478	0	68.90	21
A5	459	0	68.80	22
ROOM C5	468	0	69.90	23
ROOM C6	455	0	71.40	23
ROOM C7	454	0	72.10	22
ROOM C4	475	0	73.00	22
ROOM C8	455	0	73.60	24

Building Inspected: Jefferson Twp. Middle School  
Address: 1010 Weldon Road  
Building Owner: Jefferson Twp. BOE

PEOSH INDOOR AIR QUALITY INSPECTION REPORT

Date: March 24, 2021  
Inspector: Dan Schlosser

<b>SAMPLE LOCATION</b>	<b>CO2 (PPM)</b>	<b>CO (PPM)</b>	<b>TEMPERATURE (F)</b>	<b>HUMIDITY (%)</b>
ROOM C3	477	0	72	27
ROOM C9	468	0	73.6	20
ROOM C10	466	0	73.2	21
ROOM C2	461	0	71.6	21
ROOM C11	471	0	72.7	21
ROOM C1	463	0	72.4	21
ROOM C12	469	0	72.6	21
ROOM A6	475	0	72.1	21
ROOM A3	475	0	70.9	21
ROOM A4	471	0	71.8	21
CST	755	0	72	21

Building Inspected: Jefferson Twp. Middle School  
Address: 1010 Weldon Road  
Building Owner: Jefferson Twp. BOE

PEOSH INDOOR AIR QUALITY INSPECTION REPORT

Date: March 24, 2021  
Inspector: Dan Schlosser

<b>SAMPLE LOCATION</b>	<b>CO2 (PPM)</b>	<b>CO (PPM)</b>	<b>TEMPERATURE (F)</b>	<b>HUMIDITY (%)</b>
A1	494	0	71.8	21
NUURSES OFFICE	500	0	71.9	21
LIBRARY	469	0	73.4	20
ROOM B8	472	0	72.5	241
S5	461	0	73.8	19
S5 ELECTRIC	453	0	77.9	19
ROOM B3	465	0	78.3	19
ROOM B4	437	0	74.3	21
ROOM B5	452	0	73.2	19
ROOM B6	461	0	73.1	20
ROOM B7	462	0	72.4	19

Building Inspected: Jefferson Twp. Middle School  
Address: 1010 Weldon Road  
Building Owner: Jefferson Twp. BOE

PEOSH INDOOR AIR QUALITY INSPECTION REPORT

Date: March 24, 2021  
Inspector: Dan Schlosser

<b>SAMPLE LOCATION</b>	<b>CO2 (PPM)</b>	<b>CO (PPM)</b>	<b>TEMPERATURE (F)</b>	<b>HUMIDITY (%)</b>
ROOM B9	472	0	72.5	19
ROOM B12	464	0	72	20
ROOM B11	454	0	74.5	20
ROOM B13	452	0	74.1	21
ROOM B15	454	0	74.2	20
ROOM B16	456	0	73.9	21
ROOM B18	466	0	73.3	21
ROOM B19	438	0	73.3	23
ROOM B20	474	0	73.2	27
ROOM B21	465	0	73.8	22
ROOM B29	458	0	72.9	22

Building Inspected: Jefferson Twp. Middle School  
Address: 1010 Weldon Road  
Building Owner: Jefferson Twp. BOE

PEOSH INDOOR AIR QUALITY INSPECTION REPORT

Date: March 24, 2021  
Inspector: Dan Schlosser

<b>SAMPLE LOCATION</b>	<b>CO2 (PPM)</b>	<b>CO (PPM)</b>	<b>TEMPERATURE (F)</b>	<b>HUMIDITY (%)</b>
ROOM B22	453	0	72.2	21
ROOM B24	437	0	72.7	21
ROOM B30	454	0	72.9	25
FACULTY ROOM	481	0	72.7	21
ROOM B26	466	0	72.8	23
ROOM B27	461	0	73.6	21
ROOM B28	441	0	72.8	21
ROOM G214	459	0	72.8	22
ROOM G213	462	0	72.1	22
ROOM G212	464	0	72.6	21
ROOM G211	455	0	70.9	21

Building Inspected: Jefferson Twp. Middle School  
Address: 1010 Weldon Road  
Building Owner: Jefferson Twp. BOE

PEOSH INDOOR AIR QUALITY INSPECTION REPORT

Date: March 24, 2021  
Inspector: Dan Schlosser

<b>SAMPLE LOCATION</b>	<b>CO2 (PPM)</b>	<b>CO (PPM)</b>	<b>TEMPERATURE (F)</b>	<b>HUMIDITY (%)</b>
ROOM G208	460	0	71	21
ROOM G206	456	0	72	21
ROOM G201	446	0	71.1	21
OUTSIDE SAMPLE	583	0	63	34