Rise STEM Academy For Girls

Rise STEM Academy For Girls

- **Work Completed:**
  - Geothermal works continued
  - Continued storm shelter work.
  - Continued masonry work.
  - Continued roofing installation.
  - Continued brick veneer installation.
  - Site concrete work.
  - Gyp board installation.
  - Window glazing installation continued.

- **Upcoming Work / Look Ahead:**
  - Geothermal works will continue.
  - Storm system work will continue.
  - Masonry work will continue.
  - Slab preparation and placement will continue.
  - Brick veneer installation will continue.
  - Gyp board installation will continue.
  - Window glazing installation continued.

Rise STEM Academy For Girls

Wall Gypsum Board Paint Prep In Progress

Rise STEM Academy For Girls

Tile Installation In Progress

Rise STEM Academy For Girls

Above Ceiling Work in Progress



Rise STEM Academy For Girls

Metal Panel Sub-framing In Progress

Rise STEM Academy For Girls

CMU Work In Progress

Rise STEM Academy For Girls

Window Glazing Installation In Progress

Rise STEM Academy For Girls

Z-Furring Installation in Progress

Rise STEM Academy For Girls

Site Work In Progress