

**WEST IRONDEQUOIT CENTRAL SCHOOL DISTRICT**

Template for Recordkeeping of Outlets Tested (Applicable Outlets) that Exceeded the Lead Action Level and the Remedial Actions that were/ are implemented.

Outlets Exceeding the Lead Action Level (5 micrograms per liter)																	
Laboratory ID	Outlet Location (or Sample ID)	Building	Space/ Function	Room	Outlet Type <sup>1</sup>	Sample Results			Remedial Actions (Please check all that apply)								Notes/Comments REMEDIATION
						Initial (ppb)	Post Remediation 4-22-2025	Post Remediation 9-25-25	Outlet or Plumbing Replacement <sup>2</sup>	Permanent Removal <sup>3</sup>	Filter Installed and Maintained	Signage	Supervision	Continuing Education	Flushing	Engineering Controls <sup>4</sup>	
70330678001	OV 1	Oakview	Staff Room	Room 5	Sink	7.5	10.10		X		X				X	Filter added	
70330673001	RM 1	Rogers Middle School	Classroom	Room 007	Sink	10.2	4.80	-	X			X	X	X	X		
70330673009	RM 9	Rogers Middle School	Classroom	Room 012	Sink	29.6	62.50	n/a		X						Removed from service	
70330673013	RM 13	Rogers Middle School	Bathroom	Room 138	Sink	13.5	12.10	n/a	X			X				Tempered outlet added	
70330673014	RM 14	Rogers Middle School	Kitchen	Room 142	Pot Filler	7	10.20	8.60	X						X	1- flush, 2-replace piping & fixture, 3-flush	
70330673015	RM 15	Rogers Middle School	Kitchen	Center island handwash	Room 142	Sink	18.5	17.10	1.70	X					X	Monitored location handwashing only	
70330673019	RM 19	Rogers Middle School	Kitchen	Dishwasher	Room 142	Sprayer	62.6	54.80	169.00	X					X	1- flush, 2-replace piping & fixture, 3-flush	
70330673029	RM 29	Rogers Middle School	Science Classroom	Room 120	Sink	11.2	15.40	-				X	X	X		Science room- moved to Outlets Not Tested	
70330673030	RM 30	Rogers Middle School	Classroom	Room 310	Sink	15.3	16.90	n/a		X						Removed from service	
70330673031	RM 31	Rogers Middle School	Science Classroom	Right	Room 312	Sink	17.4	17.20	-			X	X	X		Science room- moved to Outlets Not Tested	
70330673039	RM 39	Rogers Middle School	Science Classroom	Room 319	Sink	7.8	11.90	-				X	X	X		Science room- moved to Outlets Not Tested	
70330673043	RM 43	Rogers Middle School	Gym	North side	Room 124	Drinking Fountain	5.7	8.20		X					X	Add filter	
70330668013	SL 13	Southlawn Elementary School	Classroom	Room 166	Sink	11	1.70	-							X		
70330671004	EM 4	Evans McGraw Learning Center	Tutoring Center	Room 114	Sink	12.5	40.20		X		X	X			X	Filter added	
70330662008	PG 8	Pinegrove	Bathroom	Room 128	Sink	8.1	8.70	Hold	X			X			X	Promise Project- plumbing will be replaced- test once renovation is completed	
70330662009	PG 9	Pinegrove	Bathroom	Room 129	Sink	9.6	10.80	Hold	X			X			X	Promise Project- plumbing will be replaced- test once renovation is completed	
70330662010	PG 10	Pinegrove	Classroom	HNC	Room 130	Sink	5.6	4.80	-	X		X			X		
70330662016	PG 16	Pinegrove	Bathroom	Left sink	Room 109	Sink	8	6.40	Hold	X		X			X	Promise Project- plumbing will be replaced- test once renovation is completed	
70330662018	PG 18	Pinegrove	Bathroom		Room 106	Sink	11.2	32.20	Hold	X		X			X	Promise Project- plumbing will be replaced- test once renovation is completed	
70330662019	PG 19	Pinegrove	Bathroom		Room 142	Sink	36.1	29.30	Hold	X		X			X	Promise Project- plumbing will be replaced- test once renovation is completed	
70330662020	PG 20	Pinegrove	Bathroom		Room 143	Sink	23	17.40	Hold	X		X			X	Promise Project- plumbing will be replaced- test once renovation is completed	
70330662021	PG 21	Pinegrove	Workspace		Room 141	Sink	22.6	22.50	Hold	X		X			X	Promise Project- plumbing will be replaced- test once renovation is completed	
70330665008	SI 8	Seneca Elementary School	Faculty Room	Room 002	Sink	6.5	4.70	51.30	X		X				X	1- flush, 2 retested, 3 filter added	
70330665009	SI 9	Seneca Elementary School	Nurses Office	Room 106	Sink	11.9	10.50	3.90	X		X				X	Filter added	
70330665017	SI 17	Seneca Elementary School	Classroom	Room 121	Sink	6.2	65.40	1.20	X		X				X	Filter added	
70330653010	IM 10	Iroquois Middle School	Kitchen	Dishwash double left sink	Room 036	Sink	118	478.00		X		X	X		X	Dish rinsing only	
70330653012	IM 12	Iroquois Middle School	Kitchen	Dishwasher sprayer	Room 036	Sprayer	10.2	1.30	-	X		X	X		X	Dish rinsing only	
70330653013	IM 13	Iroquois Middle School	Art Room	Front left	Room 041	Sink	7	7.10	-			X	X	X	X	Art room- moved to Outlets Not Tested	
70330653014	IM 14	Iroquois Middle School	Art Room	Front Right	Room 041	Sink	13.1	8.90	-			X	X	X	X	Art room- moved to Outlets Not Tested	
70330653025	IM 25	Iroquois Middle School	Classroom	Left sink	Room 316	Sink	6.6	4.80	-	X		X			X		
70330637007	ES 7	Environmental Services	Service Bay	Matt's Area	Sink	10.6	10.70	n/a				X			X	Moving DOES to Lakeview	
70330654001	IH 1	Irondequoit High School	Technology Ed	Room 1000	Sink	10.8	7.10	-				X	X	X	X	Technology Education room- moved to Outlets Not Tested	
70330654004	IH 4	Irondequoit High School	Technology Ed	Left of the exit door	Room 1010	Sink	28.7	22.20	-			X	X	X	X	Technology Education room- moved to Outlets Not Tested	
70330654013	IH 13	Irondequoit High School	Kitchen	Under Ansul System	Room 1030-5	Sink	171	157.90	n/a		X					Removed from service	
70330654017	IH 17	Irondequoit High School	Kitchen	Near locker room	Room 1030-9	Sink	12.1	10.70	4.00	X					X	Replaced piping	
70330965001	IH 18	Irondequoit High School	Kitchen	Right of gas stove	Room 1030-10	Pot Filler	8.2	25.30	7.60	X						1- flush, 2-replace piping & fixture, 3-flush	
70330965002	IH 19	Irondequoit High School	Kitchen	Right of gas stove	Room 1030-11	Pot Filler	5.8	9.10	n/a		X					Removed from service:	
70330965005	IH 22	Irondequoit High School	Kitchen	Right of gas oven	Room 1030-13	Pot Filler	6.2	3.90	-	X					X	Replaced piping	
70330965007	IH 24	Irondequoit High School	Kitchen	Locker room	Room 1032	Sink	6	4.10	-	X		X					
70330965005	IH 22	Irondequoit High School	Kitchen	Right of gas oven	Room 1030-13	Pot Filler	6.2	3.90	18.30	X					X	1- flush, 2-replace piping & fixture, 3-flush	
70330965010	IH 27	Irondequoit High School	Kitchen	Serving line	Room 1039	Sink	12.3	6.50			X				X	Add filter	
70330965016	IH 33	Irondequoit High School	Technology Ed	Room 1071	Sink	15.9	17.50	n/a		X						Removed from service	
70330654056	IH 55-B	Irondequoit High School	Office	Room 2004	Sink	6.7	4.90	-	X			X					

**WEST IRONDEQUOIT CENTRAL SCHOOL DISTRICT**

**Template for Recordkeeping of Outlets Tested (Applicable Outlets) that Exceeded the Lead Action Level and the Remedial Actions that were/ are implemented.**

Outlets Exceeding the Lead Action Level (5 micrograms per liter)																		
Laboratory ID	Outlet Location (or Sample ID)		Building	Space/ Function		Room	Outlet Type <sup>1</sup>	Sample Results			Remedial Actions (Please check all that apply)							Notes/Comments REMEDIATION
								Initial (ppb)	Post Remediation 4-22-2025	Post Remediation 9-25-25	Outlet or Plumbing Replacement <sup>2</sup>	Permanent Removal <sup>3</sup>	Filter Installed and Maintained	Signage	Supervision	Continuing Education	Flushing	
70330654057	IH	56	Irondequoit High School	Hallway	Next to	Room 2021	Drinking Fountain	13.6	26.30		X		X				X	Replaced drinking fountain add filter
70330654068	IH	67	Irondequoit High School	Classroom		Room 3031	Sink	67.6	54.30	n/a		X						Removed from service
70330654069	IH	68	Irondequoit High School	Classroom		Room 3032	Sink	13.7	9.60	n/a		X						Removed from service
70330654070	IH	69	Irondequoit High School	Hallway	Across from classroom	Room 3033	Drinking Fountain	7.9	62.00		X		X				X	Replaced drinking fountain add filter
70330814006	DJ	6	Dake Junior High School	Classroom FACS	Back wall left	Room 133-1	Sink	6	21.00	6.60	X						X	1- flush, 2-replace piping & fixture, 3-flush
70330814007	DJ	7	Dake Junior High School	Classroom FACS	Back wall right	Room 133-2	Sink	7.2	7.70	11.20	X						X	1- flush, 2-replace piping & fixture, 3-flush
70330814008	DJ	8	Dake Junior High School	Classroom FACS	Right wall left	Room 133-3	Sink	11.5	61.90	29.10	X						X	1- flush, 2-replace piping & fixture, 3-flush
70330814020	DJ	20	Dake Junior High School	Kitchen		Room 170-1	Sink	5.2	65.40	8.80	X						X	1- flush, 2-replace piping & fixture, 3-flush
70330814026	DJ	26	Dake Junior High School	Kitchen		Room 170-7	Pot Filler	87.9	44.80	5.70	X						X	1- flush, 2-replace piping & fixture, 3-flush
70330814027	DJ	27	Dake Junior High School	Kitchen		Room 170-6	Sprayer	22.2	8.00	26.50	X						X	1- flush, 2-replace piping & fixture, 3-flush
70330814050	DJ	50	Dake Junior High School	Bathroom		Room 350	Sink	5.7	n/a	-	X			X			X	Tempered outlet

<sup>1</sup> Outlet type may include a drinking fountain/bubbler, kitchen outlets, or other.

<sup>2</sup> Outlet or Plumbing Replacement: Would include replacing existing fixtures or plumbing components with options that meet the 2014 Safe Drinking Water Act 1417 (a) (4) definition of lead-free (not containing more than 0.2 percent lead when used with respect to solder and flux; and not more than a weighted average of 0.25 percent lead when used with respect to the wetted surfaces of pipes, pipe fittings, plumbing fittings, and fixtures).

<sup>3</sup> Removing the fixture and/or capping the supply line before the fixture.

<sup>4</sup> Engineering controls may include locked doors, keys to operate an outside hose bib, or other.