Environmental Hazards Services, L.L.C.
7469 Whitepine Rd
Richmond, VA 23237
Telephone: 800.347.4010

Lead in Drinking Water Analysis Report

Report Number: 21-03-03129

Client: Stohl Environmental
3860 California Road
Orchard Park, NY 14127

Received Date: 03/16/2021
Reported Date: 04/12/2021
Sampled By: Drew Theal
Tech Certification #:

Project/Test Address: 2020L-149.1; 79th St Elementary School; 551 79th St

Client Number:
33-5980

Laboratory Results

Fax Number:
716-312-8092

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-03-03129-001	149.1-3	03/09/2021	CLASSROOM 106	22.5	04/09/2021	
21-03-03129-002	149.1-4	03/09/2021	106 BATHROOM	21.5	04/09/2021	
21-03-03129-003	149.1-6	03/09/2021	101	2.64	04/09/2021	
21-03-03129-004	149.1-8	03/09/2021	101 BATHROOM	2.05	04/09/2021	
21-03-03129-005	149.1-10	03/09/2021	107	6.52	04/09/2021	
21-03-03129-006	149.1-12	03/09/2021	107 BATHROOM	36.4	04/09/2021	
21-03-03129-007	149.1-14	03/09/2021	108	2.31	04/09/2021	
21-03-03129-008	149.1-15	03/09/2021	102	23.8	04/09/2021	
21-03-03129-009	149.1-17	03/09/2021	102 BATHROOM	2.97	04/09/2021	
21-03-03129-010	149.1-18	03/09/2021	103	5.88	04/09/2021	
21-03-03129-011	149.1-20	03/09/2021	103 BATHROOM	7.54	04/09/2021	
21-03-03129-012	149.1-21	03/09/2021	109	6.11	04/09/2021	
21-03-03129-013	149.1-22	03/09/2021	110	2.48	04/09/2021	

Client Number: 33-5980 **Report Number:** 21-03-03129

Project/Test Address: 2020L-149.1; 79th St Elementary School; 551 79th St

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-03-03129-014	149.1-23	03/09/2021	104	11.5	04/09/2021	
21-03-03129-015	149.1-24	03/09/2021	104 BATHROOM	8.05	04/09/2021	
21-03-03129-016	149.1-25	03/09/2021	104 BATHROOM	5.58	04/09/2021	
21-03-03129-017	149.1-26	03/09/2021	104 BATHROOM	41.8	04/09/2021	
21-03-03129-018	149.1-27	03/09/2021	111	2.25	04/09/2021	
21-03-03129-019	149.1-28	03/09/2021	HALL BETWEEN BATHROOMS	<1.00	04/09/2021	
21-03-03129-020	149.1-28B	03/09/2021	HALL BETWEEN BATHROOMS	<1.00	04/09/2021	
21-03-03129-021	149.1-29	03/09/2021	GIRLS BATHROOM	<1.00	04/09/2021	
21-03-03129-022	149.1-30	03/09/2021	GIRLS BATHROOM	<1.00	04/09/2021	
21-03-03129-023	149.1-31	03/09/2021	BOYS BATHROOM	<1.00	04/09/2021	
21-03-03129-024	149.1-32	03/09/2021	BOYS BATHROOM	<1.00	04/09/2021	
21-03-03129-025	149.1-33	03/09/2021	105	5.96	04/09/2021	
21-03-03129-026	149.1-34	03/09/2021	105 BATHROOM	1.42	04/09/2021	
21-03-03129-027	149.1-35	03/09/2021	CLINIC BATHROOM	<1.00	04/09/2021	
21-03-03129-028	149.1-36	03/09/2021	MAIN OFFICE STORAGE LAV	1.84	04/09/2021	
21-03-03129-029	149.1-39	03/09/2021	KITCHEN	<1.00	04/09/2021	
21-03-03129-030	149.1-40	03/09/2021	KITCHEN	8.75	04/09/2021	
21-03-03129-031	149.1-41	03/09/2021	WOMEN'S BATHROOM	7.30	04/09/2021	
21-03-03129-032	149.1-42	03/09/2021	MEN'S BATHROOM	1.12	04/09/2021	
21-03-03129-033	149.1-43	03/09/2021	BOYS COACH OFFICE	<1.00	04/09/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 **Report Number:** 21-03-03129

Project/Test Address: 2020L-149.1; 79th St Elementary School; 551 79th St

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-03-03129-034	149.1-47	03/09/2021	GIRLS LOCKER ROOM	3.92	04/09/2021	
21-03-03129-035	149.1-49	03/09/2021	207	4.59	04/09/2021	
21-03-03129-036	149.1-50	03/09/2021	BOYS BATHROOM	7.51	04/09/2021	
21-03-03129-037	149.1-51	03/09/2021	BOYS BATHROOM	2.67	04/09/2021	
21-03-03129-038	149.1-52	03/09/2021	GIRLS BATHROOM	3.47	04/09/2021	
21-03-03129-039	149.1-53	03/09/2021	GIRLS BATHROOM	12.9	04/09/2021	
21-03-03129-040	149.1-54	03/09/2021	HALL BETWEEN BATHROOMS	5.52	04/09/2021	
21-03-03129-041	149.1-55	03/09/2021	201	8.44	04/09/2021	
21-03-03129-042	149.1-56	03/09/2021	208	8.35	04/09/2021	
21-03-03129-043	149.1-57	03/09/2021	202	12.0	04/09/2021	
21-03-03129-044	149.1-58	03/09/2021	209	6.32	04/09/2021	
21-03-03129-045	149.1-59	03/09/2021	203	3.56	04/09/2021	
21-03-03129-046	149.1-60	03/09/2021	MEN'S BATHROOM	16.0	04/09/2021	
21-03-03129-047	149.1-61	03/09/2021	WOMEN'S BATHROOM	8.08	04/09/2021	
21-03-03129-048	149.1-62	03/09/2021	STAFF LOUNGE	3.59	04/09/2021	
21-03-03129-049	149.1-63	03/09/2021	204	6.44	04/09/2021	
21-03-03129-050	149.1-65	03/09/2021	210	7.77	04/09/2021	
21-03-03129-051	149.1-66	03/09/2021	205	5.53	04/09/2021	
21-03-03129-052	149.1-67	03/09/2021	211	7.29	04/09/2021	
21-03-03129-053	149.1-68	03/09/2021	GIRLS BATHOOM	1.48	04/09/2021	

Environmental Hazards Services, L.L.C

Client Number: 33-5980 **Report Number:** 21-03-03129

Project/Test Address: 2020L-149.1; 79th St Elementary School; 551 79th St

Lab Sample Number	Client Sample ID	Collection Date	Collection Location	Concentration ug/L (ppb)	Analysis Date	Narrative ID
21-03-03129-054	149.1-69	03/09/2021	GIRLS BATHOOM	1.38	04/09/2021	
21-03-03129-055	149.1-71	03/09/2021	BOYS BATHROOM	<1.00	04/09/2021	
21-03-03129-056	149.1-72	03/09/2021	HALL ACROSS FROM 211	<1.00	04/09/2021	
21-03-03129-057	149.1-73	03/09/2021	206	6.04	04/09/2021	
21-03-03129-058	149.1-75	03/09/2021	STEM LAB	1.39	04/09/2021	
21-03-03129-059	149.1-76	03/09/2021	STEM LAB SMALL ROOM	1.54	04/09/2021	
21-03-03129-060	149.1-83	03/09/2021	KITCHEN	1.11	04/09/2021	
21-03-03129-061	149.1-84	03/09/2021	KITCHEN	<1.00	04/09/2021	
21-03-03129-062	149.1-85	03/09/2021	KITCHEN	<1.00	04/09/2021	
21-03-03129-063	149.1-86	03/09/2021	CAFETERIA	<1.00	04/09/2021	

Method: EPA 200.8
Analyst: Anthony Dee
Accreditation #: NY 11714

Reviewed By Authorized Signatory: Melissa Kanode

Missy Kanode
QA/QC Clerk

Sample Results denoted with a "less than" (<) sign contain less than the reporting limit which is 1 ppb.

The EPA Maximum Contaminant Level for Lead in Drinking Water is 15 ppb. The results herein conform to NELAC standards, where applicable, unless otherwise narrated on this report. Results represent the analysis of samples submitted by the client. Sample location, description, field parameter results, etc., were provided by the client. This report cannot be reproduced, except in full, without written approval from Environmental Hazards Services, L.L.C.

LEGEND ug/L= micrograms per liter ppb = parts per billion

VB

Chain of Custody Document

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-149.1

Client: Niagara Falls CSD Contact: Earl Smeal

Building: 79th St. Elementary School Location: 551 79th St.

LEAD		Turnaround
Water by SM 19, 21 - 23 3113B (-04, -10)	X	20 Days

Sample #	Location	Outlet Type	Time
149.1-3	Classroom 106	S	10:30
149.1-4	106 bathroom	S	10:31
149.1-6	101	S	10:32
149.1-8	101 bathroom	S	10:33
149.1-10	107	S	10:34
149.1-12	107 bathroom	S	10:35
149.1-14	108	S	10:36
149.1-15	102	S	10:37
149.1-17	102 bathroom	S	10:38
149.1-18	103	S	10:39
149.1-20	103 bathroom	S	10:40
149.1-21	109	S	10:41
149.1-22	110	S	10:42
149.1-23	104	S	10:43
149.1-24	104 bathroom	S	10:44
149.1-25	104 bathroom	B	10:45
149.1-26	104 bathroom	S	10:46
149.1-27	111	S	10:47

21-03-03129

Due Date:
04/13/2021
(Tuesday)
AE

Notes:
Please e-mail lab results to labs@stohlenv.com ☑ If checked, also e-mail results to: Ehenderson@StohlEnv.com

Sampled By: Drew Theal Print Name Stohl Env: Drew Theal Date: 3/9/2021

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 3/12/2021

Received (Name / Lab): KTHARRIS OK Date: 3.16.21 Time: 10:46 AM

Sample Login (Name / Lab): A Lowery A Lowery Date: 4/6/21 Time: 7:42 AM

Analysis (Name / Lab): [signature] Date: 4/9/21 Time: 8:13 pm

QA/QC Review (Name / Lab): [signature] Date: 4/12/21 Time: 5pm

Archived / Released: QA/QC InterLAB Use: Date: Time:

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-149.1

Client: Niagara Falls CSD

Contact: Earl Smeal

Building: 79th St. Elementary School

Location: 551 79th St.

LEAD

Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround

20 Days

Sample #	Location	Outlet Type	Time
149.1-28	Hall between bathrooms	B	10:48
149.1-28B	Hal Between bathrooms	BF	10:49
149.1-29	Girls bathroom	S	10:50
149.1-30	Girls bathroom	S	10:51
149.1-31	Boys bathroom	S	10:52
149.1-32	Boys bathroom	S	10:53
149.1-33	105	S	10:54
149.1-34	105 bathroom	S	10:55
149.1-35	Clinic bathroom	S	10:56
149.1-36	Main Office storage lav	S	10:57
149.1-39	Kitchen	S	10:58
149.1-40	Kitchen	S	10:59
149.1-41	Women's bathroom	S	11:00
149.1-42	Men's bathroom	S	11:01
149.1-43	Boys coach Office	S	11:02
149.1-47	Girls locker room	S	11:03
149.1-49	207	S	11:04
149.1-50	Boys bathroom	S	11:05

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: Drew Theal Print Name Stohl Env: Drew Theal Date: 3/9/2021

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 3/12/2021

Received (Name / Lab): KTHARRIS [signature] Date: 3.16.21 Time: 10:46 AM

Sample Login (Name / Lab): A Lowery Amanda Lowery Date: 4/6/21 Time: 7:49 Am

Analysis (Name / Lab): [signature] Date: 4/9/21 Time: 4:13pm

QA/QC Review (Name / Lab): [signature] Date: 4/21/21 Time: 5pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Chain of Custody Document

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-149.1

Client: Niagara Falls CSD Contact: Earl Smeal

Building: 79th St. Elementary School Location: 551 79th St.

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

Sample #	Location	Outlet Type	Time
149.1-51	Boys bathroom	S	11:06
149.1-52	Girls bathroom	S	11:07
149.1-53	Girls bathroom	S	11:08
149.1-54	Hall between bathrooms	B	11:09
149.1-55	201	S	11:10
149.1-56	208	S	11:11
149.1-57	202	S	11:12
149.1-58	209	S	11:13
149.1-59	203	S	11:14
149.1-60	Men's bathroom	S	11:15
149.1-61	Women's bathroom	S	11:16
149.1-62	Staff lounge	S	11:17
149.1-63	204	S	11:18
149.1-65	210	S	11:19
149.1-66	205	S	11:20
149.1-67	211	S	11:21
149.1-68	Girls bathroom	S	11:22
149.1-69	Girls bathroom	S	11:23

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: Drew Theal Print Name Stohl Env: Drew Theal Date: 3/9/2021

Relinquished By: E. Henderson Jr. Print Name Stohl Env: Eric Henderson Jr. Date: 3/12/2021

Received (Name / Lab): KTHARRIS Date: 3.16.21 Time: 10:40 AM

Sample Login (Name / Lab): Amanda Lovery / AJovery Date: 4/6/21 Time: 7:55 AM

Analysis (Name / Lab): Date: 4/9/21 Time: 8:13pm

QA/QC Review (Name / Lab): Date: 4/12/21 Time: 5pm

Archived / Released: QA/QC InterLAB Use: Date: Time:

Chain of Custody Document

Stohl ENVIRONMENTAL
3860 California Road, Orchard Park, New York 14127
PHONE (716) 312-0070 FAX (716) 312-8092
WWW.STOHLENVIRONMENTAL.COM

Submitted to: (Lab Name) EHS

STOHL Job # 2020L-149.1

Client: Niagara Falls CSD

Contact: Earl Smeal

Building: 79th St. Elementary School

Location: 551 79th St.

LEAD
Water by SM 19, 21 - 23 3113B (-04, -10) X

Turnaround
20 Days

Sample #	Location	Outlet Type	Time
149.1-71	Boys bathroom	S	11:24
149.1-72	Hall across from 211	B	11:25
149.1-73	206	S	11:26
149.1-75	Stem lab	S	11:27
149.1-76	Stem lab small room	S	11:28
149.1-83	Kitchen	S	11:29
149.1-84	Kitchen	S	11:30
149.1–85	Kitchen	IM	11:31
149.1-86	Cafeteria	S	11:32

Notes:
Please e-mail lab results to labs@stohlenv.com

Sampled By: Drew Theal Print Name Stohl Env: Drew Theal Date: 3/9/2021

Relinquished By: [signature] Print Name Stohl Env: Eric Henderson Jr. Date: 3/12/2021

Received (Name / Lab): KTHARRIS [signature] Date: 3-16-21 Time: 10:46 Am

Sample Login (Name / Lab): A Lowery Amanda Lowery Date: 4/6/21 Time: 8:00 Am

Analysis (Name / Lab): [signature] Date: 4/9/21 Time: 8:13pm

QA/QC Review (Name / Lab): [signature] Date: 4/12/21 Time: 5pm

Archived / Released: _____ QA/QC InterLAB Use: _____ Date: _____ Time: _____