

Lead Testing 2024

Building: Lancaster High School
Sample Number: 104.1-2
Location: Kitchen Sink Bay Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 17.9
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only, Filter to be installed
Date Remediation Taken: 10/28/24
Actual Remediation Taken: Installed Filter
Date Taken: 10/28/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): <1 – Cleared
Date Put Back in Service: 6/9/25

Building: Lancaster High School
Sample Number: 104.1-4
Location: Kitchen Dishwash 3-bay Sink, Right
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 11
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only, Filter to be installed
Date Remediation Taken: 10/28/24
Actual Remediation Taken: Installed Filter
Date Taken: 10/28/24

Building: Lancaster High School
Sample Number: 104.1-5
Location: Kitchen Single Middle Island Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 13.2
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only, Filter to be installed
Date Remediation Taken: 10/28/24
Actual Remediation Taken: Installed Filter
Date Taken: 10/28/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): <1 – Cleared
Date Put Back in Service: 6/9/25

Building: Lancaster High School
Sample Number: 104.1-12 Location: Dish Room Single Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 17.3
Date Sample Collected: 6/4/21
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only, Filter to be installed
Date Remediation Taken: 10/28/24
Actual Remediation Taken: installed filter
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): <1 – Cleared
Date Put Back in Service: 6/9/25

Building: Lancaster High School
Sample Number: 104.1-13A
Location: Faculty Dining Room South Wall
Fixture/Outlet Type: Drinking Fountain
Laboratory Analysis (in ppb): 15.4
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: 8/26/24
Planned Remediation Measure: Replace
Date Remediation Taken: 12/9/24
Actual Remediation Taken: Installed Filter
Date Taken: 12/9/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): <1 – Cleared
Date Put Back in Service: 6/6/25

Building: Lancaster High School
Sample Number: 104.1-36
Location: Boys Pool Locker Room East Wall
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 33.5
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-38
Location: Boys Vestibule Lavatory
Fixture/Outlet Type: Sink

Laboratory Analysis (in ppb): 6.4
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-40
Location: Technology Room 167 Center
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 15.3
Date Sample Collected: 6/4/24
Date Results received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-41
Location: Technology Room 167 Right
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 11.5
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-43
Location: Technology Room 166 Center
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.2
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-52
Location: Boys Field House Locker Room 1 Left
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.5
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-101
Location: Across from Room 147
Fixture/Outlet Type: Drinking Fountain
Laboratory Analysis (in ppb): 6
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: 8/26/24
Planned Remediation Measure: Replace
Date Remediation Taken: 11/6/24
Actual Remediation Taken: Installed New Bottle Filler
Date Taken: 11/6/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): <1 – Cleared
Date Put Back in Service: 6/6/25

Building: Lancaster High School
Sample Number: 104.1-102
Location: Room 147 Left Single Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 20.5
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-103
Location: Room 147 Right Double Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.4
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-108
Location: Women's Faculty Lavatory by Room 143 Left Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.1
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-110
Location: Men's Faculty Lavatory by Room 143 Left Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.3
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-111
Location: Credit Union Room 140
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 27.6
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-114
Location: Girls G7 Lavatory Left
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.1
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-117
Location: Room 141 Left
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 8.6
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-119
Location: Room 138A
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 20.4
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24

Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-120
Location: Room 136A
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.5
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-123
Location: Fitness Center/Pool Hallway
Fixture/Outlet Type: Drinking Fountain
Laboratory Analysis (in ppb): 17
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: 8/26/24
Planned Remediation Measure: Replace
Date Remediation Taken: 10/7/24
Actual Remediation Taken: Install New Bottle Filler
Date Taken: 10/7/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): <1 – Cleared
Date Put Back in Service: 6/6/25

Building: Lancaster High School
Sample Number: 104.1-124
Location: Girls Pool Locker Room
Fixture/Outlet Type: Bubblers
Laboratory Analysis (in ppb): 20.7
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: 8/26/24
Planned Remediation Measure: Replace

Building: Lancaster High School
Sample Number: 104.1-125
Location: Girls Pool Locker Room
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 10.8
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable

Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-136
Location: Principal's Office Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 9
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-144
Location: G3 Lavatory Left Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.5
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-149
Location: B3 Lavatory Right Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.3
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-150
Location: Room 111A (Office Area)
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-155
Location: Prep Room Between S11/S12
Fixture/Outlet Type: Sink

Laboratory Analysis (in ppb): 21.1
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-156
Location: Outside Room 113
Fixture/Outlet Type: Drinking Fountain
Laboratory Analysis (in ppb): 15.1
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: 8/26/24
Planned Remediation Measure: Replace Filter
Date Remediation Taken: 12/9/24
Actual Remediation Taken: Installed New Bottle Filler
Date Taken: 12/9/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): <1 – Cleared
Date Put Back in Service: 6/6/25

Building: Lancaster High School
Sample Number: 104.1-161
Location: Room 128A
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 9.2
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-164
Location: G5 Lavatory Left Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 17.7
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-167
Location: Room 128 Left
Fixture/Outlet Type: Sink

Laboratory Analysis (in ppb): 14.7
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-168
Location: Room 128 Right
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 12.4
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-169
Location: Room 130A
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.9
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-171
Location: Room 129
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 29.8
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-172
Location: Room 131A Sink by Window
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 12.2
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-173
Location: Room 130 Left Wall Left Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 73
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-174
Location: Room 130 Left Wall Center Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 14.7
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-175
Location: Room 130 Left Wall Right Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 11.3
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-176
Location: Room 130 Back Wall Left Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 56
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-177
Location: Room 130 Back Wall Middle Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 20.3
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24

Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-178
Location: Room 130 Back Wall Right Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 16.2
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-188
Location: Women's Lavatory by 200.10 Sink by Window
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 44.7
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-189
Location: Women's Lavatory by 200.10 2nd Sink from Left
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 15.1
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-190
Location: Women's Lavatory by 200.10 3rd Sink from Left
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.2
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-225

Location: Room 216
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 11.3
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-228
Location: Across from Rifle Range in Basement
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 11.7
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-229
Location: Across from Rifle Range in Basement
Fixture/Outlet Type: Drinking Fountain
Laboratory Analysis (in ppb): 9.2
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: 8/26/24
Planned Remediation Measure: Replace
Date Remediation Taken: 12/17/24
Actual Remediation Taken: Installed Filter
Date Taken: 12/17/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): <1 – Cleared
Date Put Back in Service: 6/9/25

Building: Lancaster High School
Sample Number: 104.1-230
Location: Basement Laundry Room
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 9.4
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster High School
Sample Number: 104.1-231

Location: Basement Staff Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.7
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Lancaster Middle School
Sample Number: 104.2.10
Location: Girls Lavatory by Room 200 Center Sinks
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.5
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/24/24

Building: Lancaster Middle School
Sample Number: 104.2-16
Location: Kitchen Room 206/204 Science Office Right Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 15.1
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/24/24

Building: Lancaster Middle School
Sample Number: 104.2-17
Location: Kitchen Room 206/204 Science Office Left Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 11.3
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/24/24

Building: Lancaster Middle School
Sample Number: 104.2-56
Location: Room 108A
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 11.3
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only

Date Remediation Taken: 8/24/24

Building: Lancaster Middle School
Sample Number: 104.2-70
Location: Girls Lavatory by Room 100 Right Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.3
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/24/24

Building: Lancaster Middle School
Sample Number: 104.2-104
Location: Kitchen Dish Sprayer South Wall Right
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 72.2
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only
Date Remediation Taken: 8/24/24

Building: Lancaster Middle School
Sample Number: 104.2-105
Location: Kitchen Dish Spray by 3 Bay
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 645
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only
Date Remediation Taken: 8/24/24

Building: Lancaster Middle School
Sample Number: 104.2-106
Location: Kitchen Faucet Next to 3 Bay
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 138
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only, Filter to be installed
Date Remediation Taken: 12/9/24
Actual Remediation Taken: Installed Filter
Date Taken: 12/9/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): <1 – Cleared
Date Put Back in Service: 6/9/25

Building: Lancaster Middle School
Sample Number: 104.2-107
Location: Kitchen 3 Bay Left
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 16.2
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only, Filter to be installed
Date Remediation Taken: 12/9/24
Actual Remediation Taken: Installed Filter
Date Taken: 12/9/24
Date Sample Collected: 6/27/2025
Date Results Received: 10/21/2025
Laboratory Analysis (in ppb): 2.6- Cleared
Date Put Back in Service: 10/22/2025

Building: Lancaster Middle School
Sample Number: 104.2-108
Location: Kitchen 3 Bay Right
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.9
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only, Filter to be installed
Date Remediation Taken: 12/9/24
Actual Remediation Taken: Installed Filter
Date Taken: 12/9/24
Date Sample Collected: 6/27/2025
Date Results Received: 10/21/2025
Laboratory Analysis (in p p b):<1 - Cleared
Date Put Back in Service: 10/22/2025

Building: William Street School
Sample Number: 104.3-6
Location: Kitchen Handwash in Corner
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.5
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: William Street School
Sample Number: 104.3-11

Location: Kitchen Single Sink by Coffee
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 10.1
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 9/27/24
Actual Remediation Taken: Installed Filter
Date Taken: 9/27/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): 4.7 – Cleared
Date Put Back in Service: 6/9/25

Building: William Street School
Sample Number: 104.3-16
Location: Kitchen Serving Area Handwash
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.8
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: William Street School
Sample Number: 104.3-18
Location: Kitchen Handwash by Stove
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 29.1
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: William Street School
Sample Number: 104.3-40
Location: Room B103
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 11.1
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: William Street School

Sample Number: 104.3-130
Location: Room B203
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.6
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: William Street School
Sample Number: 104.3-180
Location: Room D219
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 10.9
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: William Street School
Sample Number: 104.3-211
Location: D220
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.9
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Como Park
Sample Number: 104.4-6
Location: Room 107
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.7
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Como Park
Sample Number: 104.4-9
Location: Room 8 Bathroom Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 13.6
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24

Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-12
Location: Bathroom outside of Room 109
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 15.4
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-15
Location: Room 114 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 17.1
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-18
Location: Room 109 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 14.6
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-21
Location: Room 113 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 15.6
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-24
Location: Room 110 Art Room Lavatory

Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 26.3
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-27
Location: Room 112 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 15.6
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-33
Location: Room 207 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 10.6
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 12/15/20

Building: Como Park
Sample Number: 104.4-36
Location: Room 208 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 11.8
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 12/15/20

Building: Como Park
Sample Number: 104.4-39
Location: Room 206 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 14.2
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-42
Location: Room 209 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.7
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Location: Room 205 Lavatory
Sample Number: 104.4-45
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 8.9
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-46
Location: All Gender Bathroom
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 13.8
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-49
Location: Room 204 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 9.3
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 12/15/20

Building: Como Park
Sample Number: 104.4-52
Location: Room 203 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 13.2
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24

Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-55
Location: All Gender Bathroom
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 20.7
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-63
Location: Room 120
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.1
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-68
Location: 127 Library Media Center
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 11.8
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-69
Location: Room 126 Main
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 13.2
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-70
Location: Room 126 Lavatory

Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.3
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-71
Location: Room 125 Main
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 11.5
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-72
Location: Room 125 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 12.5
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-74
Location: Room 204 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 12.2
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-73
Location: Room 106 Nurse Main
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 12.4
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Como Park
Sample Number: 104.4-75
Location: Outside of Room 106
Fixture/Outlet Type: Drinking Fountain
Laboratory Analysis (in ppb): 5.1
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: 8/26/24
Planned Remediation Measure: Replace
Date Remediation Taken: 10/31/24
Actual Remediation Taken: Installed New Bottle Filler
Date Taken: 10/31/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): <1 – Cleared
Date Put Back in Service: 6/6/25

Building: Como Park
Sample Number: 104.4-76
Location: Outside of Room 227
Fixture/Outlet Type: Drinking Fountain
Laboratory Analysis (in ppb): 8.5
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: 8/26/24
Planned Remediation Measure: Replace
Date Remediation Taken: 10/1/24
Actual Remediation Taken: 10/1/24
Date Taken: 10/1/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): <1 – Cleared
Date Put Back in Service: 6/6/25

Building: Como Park
Sample Number: 104.4-81
Location: Room 223
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 23.9
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 12/15/20

Building: Como Park
Sample Number: 104.4-86
Location: Girl's

Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 8
Date Sample Collected: 6/5/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Court Street School
Sample Number: 104.5-1
Location: Gym Office Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 9.1
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Court Street School
Sample Number: 104.5-2
Location: Gym Classroom
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.1
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Court Street School
Sample Number: 104.5-3
Location: Kitchen Sprayer
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 18.7
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only, Filter to be installed
Date Remediation Taken: 10/31/24
Actual Remediation Taken: Installed Filter
Date Taken: 10/31/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): <1 – Cleared
Date Put Back in Service: 6/9/25

Building: Court Street School
Sample Number: 104.5-10
Location: Room Gym Passage Left Lavatory

Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 12.9
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Court Street School
Sample Number: 104.5-23
Location: Girls Lavatory Right
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 8.2
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Court Street School
Sample Number: 104.5-27
Location: Room 105
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 21
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Court Street School
Sample Number: 104.5-30
Location: Room 109
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 9.1
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Court Street School
Sample Number: 104.5-32
Location: Room 108
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 9.7
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Court Street School
Sample Number: 104.5-35
Location: Principal Office Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 8
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Court Street School
Sample Number: 104.5-38
Location: Nurse Office Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 8.2
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only, Filter to be installed
Date Remediation Taken: 10/31/24
Actual Remediation Taken: Installed Filter
Date Taken: 10/31/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): 2.0 – Cleared
Date Put Back in Service: 6/9/25

Building: Court Street School
Sample Number: 104.5-45
Location: Room 132
Fixture/Outlet Type: Bubblers
Laboratory Analysis (in ppb): 5.4
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: 8/27/24
Planned Remediation Measure: Taken Out of Service

Building: Court Street School
Sample Number: 104.5-61
Location: Room 129
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.9
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Court Street School
Sample Number: 104.5-64
Location: Room 126
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.5
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Court Street School
Sample Number: 104.5-67
Location: Room 128
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.1
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Court Street School
Sample Number: 104.5-69
Location: Room 127
Fixture/Outlet Type: Bubbler
Laboratory Analysis (in ppb): 5.3
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: 8/27/24
Planned Remediation Measure: Taken Out of Service

Building: Court Street School
Sample Number: 104.5-74
Location: Room 118B
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 28.6
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Hillview Elementary School
Sample Number: 104.6-1
Location: Kitchen 3 Bay Left
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.2
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24

Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only, Filter to be installed
Date Remediation Taken: 12/12/24
Actual Remediation Taken: Installed Filter
Date Taken: 12/12/24
Date Sample Collected: 6/27/2025
Date Results Received: 10/21/2025
Laboratory Analysis (in ppb): 2.8 - Cleared
Date Put Back in Service: 10/22/2025

Building: Hillview Elementary School
Sample Number: 104.6-3
Location: Kitchen Staff Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.5
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Hillview Elementary School
Sample Number: 104.6-5
Location: Cafeteria Fountain
Fixture/Outlet Type: Drinking Fountain
Laboratory Analysis (in ppb): 6.6
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: 8/27/24
Planned Remediation Measure: Replace
Date Remediation Taken: 10/1/24
Actual Remediation Taken: Installed New Bottle Filler
Date Taken: 10/1/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): <1 – Cleared
Date Put Back in Service: 6/9/25

Building: Hillview Elementary School
Sample Number: 104.6-11
Location: Principal's Office Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 17.6
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Hillview Elementary School
Sample Number: 104.6-14
Location: Room 1 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 29.4
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Hillview Elementary School
Sample Number: 104.6-26
Location: Room 5 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 18.8
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Hillview Elementary School
Sample Number: 104.6-29
Location: Room 4 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.4
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Hillview Elementary School
Sample Number: 104.6-33
Location: Room 9 Main
Fixture/Outlet Type: bubbler
Laboratory Analysis (in ppb): 6.3
Date Sample Collected: 6/4/24
Date Results Received: 8/15/24
Date Taken Out of Service: 8/27/24
Planned Remediation Measure: Taken Out of Service

Building: Hillview Elementary School
Sample Number: 104.6-36
Location: Nurse Exam
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.5
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24

Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: No

Building: Hillview Elementary School
Sample Number: 104.6-43
Location: Room 32 Art Office Right
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.3
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: No

Building: Hillview Elementary School
Sample Number: 104.6-52
Location: Room 11
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.7
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: No

Building: Hillview Elementary School
Sample Number: 104.6-53
Location: Room 11
Fixture/Outlet Type: Bubblers
Laboratory Analysis (in ppb): 6
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: 8/27/24
Planned Remediation Measure: Taken Out of Service

Building: Hillview Elementary School
Sample Number: 104.6-63
Location: Girls Locker Coach Office
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.3
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Hillview Elementary
Sample Number: 104.6-64
Location: Girls Locker Room
Fixture/Outlet Type: Sink

Laboratory Analysis (in ppb): 24.2
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Hillview Elementary School
Sample Number: 104.6-67
Location: Boys Gym Office
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.3
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Hillview Elementary School
Sample Number: 104.6-74
Location: Room 17
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.6
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: Hillview Elementary School
Sample Number: 104.6-98
Location: Basement
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 10.4
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: John A. Sciole Elementary School
Sample Number: 104.7-2
Location: Room 1
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 20.1
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: New Faucet in Construction Updates
Date Remediation Taken: 8/27/24

Actual Remediation Taken: New Faucet Installed
Date Taken: 8/27/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): 4.3 – Cleared
Date Put Back in Service: 6/6/25

Building: John A. Sciole Elementary School
Sample Number: 104.7-3
Location: Room 4
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.3
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: John A. Sciole Elementary School
Sample Number: 104.74
Location: Room 3
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 10.8
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: New Faucet in Construction Updates
Date Remediation Taken: 8/27/24
Actual Remediation Taken: New Faucet Installed
Date Taken: 8/27/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): 3.7 – Cleared
Date Put Back in Service: 6/9/25

Building: John A. Sciole Elementary School
Sample Number: 104.7-5
Location: Room 6
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 11.7
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: John A. Sciole Elementary School
Sample Number: 104.7-6
Location: Room 5

Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.9
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: New Faucet in Construction Updates
Date Remediation Taken: 8/27/24
Actual Remediation Taken: New Faucet Installed
Date Taken: 8/27/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): 3.4 – Cleared
Date Put Back in Service: 6/6/25

Building: John A. Sciole Elementary School
Sample Number: 104.7-7
Location: Room 8
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.7
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: John A. Sciole Elementary School
Sample Number: 104.7-8
Location: Room 7
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 10
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: New Faucet in Construction Updates
Date Remediation Taken: 8/27/24
Actual Remediation Taken: New Faucet Installed
Date Taken: 8/27/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): 3.4 – Cleared
Date Put Back in Service: 6/6/25

Building: John A. Sciole Elementary School
Sample Number: 104.7-9
Location: Room 10
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.3
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24

Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: John A. Sciole Elementary School
Sample Number: 104.7-10
Location: Room 9
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.7
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: New Faucet in Construction Updates
Date Remediation Taken: 8/27/24
Actual Remediation Taken: New Faucet Installed
Date Taken: 8/27/24

Building: John A. Sciole Elementary School
Sample Number: 104.7-12
Location: Room 11
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.5
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: New Faucet in Construction Updates
Date Remediation Taken: 8/27/24
Actual Remediation Taken: New Faucet Installed
Date Taken: 8/27/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): 1.9 – Cleared
Date Put Back in Service: 6/6/25

Building: John A. Sciole Elementary School
Sample Number: 104.7-24
Location: Library Media Center
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.9
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: John A. Sciole Elementary School
Sample Number: 104.7-30
Location: Room 13
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.2

Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: John A. Sciole Elementary School
Sample Number: 104.7-39
Location: Room 24
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.6
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: John A. Sciole Elementary School
Sample Number: 104.7-40
Location: Room 23
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 8.7
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: John A. Sciole Elementary School
Sample Number: 104.7-41
Location: Art room West Side Left Single Handle Fixture
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 9
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: John A. Sciole Elementary School
Sample Number: 104.7-46
Location: Art Room East Side Right Single Handle Fixture
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 35.1
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/27/24

Building: John A. Sciole Elementary School

Sample Number: 104.7-55
Location: Kitchen Handwash
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.6
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only, Filter to be installed
Date Remediation Taken: 9/26/24
Actual Remediation Taken: Installed Filter
Date Taken: 9/26/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): 3.7 – Cleared
Date Put Back in Service: 6/9/25

Building: John A. Sciole Elementary School
Sample Number: 104.7-56
Location: Kitchen Prep Table Single Bay
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.2
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only, Filter to be installed
Date Remediation Taken: 9/26/24
Actual Remediation Taken: Installed Filter
Date Taken: 9/26/24
Date Sample Collected: 6/27/2025
Date Results Received: 10/21/2025
Laboratory Analysis (in ppb): <1 - Cleared
Date Put Back in Service: 10/22/2025

Building: John A. Sciole Elementary School
Sample Number: 104.7-57
Location: Kitchen Pan Fill
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 107
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only
Date Remediation Taken: 12/15/20

Building: John A. Sciole Elementary School
Sample Number: 104.7-58
Location: Kitchen 3 Bay Left Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 9.9

Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only, Filter to be installed
Date Remediation Taken: 9/26/24
Actual Remediation Taken: Installed Filter
Date Taken: 9/26/24
Date Sample Collected: 6/27/2025
Date Results Received: 10/21/2025
Laboratory Analysis (in ppb): <1 - Cleared
Date Put Back in Service: 10/22/2025

Building: John A. Sciole Elementary School
Sample Number: 104.7-59
Location: Kitchen 3 Bay Right Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 11.1
Date Sample Collected: 6/14/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand/Dish Wash Only, Filter to be installed
Date Remediation Taken: 9/26/24
Actual Remediation Taken: Installed Filter
Date Taken: 9/26/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): 1.9 – Cleared
Date Put Back in Service: 6/9/25

Building: District Office
Sample Number: 104.8-1
Location: Basement Men's Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.2
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: District Office
Sample Number: 104.8-3
Location: Basement Kitchen
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.9
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only, Filter to be installed

Date Remediation Taken: 9/26/24
Actual Remediation Taken: Installed Filter
Date Taken: 6/26/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): <1 – Cleared
Date Put Back in Service: 6/9/25

Building: District Office
Sample Number: 104.8-5
Location: Superintendent's Office Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.2
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: 295 Pleasant View Drive
Sample Number: 104.11-5
Location: Men's Lavatory Right
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 23.6
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: 295 Pleasant View Drive
Sample Number: 104.11-6
Location: Women's Lavatory Left
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 29.8
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: 295 Pleasant View Drive
Sample Number: 104.11-7
Location: Women's Lavatory Middle
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 20.1
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only

Date Remediation Taken: 8/26/24

Building: 295 Pleasant View Drive
Sample Number: 104.11-8
Location: Women's Lavatory Right
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 12.6
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: 295 Pleasant View Drive
Sample Number: 104.11-10
Location: Locker Room Middle
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 19.4
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: 295 Pleasant View Drive
Sample Number: 104.11-11
Location: Locker Room Back
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.7
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: 295 Pleasant View Drive
Sample Number: 104.11-13
Location: Back Break Room Front
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 11.4
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: 295 Pleasant View Drive
Sample Number: 104.11-15
Location: Back Break Room Left
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 13.3

Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: 295 Pleasant View Drive
Sample Number: 104.11-16
Location: Back Break Room Right
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 15.5
Date Sample Collected: 6/6/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Central Avenue
Sample Number: 104.10-1
Location: Kitchen Sink
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 8.7
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only, Filter to be installed
Date Remediation Taken: 9/26/24
Actual Remediation Taken: Installed Filter
Date Taken: 9/26/24
Date 2nd Sample Collected: 4/5/25
Date Results Received: 6/2/25
Second Sample Laboratory Analysis (in p p b): <1 – Cleared
Date Put Back in Service: 6/9/25

Building: Central Avenue
Sample Number: 104.10-4
Location: Board Room Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 5.5
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Central Avenue
Sample Number: 104.10-16
Location: Room 108
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 8.7

Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Central Avenue
Sample Number: 104.10-20
Location: Room 119 Lavatory
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 14.8
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 12/15/20

Building: Central Avenue
Sample Number: 104.10-22
Location: Boys Locker Room
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 8.8
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Central Avenue
Sample Number: 104.10-23
Location: Girls Locker Room
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.1
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Central Avenue
Sample Number: 104.10-24
Location: Room 125
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 13.8
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Central Avenue

Sample Number: 104.10-28
Location: Lavatory Near Room 127
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Central Avenue
Sample Number: 104.10-29
Location: Women's Lavatory Across from Room 131 Close to Door
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 46.7
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Central Avenue
Sample Number: 104.10-31
Location: Women's Lavatory Across from Room 131 Center Left
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 7.4
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Central Avenue
Sample Number: 104.10-30
Location: Women's Lavatory Across from Room 131 Center Right
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 23.5
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Central Avenue
Sample Number: 104.10-33
Location: Men's Lavatory Next t Room 136 Close to Door
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 9.3
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable

Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Central Avenue
Sample Number: 104.10-34
Location: Men's Lavatory Next to Room 136 Center Right
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 8.6
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Central Avenue
Sample Number: 104.10-35
Location: Men's Lavatory Next to Room 136 Center Left
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 12.1
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Central Avenue
Sample Number: 104.10-36
Location: Men's Lavatory Next to Room 136 Close to Window
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 6.4
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 8/26/24

Building: Central Avenue
Sample Number: 104.10-37
Location: Room 135
Fixture/Outlet Type: Sink
Laboratory Analysis (in ppb): 49.9
Date Sample Collected: 6/7/24
Date Results Received: 8/15/24
Date Taken Out of Service: not applicable
Planned Remediation Measure: Hand Wash Only
Date Remediation Taken: 12/15/20

Building: Central Avenue
Sample Number: 104.10-42
Location: Room 131
Fixture/Outlet Type: Sink

Laboratory Analysis (in ppb): 40.2

Date Sample Collected: 6/7/24

Date Results Received: 8/15/24

Date Taken Out of Service: not applicable

Planned Remediation Measure: Hand Wash Only

Date Remediation Taken: 12/15/20