

Rise STEM Academy For Girls



Week Ending October 24, 2025



Rise STEM Academy For Girls

➤ **Work Completed:**

- Continued storm system work.
- Continued storm shelter work.
- Continued masonry work.
- Continued above ceiling work.
- Continued roofing installation.
- Continued site concrete work.
- Continued gyp board installation.
- Continued window glazing installation.
- Continued tile installation.

➤ **Upcoming Work / Look Ahead:**

- Storm system work will continue.
- Storm shelter work will continue.
- Above ceiling work continue.
- Gyp board installation will continue.
- Window glazing installation will continue.
- Tile installation will continue.
- Terrazzo installation will begin.



Rise STEM Academy For Girls

Site Work in Progress



Week Ending October 24, 2025

Rise STEM Academy For Girls

Kitchen Work In Progress



Week Ending October 24, 2025

Rise STEM Academy For Girls


Stud Frame Work In Progress



Week Ending October 24, 2025

Rise STEM Academy For Girls

Paint Work In Progress



Week Ending October 24, 2025

Rise STEM Academy For Girls

Z-Furring Installation in Progress



Week Ending October 24, 2025

Rise STEM Academy For Girls

Exterior Gypsum Work In Progress



Week Ending October 24, 2025

Rise STEM Academy For Girls

Curtainwall Glazing Installation In Progress



Week Ending October 24, 2025



Rise STEM Academy For Girls

Roof Work In Progress



Week Ending October 24, 2025