

Rise STEM Academy For Girls



Week Ending November 7, 2025



Rise STEM Academy For Girls

➤ **Work Completed:**


- Continued storm system work.
- Continued above ceiling work.
- Continued roofing installation.
- Continued site concrete work.
- Continued gyp board installation.
- Continue floor prep for terrazzo.
- Continued tile installation.

➤ **Upcoming Work / Look Ahead:**

- Storm system work will continue.
- Storm shelter work will continue.
- Above ceiling work continue.
- Gyp board installation will continue.
- Window glazing installation will continue.
- Tile installation will continue.
- Terrazzo installation will begin.

Rise STEM Academy For Girls


Mechanical Colset Work In Progress





Rise STEM Academy For Girls


MDF Room Work In Progress



Week Ending November 7, 2025

Rise STEM Academy For Girls


Stud Framing Work In Progress



Week Ending November 7, 2025

Rise STEM Academy For Girls

Tile Work In Progress





Rise STEM Academy For Girls

Above Ceiling Work in Progress



Week Ending November 7, 2025

Rise STEM Academy For Girls

Terrazzo Floor Preparation In Progress



Week Ending November 7, 2025

Rise STEM Academy For Girls

Roof Work In Progress



Week Ending November 7, 2025

Rise STEM Academy For Girls

Site Work In Progress



Week Ending November 7, 2025