

Lead in Drinking Water Report



Date of Sample	Nov. 2023	Feb. 2024	Oct. 2024	Nov. 2024	Final Remediation
Sampled by	WSDOH	Terracon	Terracon	Terracon	
Fixture location	Lead Test Result (ppb)	Lead Test Result (ppb)	Lead Test Result (ppb)	Lead Test Result (ppb)	
Room 11- primary tap	21	7	18	16	Handwashing only
Room 10 - Water fountain	60	42	180	72	Fountain off
Room 10- primary tap	25	15	76	37	Handwashing only
Room 9 - primary tap	N/A	2.9			
Room 9 - coffee maker water dispenser	N/A	3.4			
Staff Lounge - primary tap	N/A	3.2			
Room 13 - Primary tap	10	18	52	49	Handwashing only
Room 12- Primary tap	7	6.6	86	13	Handwashing only
Kitchen - Food Prep Sink	3	2.3			
Hallway outside cafeteria - left water fountain	6	<1.0			
Hallway outside Cafeteria -right water fountain	6	<1.0			
Hallway outside cafeteria - water bottle filler	13	<1.0			
Room 8 - inner classroom, non bathroom/handwashing	<1.0	1.1			

Room 8 Outside left RR (labeled: botys)	N/A	<1.0		
Room 8 -outside right RR	N/A	<1.0		
Room 8 - large RR tap	N/A	<1.0		
Outside Room 8 - closest to hallway	N/A	<1.0		
Outside Room 8- second closest to hallway	N/A	<1.0		
Outside room 8 - closest to exit door	N/A	1.1		
Outside room 8 - second closest to exit door	N/A	<1.0		
Room 1 primary tap	5	3.4		
Room 2 - primary tap	5	1.8		
Room 2 - water fountain	2	<1.0		
Room 7 - primary tap	1	<1.0		
Room 7 - water fountain	<1.0	1		
Room 7 - restroom tap	N/A	2.6		
Room 3 - primary ta	4	2.8		
Room 33 - water fountain	2	1.4		
Room 4- primary tap	5	2.7		
Room 4- water fountain	<1.0	1.7		
Room 5 primary tap	6	9.1	5.3	3.1
Room 5 water fountain	3	<1.0		
Room 6 Primary tap	28	1.9		
Room 6 - water fountain	<1.0	1		
2nd floor hallwya -water fountain	8	24		Fountain Off