

Rise STEM Academy For Girls



Week Ending November 21, 2025



Rise STEM Academy For Girls

➤ **Work Completed:**

- Continued storm system work.
- Continued above ceiling work.
- Continued roofing installation.
- Continued site concrete work.
- Continued gyp board installation.
- Continue floor prep for terrazzo.
- Continued tile installation.
- Canopy structure installation.

➤ **Upcoming Work / Look Ahead:**

- Storm system work will continue.
- Storm shelter work will continue.
- Above ceiling work continue.
- Gyp board installation will continue.
- Window glazing installation will continue.
- Tile installation will continue.
- Terrazzo installation will begin.
- Canopy structure installation will continue.

Rise STEM Academy For Girls

Wall Tile Installation In Progress



Rise STEM Academy For Girls


Drywall Installation In Progress



Week Ending November 21, 2025


Rise STEM Academy For Girls

Terrazzo Work In Progress



Rise STEM Academy For Girls


Above Ceiling Work in Progress



Week Ending November 21, 2025

Rise STEM Academy For Girls

Stud Frame Installation In Progress



Week Ending November 21, 2025

Rise STEM Academy For Girls

Elevator Door Frame Installation In Progress



Week Ending November 21, 2025

Rise STEM Academy For Girls

Canopy Steel Structure Installation In Progress



Week Ending November 21, 2025

Rise STEM Academy For Girls

Site Work In Progress



Week Ending November 21, 2025