

Lead in School Drinking Water Report

Delta High School



EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: leadfreekids@doh.wa.gov.

DEFINITIONS

Fixture Housing
Location

Room/space where
fixture is located
(i.e. room number,
gym, playground)

Fixture Housing Type

Structure that contains
the individual fixtures
where water samples
were collected from.
Fixture housing may
contain one or more
individual fixture for
sampling.

Fixture Location
Details

Location within a
room or space where
fixture housing is
located, starting to the
left of the entrance and
rotating clockwise, of
the total number of
fixture housings in a
room or space
(e.g. 1/5, 2/5)

Fixture Type

Tap, Sprayer, Water
Fountain, Water Bottle
Filler, Ice maker

Fixture Position

Left, Center, Right

Date(s) collected: 2025-04-09

Date(s) analyzed: 2025-04-17, 2025-05-05

.	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	388942	Main Building	Ice Machine	Staff Lounge	2 of 2 fridge		center	<1
2	388944	Main Building	Sink	Nurse Room	1 of 1	Tap	center	<1
3	388946	Main Building	Sink	Nurse Room	1 of 1	Sprayer	right	<1
4	388948	Main Building	Fountain - Multi-Level with Bottle Filler	Main Hallway Outside Restroom	1 of 1	Water Fountain	left	<1
5	388950	Main Building	Fountain - Multi-Level with Bottle Filler	Main Hallway Outside Restrooms	1 of 1	Water Fountain	right	<1
6	388952	Main Building	Fountain - Multi-Level with Bottle Filler	Main Hallway Outside Restrooms	1 of 1	Water Bottle Filler	center	<1
7	388954	Main Building	Sink	Kitchen	1 of 7	Sprayer	center	<1
8	388956	Main Building	Sink - Multi-Compartment	Kitchen	3 of 7	Tap	left	<1
9	388958	Main Building	Sink - Multi-Compartment	Kitchen	3 of 7	Sprayer	right	<1
10	388960	Main Building	Sink - Multi-Compartment	Kitchen	6 of 7	Tap	center	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
11	388962	Main Building	Pot Filler	Kitchen	7 of 7	Tap	center	<1
12	388964	Main Building	Fountain - Multi-Level with Bottle Filler	Cafeteria	1 of 1	Water Fountain	left	<1
13	388966	Main Building	Fountain - Multi-Level with Bottle Filler	Cafeteria	1 of 1	Water Fountain	right	<1
14	388968	Main Building	Fountain - Multi-Level with Bottle Filler	Cafeteria	1 of 1	Water Bottle Filler	center	<1
15	388970	Main Building	Fountain - Multi-Level with Bottle Filler	Main Hallway South	1 of 1	Water Fountain	left	<1
16	388972	Main Building	Fountain - Multi-Level with Bottle Filler	Main Hallway South	1 of 1	Water Fountain	right	<1
17	388974	Main Building	Fountain - Multi-Level with Bottle Filler	Main Hallway South	1 of 1	Water Bottle Filler	center	<1
18	388976	Main Building	Fountain - Multi-Level with Bottle Filler	Main Hallway East	1 of 1	Water Fountain	left	<1
19	388977	Main Building	Sink - Multi-Compartment	Staff Lounge	1 of 2	Tap	center	<1

.	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
20	388978	Main Building	Fountain - Multi-Level with Bottle Filler	Main Hallway East	1 of 1	Water Fountain	right	<1
21	388979	Main Building	Sink - Multi-Compartment	Staff Lounge	1 of 2	Sprayer	right	<1
22	389706	Main Building	Fountain - Multi-Level with Bottle Filler	Main Hallway East	1 of 1	Water Bottle Filler	center	<1