

Lead in School Drinking Water Report

Chiawana High School



EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: leadfreekids@doh.wa.gov.

DEFINITIONS

Fixture Housing
Location

Room/space where
fixture is located
(i.e. room number,
gym, playground)

Fixture Housing Type

Structure that contains
the individual fixtures
where water samples
were collected from.
Fixture housing may
contain one or more
individual fixture for
sampling.

Fixture Location
Details

Location within a
room or space where
fixture housing is
located, starting to the
left of the entrance and
rotating clockwise, of
the total number of
fixture housings in a
room or space
(e.g. 1/5, 2/5)

Fixture Type

Tap, Sprayer, Water
Fountain, Water Bottle
Filler, Ice maker

Fixture Position

Left, Center, Right

Date(s) collected: 2025-04-16, 2025-04-23

Date(s) analyzed: 2025-05-01, 2025-07-10, 2025-07-14

.	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	372002	Main Building	Ice Machine	Rm 1103a Lower D Staff	2 of 2	Ice Machine	center	12
2	389597	Main Building	Ice Machine	Rm 1115	1 of 1 fridge	Ice Machine	center	11
3	389595	Main Building	Sink - Multi-Compartment	Lower C Wing Staff Lounge	2 of 2	Sprayer	right	8
4	389605	Main Building	Sink - Multi-Compartment	D Wing Staff Lounge	2 of 2	Sprayer	right	6
5	371981	Main Building	Sink - Multi-Compartment	2017c	2 of 2	Sprayer	right	5
6	371995	Main Building	Sink - Multi-Compartment	2043 C Upper C Wing Staff	2 of 2	Sprayer	right	5
7	372039	Main Building	Sink - Multi-Compartment	1075	2 of 2	Sprayer	right	5
8	373259	Main Building	Sink	Kitchen	8 of 10	Sprayer	left	5
9	389599	Main Building	Ice Machine	Rm 1030	1 of 1		center	5
10	371980	Main Building	Sink	Rm 1004 Prep	1 of 2	Tap	center	4
11	373193	Main Building	Sink - Multi-Compartment	Main Office Staff Lounge	2 of 2	Sprayer	center	4

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
12	373253	Main Building	Sink - Multi-Compartment	Kitchen	6 of 10	Tap	center	4
13	372025	Main Building	Sink	1135	11 of 12	Tap	center	3
14	372031	Main Building	Sink	1132	2 of 3	Tap	center	3
15	373250	Main Building	Pot Filler	Kitchen	9 of 10	Tap	left	3
16	373254	Main Building	Pot Filler	Kitchen	10 of 10	Tap	right	3
17	371990	Main Building	Ice Machine	Rm 1025	3 of 3 fridge	Ice Machine	center	2
18	371997	Main Building	Ice Machine	Rm 2048-2050 Science Prep	1 of 1 fridge	Ice Machine	center	2
19	372027	Main Building	Sink	1135	12 of 12	Tap	center	2
20	372029	Main Building	Sink	1132	1 of 3	Tap	center	2
21	372041	Main Building	Sink - Multi-Compartment	1065	1 of 3	Tap	center	2
22	373185	Main Building	Sink - Multi-Compartment	Athletics 1195	2 of 2	Sprayer	center	2
23	373189	Main Building	Ice Machine	1164 Sick Room	3 of 3	Ice Machine	right	2
24	373207	Main Building	Sink	1135	2 of 12	Tap	center	2
25	373209	Main Building	Sink	1135	3 of 12	Tap	center	2
26	373252	Main Building	Pot Filler	Kitchen	9 of 10	Sprayer	left	2

.	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
27	373255	Main Building	Sink - Multi-Compartment	Kitchen	6 of 10	Sprayer	left	2
28	373256	Main Building	Pot Filler	Kitchen	10 of 10	Sprayer	right	2
29	389601	Main Building	Ice Machine	D Wing Staff Lounge	1 of 2 fridge	Ice Machine	center	2
30	372000	Main Building	Sink - Multi-Compartment	Rm 1103a Lower D Staff	1 of 2	Sprayer	right	1
31	372007	Main Building	Sink - Multi-Compartment	2071c Upper B Staff	2 of 2	Sprayer	right	1
32	372035	Main Building	Ice Machine	1075	1 of 2	Ice Machine	left	1
33	373187	Main Building	Sink - Multi-Compartment	1164 Sick Room	1 of 3	Tap	center	1
34	373190	Main Building	Sink - Multi-Compartment	1252	1 of 2	Tap	center	1
35	373211	Main Building	Sink	1135	4 of 12	Tap	center	1
36	373213	Main Building	Sink	1135	5 of 12	Tap	center	1
37	373215	Main Building	Sink	1135	6 of 12	Tap	center	1
38	373217	Main Building	Sink	1135	7 of 12	Tap	center	1
39	373249	Main Building	Sink	Kitchen	2 of 10	Tap	center	1
40	373251	Main Building	Sink	Kitchen	2 of 10	Sprayer	left	1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
41	373258	Main Building	Sink	Main Gym Concessions	1 of 1	Tap	center	1
42	389591	Main Building	Ice Machine	Lower C Wing Staff Lounge	1 of 2 fridge	Ice Machine	center	1
43	371982	Main Building	Sink - Multi-Compartment	Rm 1004 Prep	2 of 2	Tap	center	<1
44	371983	Main Building	Sink - Multi-Compartment	2097c	1 of 2	Tap	center	<1
45	371984	Main Building	Sink - Multi-Compartment	Rm 1002	1 of 1	Tap	center	<1
46	371985	Main Building	Sink - Multi-Compartment	2097c	1 of 2	Sprayer	right	<1
47	371986	Main Building	Sink - Multi-Compartment	Rm 1025	1 of 3	Tap	center	<1
48	371987	Main Building	Ice Machine	2097c	2 of 2	Ice Machine	center	<1
49	371988	Main Building	Sink - Multi-Compartment	Rm 1025	2 of 3	Tap	center	<1
50	371989	Main Building	Ice Machine	2106a	1 of 1 fridge	Ice Machine	center	<1
51	371991	Main Building	Ice Machine	2043 C Upper C Wing Staff	1 of 2	Ice Machine	center	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
52	371992	Main Building	Ice Machine	Rm 1026	1 of 2 fridge	Ice Machine	center	<1
53	371993	Main Building	Sink - Multi-Compartment	2043 C Upper C Wing Staff	2 of 2	Tap	center	<1
54	371994	Main Building	Sink - Multi-Compartment	Rm 1026	2 of 2	Tap	center	<1
55	371996	Main Building	Sink - Multi-Compartment	Rm 1028	1 of 1	Tap	center	<1
56	371998	Main Building	Sink - Multi-Compartment	Rm 1103a Lower D Staff	1 of 2	Tap	center	<1
57	371999	Main Building	Fountain - Multi-Level with Bottle Filler	Upper C Wing Student Restrooms	1 of 1 bottle filler off	Water Fountain	left	<1
58	372001	Main Building	Fountain - Multi-Level with Bottle Filler	Upper C Wing Student Restrooms	1 of 1 bottle filler off	Water Fountain	right	<1
59	372003	Main Building	Ice Machine	2071c Upper B Staff	1 of 2 fridge	Ice Machine	center	<1
60	372004	Main Building	Fountain - Multi-Level with Bottle Filler	Lower D Wing Student Restrooms	1 of 1	Water Fountain	left	<1
61	372005	Main Building	Sink - Multi-Compartment	2071c Upper B Staff	2 of 2	Tap	center	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
62	372006	Main Building	Fountain - Multi-Level with Bottle Filler	Lower D Wing Student Restrooms	1 of 1	Water Fountain	right	<1
63	372008	Main Building	Fountain - Multi-Level with Bottle Filler	Lower D Wing Student Restrooms	1 of 1	Water Bottle Filler	center	<1
64	372009	Main Building	Fountain - Multi-Level with Bottle Filler	Upper B Student Restrooms	1 of 1	Water Fountain	left	<1
65	372010	Main Building	Sink	Rm 1109	1 of 1	Tap	center	<1
66	372011	Main Building	Fountain - Multi-Level with Bottle Filler	Upper B Student Restrooms	1 of 1	Water Fountain	right	<1
67	372012	Main Building	Fountain - Multi-Level with Bottle Filler	Upper D Wing Student Restrooms	1 of 1	Water Fountain	left	<1
68	372013	Main Building	Fountain - Multi-Level with Bottle Filler	Upper B Student Restrooms	1 of 1	Water Bottle Filler	center	<1
69	372014	Main Building	Fountain - Multi-Level with Bottle Filler	Upper D Wing Student Restrooms	1 of 1	Water Fountain	right	<1
70	372015	Main Building	Fountain	Track Drink Fountain	1 of 1	Water Fountain	center	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
71	372016	Main Building	Fountain - Multi-Level with Bottle Filler	Upper D Wing Student Restrooms	1 of 1	Water Bottle Filler	center	<1
72	372018	Main Building	Sink - Multi-Compartment	2017c	2 of 2	Tap	center	<1
73	372021	Main Building	Sink	1135	9 of 12	Tap	center	<1
74	372023	Main Building	Sink	1135	10 of 12	Tap	center	<1
75	372033	Main Building	Sink	1132	3 of 3	Tap	center	<1
76	372037	Main Building	Sink - Multi-Compartment	1075	2 of 2	Tap	left	<1
77	372043	Main Building	Ice Machine	1065	2 of 3	Ice Machine	center	<1
78	372045	Main Building	Sink - Multi-Compartment	1065	3 of 3	Tap	center	<1
79	373180	Main Building	Fountain - Multi-Level with Bottle Filler	Main Gym Hallway	1 of 1	Water Fountain	left	<1
80	373181	Main Building	Sink - Multi-Compartment	1220-Storage	1 of 1	Tap	center	<1
81	373182	Main Building	Fountain - Multi-Level with Bottle Filler	Main Gym Hallway	1 of 1	Water Fountain	right	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
82	373183	Main Building	Sink - Multi-Compartment	Athletics 1195	2 of 2 ice maker off	Tap	center	<1
83	373184	Main Building	Fountain - Multi-Level with Bottle Filler	Main Gym Hallway	1 of 1	Water Bottle Filler	center	<1
84	373186	Main Building	Fountain	1265 Varsity Girls Locker Room	1 of 1	Water Fountain	center	<1
85	373188	Main Building	Fountain	1260 Girl Locker Rm	1 of 1	Water Fountain	center	<1
86	373191	Main Building	Sink - Multi-Compartment	Main Office Staff Lounge	2 of 2 fridge ice maker off	Tap	center	<1
87	373192	Main Building	Ice Machine	1252	2 of 2	Ice Machine	center	<1
88	373194	Main Building	Fountain - Multi-Level with Bottle Filler	Hallway Next To Cardio Lab	1 of 1	Water Fountain	left	<1
89	373195	Main Building	Sink	1152 Art	1 of 1	Tap	center	<1
90	373196	Main Building	Fountain - Multi-Level with Bottle Filler	Hallway Next To Cardio Lab	1 of 1	Water Fountain	right	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
91	373197	Main Building	Fountain - Multi-Level	1143 Band	1 of 1	Water Fountain	left	<1
92	373198	Main Building	Fountain - Multi-Level with Bottle Filler	Hallway Next To Cardio Lab	1 of 1	Water Bottle Filler	center	<1
93	373199	Main Building	Fountain - Multi-Level	1143 Band	1 of 1	Water Fountain	right	<1
94	373200	Main Building	Fountain	1268 Boys Locker Room	1 of 1	Water Fountain	center	<1
95	373201	Main Building	Fountain - Multi-Level	1136 Choir	1 of 1	Water Fountain	left	<1
96	373202	Main Building	Fountain	1273 Varsity Boys	1 of 1	Water Fountain	center	<1
97	373203	Main Building	Fountain - Multi-Level	1136 Choir	1 of 1	Water Fountain	right	<1
98	373204	Main Building	Fountain - Multi-Level	1283	1 of 1	Water Fountain	left	<1
99	373205	Main Building	Sink	1135	1 of 12	Tap	center	<1
100	373206	Main Building	Fountain - Multi-Level	1283	1 of 1	Water Fountain	right	<1
101	373208	Main Building	Fountain - Multi-Level with Bottle Filler	1279	1 of 1	Water Fountain	left	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
102	373210	Main Building	Fountain - Multi-Level with Bottle Filler	1279	1 of 1	Water Fountain	right	<1
103	373212	Main Building	Fountain - Multi-Level with Bottle Filler	1279	1 of 1	Water Bottle Filler	center	<1
104	373214	Main Building	Sink - Multi-Compartment	Student Store	1 of 3	Tap	center	<1
105	373216	Main Building	Sink - Multi-Compartment	Student Store	1 of 3	Sprayer	center	<1
106	373218	Main Building	Ice Machine	Student Store	3 of 3		center	<1
107	373219	Main Building	Sink	1135	8 of 12	Tap	center	<1
108	373257	Main Building	Sink	Kitchen	8 of 10	Tap	center	<1
109	389581	Main Building	Fountain - Multi-Level with Bottle Filler	Lower B Wing Student Restrooms	1 of 1	Water Fountain	right	<1
110	389583	Main Building	Fountain - Multi-Level with Bottle Filler	Lower B Wing Student Restrooms	1 of 1	Water Bottle Filler	center	<1
111	389585	Main Building	Fountain - Multi-Level with Bottle Filler	Lower C Wing Student Restrooms	1 of 1	Water Fountain	left	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
112	389587	Main Building	Fountain - Multi-Level with Bottle Filler	Lower C Wing Student Restrooms	1 of 1	Water Fountain	right	<1
113	389589	Main Building	Fountain - Multi-Level with Bottle Filler	Lower C Wing Student Restrooms	1 of 1	Water Bottle Filler	center	<1
114	389593	Main Building	Sink - Multi-Compartment	Lower C Wing Staff Lounge	2 of 2	Tap	left	<1
115	389603	Main Building	Sink - Multi-Compartment	D Wing Staff Lounge	2 of 2	Tap	left	<1
116	389607	Main Building	Sink - Multi-Compartment	Rm 1004	1 of 7	Tap	center	<1
117	389609	Main Building	Sink - Multi-Compartment	Rm 1004	2 of 7	Tap	center	<1
118	389611	Main Building	Sink - Multi-Compartment	Rm 1004	3 of 7	Tap	center	<1
119	389613	Main Building	Sink - Multi-Compartment	Rm 1004	4 of 7	Tap	center	<1
120	389615	Main Building	Sink - Multi-Compartment	Rm 1004	5 of 7	Tap	center	<1
121	389617	Main Building	Sink - Multi-Compartment	Rm 1004	6 of 7	Tap	center	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
122	389618	Main Building	Fountain - Multi-Level with Bottle Filler	Lower B Wing Student Restrooms	1 of 1	Water Fountain	left	<1
123	389619	Main Building	Sink - Multi-Compartment	Rm 1004	7 of 7	Tap	center	<1