

Lead in School Drinking Water Report

Mcloughlin Middle School



EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: leadfreekids@doh.wa.gov.

DEFINITIONS

Fixture Housing
Location

Room/space where
fixture is located
(i.e. room number,
gym, playground)

Fixture Housing Type

Structure that contains
the individual fixtures
where water samples
were collected from.
Fixture housing may
contain one or more
individual fixture for
sampling.

Fixture Location
Details

Location within a
room or space where
fixture housing is
located, starting to the
left of the entrance and
rotating clockwise, of
the total number of
fixture housings in a
room or space
(e.g. 1/5, 2/5)

Fixture Type

Tap, Sprayer, Water
Fountain, Water Bottle
Filler, Ice maker

Fixture Position

Left, Center, Right

Date(s) collected: 2025-05-21

Date(s) analyzed: 2025-06-05, 2025-06-06, 2025-06-16

.	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	372146	Main Building	Sink	Rm 137	1 of 1	Tap	center	53
2	372211	Main Building	Sink	Rm 87	4 of 4	Tap	center	53
3	372191	Main Building	Sink	Rm 89	1 of 1	Tap	center	18
4	372193	Main Building	Sink - Multi-Compartment	Rm 87	1 of 4	Tap	left	7
5	372197	Main Building	Sink - Multi-Compartment	Rm 87	1 of 4 right center	Tap	right	6
6	372213	Main Building	Sink - Multi-Compartment	Rm 68a Technology	1 of 2	Tap	center	5
7	372195	Main Building	Sink - Multi-Compartment	Rm 87	1 of 4 left center	Tap	left	4
8	372199	Main Building	Sink - Multi-Compartment	Rm 87	1 of 4	Tap	right	4
9	372171	Main Building	Sink	Rm 185	1 of 1	Tap	center	3
10	372186	Main Building	Pot Filler	Kitchen	4 of 4	Tap	center	3
11	372169	Main Building	Fountain	Hallway Across From Rm 187	1 of 1	Water Fountain	center	2

.	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
12	372196	Main Building	Sink	Nurse Office	1 of 1	Tap	center	2
13	372203	Main Building	Sink - Multi-Compartment	Rm 87	2 of 4	Tap	left	2
14	372209	Main Building	Sink - Multi-Compartment	Rm 87	2 of 4	Tap	right	2
15	372215	Main Building	Sink	Rm 70 Art	1 of 4	Tap	left	2
16	372205	Main Building	Sink - Multi-Compartment	Rm 87	2 of 4 left center	Tap	left	1
17	372207	Main Building	Sink - Multi-Compartment	Rm 87	2 of 4 right center	Tap	right	1
18	372140	Main Building	Fountain - Multi-Level with Bottle Filler	Downstairs Hallway Across From Girls Restroom	1 of 1	Water Fountain	right	<1
19	372141	Main Building	Sink	Rm 70 Art	2 of 4	Tap	right	<1
20	372142	Main Building	Fountain - Multi-Level with Bottle Filler	Downstairs Hallway Across From Girls Restroom	1 of 1	Water Bottle Filler	left	<1
21	372143	Main Building	Sink	Rm 70 Art	3 of 4	Tap	center	<1
22	372144	Main Building	Sink	Rm 140	1 of 1	Tap	center	<1
23	372145	Main Building	Sink	Rm 70 Art	4 of 4	Tap	center	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
24	372147	Main Building	Fountain	Gym Hallway Between Restrooms	1 of 1	Water Fountain	center	<1
25	372148	Main Building	Fountain	Hallway Outside Library	1 of 1	Water Fountain	center	<1
26	372149	Main Building	Fountain	Gym Hallway Between 39 And 50	1 of 1	Water Fountain	center	<1
27	372151	Main Building	Sink	Rm 50	1 of 1	Tap	center	<1
28	372153	Main Building	Ice Machine	Rm 48 Storage	1 of 1		center	<1
29	372155	Main Building	Fountain	Gym	1 of 3	Water Fountain	center	<1
30	372157	Main Building	Fountain	Gym	2 of 3	Water Fountain	center	<1
31	372159	Main Building	Fountain	Gym	3 of 3	Water Fountain	center	<1
32	372161	Main Building	Fountain	Boys Locker Room	1 of 1	Water Fountain	center	<1
33	372163	Main Building	Fountain	Girls Locker Room	1 of 1	Water Fountain	center	<1
34	372165	Main Building	Sink	Rm 190	1 of 1	Tap	center	<1
35	372167	Main Building	Sink - Multi-Compartment	Rm 189	1 of 1	Tap	center	<1
36	372173	Main Building	Fountain - Multi-Level with Bottle Filler	Upstairs Hallway Across From Boys Restroom	1 of 1	Water Fountain	left	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
37	372175	Main Building	Fountain - Multi-Level with Bottle Filler	Upstairs Hallway Across From Boys Restroom	1 of 1	Water Fountain	right	<1
38	372177	Main Building	Fountain - Multi-Level with Bottle Filler	Upstairs Hallway Across From Boys Restroom	1 of 1	Water Bottle Filler	left	<1
39	372179	Main Building	Fountain - Multi-Level with Bottle Filler	Downstairs Hallway Across From Girls Restroom	1 of 1	Water Fountain	left	<1
40	372180	Main Building	Sink - Multi-Compartment	Kitchen	3 of 4	Tap	left	<1
41	372181	Main Building	Sink	Rm 88	4 of 8	Tap	center	<1
42	372182	Main Building	Sink - Multi-Compartment	Kitchen	3 of 4	Tap	right	<1
43	372183	Main Building	Sink	Rm 88	5 of 8	Tap	center	<1
44	372184	Main Building	Sink - Multi-Compartment	Kitchen	3 of 4	Sprayer	right	<1
45	372185	Main Building	Sink	Rm 88	6 of 8	Tap	center	<1
46	372187	Main Building	Sink	Rm 88	7 of 8	Tap	center	<1
47	372188	Main Building	Pot Filler	Kitchen	4 of 4	Sprayer	right	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
48	372189	Main Building	Sink	Rm 88	8 of 8 teacher station	Tap	center	<1
49	372190	Main Building	Fountain - Multi-Level with Bottle Filler	Cafeteria	1 of 1	Water Fountain	left	<1
50	372192	Main Building	Fountain - Multi-Level with Bottle Filler	Cafeteria	1 of 1	Water Fountain	right	<1
51	372194	Main Building	Fountain - Multi-Level with Bottle Filler	Cafeteria	1 of 1	Water Bottle Filler	right	<1
52	372198	Main Building	Fountain	Across 103	1 of 1	Water Fountain	center	<1
53	372200	Main Building	Sink	107	1 of 1	Tap	center	<1
54	372201	Main Building	Sink - Multi-Compartment	Rm 87	1 of 4	Water Fountain	right	<1
55	372202	Main Building	Sink	Staff Lounge 109	1 of 1	Tap	center	<1
56	372204	Main Building	Sink	Rm 88	1 of 8	Tap	center	<1
57	372206	Main Building	Sink	Rm 88	2 of 8	Tap	center	<1
58	372208	Main Building	Sink	Rm 88	3 of 8	Tap	center	<1
59	372217	Main Building	Sink	Rm 70 Art	1 of 4	Tap	right	<1

.	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
60	372219	Main Building	Sink	Rm 70 Art	2 of 4	Tap	left	<1