

Lead in Drinking Water Report Kulshan Middle School



Date of Sample			11/21/2023	
Sampled by			Washington State Department of Health	
Sample ID	Fixture Location	Fixture Type	Lead Test Result (ppb)	Final Remediation
386193	Kitchen	Sink	8	Washing only sign
386194	Kitchen	Sink - Multi-compartment	2	
386195	Kitchen	Sink	10	Washing only sign
386196	Band room	Fountain/Tap Combo	<1	
386197	Band room	Fountain/Tap Combo	<1	
386198	Wood shop	Sink	3	
386199	Wood shop	Sink	5	
386200	Hallway	Fountain	<1	
386201	Art room	Sink	1	
386202	Cafeteria	Fountain - Multi-level with Bottle Filler	<1	
386203	Cafeteria	Fountain - Multi-level with Bottle Filler	<1	
386204	Rm111	Sink	4	
386205	Common area	Fountain	<1	
386206	Rm107	Sink	<1	
386207	Mail room	Sink	2	
386208	Rm203	Fountain/Tap Combo	2	

386209	Rm203	Fountain/Tap Combo	3	
386210	Rm208	Fountain/Tap Combo	3	
386211	Rm208	Fountain/Tap Combo	2	
386212	Rm207	Fountain/Tap Combo	<1	
386213	Rm207	Fountain/Tap Combo	<1	
386214	Rm204	Fountain/Tap Combo	1	
386215	Rm204	Fountain/Tap Combo	1	
386216	Hallway	Fountain	<1	
386217	Rm205	Fountain/Tap Combo	<1	
386218	Rm205	Fountain/Tap Combo	1	
386219	Rm206	Fountain/Tap Combo	<1	
386340	Rm202	Fountain/Tap Combo	2	
386341	Rm202	Fountain/Tap Combo	1	
386342	Rm209	Fountain/Tap Combo	1	
386343	Rm209	Fountain/Tap Combo	2	
386344	Rm301	Sink - Multi-compartment	3	
386345	Rm301	Sink - Multi-compartment	2	
386346	Rm301	Sink - Multi-compartment	4	
386347	Rm301	Sink - Multi-compartment	12	Washing only sign
386348	Rm301	Sink - Multi-compartment	<1	
386349	Rm301	Sink - Multi-compartment	<1	
386350	Rm301	Sink	3	
386351	Rm302	Sink	<1	
386352	Rm302	Sink	<1	
386353	Hallway	Fountain - Multi-level with Bottle Filler	<1	
386354	Hallway	Fountain - Multi-level with Bottle Filler	<1	
386355	Library	Sink	7	Handwashing only sign
386356	Hallway-Gym	Fountain - Multi-level with Bottle Filler	<1	
386357	Hallway-Gym	Fountain - Multi-level with Bottle Filler	<1	