

Lead in School Drinking Water Report

Lynnwood High School - Corrected



EXPLANATION OF TESTING AND RESULTS

Results in this report represent sampling conducted by Washington State Department of Health (DOH). Per [RCW 28A.210.410](#) sampling and testing protocols, samples were collected as first-draw. Depending on size of the school(s) and number of drinking water fixtures, multiple dates for collecting samples may have been necessary to meet sampling and testing protocols.

[RCW 28A.210.410](#) does not require remediation for fixtures testing at 5 ppb and under. DOH offers post-remediation testing only for outlets that initially tested above 5 ppb. After a school completes remediation, DOH will provide up to two post-remediation sampling visits. If after the second post-remediation sampling, outlets test above 5 ppb, the district will be responsible for finding a contractor to conduct additional sampling and testing. For questions regarding sampling, testing, and results, please email: leadfreekids@doh.wa.gov.

DEFINITIONS

Fixture Housing
Location

Room/space where
fixture is located
(i.e. room number,
gym, playground)

Fixture Housing Type

Structure that contains
the individual fixtures
where water samples
were collected from.
Fixture housing may
contain one or more
individual fixture for
sampling.

Fixture Location
Details

Location within a
room or space where
fixture housing is
located, starting to the
left of the entrance and
rotating clockwise, of
the total number of
fixture housings in a
room or space
(e.g. 1/5, 2/5)

Fixture Type

Tap, Sprayer, Water
Fountain, Water Bottle
Filler, Ice maker

Fixture Position

Left, Center, Right

Date(s) collected: 2025-09-27

Date(s) analyzed: 2025-10-07

.	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
1	412035	Unit A - Main Building	Sink	Ne 107	1 of 1	Tap	center	11
2	412058	Unit A - Main Building	Sink	Nw131a	1 of 1	Tap	center	9
3	412079	Unit A - Main Building	Sink	Nw243	1 of 1	Tap	center	7
4	412043	Unit A - Main Building	Fountain/Tap Combo	Ne122	1 of 1	Tap	center	6
5	412031	Unit A - Main Building	Sink	Se141	1 of 1	Tap	center	5
6	412038	Unit A - Main Building	Sink	Ne115	1 of 1	Tap	center	5
7	412047	Unit A - Main Building	Sink	Ne132	3 of 3 right	Tap	center	5
8	412029	Unit A - Main Building	Sink	Se151	1 of 1	Tap	center	4
9	412037	Unit A - Main Building	Sink	Ne111	2 of 2 right	Tap	center	4
10	412048	Unit A - Main Building	Sink	Ne136	1 of 3 left	Tap	center	4

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
11	412061	Unit A - Main Building	Sink	Nw110 Commons	1 of 1	Tap	center	4
12	412082	Unit A - Main Building	Sink	Se220 Commons	1 of 1	Tap	center	4
13	412083	Unit A - Main Building	Sink	Se217	1 of 1	Tap	center	4
14	412018	Unit A - Main Building	Pot Filler	Kitchen	2 of 5 left	Tap	center	3
15	412032	Unit A - Main Building	Sink	Se144	1 of 1	Tap	center	3
16	412036	Unit A - Main Building	Sink	Ne111	1 of 2 left	Tap	center	3
17	412045	Unit A - Main Building	Sink	Ne132	1 of 3 left	Tap	center	3
18	412046	Unit A - Main Building	Sink	Ne132	2 of 3 center	Tap	center	3
19	412019	Unit A - Main Building	Pot Filler	Kitchen	2 of 5 left	Sprayer	center	2
20	412020	Unit A - Main Building	Pot Filler	Kitchen	3 of 5 right	Tap	center	2
21	412021	Unit A - Main Building	Pot Filler	Kitchen	3 of 5 right	Sprayer	center	2

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
22	412025	Unit A - Main Building	Sink - Multi-Compartment	Control Workroom	1 of 1	Tap	center	2
23	412041	Unit A - Main Building	Fountain/Tap Combo	Ne118	1 of 1	Tap	center	2
24	412044	Unit A - Main Building	Fountain/Tap Combo	Ne122	1 of 1	Water Fountain	right	2
25	412051	Unit A - Main Building	Sink	Ne137	1 of 2 left	Tap	center	2
26	412056	Unit A - Main Building	Sink	Nw131	2 of 3 center	Tap	center	2
27	412071	Unit A - Main Building	Sink	Nw240	1 of 1	Tap	center	2
28	412081	Unit A - Main Building	Sink - Multi-Compartment	Se231	2 of 2 right	Tap	center	2
29	412084	Unit A - Main Building	Sink	Se210 Commons	1 of 1	Tap	center	2
30	412017	Unit A - Main Building	Sink	Kitchen	1 of 5 north wall	Sprayer	center	1
31	412022	Unit A - Main Building	Sink - Multi-Compartment	Kitchen	4 of 5 veggie prep	Tap	center	1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
32	412030	Unit A - Main Building	Sink	Se110 Commons	1 of 1	Tap	center	1
33	412033	Unit A - Main Building	Sink	Se120	1 of 1	Tap	center	1
34	412039	Unit A - Main Building	Fountain - Multi-Level	Right Of Ne115	1 of 1	Water Fountain	left	1
35	412040	Unit A - Main Building	Fountain - Multi-Level	Right Of Ne115	1 of 1	Water Fountain	right	1
36	412049	Unit A - Main Building	Sink	Ne136	2 of 3 center	Tap	center	1
37	412059	Unit A - Main Building	Sink	Nw120 Commons	1 of 1	Tap	center	1
38	412060	Unit A - Main Building	Sink	Nw140	1 of 1	Tap	center	1
39	412070	Unit A - Main Building	Sink	Nw210 Commons	1 of 1	Tap	center	1
40	412072	Unit A - Main Building	Sink	Nw220 Commons	1 of 1	Tap	center	1
41	412080	Unit A - Main Building	Sink - Multi-Compartment	Se231	1 of 2 left	Tap	center	1
42	412089	Unit A - Main Building	Sink	Library Workroom	1 of 1	Tap	center	1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
43	412008	Unit A - Main Building	Fountain	Girl's Locker Room	1 of 1	Water Fountain	center	<1
44	412009	Unit A - Main Building	Fountain	Boys Locker Room	1 of 1	Water Fountain	center	<1
45	412010	Unit A - Main Building	Sink	Training Room	1 of 1	Tap	center	<1
46	412011	Unit A - Main Building	Fountain	Right Of Activity Room	1 of 1	Water Fountain	center	<1
47	412012	Unit A - Main Building	Fountain	Gym	1 of 2 by AV storage	Water Fountain	center	<1
48	412013	Unit A - Main Building	Fountain	Gym	2 of 2 by agora	Water Fountain	center	<1
49	412014	Unit A - Main Building	Sink	Concessions	1 of 1	Tap	center	<1
50	412015	Unit A - Main Building	Sink	Asb Workroom	1 of 1	Tap	center	<1
51	412016	Unit A - Main Building	Sink	Kitchen	1 of 5 north wall	Tap	center	<1
52	412023	Unit A - Main Building	Sink - Multi-Compartment	Kitchen	4 of 5 veggie prep	Sprayer	center	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
53	412024	Unit A - Main Building	Ice Machine	Kitchen	5 of 5	Ice Machine	center	<1
54	412026	Unit A - Main Building	Fountain - Multi-Level with Bottle Filler	Left Of Se136	1 of 1	Water Fountain	left	<1
55	412027	Unit A - Main Building	Fountain - Multi-Level with Bottle Filler	Left Of Se136	1 of 1	Water Fountain	right	<1
56	412028	Unit A - Main Building	Fountain - Multi-Level with Bottle Filler	Left Of Se136	1 of 1	Water Bottle Filler	right	<1
57	412034	Unit A - Main Building	Sink	Student Store	1 of 1	Tap	center	<1
58	412042	Unit A - Main Building	Fountain/Tap Combo	Ne118	1 of 1	Water Fountain	right	<1
59	412050	Unit A - Main Building	Sink	Ne136	3 of 3 right	Tap	center	<1
60	412052	Unit A - Main Building	Sink - Multi-Compartment	Ne137	2 of 2 right	Tap	center	<1
61	412053	Unit A - Main Building	Fountain - Multi-Level	Right Of Nw134	1 of 1	Water Fountain	left	<1
62	412054	Unit A - Main Building	Fountain - Multi-Level	Right Of Nw134	1 of 1	Water Fountain	right	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
63	412055	Unit A - Main Building	Sink	Nw131	1 of 3 left	Tap	center	<1
64	412057	Unit A - Main Building	Sink	Nw131	3 of 3 right	Tap	center	<1
65	412062	Unit A - Main Building	Sink - Multi-Compartment	Nw144	1 of 8	Tap	center	<1
66	412063	Unit A - Main Building	Sink - Multi-Compartment	Nw144	2 of 8	Tap	center	<1
67	412064	Unit A - Main Building	Sink - Multi-Compartment	Nw144	3 of 8	Tap	center	<1
68	412065	Unit A - Main Building	Sink - Multi-Compartment	Nw144	4 of 8	Tap	center	<1
69	412066	Unit A - Main Building	Sink - Multi-Compartment	Nw144	5 of 8	Tap	center	<1
70	412067	Unit A - Main Building	Sink - Multi-Compartment	Nw144	6 of 8	Tap	center	<1
71	412068	Unit A - Main Building	Sink - Multi-Compartment	Nw144	7 of 8	Tap	center	<1
72	412069	Unit A - Main Building	Ice Machine	Nw144	8 of 8	Ice Machine	center	<1
73	412073	Unit A - Main Building	Fountain - Multi-Level	Between Nw230-231	1 of 1	Water Fountain	left	<1

	Sample ID	Building Name	Fixture Housing Type	Fixture Location	Fixture Location Details	Fixture Type	Fixture Position	Lead Test Result (ppb)
74	412074	Unit A - Main Building	Fountain - Multi-Level	Between Nw230-231	1 of 1	Water Fountain	right	<1
75	412075	Unit A - Main Building	Fountain - Multi-Level	Outside Nw243	1 of 1	Water Fountain	left	<1
76	412076	Unit A - Main Building	Fountain - Multi-Level	Outside Nw243	1 of 1	Water Fountain	right	<1
77	412077	Unit A - Main Building	Fountain - Multi-Level	Left Of Ne213	1 of 1	Water Fountain	left	<1
78	412078	Unit A - Main Building	Fountain - Multi-Level	Left Of Ne213	1 of 1	Water Fountain	right	<1
79	412085	Unit A - Main Building	Fountain - Multi-Level	Left Of Se233	1 of 1	Water Fountain	left	<1
80	412086	Unit A - Main Building	Fountain - Multi-Level	Left Of Se233	1 of 1	Water Fountain	right	<1
81	412087	Unit A - Main Building	Fountain - Multi-Level	Outside Library	1 of 1	Water Fountain	left	<1
82	412088	Unit A - Main Building	Fountain - Multi-Level	Outside Library	1 of 1	Water Fountain	right	<1