

## Special Education Facilities

|                                       |                                   |                                                             |
|---------------------------------------|-----------------------------------|-------------------------------------------------------------|
| <b>Building Name</b>                  |                                   | <b>Room #</b>                                               |
| New Hanover-Upper Frederick El        |                                   | 312A                                                        |
| <b>School Building</b>                |                                   | <b>Building Description</b>                                 |
|                                       |                                   | A building in which general education programs are operated |
| <b>Classroom Measurements</b>         | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b>                       |
| 18 feet, 0 inches x 17 feet, 0 inches | 306sqft                           | 10                                                          |
| <b>Implementation Date</b>            |                                   |                                                             |
| 2021-08-16                            |                                   |                                                             |
| <b>Uploaded Files</b>                 |                                   |                                                             |
|                                       |                                   |                                                             |

### 1Assurance Check

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                               |                                   |                                                             |
|-------------------------------|-----------------------------------|-------------------------------------------------------------|
| <b>Building Name</b>          |                                   | <b>Room #</b>                                               |
| Colebrookdale El Sch          |                                   | 207                                                         |
| <b>School Building</b>        |                                   | <b>Building Description</b>                                 |
|                               |                                   | A building in which general education programs are operated |
| <b>Classroom Measurements</b> | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b>                       |

|                                       |         |    |
|---------------------------------------|---------|----|
| 36 feet, 0 inches x 24 feet, 0 inches | 864sqft | 30 |
| <b>Implementation Date</b>            |         |    |
| 2021-08-16                            |         |    |
| <b>Uploaded Files</b>                 |         |    |
|                                       |         |    |

## 2Assurance Check

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                                        |                                   |                                                             |
|----------------------------------------|-----------------------------------|-------------------------------------------------------------|
| <b>Building Name</b>                   |                                   | <b>Room #</b>                                               |
| Colebrookdale El Sch                   |                                   | 214                                                         |
| <b>School Building</b>                 |                                   | <b>Building Description</b>                                 |
|                                        |                                   | A building in which general education programs are operated |
| <b>Classroom Measurements</b>          | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b>                       |
| 14 feet, 10 inches x 11 feet, 0 inches | 163sqft                           | 5                                                           |
| <b>Implementation Date</b>             |                                   |                                                             |
| 2021-08-16                             |                                   |                                                             |
| <b>Uploaded Files</b>                  |                                   |                                                             |
|                                        |                                   |                                                             |

## 3Assurance Check

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                                       |                                   |                                                             |
|---------------------------------------|-----------------------------------|-------------------------------------------------------------|
| <b>Building Name</b>                  |                                   | <b>Room #</b>                                               |
| Boyertown Area SHS                    |                                   | 203                                                         |
| <b>School Building</b>                |                                   | <b>Building Description</b>                                 |
|                                       |                                   | A building in which general education programs are operated |
| <b>Classroom Measurements</b>         | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b>                       |
| 23 feet, 7 inches x 32 feet, 0 inches | 754sqft                           | 26                                                          |
| <b>Implementation Date</b>            |                                   |                                                             |
| 2021-08-16                            |                                   |                                                             |
| <b>Uploaded Files</b>                 |                                   |                                                             |
|                                       |                                   |                                                             |

#### 4Assurance Check

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                                        |                                   |                                                             |
|----------------------------------------|-----------------------------------|-------------------------------------------------------------|
| <b>Building Name</b>                   |                                   | <b>Room #</b>                                               |
| Boyertown Area MS-East                 |                                   | 115                                                         |
| <b>School Building</b>                 |                                   | <b>Building Description</b>                                 |
|                                        |                                   | A building in which general education programs are operated |
| <b>Classroom Measurements</b>          | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b>                       |
| 26 feet, 10 inches x 29 feet, 0 inches | 778sqft                           | 27                                                          |
| <b>Implementation Date</b>             |                                   |                                                             |
| 2021-08-16                             |                                   |                                                             |
| <b>Uploaded Files</b>                  |                                   |                                                             |
|                                        |                                   |                                                             |

#### 5Assurance Check

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                        |  |                                                             |
|------------------------|--|-------------------------------------------------------------|
| <b>Building Name</b>   |  | <b>Room #</b>                                               |
| Boyertown Area MS-West |  | 17                                                          |
| <b>School Building</b> |  | <b>Building Description</b>                                 |
|                        |  | A building in which general education programs are operated |

| Classroom Measurements                | Classroom Area Measurement | Max # of students in classroom |
|---------------------------------------|----------------------------|--------------------------------|
| 17 feet, 0 inches x 11 feet, 3 inches | 191sqft                    | 6                              |
| <b>Implementation Date</b>            |                            |                                |
| 2021-08-16                            |                            |                                |
| <b>Uploaded Files</b>                 |                            |                                |
|                                       |                            |                                |

#### 6Assurance Check

| Assurance Check                                                                                | Yes | No |
|------------------------------------------------------------------------------------------------|-----|----|
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

| Building Name                         |                            | Room #                                                      |
|---------------------------------------|----------------------------|-------------------------------------------------------------|
| Washington El Sch                     |                            | 60                                                          |
| School Building                       |                            | Building Description                                        |
|                                       |                            | A building in which general education programs are operated |
| Classroom Measurements                | Classroom Area Measurement | Max # of students in classroom                              |
| 23 feet, 0 inches x 13 feet, 0 inches | 299sqft                    | 10                                                          |
| <b>Implementation Date</b>            |                            |                                                             |
| 2021-08-16                            |                            |                                                             |
| <b>Uploaded Files</b>                 |                            |                                                             |
|                                       |                            |                                                             |

### 7Assurance Check

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                                       |                                   |                                                             |
|---------------------------------------|-----------------------------------|-------------------------------------------------------------|
| <b>Building Name</b>                  |                                   | <b>Room #</b>                                               |
| Boyertown Area MS-East                |                                   | 116                                                         |
| <b>School Building</b>                |                                   | <b>Building Description</b>                                 |
|                                       |                                   | A building in which general education programs are operated |
| <b>Classroom Measurements</b>         | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b>                       |
| 22 feet, 4 inches x 17 feet, 4 inches | 387sqft                           | 13                                                          |
| <b>Implementation Date</b>            |                                   |                                                             |
| 2021-08-16                            |                                   |                                                             |
| <b>Uploaded Files</b>                 |                                   |                                                             |
|                                       |                                   |                                                             |

### 8Assurance Check

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                                       |                                   |                                                             |
|---------------------------------------|-----------------------------------|-------------------------------------------------------------|
| <b>Building Name</b>                  |                                   | <b>Room #</b>                                               |
| Boyertown Area SHS                    |                                   | 720                                                         |
| <b>School Building</b>                |                                   | <b>Building Description</b>                                 |
|                                       |                                   | A building in which general education programs are operated |
| <b>Classroom Measurements</b>         | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b>                       |
| 36 feet, 0 inches x 29 feet, 0 inches | 1044sqft                          | 37                                                          |
| <b>Implementation Date</b>            |                                   |                                                             |
| 2021-08-16                            |                                   |                                                             |
| <b>Uploaded Files</b>                 |                                   |                                                             |
|                                       |                                   |                                                             |

#### 9Assurance Check

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                        |  |                                                             |
|------------------------|--|-------------------------------------------------------------|
| <b>Building Name</b>   |  | <b>Room #</b>                                               |
| Gilbertsville El Sch   |  | 130                                                         |
| <b>School Building</b> |  | <b>Building Description</b>                                 |
|                        |  | A building in which general education programs are operated |

| Classroom Measurements                | Classroom Area Measurement | Max # of students in classroom |
|---------------------------------------|----------------------------|--------------------------------|
| 31 feet, 0 inches x 17 feet, 0 inches | 527sqft                    | 18                             |
| <b>Implementation Date</b>            |                            |                                |
| 2021-08-16                            |                            |                                |
| <b>Uploaded Files</b>                 |                            |                                |
|                                       |                            |                                |

#### 10Assurance Check

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                                       |                                   |                                                             |
|---------------------------------------|-----------------------------------|-------------------------------------------------------------|
| <b>Building Name</b>                  |                                   | <b>Room #</b>                                               |
| Gilbertsville El Sch                  |                                   | 164                                                         |
| <b>School Building</b>                |                                   | <b>Building Description</b>                                 |
|                                       |                                   | A building in which general education programs are operated |
| <b>Classroom Measurements</b>         | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b>                       |
| 27 feet, 0 inches x 28 feet, 5 inches | 767sqft                           | 27                                                          |
| <b>Implementation Date</b>            |                                   |                                                             |
| 2021-08-16                            |                                   |                                                             |
| <b>Uploaded Files</b>                 |                                   |                                                             |
|                                       |                                   |                                                             |

**11Assurance Check**

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                                       |                                   |                                                             |
|---------------------------------------|-----------------------------------|-------------------------------------------------------------|
| <b>Building Name</b>                  |                                   | <b>Room #</b>                                               |
| New Hanover-Upper Frederick El        |                                   | 112                                                         |
| <b>School Building</b>                |                                   | <b>Building Description</b>                                 |
|                                       |                                   | A building in which general education programs are operated |
| <b>Classroom Measurements</b>         | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b>                       |
| 26 feet, 0 inches x 22 feet, 0 inches | 572sqft                           | 20                                                          |
| <b>Implementation Date</b>            |                                   |                                                             |
| 2021-08-16                            |                                   |                                                             |
| <b>Uploaded Files</b>                 |                                   |                                                             |
|                                       |                                   |                                                             |

**12Assurance Check**

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                                       |                                   |                                                             |
|---------------------------------------|-----------------------------------|-------------------------------------------------------------|
| <b>Building Name</b>                  |                                   | <b>Room #</b>                                               |
| Boyertown Area SHS                    |                                   | 207                                                         |
| <b>School Building</b>                |                                   | <b>Building Description</b>                                 |
|                                       |                                   | A building in which general education programs are operated |
| <b>Classroom Measurements</b>         | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b>                       |
| 35 feet, 5 inches x 30 feet, 0 inches | 1062sqft                          | 37                                                          |
| <b>Implementation Date</b>            |                                   |                                                             |
| 2021-08-16                            |                                   |                                                             |
| <b>Uploaded Files</b>                 |                                   |                                                             |
|                                       |                                   |                                                             |

### 13Assurance Check

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                        |  |                                                             |
|------------------------|--|-------------------------------------------------------------|
| <b>Building Name</b>   |  | <b>Room #</b>                                               |
| Gilbertsville El Sch   |  | 29                                                          |
| <b>School Building</b> |  | <b>Building Description</b>                                 |
|                        |  | A building in which general education programs are operated |

|                                       |                                   |                                       |
|---------------------------------------|-----------------------------------|---------------------------------------|
| <b>Classroom Measurements</b>         | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b> |
| 21 feet, 5 inches x 31 feet, 5 inches | 672sqft                           | 24                                    |
| <b>Implementation Date</b>            |                                   |                                       |
| 2021-08-16                            |                                   |                                       |
| <b>Uploaded Files</b>                 |                                   |                                       |
|                                       |                                   |                                       |

#### 14Assurance Check

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                                       |                                   |                                                             |
|---------------------------------------|-----------------------------------|-------------------------------------------------------------|
| <b>Building Name</b>                  |                                   | <b>Room #</b>                                               |
| Boyertown Area MS-East                |                                   | 324                                                         |
| <b>School Building</b>                |                                   | <b>Building Description</b>                                 |
|                                       |                                   | A building in which general education programs are operated |
| <b>Classroom Measurements</b>         | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b>                       |
| 33 feet, 0 inches x 28 feet, 8 inches | 946sqft                           | 33                                                          |
| <b>Implementation Date</b>            |                                   |                                                             |
| 2021-08-16                            |                                   |                                                             |
| <b>Uploaded Files</b>                 |                                   |                                                             |
|                                       |                                   |                                                             |

**15Assurance Check**

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                                       |                                   |                                                             |
|---------------------------------------|-----------------------------------|-------------------------------------------------------------|
| <b>Building Name</b>                  |                                   | <b>Room #</b>                                               |
| Boyertown El Sch                      |                                   | 183                                                         |
| <b>School Building</b>                |                                   | <b>Building Description</b>                                 |
|                                       |                                   | A building in which general education programs are operated |
| <b>Classroom Measurements</b>         | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b>                       |
| 19 feet, 0 inches x 38 feet, 0 inches | 722sqft                           | 25                                                          |
| <b>Implementation Date</b>            |                                   |                                                             |
| 2021-08-16                            |                                   |                                                             |
| <b>Uploaded Files</b>                 |                                   |                                                             |
|                                       |                                   |                                                             |

**16Assurance Check**

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                                       |                                   |                                                             |
|---------------------------------------|-----------------------------------|-------------------------------------------------------------|
| <b>Building Name</b>                  |                                   | <b>Room #</b>                                               |
| Washington El Sch                     |                                   | 48                                                          |
| <b>School Building</b>                |                                   | <b>Building Description</b>                                 |
|                                       |                                   | A building in which general education programs are operated |
| <b>Classroom Measurements</b>         | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b>                       |
| 32 feet, 0 inches x 24 feet, 0 inches | 768sqft                           | 27                                                          |
| <b>Implementation Date</b>            |                                   |                                                             |
| 2021-08-16                            |                                   |                                                             |
| <b>Uploaded Files</b>                 |                                   |                                                             |
|                                       |                                   |                                                             |

#### 17Assurance Check

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                        |  |                                                             |
|------------------------|--|-------------------------------------------------------------|
| <b>Building Name</b>   |  | <b>Room #</b>                                               |
| Boyertown Area SHS     |  | 611                                                         |
| <b>School Building</b> |  | <b>Building Description</b>                                 |
|                        |  | A building in which general education programs are operated |

|                                       |                                   |                                       |
|---------------------------------------|-----------------------------------|---------------------------------------|
| <b>Classroom Measurements</b>         | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b> |
| 26 feet, 6 inches x 28 feet, 0 inches | 742sqft                           | 26                                    |
| <b>Implementation Date</b>            |                                   |                                       |
| 2021-08-16                            |                                   |                                       |
| <b>Uploaded Files</b>                 |                                   |                                       |
|                                       |                                   |                                       |

#### 18Assurance Check

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                                       |                                   |                                                             |
|---------------------------------------|-----------------------------------|-------------------------------------------------------------|
| <b>Building Name</b>                  |                                   | <b>Room #</b>                                               |
| Boyertown Area MS-East                |                                   | 322                                                         |
| <b>School Building</b>                |                                   | <b>Building Description</b>                                 |
|                                       |                                   | A building in which general education programs are operated |
| <b>Classroom Measurements</b>         | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b>                       |
| 30 feet, 0 inches x 28 feet, 8 inches | 860sqft                           | 30                                                          |
| <b>Implementation Date</b>            |                                   |                                                             |
| 2021-08-16                            |                                   |                                                             |
| <b>Uploaded Files</b>                 |                                   |                                                             |
|                                       |                                   |                                                             |

**19Assurance Check**

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

|                                       |                                   |                                                             |
|---------------------------------------|-----------------------------------|-------------------------------------------------------------|
| <b>Building Name</b>                  |                                   | <b>Room #</b>                                               |
| Boyertown Area MS-West                |                                   | 95                                                          |
| <b>School Building</b>                |                                   | <b>Building Description</b>                                 |
|                                       |                                   | A building in which general education programs are operated |
| <b>Classroom Measurements</b>         | <b>Classroom Area Measurement</b> | <b>Max # of students in classroom</b>                       |
| 32 feet, 0 inches x 35 feet, 0 inches | 1120sqft                          | 40                                                          |
| <b>Implementation Date</b>            |                                   |                                                             |
| 2021-08-16                            |                                   |                                                             |
| <b>Uploaded Files</b>                 |                                   |                                                             |
|                                       |                                   |                                                             |

**20Assurance Check**

|                                                                                                |     |    |
|------------------------------------------------------------------------------------------------|-----|----|
| Assurance Check                                                                                | Yes | No |
| The class is maintained as close as appropriate to the ebb and flow of usual school activities | Yes |    |
| The class is located where noise will not interfere with instruction                           | Yes |    |
| The class is located only in space that is designed for purposes of instruction                | Yes |    |
| The class is readily accessible                                                                | Yes |    |
| The class is composed of at least 28 square feet per student                                   | Yes |    |
| The location of the class has been maintained for at least 3 school years.                     | Yes |    |

