

## 1.2 Executive Summary of Sampling and Analysis:

### Summary of Samples Collected at Victor Early Childhood School:

| Building Name                 | Date of Sampling | Total Samples | At or Below Action Level* | Above Action Level* |
|-------------------------------|------------------|---------------|---------------------------|---------------------|
|                               |                  |               |                           |                     |
| Victor Early Childhood School | June 3, 2025     | 182           | 164                       | 18                  |
|                               | August 27, 2025  | 18            | 13                        | 5                   |
|                               | January 13, 2026 | 4             | 4                         | 0                   |
|                               |                  |               |                           |                     |

\*NYS Action Level is 5 parts per billion

### Listing of Outlets Requiring Remediation

The following outlets were analyzed above the NYS Action Level:

| Sample #  | Location                   | Fixture/Outlet Type | Laboratory Analysis (in ppb) |                 |                 |
|-----------|----------------------------|---------------------|------------------------------|-----------------|-----------------|
|           |                            |                     | 6/3/2025                     | 8/27/2025       | 1/13/2026       |
| 203.4-06  | Boys Lav by elevator right | Sink                | 6.9                          | 1.7 – Cleared   | —               |
| 203.4-10  | Girls Lav by 208 Left      | Sink                | 5.1                          | 1.4 – Cleared   | —               |
| 203.4-11  | Girls Lav by 208 Right     | Sink                | 6.4                          | 1.2 – Cleared   | —               |
| 203.4-13  | Room 208                   | Drinking Fountain   | 5.0                          | < 1.0 – Cleared | —               |
| 203.4-18  | Room 218                   | Sink                | 8.4                          | 61.8            | <1.00 – Cleared |
| 203.4-19  | Room 218                   | Drinking Fountain   | 9.4                          | 1.9 – Cleared   | —               |
| 203.4-58  | Room 013 Main              | Sink                | 10.4                         | 6.9             | —               |
| 203.4-59  | Room 013 Fac Lav           | Sink                | 7.8                          | 9.1             | <1.00 – Cleared |
| 203.4-81  | Kitchen 3 Bay Left         | Sink                | 23.1                         | 5.9             | <1.00 – Cleared |
| 203.4-86  | Kitchen Dishwash Handwash  | Sink                | 9.7                          | 1.5 – Cleared   | —               |
| 203.4-88  | PT Room 122/123            | Sink                | 5.6                          | 4.6 – Cleared   | —               |
| 203.4-89A | DF Across from Gym         | Drinking Fountain   | 14.1                         | 1.6 – Cleared   | —               |
| 203.4-89B | DF Across from Gym         | Bottle Fill         | 23.3                         | 1.6 – Cleared   | —               |
| 203.4-91  | 119 Lav                    | Sink                | 12.5                         | 4.3 – Cleared   | —               |
| 203.4-92  | Room 118                   | Sink                | 5.5                          | 2.4 – Cleared   | —               |
| 203.4-104 | 129 Rear Room              | Sink                | 6.2                          | 4.8 – Cleared   | —               |
| 203.4-119 | Girls Lav by 101 Left      | Sink                | 6.6                          | 1.8 – Cleared   | —               |
| 203.4-158 | Mens Lav Main Entrance     | Sink                | 8.8                          | 6.2             | <1.00 – Cleared |

## 1.2 Executive Summary of Sampling and Analysis:

### Summary of Samples Collected at Victor Primary School:

| Building Name         | Date of Sampling | Total Samples | At or Below Action Level* | Above Action Level* |
|-----------------------|------------------|---------------|---------------------------|---------------------|
|                       |                  |               |                           |                     |
| Victor Primary School | June 3, 2025     | 174           | 141                       | 33                  |
|                       | August 27, 2025  | 29            | 11                        | 18                  |
|                       | January 13, 2026 | 11            | 10                        | 1                   |
|                       |                  |               |                           |                     |

\*NYS Action Level is 5 parts per billion

### Listing of Outlets Requiring Remediation

The following outlets were analyzed above the NYS Action Level:

| Sample #  | Location                         | Fixture/Outlet Type | Laboratory Analysis (in ppb) |                |                 |
|-----------|----------------------------------|---------------------|------------------------------|----------------|-----------------|
|           |                                  |                     | 6/3/2025                     | 8/27/2025      | 1/13/2026       |
| 172.3-9   | Kitchen Combitherm Sprayer Right | Sink                | 8.0                          | —              | —               |
| 172.3-14  | Room 138                         | Sink                | 11.7                         | 1.7 – Cleared  | —               |
| 172.3-15  | Room 138                         | Drinking Fountain   | 6.4                          | <1.0 – Cleared | —               |
| 172.3-16  | Room 136                         | Sink                | 6.5                          | 1.7 – Cleared  | —               |
| 172.3-17  | Room 131 Lav                     | Sink                | 5.9                          | 1.8 – Cleared  | —               |
| 172.3-18  | Room 131 Lav                     | Sink                | 7.5                          | —              | —               |
| 172.3-23  | 129 Women's Fac Left             | Sink                | 5.1                          | Sample Hold    | —               |
| 172.3-25  | Room 134                         | Sink                | 9.1                          | <1.0 – Cleared | —               |
| 172.3-27  | Room 132                         | Sink                | 12.0                         | Sample Hold    | —               |
| 172.3-28  | Room 132                         | Drinking Fountain   | 39.1                         | 1.1 – Cleared  | —               |
| 172.3-29  | Room 130                         | Sink                | 12.6                         | <1.0 – Cleared | —               |
| 172.3-30  | Room 128                         | Sink                | 7.5                          | 3.9 – Cleared  | —               |
| 172.3-34  | Room 125 Rear                    | Sink                | 14.0                         | 26.5           | <1.00 – Cleared |
| 172.3-35  | Kiln Room                        | Sink                | 13.4                         | 105            | 1.14 – Cleared  |
| 172.3-37  | Room 123                         | Drinking Fountain   | 14.2                         | <1.0 – Cleared | —               |
| 172.3-62  | Room 113                         | Drinking Fountain   | 5.5                          | <1.0 – Cleared | —               |
| 172.3-86  | Room 107                         | Drinking Fountain   | 5.0                          | 3.3 – Cleared  | —               |
| 172.3-87  | Room 143                         | Drinking Fountain   | 10.3                         | 1.1 – Cleared  | —               |
| 172.3-125 | Room 168                         | Sink                | 5.8                          | 2.8 – Cleared  | —               |
| 172.3-133 | Room 164                         | Sink                | 5.1                          | 2.4 – Cleared  | —               |

| Sample #  | Location               | Fixture/Outlet Type | Laboratory Analysis<br>(in ppb) |                |                 |
|-----------|------------------------|---------------------|---------------------------------|----------------|-----------------|
|           |                        |                     | 6/3/2025                        | 8/27/2025      | 1/13/2026       |
| 172.3-134 | Room 161               | Sink                | 9.9                             | 5.1            | <1.00 – Cleared |
| 172.3-135 | Room 161               | Drinking Fountain   | 14.5                            | 1.2 – Cleared  | —               |
| 172.3-141 | Room 160               | Drinking Fountain   | 5.0                             | <1.0 – Cleared | —               |
| 172.3-142 | Room 157               | Sink                | 6.1                             | 5.1            | <1.00 – Cleared |
| 172.3-145 | Room 158               | Sink                | 8.3                             | 14.3           | <1.00 – Cleared |
| 172.3-146 | Room 158               | Drinking Fountain   | 12.1                            | <1.0 – Cleared | —               |
| 172.3-148 | Room 201               | Sink                | 11.2                            | 9.5            | <1.00 – Cleared |
| 172.3-149 | Room 156               | Sink                | 5.0                             | 4.6 – Cleared  | —               |
| 172.3-151 | Room 156 Lav           | Sink                | 5.6                             | 6.1            | <1.00 – Cleared |
| 172.3-157 | Girls Lav Center Left  | Sink                | 8.1                             | 8.4            | 2.45 – Cleared  |
| 172.3-158 | Girls Lav Center Right | Sink                | 8.0                             | 6.2            | 13.6            |
| 172.3-159 | Girls Lav 2nd Right    | Sink                | 6.7                             | 8.5            | <1.00 – Cleared |
| 172.3-174 | Room 153 Lav           | Sink                | 8.2                             | 12.4           | <1.00 – Cleared |

## 1.2 Executive Summary of Sampling and Analysis:

### Summary of Samples Collected at Victor Intermediate School:

| Building Name              | Date of Sampling | Total Samples | At or Below Action Level* | Above Action Level* |
|----------------------------|------------------|---------------|---------------------------|---------------------|
|                            |                  |               |                           |                     |
| Victor Intermediate School | June 2, 2025     | 165           | 117                       | 48                  |
|                            | August 27, 2025  | 44            | 16                        | 28                  |
|                            | January 13, 2026 | 26            | 24                        | 2                   |
|                            |                  |               |                           |                     |

\*NYS Action Level is 5 parts per billion

### Listing of Outlets Requiring Remediation

The following outlets were analyzed above the NYS Action Level:

| Sample #  | Location                       | Fixture/Outlet Type | Laboratory Analysis (in ppb) |               |                 |
|-----------|--------------------------------|---------------------|------------------------------|---------------|-----------------|
|           |                                |                     | 6/2/2025                     | 8/27/2025     | 1/13/2026       |
| 203.2-01  | Receiving 143 Unisex Rest Room | Sink                | 5.6                          | 2.1 – Cleared | —               |
| 203.2-10  | Kitchen 3 Bay Right            | Sink                | 10.1                         | —             | —               |
| 203.2-11  | Kitchen 3 Bay Left             | Sink                | 8.5                          | —             | —               |
| 203.2-14  | Snack Bar 146                  | Sink                | 10.6                         | 9.5           | 3.96 – Cleared  |
| 203.2-15  | Aide Room 149 inside room 148  | Sink                | 7.5                          | —             | —               |
| 203.2-18  | Fac Women by 195 left          | Sink                | 5.0                          | 2.0 – Cleared | —               |
| 203.2-19  | Unisex in 195                  | Sink                | 485                          | 8.1           | <1.00 – Cleared |
| 203.2-20  | PPS Office Fac Lav Left        | Sink                | 8.1                          | 1.1 – Cleared | —               |
| 203.2-21  | PPS Office Fac Lav Right       | Sink                | 9.3                          | 1.6 – Cleared | —               |
| 203.2-22  | Room 160 Lav                   | Sink                | 155                          | 6.6           | —               |
| 203.2-34  | Music Room 193                 | Sink                | 18.9                         | 85.8          | —               |
| 203.2-56  | Girls Lav Outside 116A C       | Sink                | 9.1                          | 6.4           | <1.00 – Cleared |
| 203.2-57  | Girls Lav outside 116a R       | Sink                | 6.1                          | 14.4          | <1.00 – Cleared |
| 203.2-62  | Room 184                       | Sink                | 7.3                          | Sample Hold   | —               |
| 203.2-63  | Room 183                       | Sink                | 6.0                          | 3.1 – Cleared | —               |
| 203.2-107 | DF by Elevator                 | Drinking Fountain   | 5.2                          | 1.0 – Cleared | —               |
| 203.2-108 | Room 134                       | Sink                | 9.5                          | 16.7          | <1.00 – Cleared |
| 203.2-110 | Room 135                       | Sink                | 16.3                         | 142           | <1.00 – Cleared |
| 203.2-111 | Room 136                       | Sink                | 21.9                         | 150           | <1.00 – Cleared |
| 203.2-112 | Room 137                       | Sink                | 18.7                         | 50.6          | <1.00 – Cleared |

| Sample #  | Location                 | Fixture/Outlet Type | Laboratory Analysis<br>(in ppb) |                 |                 |
|-----------|--------------------------|---------------------|---------------------------------|-----------------|-----------------|
|           |                          |                     | 6/2/2025                        | 8/27/2025       | 1/13/2026       |
| 203.2-113 | Boys Lav by Lib L        | Sink                | 5.2                             | 7.2             | <1.00 – Cleared |
| 203.2-115 | Boys Lav by Lib RC       | Sink                | 11.6                            | 1.2 – Cleared   | —               |
| 203.2-116 | Boys Lav by Lib R        | Sink                | 149                             | 10.7            | <1.00 – Cleared |
| 203.2-119 | Girls Lav by Lib L       | Sink                | 12.1                            | 7.0             | 5.83            |
| 203.2-121 | Girls Lav by Lib RC      | Sink                | 8.7                             | 1.1 – Cleared   | —               |
| 203.2-124 | Room 213                 | Sink                | 10.3                            | 8.7             | <1.00 – Cleared |
| 203.2-125 | Room 212                 | Sink                | 6.7                             | 12.9            | 4.10 – Cleared  |
| 203.2-126 | Room 214                 | Sink                | 13.5                            | 1.8 – Cleared   | —               |
| 203.2-127 | Room 211                 | Sink                | 6.8                             | 13.7            | <1.00 – Cleared |
| 203.2-128 | Room 215                 | Sink                | 7.7                             | 3.7 – Cleared   | —               |
| 203.2-129 | Room 210                 | Sink                | 8.2                             | 14.7            | <1.00 – Cleared |
| 203.2-131 | Room 209                 | Sink                | 8.0                             | 2.3 – Cleared   | —               |
| 203.2-132 | Room 208                 | Sink                | 6.7                             | 46.6            | <1.00 – Cleared |
| 203.2-133 | Room 217                 | Sink                | 8.3                             | 24.7            | <1.00 – Cleared |
| 203.2-136 | Boys Lav Across 207 RC   | Sink                | 6.4                             | < 1.0 – Cleared | —               |
| 203.2-140 | Room 207                 | Sink                | 13.3                            | 44.7            | <1.00 – Cleared |
| 203.2-147 | Room 219 Handwash sink L | Sink                | 10.5                            | 3.9 – Cleared   | —               |
| 203.2-148 | Room 221 Handwash sink L | Sink                | 10.8                            | 2.9 – Cleared   | —               |
| 203.2-149 | Room 206                 | Sink                | 12.2                            | 65.0            | <1.00 – Cleared |
| 203.2-150 | Room 205                 | Sink                | 13.1                            | 6.0             | <1.00 – Cleared |
| 203.2-151 | Room 223                 | Sink                | 15.0                            | 3.6 – Cleared   | —               |
| 203.2-154 | Room 204                 | Sink                | 11.4                            | 20.9            | <1.00 – Cleared |
| 203.2-155 | Room 203                 | Sink                | 13.0                            | 41.2            | <1.00 – Cleared |
| 203.2-156 | Room 227                 | Sink                | 26.5                            | 6.2             | <1.00 – Cleared |
| 203.2-157 | Room 202 Far Door L      | Sink                | 14.4                            | 24.3            | 91.2            |
| 203.2-159 | Room 202 Near Door L     | Sink                | 8.8                             | 16.5            | <1.00 – Cleared |
| 203.2-160 | Room 202 Near Door R     | Sink                | 10.3                            | 26.0            | <1.00 – Cleared |
| 203.2-161 | DF Outside 227           | Drinking Fountain   | 5.5                             | 1.3 – Cleared   | —               |

## 1.2 Executive Summary of Sampling and Analysis:

### Summary of Samples Collected at Victor Jr/Sr High School:

| Building Name            | Date of Sampling | Total Samples | At or Below Action Level* | Above Action Level* |
|--------------------------|------------------|---------------|---------------------------|---------------------|
|                          |                  |               |                           |                     |
| Victor Jr/Sr High School | June 2, 2025     | 207           | 192                       | 15                  |
|                          | August 27, 2025  | 4             | 3                         | 1                   |
|                          | January 13, 2026 | 1             | 1                         | 0                   |
|                          |                  |               |                           |                     |

\*NYS Action Level is 5 parts per billion

### Listing of Outlets Requiring Remediation

The following outlets were analyzed above the NYS Action Level:

| Sample #  | Location                    | Fixture/Outlet Type | Laboratory Analysis (in ppb) |                 |                 |
|-----------|-----------------------------|---------------------|------------------------------|-----------------|-----------------|
|           |                             |                     | 6/2/2025                     | 8/27/2025       | 1/13/2026       |
| 203.1-30  | C244 Center                 | Sink                | 7.0                          | 2.3 – Cleared   | —               |
| 203.1-50  | A221A Storage               | Sink                | 9.3                          | —               | —               |
| 203.1-80  | Old Boys Locker L           | Sink                | 55.4                         | —               | —               |
| 203.1-81  | Old Boys Locker C           | Sink                | 29.9                         | —               | —               |
| 203.1-82  | Old Boys Locker R           | Sink                | 9.8                          | —               | —               |
| 203.1-87  | Middle Kitchen Sink         | Sink                | 9.4                          | —               | —               |
| 203.1-88  | Double Sink Left            | Sink                | 12.1                         | —               | —               |
| 203.1-89  | Double Sink Right           | Sink                | 40.4                         | —               | —               |
| 203.1-90  | Sprayer in middle           | Sink                | 59.7                         | —               | —               |
| 203.1-94  | DF Outside 166 Left         | Drinking Fountain   | 11.5                         | < 1.0 – Cleared | —               |
| 203.1-102 | Boys Locker L               | Sink                | 21.4                         | 1.1 – Cleared   | —               |
| 203.1-115 | Boys Locker L               | Sink                | 17.9                         | 16.3            | < 1.0 – Cleared |
| 203.1-140 | Room 116A Prep              | Sink                | 10.6                         | —               | —               |
| 203.1-178 | Kitchen By Dough Mixer      | Sink                | 9.1                          | —               | —               |
| 203.1-182 | Concession Stand Sink Right | Sink                | 8.5                          | —               | —               |